

REPORT

ASS: REC: BY:

REF: CS/FCI/702045 / S/bn2 Special Instruction

Surveyor: Sebastian ASSIGNMENT (Office)

CWS

From (Person): Karen Tan of FCI Date/Time: 9.22am @ 01/11/17

Estimated Cost: Bill to:

OD: TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCR 8550X Insured: SHC 1476T

at Workshop m/s: Hui Hong Pte. Ltd. Tel: 66619688

of 25D Sungai kadut Street 1

Policy No: Claim No: D17010166 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 28/10/2017

(Client's Record) 'up' 03.11.2017 @ after 1pm

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.30am @ 01/11/17 Person Contacted: Yvonne Vehicle IN/OUT

Date/Time: Action/Instruction (✓) Estimate

SCR 8550X - CC7 / AIG 12013549 / KI-1 - D.O.A : 9/7/2012

SHC 1476T - CC1 / AXA 16019220 / M/WG 392 - D.O.A : 9/10/2016

lump sum \$1750 (Red: 765.44 : 30%)

Date: 03/11/2017

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Make of Veh

| Date / Time | Action / Instruction |
|-------------|----------------------|
|-------------|----------------------|

Verf: JCK 8540 x 4/1/1008

Howden Civic cc 1799

|        |        |     |                         |
|--------|--------|-----|-------------------------|
| Colour | Silver | A/C | Insured / Std / NI / NA |
|--------|--------|-----|-------------------------|

So Reading: 320333 T-Radio: Insured / Std / NI / NA

Enc No

CN: JHMF0163085211083

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: **ND** / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R<sub>2</sub> 41

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or Continental

Front

|        |    |        |    |
|--------|----|--------|----|
| R/Bal. | mm | R/Bal. | mm |
|--------|----|--------|----|

L Ba 6 mm
 L Ba 6 mm

DOA 12/10/2017. DOA 3/11/2017.

Survey held at Hua Ung

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 04 JAN 2011

2007-07-16 14:16:10

# AI Typist

Data Time File Return 22

☐ : Prel. Report  
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Suppose

Add Fee: ☐ Size Fee: \$

|  |    |    |    |    |
|--|----|----|----|----|
|  | 17 | 18 | 19 | 20 |
|--|----|----|----|----|

1070-0110/01/0000-0000\$05.00/0

| Author(s) | Year | Country | Sample Size | Study Design |
|-----------|------|---------|-------------|--------------|
| ...       | ...  | ...     | ...         | ...          |

|                                                                                      |                                                                                      |
|--------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <p> <input type="checkbox"/> <b>Yes</b><br/> <input type="checkbox"/> <b>No</b> </p> | <p> <input type="checkbox"/> <b>Yes</b><br/> <input type="checkbox"/> <b>No</b> </p> |
|--------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|

110

50

50

30

240

### Report Format:

Lump Sum/L.B.E. = 6



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17020845/Stb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-11-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SHC 1476T       | Veh. Inspected | SCR 8550X  |
| Policy No.   |                 | Coverage (\$)  | 0.00       |
| Claim No.    | D17010166MFSH   | Excess (\$)    | 0.00       |
| Assign From  | CWS (KAREN TAN) | Assign Date    | 01/11/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                                                |                 |
|----------------|----------------------------------------------------------------|-----------------|
| Accident Date  | 28/10/2017                                                     | Inspection Date |
| Survey held at | HUA HONG PTE LTD<br>25D SUNGEI KADUT STREET 1 SINGAPORE 729332 |                 |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

Job Sheet (/ClaimWS/Surveyor/JobSheet/229670)



PRI Documents



Close



## PRI Header Details

|                          |                                                       |                                              |                                                                                                                                               |                                 |              |
|--------------------------|-------------------------------------------------------|----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|--------------|
| <b>Claim No</b>          | D17010166MFSH                                         | <b>Policy No</b>                             | D-15072701MFSH                                                                                                                                | <b>Claimant S.No &amp; Name</b> | 1 & HUA HONG |
| <b>Workshop Name</b>     | HUA HONG PRIVATE LIMITED<br>(Contact Person : MS TAN) | <b>Survey Location &amp; Contact Details</b> | 25D SUNGEI KADUT STREET 1<br><b>Mobile:</b> 66619695 , <b>Phone:</b> 66619688 , <b>Fax:</b> 66619695<br><b>EmailId:</b> YVONNE@HUAHONG.COM.SG |                                 |              |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD                          | <b>Instructions To Surveyor</b>              | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM T                                                                                               |                                 |              |
| <b>Insured Name</b>      | COMFORT TRANSPORTATION PTE LTD                        | <b>Insured Vehicle No</b>                    | SHC1476T                                                                                                                                      | <b>TP Vehicle No</b>            | SCR8550X     |
| <b>PRI Recieved Date</b> | 31-10-2017 07:56:31 PM                                | <b>Surveyor Appointed Date</b>               | 01-11-2017 09:21:46 AM                                                                                                                        | <b>Surveyor Accept Date</b>     | 01-11-2017 0 |

## Survey Report Upload

|                                    |                      |                             |            |                                |                                            |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--------------------------------------------|
| <b>Surveyor Inspection Date *:</b> | <input type="text"/> | <b>Surveyor Report Date</b> | 01-11-2017 | <b>Upload Survey Report *:</b> | <input type="button" value="Choose File"/> |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--------------------------------------------|

## Vehicle Particulars

|                  |                                                 |                       |                                                  |                |                                          |
|------------------|-------------------------------------------------|-----------------------|--------------------------------------------------|----------------|------------------------------------------|
| <b>Make</b>      | <input type="text" value="Please Select Make"/> | <b>Model</b>          | <input type="text" value="Please Select Model"/> | <b>Year</b>    | <input type="text" value="Select Year"/> |
| <b>Chasis No</b> | <input type="text"/>                            | <b>Engine No</b>      | <input type="text"/>                             | <b>Mileage</b> | <input type="text"/>                     |
| <b>Color</b>     | <input type="text"/>                            | <b>Cubic Capacity</b> | <input type="text"/>                             |                |                                          |

## Multiple Documents Upload

|                                                          |               |
|----------------------------------------------------------|---------------|
| <input type="button" value="Upload Multiple Documents"/> |               |
| <b>File Name</b>                                         | <b>Action</b> |

## Surveyor Job Remarks

|                |                      |                                     |
|----------------|----------------------|-------------------------------------|
| <b>Remarks</b> | <input type="text"/> | <input type="button" value="Save"/> |
|----------------|----------------------|-------------------------------------|

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                          |
|-------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>    |                          |
| Owner ID Type                       | Singapore NRIC           |
| Owner ID                            | 2420G                    |
| <b>Vehicle Details</b>              |                          |
| Vehicle No.                         | SCR8550X                 |
| Vehicle to be Exported              | Yes                      |
| Intended De-registration Date       | 03 Nov 2017              |
| Vehicle Make                        | HONDA                    |
| Vehicle Model                       | CIVIC 1.8L A             |
| Primary Colour                      | Silver                   |
| Manufacturing Year                  | 2007                     |
| Engine No.                          | R18A13018051             |
| Chassis No.                         | JHMF16308S211083         |
| Maximum Power Output                | 103.0 kW (138 bhp)       |
| Open Market Value                   | \$20,899.00              |
| Original Registration Date          | 04 Jan 2008              |
| First Registration Date             | 04 Jan 2008              |
| Transfer Count                      | 0                        |
| Actual ARF Paid                     | \$22,989.00              |
| <b>Intended PARF Rebate Details</b> |                          |
| PARF Eligibility                    | Yes                      |
| PARF Eligibility Expiry Date        | 03 Jan 2018              |
| PARF Rebate Amount                  | \$11,494.00              |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date                     | 03 Jan 2018              |
| COE Category                        | B - Car (1601cc & above) |
| COE Period(Years)                   | 10                       |
| QP Paid                             | \$13,114.00              |
| COE Rebate Amount                   | \$218.00                 |
| <b>Total Rebate Amount</b>          | <b>\$11,712.00</b>       |

The information contained herein is correct as at 03 Nov 2017

OK



# HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

1 November 2017

First Capital Insurance Limited  
36 Robinson Road  
#16-01 City House  
Singapore 068877

Attn: Motor Claims Department

Sebastian  
3/11/2017  
- Lump Sum Repair  
- Photo After Paint  
96036121  
sebastianyeang@hkanto.com

4 days.

hence notify

of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to confirmation by the Company

HTTPC17-94

Acknowledged by Repairer

Signature:

Date:

## ACCIDENT INVOLVING SCR 8550 X & SHC 1476 T ON 28/10/2017 ALONG MANDAI ROAD AT ABOUT 2105 HOURS

Insured : PETER NEO KEE WEE  
Vehicle Registration No : SCR 8550 X  
Vehicle Make : HONDA  
Vehicle Model : CIVIC 1.8L A  
Vehicle Chassis No : JHMF16308S211083  
Policy No : Z17VP05012862  
Date of Accident : 28/10/2017

Type of Claim: Third Party

| S/N                                                                                                                                                                             | Quantity | Description                         | Unit Price S\$ | Amount S\$       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------------------------------|----------------|------------------|
| 1                                                                                                                                                                               | 1        | Front Door (RH) ✓ VDT               |                | \$ 841.30        |
| 2                                                                                                                                                                               | 1        | Front Door Protector (RH) ✓ NEC     |                | \$ 107.40        |
| 3                                                                                                                                                                               | 1        | Front Door Weather Strip (RH) ✓ NEC |                | \$ 94.80         |
| 4                                                                                                                                                                               | 1        | Front Outer Moulding (RH) ✓ Cut     |                | \$ 125.80        |
|                                                                                                                                                                                 |          |                                     |                | \$ 1,169.30      |
| Less 20%                                                                                                                                                                        |          |                                     |                | \$ (233.86)      |
|                                                                                                                                                                                 |          |                                     |                | \$ 935.44        |
| To dismantle, repair & refit front bumper, dismantle & change front RH door, knocking & pull straight front RH rocker panel, front RH fender and all area affected by accident. |          |                                     |                | \$ 700.00<br>500 |
| To perform wire checking.                                                                                                                                                       |          |                                     |                | \$ 20.00 ✓       |
| To dismantle & transfer front RH door fitting and mechanism to new door.                                                                                                        |          |                                     |                | \$ 60.00 ✓       |
| To spray front RH door, front RH rocker panel, front RH fender, front RH side mirror and front RH mud flaps.                                                                    |          |                                     |                | \$ 800.00 700    |
|                                                                                                                                                                                 |          |                                     |                | \$ 2,515.44      |
| 7% GST                                                                                                                                                                          |          |                                     |                | \$ 176.08        |
| Total                                                                                                                                                                           |          |                                     |                | \$ 2,691.52      |

Authorised by Claims Dept  
Mrs Tan @ 9639 9195



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                |                 |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|-----------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                |                 | Ref : CS/FCI17020845/Stbn2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                |                 | Date : 04-01-2018          |  |
|                                                                                                                                                                                        |                                                                |                 | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                |                 |                            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 1476T                                                      | Veh. Inspected  | SCR 8550X                  |                                                                                     |
| Policy No.                                                                                                                                                                             | D-15072701MFSH                                                 | Coverage (\$)   | 0.00                       |                                                                                     |
| Claim No.                                                                                                                                                                              | D17010166MFSH                                                  | Excess (\$)     | 0.00                       |                                                                                     |
| Assign From                                                                                                                                                                            | KARENT                                                         | Assign Date     | 01/11/2017                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                |                 |                            |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA CIVIC                                                    | c.c             | 1799                       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                         | Year of Reg.    | 2008                       |                                                                                     |
| Chassis No.                                                                                                                                                                            | JHMF16308S211083                                               | Colour          | SILVER                     |                                                                                     |
| Odometer                                                                                                                                                                               | 20333                                                          | Steering        | IN ORDER                   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                       | Modification    | NIL                        |                                                                                     |
| General                                                                                                                                                                                | FAIR                                                           |                 |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                |                 |                            |                                                                                     |
|                                                                                                                                                                                        | Size                                                           | Make            | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 205/55 R16                                                     | CONTINENTAL     | 6 mm                       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 205/55 R16                                                     | CONTINENTAL     | 6 mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 205/55 R16                                                     | CONTINENTAL     | 6 mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 205/55 R16                                                     | CONTINENTAL     | 6 mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                |                 |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.<br>DAMAGES SEE DETAILS.                                                                                                                 |                                                                |                 |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                |                 |                            |                                                                                     |
| Accident Date                                                                                                                                                                          | 28/10/2017                                                     | Inspection Date | 03/11/2017                 |                                                                                     |
| Survey held at                                                                                                                                                                         | HUA HONG PTE LTD<br>25D SUNGEI KADUT STREET 1 SINGAPORE 729332 |                 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                |                 |                            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                |                 |                            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                |                 |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                | 4 Working Days  |                            |                                                                                     |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCR 8550X**

| Qty | Description of Parts                                                                                                                                                        | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                                                                                                                          |           |                           |                   |
| 1   | FRONT DOOR (RH)                                                                                                                                                             | DENTED    | 841.30                    | 841.30            |
| 1   | FRONT DOOR PROTECTOR (RH)                                                                                                                                                   | NECESSARY | 107.40                    | 107.40            |
| 1   | FRONT DOOR WEATHER STRIP (RH)                                                                                                                                               | NECESSARY | 94.80                     | 94.80             |
| 1   | FRONT OUTER MOULDING (RH)                                                                                                                                                   | CUT       | 125.80                    | 125.80            |
|     | LESS 20% DISCOUNT                                                                                                                                                           |           | -233.86                   | -233.86           |
|     |                                                                                                                                                                             |           | <b>935.44</b>             | <b>935.44</b>     |
|     | <b><u>LABOUR</u></b>                                                                                                                                                        |           |                           |                   |
|     | TO DISMANTLE,REPAIR & REFIT FRONT BUMPER,DISMANTLE & CHANGE FRONT RH DOOR,KNOCKING & PULL STRAIGHT FRONT RH ROCKER PANEL,FRONT RH FENDER AND ALL AREA AFFECTED BY ACCIDENT. |           | 700.00                    | 500.00            |
|     | TO PERFORM WIRE CHECKING.                                                                                                                                                   |           | 20.00                     | 20.00             |
|     | TO DISMANTLE & TRANSFER FRONT RH DOOR FITTING AND MECHANISM TO NEW DOOR.                                                                                                    |           | 60.00                     | 60.00             |
|     | TO SPRAY FRONT RH DOOR,FRONT RH ROCKER PANEL,FRONT RH FENDER,FRONT RH SIDE MIRROR AND FRONT RH MUD FLAPS.                                                                   |           | 800.00                    | 700.00            |
|     |                                                                                                                                                                             |           | <b>1,580.00</b>           | <b>1,280.00</b>   |
|     | <b>GRAND TOTAL</b>                                                                                                                                                          |           | <b>2,515.44</b>           | <b>2,215.44</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>                                                                                                 |           |                           | <b>1,750.00</b>   |

Report Ref No. CS/FCI17020845/Stbn2

**YEANG WAI KEEN**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.