















































HONDA AUTOMOBILE(THAILAND)CO.,LTD.
CHASSIS NO. MRHRU1830FP000141
ENGINE NO. L15Z7-1000165
T8P F ZB6 NH731P A





After Repair