

20/03/2008

ASSIGNED BY:

REF: CS/FCI17020910/Arbnz Special Instruction:

Supervisor:

CWS

ASSIGNMENT (Office)

From (Person):

Serene Ter

of

FCI

Date/Time:

5:22pm @ 1/11/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 4467D

Insured:

SHD 6849M

at Workshop m/s

Kah Motor

Tel:

68465671

of

15 Ubird 4

Policy No:

Claim No:

D17010207MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 31/10/17

CA / REV / REP. / REV 24 HRS

Wp/

07.11.2017 @ 12:30pm owner waiting

R.O.D. Endorsement

Date/Time:

5:38pm @ 1/11/17

Person Contacted:

Mr. Lim

Vehicle-INVOLV

Date/Time

Action/Instruction (✓) Estimate

SLQ 4467D - X

SHD 6849M - CS/FCI17009023/b-D.O.A: 02/05/2017

REF: FCI

ASSIGNMENT

From: _____ Date: 7/11/2017

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 4467D

at Workshop m/s: Kah Motor

of: 15 Ubi Rd 4

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record) Mr. Lim

Make of Veh: _____

(Policy Condition) 12:30pm @ owner waiting

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Van No: SLQ4467D Yr Regn: 2017 July

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Jade cc: 1496

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 3786 T. Radio: Insured / Std / NI / NA

Eng. No: _____

C/No: JHMPR5860FC 200336

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder? / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17

R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>07/11/17</u>

Survey held at: Kah Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

N/S	O/S

TP 1st Cap.
Final fig \$3,369.24 (Red. 180f, 5%)

[Signature]
4/1/2018

RECEIVED 4 JAN 2018

Date/Time File Pass to? Preli. Report

1) typint Final Report

Date/Time File Return to? _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: Site Insp. (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: _____

Transportation: _____

Photos: _____

Charts: _____

Report Format: TP

Lump Sum / (\$3,369.24)

130
50
50
15
245

Survey Department Check List (Case Handler)

Reference No. : CE/FCL17020910/Arb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are ACCURATE.

		Y-Date	N-Date	Y-Date	N-Date
(1) Office Assign Form					
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

		Y-Date	N-Date	Y-Date	N-Date
(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)					
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded	✓			

Check By: Catherine 29/07/17
 Case Handler Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC117020910/Arb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6849M	Veh. Inspected	SLQ 4467D
Policy No.		Coverage (\$)	0.00
Claim No.	D17010207MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	01/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/10/2017	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Celine Fong (LKKAuto)

From: Celine Fong (LKKAuto)
Sent: Friday, 29 December, 2017 3:13 PM
To: 'Lim Chou Siong'; SUR
Subject: RE: Pre-Invoice Of Vehicle No: SLQ4467D For Finalising

Dear Mr Lim,

Confirm final fig \$3,369.24 (excl GST) , 4 days

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Chou Siong [mailto:cslim@honda.com.sg]
Sent: Friday, 29 December, 2017 8:20 AM
To: SUR <sur@lkkauto.com>
Subject: Pre-Invoice Of Vehicle No: SLQ4467D For Finalising

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLQ4467D

Final Repair Costs (include GST) \$3,605.09

Repair Period*(Working Day) 04

*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong
Contact No: 81006303 HP
KAH MOTOR CO. SDN. BHD.
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
15 Ubi Road 4 Singapore 408610
Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is

MOTOR SURVEY ASSIGNMENT

Date	01-11-2017	Our Ref No. D17010207MFSH
Accident Date	31-10-2017	Claim Type. Third Party
Insured Vehicle	SHD6849M	Third Party Vehicle. SLQ4467D
Survey Location	15 UBI ROAD 4	
Contact Person.	LIM CHOU SIONG	
Contact No.	68465671/ 81006303	Fax No. 67480770
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229721)



PRI Documents



Close



PRI Header Details

Claim No	D17010207MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & KAH MOTC
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : LIM CHOU SIONG)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 81006303 , Phone: 68465671 , Fax: 67480770 EmailId: CSLIM@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6849M	TP Vehicle No	SLQ4467D
PRI Recieved Date	01-11-2017 05:39:23 PM	Surveyor Appointed Date	01-11-2017 05:21:46 PM	Surveyor Accept Date	01-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	01-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name


Action

Surveyor Job Remarks

Remarks



Liberty
Insurance



Liberty Insurance Pte Ltd

Registration no. 199002791D
51 Club Street
#03-00 Liberty House
Singapore 069428
Tel: (65) 6221 8611 Fax: (65) 6225 6890
Website: <http://www.libertyinsurance.com.sg>

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD17V08268 /NPC2 /R00
Form	MX1
Date of Issue	11-JUL-2017
1.Index Mark and Registration No. of Vehicle:	SLQ4467D
2.Chassis number of Vehicle:	JHMFR5860FC200336
3.Name of Policyholder:	WONG WE HUNG
4.Effective date of Commencement of Insurance for the purposes of the Act:	10-JUL-2017 00:00 AM
5.Date of Expiry of Insurance:	09-JUL-2019 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	
A) The Policyholder.	
B) Any other person who is driving on the Policyholder's order or with his permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
7.Limitations as to use*:	
Use only for social, domestic and pleasure purposes and for the Policyholder's business.	
8.The Policy does not cover:	
A) Use for hire or reward.	
B) Use for racing, pace-making, reliability trials or speed-testing.	
C) Use for the carriage of goods (other than samples) in connection with any trade or business.	
D) Use for any purpose in connection with the Motor Trade.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers  <hr/> Authorised Signature	
For Information only:	
COVERAGE :	Comprehensive, Unlimited Windscreen, NCD Protection
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Section I S\$600, Additional Excess For Young & Inexperienced Drivers S\$3000, Windscreen Excess S\$100
FINANCE COMPANY:	
PRODUCER NAME:	KAH MOTOR COMPANY SDN BERHAD

PLCJ/PLCJ/18-JUL-17

S1_CI_T1_T3_OE_Template2-Ver1.

18-JUL-17

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2589450B



Name
WONG WE HUNG

王維翰

Race
CHINESE

Date of Birth 13-09-1965 Sex M

Country of Birth
MALAYSIA



REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number S2589450B

Name
WONG WE HUNG

Exp. Date 13 Sep 1965

Issue Date 05 Apr 2003

1000347599A




3143689



NRIC No. S2589450B



Blood Group B+ Date of issue 07-04-2000

APT BLK 632 UPPER THOMSON ROAD #12-82
SINGAPORE 787133

NRIC No: S2589450B Date: 18/08/2012 No: 7169336

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

CLASS	VEHICLE CLASSIFICATION	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	27 Apr 1991
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	27 Apr 1991

NP 428A

Licence No: S2589450B





KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*Kindly Help to arrange
Surveyor to Survey this
Vehicle thanks*

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	Document No.	: SQT17004463	Page	1
Registration No	: SLQ4467D	Date	: 31. Oct 2017	Customer No.	: WZF002
Chassis No	: JHMFR5860FC200336	Svc Advisor	: LIM CHOU SIONG	Engine No	: L15B3250336
Model	: JADE YM15	Date Time	: 31. Oct 2017 3:33:18 PM	Surveyor Name	:
Owner's Name	: WONG WE HUNG	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 31/10/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: WONG WE HUNG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 31/10/2017 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SHD6849M						
67010-T4R-000ZZ	PANEL COMPR.FR.DOOR <i>deduct</i>	1	864.70	25	648.52	45.40	✓ 693.92
67325-T4R-003	TAPER.FR.DOOR SASH UPPER <i>new</i>	1	35.80	25	26.85	1.88	✓ 28.73
67510-T4R-000ZZ	PANEL COMPR.RR.DOOR <i>deduct</i>	1	875.30	25	656.47	45.95	✓ 702.42
67825-T4R-003	TAPER.RR.DOOR SASH UPPER <i>new</i>	1	23.20	25	17.40	1.22	✓ 18.62
					Sum Item	1349.24	94.45 1,443.69
						<i>120</i>	<i>1120</i>
BOMISC1	REPLACE FR R DOOR & RR R DOOR	1	1200.00		1200.00	84.00	1284.00
BP02R	SPRAY PAINTING ON FR R DOOR & RR R DOOR	1	1000.00		1000.00	70.00	1070.00
					Sum Labor	2200.00	154.00 2,354.00

Survey By	<u>Adrian Lij</u>	C S Lim	Total Amount	3,549.24	248.45	3,797.69
Date & Time	<u>07/11/17.</u>	81006303 (MP)	Total (Inclusive of GST)			<u>3,797.69</u>
Excess	_____					
Status	_____					
Signature	<u><i>[Signature]</i></u>	04 days.				

Printed on 31/10/2017 6:00:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

01/12/2017

Page 1/1

SERVICE PRE-INVOICE

Attn: Adrian Ling (L.K.K.)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

4 days

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMFR5860FC200336
License No: SLQ4467D
Mileage: 4232
Engine No: L15B3250336

Document No: SVO17074181
Printed By: CSLIM
Order Date: 27. November 2017
Order Time: 8:13:02 AM
Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO: 69480) OWNER: WONG WE HUNG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 31/10/2017 SURVEYED BY: ADRIAN LING (L.K.K.) DATE: 07/11/2017 @ 12:30PM REF NO: TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SHD6849M						
67010-T4R-000ZZ	PANEL COMPR.FR.DOOR	1	864.70	25	648.52	45.40	693.92
67325-T4R-003	TAPER.FR.DOOR SASH UPPER	1	35.80	25	26.85	1.88	28.73
67510-T4R-000ZZ	PANEL COMPR.RR.DOOR	1	875.30	25	656.47	45.95	702.42
67825-T4R-003	TAPER.RR.DOOR SASH UPPER	1	23.20	25	17.40	1.22	18.62
	SUM PARTS:				1,349.24	94.45	1,443.69
BOMISC1	EXT-YJ REPLACE FR R DOOR & RR R DOOR	1	1,120.00		1,120.00	78.40	1,198.40
BP02R	EXT-YBH SPRAY PAINTING ON FR R DOOR & RR R DOOR	1	900.00		900.00	63.00	963.00
	SUM LABOUR:				2,020.00	141.40	2,161.40
	TOTAL SGD				3,369.24	235.85	3,605.09
	Total Payable (SGD)						3,605.09

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17020910/Arbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6849M	Veh. Inspected	SLQ 4467D
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010207MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	01/11/2017
2. Vehicle Particulars & Condition			
Make & Model	HONDA JADE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMFR5860FC200336	Colour	BROWN
Odometer	3786	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/10/2017	Inspection Date	07/11/2017
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4467D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL COMPR FR DOOR (SN)	DENTED	648.52	648.52
1	TAPER FR DOOR SASH UPPER (SN)	NECESSARY	26.85	26.85
1	PANEL COMPR RR DOOR (SN)	DENTED	656.47	656.47
1	TAPER RR DOOR SASH UPPER (SN)	NECESSARY	17.40	17.40
			1,349.24	1,349.24
LABOUR				
	REPLACE FR R DOOR & RR R DOOR.		1,200.00	1,120.00
	SPRAY PAINTING ON FR R DOOR & RR R DOOR.		1,000.00	900.00
			2,200.00	2,020.00
GRAND TOTAL			3,549.24	3,369.24
RECOMMENDED COST OF REPAIRS				3,369.24

Report Ref No. CS/FCI17020910/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.