

ASS. REC BY

REF

CS3 / AIG 17020953 / A1692

OAR & days

Cust/Agent

Rusul

ASSIGNMENT (Office)

From Person

Mesmer

To Person

Chin Lee Ying

AIG

Date/Time 2/11/17 @ 11:11 am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKJ 4500P

Insured

GBF 5035 L

at Workshop no.

Eng Soon Painting

Tel

6760 6271

of Blk 4 Yew Tee Ind. Est 393-J Woodlands Rd, 677978

Policy No.

Claim No.

Sum Insured

Excess

Make of Vehicle

D.O.A. 31/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

21.11.2017 @ morning

H.O.D. Endorsed

Date/Time

1:15pm @ 2/11/17

Person Contacted

Mr. Teo

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKJ 4500P - X

GBF 5035L - X

Dismantle Part 22.11.2017

PRG *Faru*

REF: ALH

ASSIGNMENT

From: _____ Date: **21-11-2017**

Estimated Cost: _____

QD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SKJ 4500P**

at Workshop no: **Eng Soon**

of: **Blk 4 Yew Tee Ind Est 393-J**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Morning

NS	OS

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Date: _____ Person Contacted: _____ Vehicle IN / OUT

Veh No: **SKJ 4500P** Reg: **2013 Apr 01**

Type: C M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **MERCEDES Benz** **S300L** **297**

Colour: **Grey** A/C Insured / Std / Nil / NA

So. Reading: **109274** T/Radio Insured / Std / Nil / NA

Eng No: _____

C No: **WDD 2211542AS16631**

Gen. Cond. Good C / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / STD A/Rim or

Tyre Size: F: **255/45R18** R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **Continental**

Front: **6** mm Rear: **6** mm

R/Bal: **6** mm L/Bal: **6** mm

D.O.A: **31/10/17** D.O.I: **21/11/17 C 1209pm**

Survey held at: **Eng Soon**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **n/s Rnre**

The U/C / Chassis frame / Body Structure affected due to collision

URGENT

RECEIVED 06 MAR 2018

Date/Time File Pass to: **06/03/2018**

Date/Time File Return to: _____

Report Format: **PRG**

Lump Sum / I.B.N: \$

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transporter: _____

Phone: _____

Address: _____

Add Fee: ☐ Site Insp \$ ☐ Inter. Exp \$ ☐ Test. Exp \$ ☐ Clean up \$

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17020953/R1b	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 02-11-2017	
		Code : AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBF 5035L	Veh. Inspected	SKJ 4500P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	02/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/10/2017	Inspection Date	21/11/2017
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Your password will expire in 10 days. [Click here to change it.](#)

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE GBF5035L AND SKJ4500P ON 31/10/2017**

From: Chin, Lee-Ying

To: 'assignments', 'Admin A'

Cc: Fong, Andy-SY

Sent: Thursday, 2 November, 2017 11:11:28 AM

Attachments:  Fax47C2.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel : (65) 6536 6026
Fax : (65) 6536 2279
[Not for service of court documents]
GST Reg No. 201203547Z

Your Vehicle: GBF 5035 L
Our Vehicle: EngSoon-SKJ 4500 P

Date : 1 November 2017

M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

By Fax 6835 7416 only

Dear Sirs,

ACCIDENT INVOLVING SKJ 4500 P & GBF 5035 L ON 31 OCTOBER 2017

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SKJ 4500 P at M/s Eng Soon Painting Services, Block 4 Yew Tee Industrial Estate 393-J Woodlands Road Singapore 677978.

Your faithfully


BONNIE KWOK
c.c. Client

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/11/2017 10:31
Date Of Accident	31/10/2017 10:30
Exact Location Of Accident	52 TUAS CRESCENT CARPARK LOT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ4500P
Insured/Policyholder	
Name Of Registered Owner	YUM FONG TRADING COMPANY PTE. LTD.
Co Reg No	200704916W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98317783
Alternative Phone No	OFFICE-68623848

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S360L

Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
--	--------------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088606183
Cover Note Number	

Driver

Name of Driver	CHONG YUM FONG
NRIC No	S2197533H
Date Of Birth	01/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	20/03/1979
Driving Experience	38 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98317783
Fax Number	
Contact Number	OFFICE-68623848
Email Address	NOEMAIL

Address

BLK 788C WOODLANDS CRESCENT
#11-176

Postcode

733788

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - DIRECTOR

Vehicle Registration Number of Driver's Own
Vehicle

-
-
-
-
-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

AFTER RAIN

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED. VEH B REVERSED AND HIT MY VEH

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBF5035L

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

ONG HUP WEI

NRIC/Passport Number

S7125900E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or **withholding of material facts** may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/10/2017 at 1030 Hrs. My car SKJ 4500P was parked stationary in a parking lot.

GBF 5035L had tried to reversed out of the parking lot. while reversing out of the lot. He ~~had~~ reversed into my vehicle which was parked stationary in my lot.

I was nearby the my vehicle and witness the accident occur.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	4916W
Vehicle Details	
Vehicle No.	SKJ4500P
Vehicle to be Exported	No
Intended De-registration Date	02 Dec 2017
Vehicle Make	MERCEDES BENZ
Vehicle Model	S 300L (HID SR DRL)
Primary Colour	Grey
Manufacturing Year	2012
Engine No.	27294632081417
Chassis No.	WDD2211542A516631
Maximum Power Output	170.0 kW (227 bhp)
Open Market Value	\$83,473.00
Original Registration Date	01 Apr 2013
First Registration Date	01 Apr 2013
Transfer Count	0
Actual ARF Paid	\$83,473.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	31 Mar 2023
PARF Rebate Amount	\$62,604.00
Intended COE Rebate Details	
COE Expiry Date	31 Mar 2023
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$96,101.00
COE Rebate Amount	\$51,202.00
Total Rebate Amount	\$113,806.00

The information contained herein is correct as at 02 Dec 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

Condition (CON)
 (01)Item (2)Demised (3)Distorted (4)Cracked (5)Cut (6)Scratched
 (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
 (12)Missing (13)Tom (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (2)Repair (3)Recondition (4)Not Consistent (NC)

Vehicle No:

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	cut		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	na	18	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	gca	1	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			P
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

3 days

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Dec 2017 Edit Reg		02 Nov 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	YUM FONG TRADING COMPANY PTE. LTD., Co. Reg. No.: 200704916W		
Vehicle Reg. No.:	SKJ4500P	Date of Loss:	31/10/2017 10:00 - :59
Claim Type:	TP / 4637230837SG	Policy/Cover Note No.:	2100490756 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF5035L	Policy No. (Claimant):	
		Excess:	
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/12/2017]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (04/12/2017): Vehicle number GBF4500P

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SKJ4500P (4637230837SG)**
[GBF5035L]

TP
YUM FONG TRADING COMPANY PTE. LTD.
Oct 31 2017 10:30AM

[-]
Eng Soon Painting Services

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/18 16:23	Odometer Reading	 Load JPG	☒
2	08/01/18 16:23	Chassis Number	 Load JPG	☒
3	08/01/18 16:23	General View	 Load JPG	☒
4	08/01/18 16:23	General View	 Load JPG	☒
5	08/01/18 16:23	General View	 Load JPG	☒
6	08/01/18 16:23	General View	 Load JPG	☒
7	08/01/18 16:23	General View	 Load JPG	☒
8	08/01/18 16:23	General View	 Load JPG	☒
9	08/01/18 16:23	General View	 Load JPG	☒
10	08/01/18 16:23	General View	 Load JPG	☒
11	08/01/18 16:23	General View	 Load JPG	☒
12	08/01/18 16:23	General View	 Load JPG	☒
13	08/01/18 16:23	General View	 Load JPG	☒
14	08/01/18 16:23	General View	 Load JPG	☒
15	08/01/18 16:23	General View	 Load JPG	☒
16	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
17	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
18	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
19	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
20	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
21	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
22	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
23	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒
24	08/01/18 16:24	Photographs of Damaged Parts	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17020953/R1BS2
Date: 06/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100490756
 Claimant Vehicle No: SKJ4500P Insured Vehicle No: GBF5035L
 Date of Loss: 31/10/2017 Nature of Claim: TP Claim No: 4637230837SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKJ4500P
 Make & Model: MERCEDES-BENZ S300L, 3.0 (A) Engine No: 27294632081417
 Reg. Date: 01/04/2013 (Man. Year: 2012) Chassis No: WDD2211542A516631
 Colour: Grey Odometer: 109274 km
 Engine Capacity: 2997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45R18 Rear Tyre Size: 255/45R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/11/2017
 Date Inspected: 21/11/2017 Inspected At: Eng Soon Painting Services
 BLK 4 YEW TEE IND EST 393 - J
 WOODLANDS ROAD
 SINGAPORE 677978
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	8		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
4	1		*REAR RH FENDER	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >