

Surveyor: Melina REF: CSS/MS(117021004/Sabel  
**ASSIGNMENT (Office)**  
 From (Person): Irene Tan of MSL Date/Time: 10012018  
 Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

Special Instructions:  
4S: \$ 5200.00  
 Third Parties:  
 Claimant:  
 Surveyor: Autamax Survej  
 Workshop: Eng Soon.

OD/TP Re-inspection / Evaluation  
 To Inspect Vehicle No: SKW 903T Insured: GBF 2585K  
 at Workshop m/s Eng Soon Tel: 6760 6271  
 of 3939 Woodlands Road  
 Policy No: 2900 6428 MKC Claim No: 535302  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_ D.O.A. 31.10.2017  
 (Client's Record)

Do Not Finalize  
 H.O.D. Endorsement/Date: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT  
 Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 7 days)  
 Date/Time: 23/1 Submit Final Fig 21700, 4 days (Red \$ 3500 / 67 %; Original 7 days)

Date/Time	Action/Instruction
	<u>Sebastian</u>
	<u>PLS see my remarks</u>
	<u>* PPS + PS</u>
	<u>25/1/2018</u>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 24 JAN 2018

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by:	Fee Charged:	Date:				
Salvage Value : _____		Basic & Add	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>				
Nett Value : _____	Transport						
1) Date/Time <u>24/1/18</u> File Pass to <u>tn pira</u>	Photos						
3) Date/Time _____ File Pass to _____	Others						
5) Date/Time _____ File Pass to _____	Total	2) Date/Time _____ File Return to _____					
		4) Date/Time _____ File Return to _____					
		6) Date/Time _____ File Return to _____					

N

REF:

CS3/MSG17021004/Sb

Special Instruction:

Range

ASS. REC. BY:

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person): Irene Tan

of MSH

Date/Time:

02/11/2017 5:15 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 903T

Insured:

GBF 2585K

at Workshop m/s

Eng Soon Painting

Tel:

67606291

of

393J Woodlands Road

Policy No:

29006428 MKL

Claim No:

535302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

31.10.2017

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

02-11-2017 5:55pm

Person Contacted:

Mr Teo

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKW 903T - X
	GBF 2585K - X
25-11-17 5:22pm	Email to Irene Tan thru Marimen.





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17021004/Sb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-11-2017



Code : MSG

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBF 2585K	Veh. Inspected	SKW 903T
Policy No.	29006428MKC	Coverage (\$)	0.00
Claim No.	535302	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	02/11/2017

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	31/10/2017	Inspection Date	06/11/2017
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		

### 5a. Remarks

A)	THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)	THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C)	ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## Survey Department Check List (Case Handler)

Reference No. : CS3/MEG17031004/Syb  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin ( Catherine )**: Case handler to make sure all Information created by the assignment team are ACCURATE.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor ( Sebastian )**: Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Catherine 20/1/18  
 Case Handler Date

\*C: Critical \*N: Non-Critical

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		02 Nov 2017 17:15 Assign				<b>New Assignment</b> Cancel Case

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
<b>Insured:</b>	DIETHELM MARINEDIESEL PTE LTD, Co. Reg. No.: 200919137E								
<b>Main Claimant:</b>	YUM FONG TRADING COMPANY PTE. LTD., Co. Reg. No.: 200704916W								
<b>Vehicle Reg. No.:</b>	SKW903T	<b>Date of Loss:</b> 31/10/2017 00:00 - :59							
<b>Claim Type:</b>	TP / 535302	<b>Policy/Cover Note No.:</b> 29006428MKC (Comprehensive) Coverage: 22/08/2017 - 21/08/2018							
<b>Vehicle Reg. No. (Insured):</b>	GBF2585K	<b>Policy No. (Claimant):</b>							
		<b>Excess:</b>							
<b>Repairer:</b>	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271								
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/11/2017]								
<b>ASSOCIATED MAIL RECEIVED</b>		<input type="button" value="View All"/> <input type="button" value="Compose Case Mail"/>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<input type="button" value="View All"/> <input type="button" value="Search Tasks"/> <input type="button" value="Create New Task"/> <input type="button" value="Complete"/>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SKW903T (535302)**  
**[GBF2585K]**

TP  
YUM FONG TRADING COMPANY PTE. LTD.  
Oct 31 2017 12:00AM  
[DIETHELM MARINEDIESEL PTE LTD]  
Eng Soon Painting Services

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 25/11/2017 17:22 PM.  
**To** MSI\_ITAN  
**Subject** Pre-repair Inspection

Dear Irene,

Refer to your assignment on 02.11.2017 at 5.15PM.

Please be informed that we have inspected the vehicle SKW 903T on 06.11.2017 at 12.51PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

**Irene Tan**

---

**From:** Irene Tan  
**Sent:** Wednesday, 10 January, 2018 4:42 PM  
**To:** Veron Chen (LKKAuto); Shiau Chan (LKKAuto); 'Catherine Chong (LKK Auto)'; 'Bryan Ang (LKKAuto)'  
**Cc:** assignments  
**Subject:** Mr Sebastian Yeang's survey on SKW903T; Our claim no.: 535302/IT  
**Importance:** High

**FOR YOUR IMMEDIATE ACTION, PLEASE**

Dear Veron,

We refer to the PRI assignment given to your Company on 2.11.17 via the merimen.

But todate, we have not received your Preliminary Advice.

Anyway, the 3<sup>rd</sup> party's law firm have submitted their claim and the final repair bill and survey report with pictures have been uploaded in the Merimen.

Please let us know whether a post-repair survey is required or Mr Yeang is able to prepare a paper survey report from the 3<sup>rd</sup> party's colour pictures?

We look forward to your reply asap or within the next 2 days by Friday, 12.1.18.

Best Regards

**Irene Tan**  
Senior Executive, Claims Services (Motor)  
Direct line +65 6594 2541 | Direct fax +65 6225 7402 | [irene\\_tan@sg.msigg-asia.com](mailto:irene_tan@sg.msigg-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msigg.com.sg](http://msigg.com.sg)



A Member of **MS&AD** INSURANCE GROUP

## Irene Tan

---

**From:** Woon Choo Kwok  
**Sent:** Tuesday, 9 January, 2018 1:02 PM  
**To:** Irene Tan; Tan Jin Hao  
**Cc:** Christopher Chionh; Foo Ai Ngoh; Jason Sim  
**Subject:** FW: "Our Ref: Bk. 18346.18 Client Yum Fong Trading Company P/L. Accident Involving SKW 903 T & GBF 2585 K On 31 October 2017"  
**Attachments:** 18346.18.pdf

Dear IT & TJH

FYA

Best Regards

**Kwok Woon Choo**  
Senior Administrative Officer, Claims Services  
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | [woonchoo\\_kwok@sg.msig-asia.com](mailto:woonchoo_kwok@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)    

A Member of **MS&AD** INSURANCE GROUP

---

**From:** Agnes Lee  
**Sent:** Tuesday, January 09, 2018 11:36 AM  
**To:** Woon Choo Kwok <[WoonChoo\\_Kwok@sg.msig-asia.com](mailto:WoonChoo_Kwok@sg.msig-asia.com)>  
**Subject:** FW: "Our Ref: Bk. 18346.18 Client Yum Fong Trading Company P/L. Accident Involving SKW 903 T & GBF 2585 K On 31 October 2017"

**From:** [bonnie kwok \[mailto:litigation@bonniekwok.com\]](mailto:litigation@bonniekwok.com)  
**Sent:** 09 January 2018 10:28  
**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>  
**Subject:** "Our Ref: Bk. 18346.18 Client Yum Fong Trading Company P/L. Accident Involving SKW 903 T & GBF 2585 K On 31 October 2017"

**Your Ref:** GBF 2585 K

**Our Ref:** [BK.18346.18.sg](http://BK.18346.18.sg)

9 January 2018

M/s MSIG Insurance (Singapore) Pte. Ltd.

By E-mail

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Dear Sirs

**ACCIDENT INVOLVING SKW 903 T & GBF 2585 K ON 31 OCTOBER 2017**

We act for M/s Yum Fong Trading Company P/L, the owner of vehicle no: SKW 903 T in the above matter.

We are instructed that on the 31 October 2017, your insured riding motor vehicle no. GBF 2585 K had negligently collided into our client's said vehicle.

We are instructed that as a result of the said collision, our client has suffered loss and damage as follows: -

i.	Cost of Repairs	-\$ 5,200.00
ii.	Loss of Use (9 days x \$180.00)	-\$ 1,620.00
iii.	Survey Report fees	-\$ 650.00
iv.	LTA search fees	-\$ 8.00
v.	GIA search fees	-\$ 29.00
vi.	Transport, Postage, Xerox and other incidental	-\$ 53.50
vii.	Costs	<u>-\$ 1,070.00</u>
	<b>Total</b>	<b><u>\$ 8,630.50</u></b>

We enclose herewith a copy of the LTA search result, GIA report of our client and your insured, survey report and invoice, repair bill, the certificate of insurance and 52 original photographs for your attention.

Kindly note that under the NIMA protocol, all requests for resurvey are required to be made during the protocol period in eight (8) weeks from receipt of this letter.

Kindly revert whether liability is admitted.

Yours faithfully

**BONNIE KWOK**

Enc. (by hand)

c.c. Client; and

Hanapi Bin Ahmad

**BONNIE KWOK LLC**

Advocates & Solicitors  
101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358  
TEL: 6536 6026  
FAX: 6536 2279  
email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)  
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/11/2017 09:57
Date Of Accident	31/10/2017 08:35
Exact Location Of Accident	21 TUAS AVE 13 CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW903T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YUM FONG TRADING COMPANY PTE. LTD.
Co Reg No	200704916W
Email Address	ALEXCHONG.YUMFONG@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68623848

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER 2.0M
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076182712-01
Cover Note Number	

### Driver

Name of Driver	CHONG WEI MING
NRIC No	S9019140C
Date Of Birth	31/05/1990
Occupation	OUTDOOR
Date Of Driving Pass	29/11/2010
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93667783
Fax Number	
Contact Number	OFFICE-68623848
Email Address	ALEXCHONG.YUMFONG@GMAIL.COM

Address	BLK 788C WOODLANDS CRESCENT #11-176
Postcode	733788
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	AFTER RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED - VEH B REVERSED AND HIT MY VEH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	GBF2585K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	HANAPI BIN AHMAD
NRIC/Passport Number	S1492472H
Contact Number	92383455
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/10/17, My Car was parked stationary at 21 Tuas Ave 13, inside the parking lot.

The Lorry of GBF2585K had reversed and hit my car, causing damages to my side tender, (driverside), side mirror (driverside) and driver's door.

The road is wet after rain, rain had stop the sky is cleared.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 1/11/2017

*[Handwritten Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Handwritten Signature]*

1000 hrs.

## Sketch Plan #2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 1/11/2017

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

10004ng.

MSAT17147368 / Sng Ah Tee Motor & Panel Service Pte Ltd - Pioneer  
ENTRY DATE & TIME: 07/11/2017 14:21

**Your NCD will be affected due to late reporting**  
**Actual e-Filing Submission Date & Time: 07/11/2017 17:03**

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report 07/11/2017 14:21  
Date Of Accident 30/10/2017 08:20  
Exact Location Of Accident INSIDE PARKING LOT OF CANTEEN TUAS AVE 13  
Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF2585K  
**Insured/Policyholder**  
Name Of Registered Owner DIETHELM MARINEDIESEL PTE. LTD.  
Co Reg No 200919137E  
Email Address NOEMAIL  
Mobile Phone No  
Alternative Phone No Office-66353610  
**Vehicle Particulars**  
Manufacturer MITSUBISHI  
Model CANTER-3.0 D FEA01BR2SDEB (CBU) (M)  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken REPORTING ONLY  
Vehicle Category COMMERCIAL VEHICLE  
**Insurance Company**  
Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number A29006428MKC  
Cover Note Number  
**Driver**  
Name of Driver HANAPI BIN AHMAD  
NRIC No S1492472H  
Date Of Birth 07/02/1961  
Occupation OUTDOOR  
Date Of Driving Pass 23/01/1981  
Driving Experience 36 YEARS AND 9 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-92383455

Fax Number  
 Contact Number  
 EMail Address NOEMAIL  
 Address  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLIDED INTO PARKED VEHICLE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

ON 30/10/2017 AT ABOUT 0820 HRS. WHILE I WANT PARK MY VEHICLE INTO THE PARKING LOT. WHILE I REVERSE TO PARK MY VEHICLE. MY VEHICLE ACCIDENTALLY TOUCH ONTO VEHICLE B SIDE MIRROR. NO ONE WAS INJURED . THAT ALL

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKW903T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver CHONG WEI MING  
 NRIC/Passport Number S9019140C  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of thereport being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
  - (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.



Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre



Describe Circumstances of the Accident

refer to circumstances

Large lined area for describing the accident circumstances.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If Driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Claim own policy  
 Claim third party  
 Claim OD / TP at other workshop \_\_\_\_\_  
 For record purpose  
 Policy No. A29006428MCC  
 Insurer MSIG Veh.No. GBF258SK

# ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677978  
Tel: 6760 6271

---

M/s Yum Fong trading Company P/L  
c/o M/s Eng Soon Painting Services  
Block 4 Yew Tee Ind Est 393-J  
Woodlands Road  
Singapore 677969

Date: 8 December 2016

Dear Sir,

Date of accident : 31/10/2017  
Final repair bill to SKW 903 T

To Supply,

Lump Sum repairs recommended By the surveyor .....	\$5,200.00
<b>Total</b>	<b>\$5,200.00</b>

**Dollars : FIVE THOUSAND AND TWO HUNDRED ONLY**

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9855 6879      Email : automaxsurvey@gmail.com  
Registration No. 53110062J

Billing To: Yum Fong Trading Company Pte Ltd  
c/o Eng Soon Painting SVC  
Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677969

Invoice no.: TP17100016  
Date: 08 DEC 2016

Vehicle no: SKW 903 T

Model : MITSUBISHI LANCER EX 2.0 GT

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 11 November 2017 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 650.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	<b>TOTAL :</b>	<b>\$ 650.00</b>

**Notes :**

- All cheque payment should be "crossed" and made payable to "Automax Survey".  
Please contact us if there are further enquiries on the invoice.





## AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Front & side** portion(s). For more detail of the damages, please see photograph attached

4. Estimated normal period of repair : 07 working days to complete
  
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.
  
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SKW 903 T

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$\$)	Our Revised Estimation (\$\$)
<u>Nett Items</u>				
1 pc	Front bumper face R	bent	\$ 737.00	\$ 737.00
1 pc	Front bumper side retainer - RH ✓ NEC	damaged	\$ 41.00	\$ 41.00
12 pcs	Front bumper side retainer riverts ✓ NEC	necessary	\$ 36.00	\$ 36.00
10 pcs	Front bumper clips ✓ NEC	necessary	\$ 30.00	\$ 30.00
1 pc	Front bumper badge ✓ NEC	damaged	\$ 37.00	\$ 37.00
1 pc	Front fender - RH R	bent	\$ 479.00	\$ 479.00
1 pc	Front fender splash shield X RN	bent	\$ 107.00	\$ 107.00
8 pcs	Front fender splash shield clips X RN	necessary	\$ 24.00	\$ 24.00
1 pc	Side mirror housing assy ✓ DMG	grazed/deformed	\$ 779.70	\$ 779.70
1 pc	Front knuckle arm - RH X	bent	\$ 320.00	\$ 320.00
1 pc	Front lower arm X RN	bent	\$ 239.00	\$ 239.00
1 pc	Front wheel bearing kit X	damaged	\$ 134.00	\$ 134.00
1 pc	Front wheel bearing hup X	bent	\$ 240.00	\$ 240.00
1 pc	Front absorber X	bent	\$ 460.00	\$ 460.00
1 pc	Front absorber mounting X	bent	\$ 106.00	\$ 106.00
1 pc	Front absorber mounting bush X	damaged	\$ 22.00	\$ 22.00
		Parts Sub-Total	\$ 3,791.70	\$ 3,791.70
		Discount 10.00%	\$ 758.34	\$ 758.34
			\$ 3,033.36	\$ 3,033.36

Vehicle Number : SKW 903 T

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$\$)	Our Revised Estimation (\$\$)
<u>Special Nett Items</u>				
1 pc	Rim Assembly (Sport) X RN	damaged	\$ 650.00	\$ 650.00
		Special Nett Sub-Total	\$ 650.00	\$ 650.00
		Spare Parts Total	\$ 3,683.36	\$ 3,683.36

923.70  
-10%  
831.33

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
Spare Parts Total c/f		\$ 3,683.36	\$ 3,683.36
1	Towing	\$ 120.00	\$ 120.00 X Δ
2	To check wiring system	\$ 80.00	\$ <del>80.00</del> 40 ✓
3	To tuff coat affected areas	\$ 180.00	\$ 150.00 40 X Δ
4	To remove and refix front undercarriage	\$ 350.00	\$ 320.00 X
5	To check and adjust computer wheel alignment (before & after)	\$ 200.00	\$ 180.00 ✓ 600
6	To respray affected areas	\$ 1,000.00	\$ <del>800.00</del> 600
7	To renew damaged parts, straighten & repair front support panel, front fender inner panel & aligned all parts	\$ 1,400.00	\$ <del>1,200.00</del> 600
Total		7,013.36	6,513.36

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

\$ 5,200.00

1400

Fong Kbk Heng  
Qualified Appraiser



Parts - \$ 831.33  
 Labour - \$ 1400.00  


---

 2231.33  
 Lump Sum - 20%  


---

 1785.06

Total: \$ 1800 @ 4 days

730253

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Nov 2017		02 Nov 2017 17:15 <a href="#">Edit Adj Rpt</a>	<b>S\$1,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	<b>DIETHELM MARINEDIESEL PTE LTD</b> , Co. Reg. No.: 200919137E		
Main Claimant:	<b>YUM FONG TRADING COMPANY PTE. LTD.</b> , Co. Reg. No.: 200704916W		
Vehicle Reg. No.:	<b>SKW903T</b>	Date of Loss:	31/10/2017 00:00 - :59
Claim Type:	<b>TP / 535302</b>	Policy/Cover Note No.:	29006428MKC (Comprehensive) Coverage: 22/08/2017 - 21/08/2018
Vehicle Reg. No. (Insured):	<b>GBF2585K</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Eng Soon Painting Services (HQ)</b> 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... [Imm.Advice due 03/11/2017]		

[View All](#) [Compose Case Mail](#)

---

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKW903T (535302)

[GBF2585K]

TP

YUM FONG TRADING COMPANY PTE. LTD.

Oct 31 2017 12:00AM

[DIETHELM MARINEDIESEL PTE LTD]

Eng Soon Painting Services

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
<b>Assessment Reports</b>			1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail <input type="checkbox"/>
1	10/01/18 17:18	<b>Accident Statement</b> From: SC - Reg. No: GBF2585K, Claimant: DIETHELM MARINEDIESEL PTE. LTD.	Load HTM <input type="checkbox"/>
<b>Photos/Images</b>			3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
2	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
3	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
4	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
5	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
6	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
7	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
8	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
9	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
10	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
11	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
12	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
13	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
14	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
15	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
16	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
17	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
18	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
19	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
20	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
21	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
22	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
23	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
24	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
25	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
26	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
27	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
28	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
29	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
30	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>
31	24/01/18 10:41	<b>General View</b>	Load JPG <input type="checkbox"/>

32	24/01/18 10:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	24/01/18 10:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	24/01/18 10:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
36	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
37	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
38	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
39	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
40	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
41	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
42	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
43	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
44	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
45	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
46	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
47	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
48	24/01/18 10:42	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
49	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
50	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
51	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
52	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
53	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
54	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
55	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
56	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
57	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
58	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
59	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
60	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
61	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
62	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
63	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
64	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
65	24/01/18 10:43	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
66	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
67	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
68	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
69	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
70	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
71	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
72	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
73	24/01/18 10:44	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
				1 per page	<input checked="" type="checkbox"/>
<b>Documentation</b>				<b>Thumbnail</b>	<b>Print</b>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
1	02/11/17 17:16	Survey DISAGREE ON SJE, Appoint LKK as Surveyor	1	Load PDF	
2	02/11/17 17:16	Request Pre-Repair Inspection	1	Load PDF	
3	09/01/18 13:49	LOD from Bonnie Kwok	1	Load PDF	
4	10/01/18 15:00	Final Repair Bill	1	Load PDF	
5	10/01/18 15:00	Survey Fee & Report	1	Load PDF	
6	10/01/18 15:00	Survey Report Photos	1	Load PDF	

7	10/01/18 17:10	<b>our email to LKK on whether their surveyor needs to do post repair survey or just a paper survey report</b>		Load PDF	
8	10/01/18 17:18	<b>SKW903T GIA RPT</b> From: SC - Reg. No: GBF2585K, Claimant: DIETHELM MARINEDIESEL PTE. LTD.		Load PDF	
No	<b>Relabel/Reorder</b>	<b>LKK Auto Consultants Pte Ltd (HQ)</b>		<b>Thumbnail</b>	<b>Print</b>
1	25/01/18 08:50	<b>PHOTO</b>		Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021004/SQBE2

Date: 25/01/2018

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 29006428MKC	
Claimant Vehicle No : SKW903T	Insured Vehicle No : GBF2585K	
Date of Loss: 31/10/2017	Nature of Claim: TP	Claim No: 535302

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW903T		
Make & Model:	MITSUBISHI LANCER EX, 2.0 GT 5 ABS D/AB HID (M)	Engine No:	4B11DG2043
Reg. Date:	23/09/2010 (Man. Year: 2009)	Chassis No:	JMYSNCY4AAU000334
Colour:	White	Odometer:	169440 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth.*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,062.53	831.33	3,231.20	79.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,300.00	2,030.00	60.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,392.53</b>	<b>2,131.33</b>	<b>5,261.20</b>	<b>71.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,392.53</b>	<b>1,700.00</b>	<b>5,692.53</b>	<b>77.00</b>

#### INSPECTION

Date of Assignment:	02/11/2017		
Date Inspected:	06/11/2017	Inspected At:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD Singapore 677978
Estimated Period of Repair:	4.0 days		

**Adjuster:** Sebastian Yeang Wai Keen

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2018)
<b>Parts:</b> 143	mitsubishi LANCER EX 2.0 GT 5 ABS D/AB HID (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW903T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER FACE	Repair	737.00 FN	*- FN	
2	1		*FRONT BUMPER SIDE RETAINER - RH	Necessary	41.00 FN	*41.00 FN	
3	12		*FRONT BUMPER SIDE RETAINER RIVERTS	Necessary	36.00 FN	*36.00 FN	
4	10		*FRONT BUMPER CLIPS	Necessary	30.00 FN	*30.00 FN	
5	1		*FRONT BUMPER BADGE	Necessary	37.00 FN	*37.00 FN	
6	1		*FRONT FENDER - RH	Repair	479.00 FN	*- FN	
7	1		*FRONT FENDER SPLASH SHIELD	Not Necessary	107.00 FN	*- FN	
8	8		*FRONT FENDER SPLASH SHIELD CLIPS	Not Necessary	24.00 FN	*- FN	
9	1		*SIDE MIRROR HOUSING ASSY	Damaged	779.70 FN	*779.70 FN	
10	1		*FRONT KNUCKLE ARM - RH	Not Necessary	320.00 FN	*- FN	
11	1		*FRONT LOWER ARM	Not Necessary	239.00 FN	*- FN	
12	1		*FRONT WHEEL BEARING KIT	Not Necessary	134.00 FN	*- FN	
13	1		*FRONT WHEEL BEARING HUP	Not Necessary	240.00 FN	*- FN	
14	1		*FRONT ABSORBER	Not Necessary	460.00 FN	*- FN	
15	1		*FRONT ABSORBER MOUNTING	Not Necessary	106.00 FN	*- FN	
16	1		*FRONT ABSORBER MOUNTING BUSH	Not Necessary	22.00 FN	*- FN	
17	1		*RIM ASSEMBLY (SPORT)	Not Necessary	650.00 FS	*- FS	
					<b>Sub Total (S\$)</b>	<b>4,441.70</b>	<b>923.70</b>
					<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	<b>379.17</b>	<b>92.37</b>
					<b>Total Parts (S\$)</b>	<b>4,062.53</b>	<b>831.33</b>

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	120.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	40.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	0.00
4	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	350.00	0.00
5	TO CHECK AND ADJUST COMPUTER WHEEL ALIGNMENT (BEFORE & AFTER)	New	200.00	60.00
6	TO RESPRAY AFFECTED AREAS	New	1,000.00	600.00
7	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR FRONT SUPPORT PANEL, FRONT FENDER INNER PANEL & ALIGNED ALL PARTS	New	1,400.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,330.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >