

22/03/2007

ASS. REC. BY:

REF: CS/FWDH021072 / Grber

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

mimen

From (Person):

Clara Li

of

FWD

Date/Time: 3/11/17 @ 4:09pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 2553M

Insured:

SLG 69845

at Workshop m/s

V.Z. Automotive

Tel:

9336 5311

of

1 Kaki Bukit Ave 6 # 02-02, 417883

Policy No:

Claim No:

1201700007395

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/10/2017

CA / REV / REP. / REV 24 HRS

wp'

H.O.D. Endorsement:

Date/Time:

4:18pm @ 3/11/17

Person Contacted:

Ah hual

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJX 2553M-X

SLG 69845-X

confirm \$3800, 6 days

Red: 87659.00, 67%

Signature

XCL

REF:

ASSIGNMENT

From:

Date: 03-11-2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

SJX 2553M

at Workshop m/s

Sung Hai

of

Blk 1 Kaki Bukit Ave 6 #02-13

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

An Huat

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

RECEIVED 09 MAY 2018

Veh No:

SJX2553M

Yr Regn:

27 May 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA cerato forte 1.6

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading:

167023

T/Radio: Insured / Std / NI / NA

Eng/No:

KNAFW611MA5228517

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45 R17

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

6

mm

Rear

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

03-11-17

Survey held at

w/s

6pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1) typist



: Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / H.B.T. (\$

3800

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

250
50450
10
50




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS/FWD17021072/Ggb	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986			Date : 03-11-2017	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 6984S	Veh. Inspected	SJX 2553M	
Policy No.		Coverage (\$)	0.00	
Claim No.	1201700007395	Excess (\$)	0.00	
Assign From	CLARA LI	Assign Date	03/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/10/2017	Inspection Date	03/11/2017	
Survey held at	V.Z. AUTOMOTIVE - BLK 1 KAKI BUKIT AVE 6 #02-02			
Repairer	SIONG HAI MOTOR WORKSHOP			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Friday, 3 November, 2017 4:09 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Subject: FW: Accident involving SJX2553M & SLG6984S on 27/10/17 (Our File Ref: PD/DL/1701132 (ml) Our Ref: 1201700007395
Attachments: 2nd PRS Letter to FWD 03112017.pdf; SLG6984S (27.10.2017) 1201700007395.zip
Importance: High

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Attached is the OI GIA report.

Please create the case in Merimen.

Thank you.

Clara Li
Senior Executive, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01
Suntec Tower 4, Singapore 038986
T +65 6727 5722
E clara.li@fwd.com

With FWD, you get to keep your
50% NCD for Life. No matter what.
get a quick quote now >



F
Ins

From: Margaret Lim [mailto:MargaretLim@satwantlaw.com.sg]
Sent: Friday, 3 November, 2017 3:54 PM
To: Clara Li Zirong - SGUser
Cc: vincent@iova.com.sg; gilbert_goh@hotmail.com; Cordell Chan; Danny Lim
Subject: Re: Accident involving SJX2553M & SLG6984S on 27/10/17 (Our File Ref: PD/DL/1701132 (ml)
Importance: High

WITHOUT PREJUDICE

Hi Clara,

We have instructions to nominate LKK Auto Consultants Pte Ltd as the SJE. Kindly see attached letter.

The workshop details are as below:-

Workshop: V.Z Automotive Pte Ltd
Address: 1 Kaki Bukit Avenue 6 #02-02 Singapore 417883
Contact: Ah Huat (HP: 9336 5311)

Kindly liaise with the workshop directly for the PRS on an urgent basis. Thank you.

Thank you & Best Regards
Margaret Lim (Branch Office)
Secretary

For and on behalf of

SATWANT & ASSOCIATES

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Branch Office: 450 Lorong 6 Toa Payoh #02-03 Harsing Centre Singapore 319394 | tel: 6221 6114 | fax: 6266 6925

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at margaretlim@satwantlaw.com.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses. We take no responsibility for any loss or damage, whether caused by our own negligence or not, that results from a computer virus or a defect in the transmission of this email or any attached file

From: clara.li@fwd.com <clara.li@fwd.com>

Sent: Friday, November 3, 2017 2:33 PM

To: Margaret Lim

Cc: vincent@iova.com.sg; gilbert_goh@hotmail.com

Subject: RE: Accident involving SJX2553M & SLG6984S on 27/10/17 (Our File Ref: PD/DL/1701132 (ml))

WITHOUT PREJUDICE

Dear Margaret,

We refer to your letter dated 03 November 2017 of the PRI Notice of your client's vehicle SJX2553M.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

Clara Li
Senior Executive, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01
Suntec Tower 4, Singapore 038986
T +65 6727 5722
E clara.li@fwd.com

With FWD, you get to keep your
50% NCD for Life. No matter what.
get a quick quote now >



F
ins

From: Margaret Lim [<mailto:MargaretLim@satwantlaw.com.sg>]
Sent: Friday, 3 November, 2017 12:37 PM
To: SG Corporate Contact
Cc: vincent@iova.com.sg; gilbert_goh@hotmail.com; Cordell Chan; Danny Lim
Subject: Accident involving SJX2553M & SLG6984S on 27/10/17 (Our File Ref: PD/DL/1701132 (ml))
Importance: High

WITHOUT PREJUDICE

Hi,

Kindly see attached our PRS letter for your urgent attention.

Thank you & Best Regards
Margaret Lim (Branch Office)
Secretary

For and on behalf of

SATWANT & ASSOCIATES

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Branch Office: 450 Lorong 6 Toa Payoh #02-03 Harsing Centre Singapore 319394 | tel: 6221 6114 |
fax: 6266 6925

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at margaretlim@satwantlaw.com.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses. We take no responsibility for any loss or damage, whether caused by our own negligence or not, that results from a computer virus or a defect in the transmission of this email or any attached file

Satwant & Associates

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Conveyancing: Blk 186 Toa Payoh Central #02-420, Singapore 310186 | tel: 6635 7493 | fax: 6635 7494

The information contained in this communication is confidential and may be legally privileged. It is intended solely for the use of the individual or entity to whom it is addressed and others authorised to receive it. If you are not the intended recipient you are hereby notified that any disclosure, copying, distribution or taking any action with respect to the content of this information is strictly prohibited and may be unlawful, and kindly inform the sender via email or call SATWANT & ASSOCIATES at (65) 6 2999 470 immediately and destroy all copies. SATWANT & ASSOCIATES is neither liable for the proper and complete transmission of the information contained in this communication nor for any delay in its receipt.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Satwant & Associates

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Conveyancing: Blk 186 Toa Payoh Central #02-420, Singapore 310186 | tel: 6635 7493 | fax: 6635 7494

The information contained in this communication is confidential and may be legally privileged. It is intended solely for the use of the individual or entity to whom it is addressed and others authorised to receive it. If you are not the intended recipient you are hereby notified that any disclosure, copying, distribution or taking any action with respect to the content of this information is strictly prohibited and may be unlawful, and kindly inform the sender via email or call SATWANT & ASSOCIATES at (65) 6 2999 470 immediately and destroy all copies. SATWANT & ASSOCIATES is neither liable for the proper and complete transmission of the information contained in this communication nor for any delay in its receipt.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Sarwant Singh
Danny Teo Kim Soon
Pritam Singh
Tan Shu Hua, Vanessa
Khong Zi-Wei

SATWANT ASSOCIATES

AN OFFICIAL MEMBER OF THE LAWYER NETWORK, AN INTERNATIONAL NETWORK OF LAW FIRMS

CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)

Your Ref: To be advised
Our Ref: PD/DL/1701132 (ml) – Toa Payoh Office
(margarettlim@satwantlaw.com.sg)

03 November 2017

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986

BY EMAIL ONLY

Attention: Motor Claims Department

Dear Sir/Mdm,

**ACCIDENT INVOLVING SJX2553M & SLG6984S ALONG CHONG PANG CAMP ON
27/10/2017 @ 15:00**


We refer to your email dated 3 November 2017 confirming your intention to conduct a pre-repair survey on our client's vehicle SJX2553M.

Please be informed that said vehicle can be inspected at:

Location: 1 Kaki Bukit Avenue 6 #02-02 Singapore 417883
Contact Person: Ah Huat (HP: 9336 5311)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,


SATWANT & ASSOCIATES
(Danny Teo)

cc client

For Surveyor: To initial after Completion

1st Inspection
Appointed surveyor
(Name & Signature)

Date & Time

2nd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

3rd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

NB: Any Settlement of offer is on the express condition that this settlement is in respect of our client's claim for property related damaged only and shall not preclude our client from claiming injury-related damages arising from this accident. This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/11/2017 12:32
Date Of Accident	27/10/2017 15:00
Exact Location Of Accident	CHONG PANG CAMP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX2553M
Insured/Policyholder	
Name Of Registered Owner	ONG TWEE WAN
NRIC No	S0166732G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93978544
Alternative Phone No	OFFICE-93978544

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5068357447-02 CLASSIC
Cover Note Number	

Driver

Name of Driver	ONG KANG JIE
NRIC No	S8605955Z
Date Of Birth	12/03/1986
Occupation	OUTDOOR
Date Of Driving Pass	03/04/2007
Driving Experience	10 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98177653
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 24 TEBAN GARDENS ROAD #07-163
Postcode	600024
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG6984S
Vehicle Make/Model/Colour	NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	91152218
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	BENSON HEW
Phone Number	96274600
Email Address	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 OCT 2017, around 1500hr, my vehicle SJX2553M was parked [stationary] in the parade square of chong pang camp. At around 1500hr, ~~the~~ two eye witness, ~~witnessed~~ ^{he} saw a NISSAN X-TRAIL drove off from the parking lot in the parade square and collided into the left rear side of my vehicle.

The eye witness saw the ~~NISSAN~~ accident and informed me about it thereafter. The initial discussion with the NISSAN X-Trail driver [SLG 69845] was to settle it privately, however due to the cost of repair is too high, the ~~the~~ NISSAN X-TRAIL driver agreed for me to claim his insurance for the repair work for my vehicle [SJX2553M].

Eye witness : Benson Hew / 9627 4600.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: - 3 NOV 2017

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders;

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: vackb@singnet.com.sg

Policyholder's Signature:
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: - 3 NOV 2017

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

国强

V.Z AUTOMOTIVE PTE LTD

No. 1 Kaki Bukit Avenue 6, #02-03 (Autobay), Singapore 417883 TEL:

6555 7272

H/P: 9336 5311 (Ah Huat)

Vehicle number: SJX2553M

Vehicle Made & Model: KIA KOUP

Qty	List Items	Amount \$
1	Rear bumper / RL	685.00 /
2	Rear bumper disfusser X { NN	345.00 X
2	Rear bumper mudflap X	89.00 X
2	Rear bumper side retainers @ 55 < LH-MC RHX NN	110.00 55
10	Rear bumper clips @ 4.50 / MC	45.00 /
1	Rear fender - LH / MC	1,385.00 1285
1	Rear fender air vent X { NN	86.00 X
1	Rear fender inner trim X	289.00 X
10	Rear fender inner trim clips @ 4.50 / MC	45.00 /
1	Rear fender inner shield / RL	92.00 /
1	Rear fender 1/4 glass moulding assy - MC	345.00 /
1	Rear fender inner panel X repair.	765.00 X
1	Rear Fuel lid X	112.00 X
1	Rear shock absorber - LH X { NN	283.00 X
1	Rear axle beam X	1,486.00 X
1	Rear wheel hub with bearing - LH / MC	485.00 325
1	Rear taillamp - LH / MC	326.00 /
1	Rear taillamp panel - LH X NN	115.00 X
1	Rear windscreen moulding / MC	122.00 /
Sub-total		7,210.00
Less 10%		721.00
Total List		6,489.00

Special Nett Items

1	Rear windscreen sealant 40 / MC	80.00	1	Rear wheel sport rim - LH 300 - MC	550.00
1	Rear tyre - LH X NN				400.00
1	set Rear fender 1/4 glass sealant / MC				80.00 30
Total Special Nett					1,110.00

Vehicle number: SJX2553MVehicle Make & Model: KIA KOUPLabour Charges

To check rear electrical wiring	50.00	30
To remove, refix rear windscreen & fender 1/4 glass	300.00	150
To remove, refix rear undercarriage	350.00	50
To check wheel alignment	120.00	60
To re-seal anti-rust	100.00	60 80 60
To remove, refix interior upholstery to facilitate repair works	120.00	60 80 60
To reinstall rear fuel tank to assist repair	120.00	60 400
To respray painting & etc	1,200.00	400 to 500
Panel beating, cut, weld, remove & replacing above parts	1,500.00	600
Total Labour	3,860.00	

6 Days.
unpsm repair.

~~\$3200~~
\$3800

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

11,459.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2017 Edit Reg		03 Nov 2017 00:00 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Ho Sin Gian , ID: S8137774Z									
Main Claimant: -									
Vehicle Reg. No.: SJX2553M		Date of Loss: 27/10/2017 00:00 - :59 [89 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1201700007395		Policy/Cover Note No.: PNPV2017-00007322 (Comprehensive)							
Vehicle Reg. No. (Insured): SLG6984S		Policy No. (Claimant):							
		Excess:							
Repairer: V.z Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #02-02, 417883 Kaki Bukit - Tel:									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/11/2017]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




































*SJX2553M (1201700007395)
[SLG6984S]




























TP

Oct 27 2017 12:00AM

[Ho Sin Gian]

V.z Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
2	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
3	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
6	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
22	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
23	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
24	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
25	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
26	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
27	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
28	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
29	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
30	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
31	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
32	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
33	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
34	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
35	08/11/17 14:13	General View							 Load JPG	<input checked="" type="checkbox"/>	
36	09/05/18 14:25	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
37	09/05/18 14:25	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	09/05/18 14:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD17021072/GRB

Date: 14/05/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00007322
 Claimant Vehicle No: SJX2553M Insured Vehicle No: SLG6984S
 Date of Loss: 27/10/2017 Nature of Claim: TP Claim No: 1201700007395

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX2553M Engine No: G4FCAH385738
 Make & Model: KIA CERATO, 1.6 (A) Chassis No: KNAFW611MA5228517
 Reg. Date: 27/05/2010 (Man. Year: 2010) Odometer: 167023 km
 Colour: Blue
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,599.00	3,362.50	4,236.50	55.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,470.00	2,390.00	61.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,459.00	4,832.50	6,626.50	57.83
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	11,459.00	3,800.00	7,659.00	66.84

INSPECTION

Date of Assignment: 03/11/2017
 Date Inspected: 03/11/2017 Inspected At: V.z Automotive Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6 #02-02
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2018)
Parts: 143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJX2553M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	685.00 FL	*685.00 FL
2	2		*REAR BUMPER DISFUSSE	Not Necessary	345.00 FL	*- FL
3	2		*REAR BUMPER MUDFLAP	Not Necessary	89.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINERS	N/S Necessary/O/SNot Necessary	110.00 FL	*55.00 FL
5	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
6	1		*REAR FENDER - LH	Buckled	1,385.00 FL	*1,285.00 FL
7	1		*REAR FENDER AIR VENT	Not Necessary	86.00 FL	*- FL
8	1		*REAR FENDER INNER TRIM	Not Necessary	289.00 FL	*- FL
9	10		*REAR FENDER INNER TRIM CLIPS	Necessary	45.00 FL	*45.00 FL
10	1		*REAR FENDER INNER SHIELD	Deformed	92.00 FL	*92.00 FL
11	1		*REAR FENDER 1/4 GLASS MOULDING ASSY	Necessary	345.00 FL	*345.00 FL
12	1		*REAR FENDER INNER PANEL	Repair	765.00 FL	*- FL
13	1		*REAR FUEL LID	Not Necessary	112.00 FL	*- FL
14	1		*REAR SHOCK ABSORBER - LH	Not Necessary	283.00 FL	*- FL
15	1		*REAR AXLE BEAM	Not Necessary	1,486.00 FL	*- FL
16	1		*REAR WHEEL HUB WITH BEARING - LH	Necessary	485.00 FL	*325.00 FL
17	1		*REAR TAILLAMP - LH	Cut	326.00 FL	*326.00 FL
18	1		*REAR TAILLAMP PANEL - LH	Not Necessary	115.00 FL	*- FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	122.00 FL	*122.00 FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*REAR WHEEL SPORT RIM - LH	Cut	550.00 FS	*300.00 FS
22	1		*REAR TYRE - LH	Not Necessary	400.00 FS	*- FS
23	1		*SET REAR FENDER 1/4 GLASS SEALANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,320.00	3,695.00
- List Item Discount on L Items 10.00/10.00% (S\$)	721.00	332.50
Total Parts (S\$)	7,599.00	3,362.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE, REFIX REAR WINDSCREEN & FENDER 1/4 GLASS	New	300.00	150.00
3	TO REMOVE, REFIX REAR UNDERCARRIAGE	New	350.00	50.00
4	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
5	TO RE-SEAL ANTI-RUST	New	100.00	60.00
6	TO REMOVE, REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR WORKS	New	120.00	60.00
7	TO REINSTALL REAR FUEL TANK TO ASSIST REPAIR	New	120.00	60.00
8	TO RESPRAY PAINTING & ETC	New	1,200.00	400.00
9	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,860.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >