

ASS. RWC BY

REF: CS/CTI1702/120/Arbn2

Special Instruction

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Alfred Toh

of

CTIDate/Time: 11:39am @ 6/11/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GW1243E

Insured:

SLP9920J

at Workshop m/s

U2 Spray Painting

06 6443 @ gmail.com

Tel:

8618 6474of 25 Kaki Bukit Rd 4 # 06-43 Synergy 1417800

Policy No:

DMHCRN17H5031700

Claim No:

SNM17D06376C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/10/2017

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time: 12:10pm @ 6/11/17

Person Contacted:

Mr. DavidVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GW1243E - X</u>
	<u>SLP9920J - X</u>

Signature

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 6W1243E Yr Regn: 17 mar 2003
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2986
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 295531 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: STFUF 34Y 203000895

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185R14C Aurstone
 R: 155R12C Condor

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>06</u> mm	R/Bal.	<u>06</u> mm
L/Bal.	<u>06</u> mm	L/Bal.	<u>06</u> mm
D.O.A.		D.O.I.	<u>06/11/17</u>

Survey held at: U2

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Chins</u>
<u>11/6</u>	<u>Adrian confirmed 12 @ 1450/- and 3 days with repainer. (Red 2590.95, 64%)</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format : TP

Lump Sum / I.B.I: (\$ 1450/-)

130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17021120/Agb

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-11-2017

Code : CTI



1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 9920J	Veh. Inspected	GW 1243E
Policy No.		Coverage (\$)	0.00
Claim No.	SNM17D06376C02/0	Excess (\$)	0.00
Assign From	ALFRED TOH	Assign Date	06/11/2017

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

5.

General Information

Accident Date	20/10/2017	Inspection Date	06/11/2017
Survey held at	U2 SPRAY PAINTING PTE LTD 25 KAKI BUKIT ROAD 4 #06-43 SYNERGY @ KB SINGAPORE 417800		

5a.

Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No. : CS/CT/1702/120/Arb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1.) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

Catherine 12/6/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/201

Catherine Chong (LKK Auto)

From: Ai Phing (LKKAuto) <aiphing@lkkauto.com>
Sent: Monday, 6 November, 2017 11:39 AM
To: assignments
Subject: FW: PRS appointment; Our Ref: U9-104848-17; Your Ref: SLP 9920 J accident on 20-10-2017
Attachments: image001.emz; image003.emz; 20171106111425.pdf

Dear Assignment Team,

FYNA.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Claims Dept of CTI [mailto:claimsdept@sg.cntaiping.com]
Sent: Monday, 6 November, 2017 11:32 AM
To: jactan@visionlawllc.com; Investigation <investigation@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: PRS appointment; Our Ref: U9-104848-17; Your Ref: SLP 9920 J accident on 20-10-2017

Without Prejudice

Your Ref: AM.ht.ins.U9 GW1243E.17(sj)

Our Ref: SNM17D06376C02/0 (SLP9920J)

Dear Ms Jacqueline Tan

We thank you for your email pertaining to the above matter.

Please be advised that we shall be appointing M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle while WAITING for our client to file accident report.

Aside to M/s LKK Auto Consultants Pte Ltd., please assist to arrange for the survey.

Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower

Singapore 079909
Co. Reg. No. 200208384E
TEL: +65 6389 6116
FAX: +65 6224 7175/6224 7478
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Jacqueline Tan [<mailto:jactan@visionlawllc.com>]
Sent: Monday, November 06, 2017 11:12 AM
To: Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: FW: PRS appointment; Our Ref: U9-104848-17; Your Ref: SLP 9920 J accident on 20-10-2017

Hi Alfred,

Sorry here is the attachment.

Regards

Jacqueline Tan
Secretary
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811, Fax: 6535-6802

From: Jacqueline Tan [<mailto:jactan@visionlawllc.com>]
Sent: Monday, 6 November, 2017 10:58 AM
To: 'Alfred Toh'
Cc: 'Lee Yew Hok'
Subject: PRS appointment; Our Ref: U9-104848-17; Your Ref: SLP 9920 J accident on 20-10-2017

Dear Alfred,

Refer to the above matter and our letter of 2-11-2017, copy enclosed. As spoken, we have our client's instruction to appoint LKK Auto as the SJE for this matter.

Please be informed that our client's vehicle (GW1243 E) is available for inspection as follows:-

Venue: U2 Spray Painting Pte Ltd
25 Kaki Bukit Road 4
#06-43 Synergy @ KB
Singapore 417800

Contact Person: Mr David Chong (6385-0687) (8618-6474)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

Appointed surveyor
(Name & Signature)

Jacqueline Tan
Secretary
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811, Fax: 6535-6802

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	5590E

Vehicle Details

Vehicle No.	GW1243E
Vehicle to be Exported	No
Intended De-registration Date	29 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	DYNA 150 D
Primary Colour	Silver
Manufacturing Year	2003
Engine No.	5L5304592
Chassis No.	JTFUF34Y203000895
Maximum Power Output	-
Open Market Value	\$23,726.00
Original Registration Date	17 Mar 2003
First Registration Date	17 Mar 2003
Transfer Count	2
Actual ARF Paid	\$1,187.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	31 Mar 2022
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	5
PQP Paid	\$24,394.00
COE Rebate Amount	\$21,167.00
Total Rebate Amount	\$21,167.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 29 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/10/2017 10:37
Date Of Accident	20/10/2017 11:00
Exact Location Of Accident	KB @ SYNERGY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GW1243E
Insured/Policyholder	
Name Of Registered Owner	FABBSTONE PTE LTD
Co Reg No	201415590E
Email Address	FIBERWALKER@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-94777098
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3029261700
Cover Note Number	
Driver	
Name of Driver	WONG KAI KHEK
NRIC No	S7123849J
Date Of Birth	20/07/1971
Occupation	OUTDOOR
Date Of Driving Pass	13/05/1999
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82004966
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP9920J

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Robstone Pte Ltd
201415690E


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A: GW1243E

B: SLP1120J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened on 20/10/2017 at 11am inside KB @ Synergy. Vehicle A was stationary and was about to open the driver side door when he saw vehicle B coming straight at a fast speed. The driver of vehicle A proceed to pull the door back out but vehicle B left. ^{left}ving mirror still hit the door of vehicle A

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Innoblone Pte Ltd
2014156888

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

U2 SPRAY PAINTING PTE LTD

25 Kaki Bukit Road 4 #06-43 Synergy @ KB Singapore 417800

H/P: 8618 6474

TEL: 6385 0687

LY23SR300089

TP Chinn
Rite

Vehicle No.: GW 1243E

Model: TOYOTA DYNA

QTY	List Price:	Prices \$
1	Front door- RH <i>Deled</i>	1587.60 ✓ <i>1208</i>
1	Front door outer handle <i>new</i>	121.60 x
1	Front door glass outer moulding <i>Deled</i>	124.20 ✓
1	Front door glass run channel <i>not new</i>	155.60 x
1	Front door w/strip	181.20 x
1	Front door inner lock	481.55 x
1	Front door insulation	120.35 x
1	Front door inner board	681.60 x
1	Front door checker	89.90 ✓
2	Front door hinges @ 85.50	171.00 x
		3714.60
Less 25%		(928.65)
Subtotal		2785.95

Special Nett Items:

1	Front door lettering sticker <i>new</i>	45.00 <i>30</i>
Subtotal		45.00

Labour Charges:

To checking front electrical wiring	780	30.00 ✓
To respray undercoating		80.00 x
To respray painting and etc		600.00 <i>550</i>
Panel beating, cut, weld, remove and replacing above parts		500.00 <i>200</i>
Subtotal		1210.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

4040.95

total: 1809.15
4/5: 1450
030 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117021120/ARBN2

Date: 13/06/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1745031700
Claimant Vehicle No :	GW1243E	Insured Vehicle No :	SLP9920J
Date of Loss:	20/10/2017	Nature of Claim:	TP
		Claim No:	SNM17D06376C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW1243E	Engine No:	5L5304592
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFUF34Y203000895
Reg. Date:	17/03/2003 (Man. Year: 2003)	Odometer:	295531 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185R14C	Rear Tyre Size:	155R12C
Front Left Side:	Austone 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,830.95	1,029.15	1,801.80	63.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	780.00	430.00	35.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,040.95	1,809.15	2,231.80	55.23
Approved Total (Overridden) (S\$)		1,450.00		
Nett Amount (S\$)	4,040.95	1,450.00	2,590.95	64.12

INSPECTION

Date of Assignment:	07/11/2017	
Date Inspected:	06/11/2017 Inspected At:	U2sray Painting Pte Ltd - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #06-43 Synergy @ KB Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jun 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW1243E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Dented	1,587.60 FL	*1,208.00 FL
2	1		*FRONT DOOR OUTER HANDLE	Not Necessary	121.60 FL	*- FL
3	1		*FRONT DOOR GLASS OUTER MOULDING	Deformed	124.20 FL	*124.20 FL
4	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	155.60 FL	*- FL
5	1		*FRONT DOOR W/STRIP	Not Necessary	181.20 FL	*- FL
6	1		*FRONT DOOR INNER LOCK	Not Necessary	481.55 FL	*- FL
7	1		*FRONT DOOR INSULATION	Not Necessary	120.35 FL	*- FL
8	1		*FRONT DOOR INNER BOARD	Not Necessary	681.60 FL	*- FL
9	1		*FRONT DOOR CHECKER	Not Necessary	89.90 FL	*- FL
10	2		*FRONT DOOR HINGES	Not Necessary	171.00 FL	*- FL
11	1		*FRONT DOOR LETTERING STICKER	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,759.60	1,362.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	928.65	333.05
Total Parts (\$\$)	2,830.95	1,029.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECKING FRONT ELECTRICAL WIRING	New	30.00	30.00
2	TO RESPRAY UNDERCOATING	New	80.00	-
3	TO RESPRAY PAINTING AND ETC	New	600.00	550.00
4	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	500.00	200.00
Gross Labour Cost (\$\$)			1,210.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >