

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>		D.O.A → 6/9/2017-	
Owner ID Type		Company	
Owner ID		0882E	
<b>Vehicle Details</b>			
Vehicle No.	FBH651E	24	02 <sup>12</sup> 2017 <sup>1/2</sup>
Vehicle to be Exported	No	06	09 2017
Intended De-registration Date	06 Dec 2017	18	05 5
Vehicle Make	YAMAHA	(0.6 month)	
Vehicle Model	YBR 125 MANUAL		
Primary Colour	Red	Balance → 5 yr 5.6 month	
Manufacturing Year	2012		
Engine No.	E3J2E005790		
Chassis No.	LBPKE1782D0009143		
Maximum Power Output	-		
Open Market Value	\$1,263.00		
Original Registration Date	25 Feb 2013		
First Registration Date	25 Feb 2013		
Transfer Count	1		
Actual ARF Paid	\$190.00		
<b>Intended PARF Rebate Details</b>			
PARF Eligibility	No		
PARF Eligibility Expiry Date	-		
PARF Rebate Amount	\$0.00		
<b>Intended COE Rebate Details</b>			
COE Expiry Date	24 Feb 2023		
COE Category	D - Motorcycle		
COE Period(Years)	10		
QP Paid	\$1,782.00		
COE Rebate Amount	\$930.00		
<b>Total Rebate Amount</b>	<b>\$930.00</b>		

The information contained herein is correct as at 06 Dec 2017

~~Net Value~~ → \$5500

OK

~~Net Value~~ = \$5500 - \$930  
= \$4570





Looking for more?

Get more deals, more choices and more opportunities by signing with G99. [View details](#)



**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 24/05/2012 Type: Street Bikes 124cc 30000km

1 owner. Trade in Cash, many other brand new and used motorcycles available. Come visit us at Star Hill Brothers (Singapore) Pte Ltd 86-1072 Ang Mo Kio Industrial Park 2 #01-19 Singapore 569525.

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at C.S.T & Pte Ltd](#) [View at Star Hill Brothers](#)

**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 18/02/2014 Type: Street Bikes 124cc -

Low mileage, 1 careful owner. Cheapest in town. Trade/offer available. View at C.S.T & Pte Ltd, 487 Geylang Road, Geylang.

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at C.S.T & Pte Ltd](#) [View at Star Hill Brothers](#)

**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 05/01/2011 Type: Street Bikes 124cc 37000km

Yamaha YBR125. Out Quality used bike all comes with warranty. Bike available for viewing at Cass Hill Cheong Trading, 11101108 Serangoon Road Singapore 532096. Trade/offer 98224811. Trade in welcome.

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at Cass Hill Cheong Trading](#) [View at Star Hill Brothers](#)

CSE Results

As of 12 Nov 2017	GAT D
CSE Rating of Motorcycle	55992

**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 11/08/2013 Type: Street Bikes 124cc -

Cheapest in The Market! Address at 210 Sun Club Road Lot #10. Trade in/offer available. Call Now!

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at Sun Club Road](#) [View at Star Hill Brothers](#)

**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 03/02/2013 Type: Street Bikes 124cc 30000km

Yamaha YBR125. Well maintained condition. Trade in welcome. Please call 98221196 to arrange the viewing. Viewing at 488.

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at Sun Club Road](#) [View at Star Hill Brothers](#)

Work around your schedule

All you need is a mobile and a smartphone. [View details](#)

**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 23/04/2013 Type: Street Bikes 124cc -

W3 condition Yamaha YBR125 for sale. Come with one month warranty. Loan available trade in bike or welcome for interested low down payment to use away. Come view the bike at our warehouse.

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at Sun Club Road](#) [View at Star Hill Brothers](#)

**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 10/11/2012 Type: Street Bikes 124cc 42000km

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at Sun Club Road](#) [View at Star Hill Brothers](#)

**Yamaha YBR125** (Listing usedbikes/yamaha/yamaha-ybr125/26181)

Reg: 08/04/2012 Type: Street Bikes 124cc -

Viewing at Bala Production Pte Ltd. Please verify call to confirm availability before viewing. Address: 510 Serangoon Road #01-82 Tel: 62622633. Trade in/offer welcome and many other brands open.

Viewed at: [18040](#) [18041](#) [18042](#) [18043](#) [18044](#) [18045](#) [18046](#) [18047](#) [18048](#) [18049](#) [18050](#) [18051](#) [18052](#) [18053](#) [18054](#) [18055](#) [18056](#) [18057](#) [18058](#) [18059](#) [18060](#)

[Details](#) [View at Sun Club Road](#) [View at Star Hill Brothers](#)

[FIRST OF PAGE](#) [1](#) [PRICE\\_TO=REG\\_YEAR\\_FROM=2011](#) [BIKE\\_MODEL=YAMAHA-YBR125](#) [CATEGORY=STREET](#) [LICENSE\\_CLASS=BIKE](#) [TYPE=REG\\_YEAR\\_TO=2017](#) [PRICE\\_FROM=6000](#) [PAGE=1](#) [PRICE\\_TO=REG\\_YEAR\\_FROM=2011](#) [BIKE\\_MODEL=YAMAHA-YBR125](#) [CATEGORY=STREET](#) [LICENSE\\_CLASS=BIKE](#) [TYPE=REG\\_YEAR\\_TO=2017](#) [PRICE\\_FROM=6000](#) [PAGE=1](#) [PRICE\\_TO=REG\\_YEAR\\_FROM=2011](#) [BIKE\\_MODEL=YAMAHA-YBR125](#) [CATEGORY=STREET](#) [LICENSE\\_CLASS=BIKE](#) [TYPE=REG\\_YEAR\\_TO=2017](#) [PRICE\\_FROM=6000](#) [PAGE=1](#) [PRICE\\_TO=REG\\_YEAR\\_FROM=2011](#) [BIKE\\_MODEL=YAMAHA-YBR125](#) [CATEGORY=STREET](#) [LICENSE\\_CLASS=BIKE](#) [TYPE=REG\\_YEAR\\_TO=2017](#) [PRICE\\_FROM=6000](#) [PAGE=1](#)

**Explore SGBikemart**  
 SGBikemart is the Number One Motorcycle Classified Ads Portal in Singapore for buying Singaporean, Sportbikes, Superbikes, Dirtbikes, Scooters, Custom, CSE Bikes, Scooters, Cabs, Sport Taxis, Super Minis, Street Bikes, Classic Bikes, Three wheelers, Parallel imported bikes and more. Buying & selling from new motorcycle distributors, Used motorcycle dealers, Motorcycle accessories & gadgets, repairs & services. Search through our motor directory (<http://www.sgbikemart.com.sg/listing/usedbikes/>) to find your favorite motorcycle shop. Post your used motorcycle (<http://www.sgbikemart.com.sg/listing/usedbikes/>) & accessories (<http://www.sgbikemart.com.sg/listing/usedbikes/>) for sale in 3 easy steps. Motorcycle Auction (<http://www.sgbikemart.com.sg/auction/>) by all finance companies, and users and dealers.  
 Get the best offers for your SGBike.  
 Our instant motorcycle insurance (<http://www.sgbikemart.com.sg/insurance/>) quote provides the cheapest & most affordable premium to all our SGBike members. Get a motorcycle insurance quote for less than 30 secs. When you purchase the motor insurance with us, your motorcycle is guaranteed to be insured in our SGBikemart member's E-wallet. We need hassle of bringing out the photos of the bike insurance card. All you need to do is fill up your SGBikemart App.  
 If you're into motorcycle meet, events, services, promotions, top deals, Motorcycle blogs, like rental, bike stickers, bike packs and bike accessories. Find useful products & services like job posting, motorcycle accessories, Malaysia Bikes, motorcycle repair.  
 SGBike (<http://www.sgbikemart.com.sg/>) Not. Singaporean. No. 189, share and control Singaporean to learn and fulfil their dreams. Read more related motorcycle knowledge, information, safety motorcycle riding tips, discussion with fellow riders & bikers. We aim to organize Singaporean, motorcycle riding to have a more safety riding experience. We will also attend and safety overseas riding trips throughout the year. Our goal, We fulfil your dreams. Ride to live & live to ride.  
 © SGBikemart. Some rights reserved.  
 - Privacy Policy ([SGBikemart privacy statements](#))  
 - Personal Data Protection Statement ([SGBikemart personal data protection statements](#))  
 - Terms & Conditions ([SGBikemart terms conditions](#))  
 - Contact Us ([Contact Us](#))

# MOTO 51 PTE LTD

Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : moto51@n51.com.sg  
Company Reg. No. : 201536417C

LUCKY JOINT CONSTRUCTION PTE LTD  
10 TUAS DRIVE 2  
SINGAPORE 638645

Contact : 62840288 97716789, 86576477

## TAX INVOICE

Date : 14/10/2017

Date in : 06/09/2017

Vehicle Num. : FBH651E

Make/Model : YAMAHA YBR 125 MANUAL-2012

Chassis/Eng# : LBPKE1782D0009143/E3J2E005790

Accident Date : 06/09/2017

Claim No : CLM13225

Reference : SEPT-03/2017

Policy No. : 2017-V0085202-VMF-R006 (29/05/2019)

Amount S\$

6,400.00

LUMPSUM REPAIR BILL  
AS PER SURVEYOR REPORT  
REF : CAS/17-10/026 DATED 08/09/2017  
BY CONSTANT APPRAISER SERVICES

E. & O.E. Sub S\$ : 6,400.00

Total Amount S\$ : 6,400.00



for MOTO 51 PTE LTD

**TAX INVOICE**

Our Ref No: GR-17-134062

Date of Request: 08/09/2017

Your Ref No: WALK IN LIOW SL

MOTO 51 PTE LTD  
10 KAKI BUKIT ROAD #01-16 FIRST EAST CENTRE  
SINGAPORE 417868

Dear Sir/Madam,

Date of Accident: 06/09/2017

Vehicle No: FBH651E

Place of Accident: woodlands road opposite esso petrol station

Involving Vehicle No: GZ6927S

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GZ6927S	woodlands road opposite esso petrol station	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

**Enquire Vehicle & Owner Information ( Vehicle No. GZ6927S As At 06 Sep 2017 / 07:45:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: FBH651E

**Current Owner Details**

Owner ID Type: Company

Owner ID: 199900728K

Owner Name: YSE GLOBAL PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 10

Registered Street Name: BUKIT BATOK CRESCENT

Registered Unit No.: # 07 - 05

Registered Building Name: THE SPIRE

Registered Postal Code: 658079

**Current Vehicle Details**

Vehicle No.: GZ6927S

Make Description/Model: NISSAN / CABSTAR G

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).  
Please do not use the [Back](#) or [Forward](#) buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution  
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)  
Last updated on 27 Aug 2017 at 01:09 AM

AUTOBAY TOWNSHIP  
 1 Kaki Bukit Avenue 5  
 #01-55 AutoBay @ Kaki Bukit  
 Singapore 417881  
 Tel: 9015 8696 (Aft. Hours)

**CASH SALE**

No. \_\_\_\_\_

Sold to: CUM 13225 FBH GSIE

Date: 6/9/17

**CROWN**

Item	Quantity	Description	Unit Price	Amount
		Auto Hub to Defu Lane		<del>90</del> 90
		Reporting Tow Back		7
		to MacPherson Two		
		Trips		
E. & O. E.			Sub Total :	
			GST Tax :	
			Total :	<del>90</del> 90

Issued by: \_\_\_\_\_

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7685B
Vehicle Details	
Vehicle No.	FY4427Z
Vehicle to be Exported	No
Intended De-registration Date	08 Nov 2017
Vehicle Make	SUZUKI
Vehicle Model	GN125
Primary Colour	Red
Manufacturing Year	2003
Engine No.	157FMID200401
Chassis No.	LC6PCJB1X40800890
Maximum Power Output	-
Open Market Value	\$1,179.00
Original Registration Date	21 Sep 2004
First Registration Date	21 Sep 2004
Transfer Count	1
Actual ARF Paid	\$177.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	20 Sep 2019
COE Category	D - Motorcycle
COE Period(Years)	5
PQP Paid	\$2,079.00
COE Rebate Amount	\$776.00
<b>Total Rebate Amount</b>	<b>\$776.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Nov 2017

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Riverside Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constan\_as@yahoo.com.sg  
RCB No. 53118015K

## INVOICE

To: Lucky Joint Construction Pte Ltd  
c/o 2 Kaki Bukit Ave 2  
#01-17 Kaki Bukit Autohub  
Singapore 417921

Date : 10/10/2017

Invoice No : IV17-10026/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle FBH 651F (Inclusive Of Photographs And Transport Charges)  Our reference : CAS/17-10/026	\$677.00
Total	\$677.00

E. & O.E.

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## Automobile Inspection Report

To: Lucky Joint Construction Pte Ltd c/o 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921	Date : 10/10/2017 Reference No : CAS/17-10/026
<b><u>General Information</u></b>	
Registration No : FBH 651E Accident Date : 06/09/2017	
<b><u>Particulars of Damaged Vehicle</u></b>	
Colour : Red Engine Capacity : 124 cc Mileage (KM) : 38969 Chassis No. : LBPKE1782D0009143 Registration Date : 25/02/2013	Make & Model : Yamaha YBR 125 Manual Pre-Accident Condition : Good Engine No. : F3J2H005790 Steering : Affected Brake : In Order
<b><u>Tyre Condition</u></b>	
Front Tyre : Size 2.75R18 Rear Tyre : Size 3.00R18	Make : PIRELLI Balance : 70% PIRELLI 50%
<b><u>Inspection</u></b>	
Repairer : Moto 51 Pte Ltd 2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921	
<b><u>Adjustment And Recommendation Cost Of Repair</u></b>	
Repairer's Estimate : \$8,576.40 Revised Amount : \$6,400.00 Less Excess : - Nett Total : \$6,400.00	
<b><u>Remarks</u></b>	
(A) Survey was done on 08/09/2017 (B) Re-survey was done on 15/09/2017 (C) Re-survey after repair was done on 18/09/2017 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.	

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/loss in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Constant Appraiser Services**

Vehicle No : FBH 651E

Model : Yamaha YBR 125 Manual

Reg Date : 25/2/2013

Our ref : CAS/17-10/126

**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<b><u>PARTS REPLACEMENT - LIST ITEMS</u></b>					
1	1pc	✓ Brake lever ✓ BR	Broken	45.00	45.00 ✓
2	1pc	✓ Clutch lever ✓ SCR	Grazed	45.00	45.00 ✓
3	1pc	✓ Exhaust muffler assy ✓ SCR/DD	Dented/Grazed	450.00	450.00 ✓
4	1pc	✓ Exhaust muffler chrome cover ✓ SCR	Grazed	78.00	78.00 ✓
5	1pc	✓ Exhaust muffler protector	Grazed	35.00	35.00 ✓
6	1pc	✓ Front brake disc ✓ WIP	Bent/Warped	280.00	280.00 ✓
7	1pc	✓ Front footrest bracket ✓ BT	Bent	104.00	104.00 ✓
8	2pcs	✓ Front footrest rubber R/L @ \$22.00 ✓ Torn	Torn	44.00	44.00 ✓
9	2pcs	✓ Front fork assy R/L @ \$450.00 ✓ BT	Bent/Twisted	900.00	900.00 ✓ 700
10	1pc	✓ Front fork bracket bottom ✓ BT	Bent	135.00	135.00 ✓
11	1pc	✓ Front mudguard ✓ CRA	Broken	85.00	85.00 ✓
12	2pcs	✓ Front signal R/L @ \$32.00 ✓ SCR	Grazed/Broken	64.00	64.00 ✓
13	1pc	✓ Front wheel rim ✓ WP	Dented/Warped	485.00	<del>485.00</del> 350 ✓
14	1pc	✓ Front wheel rim shaft ✓ BT	Bent	85.00	85.00 ✓
15	1pc	✗ Fuel tank assy X R	Repair	425.00	- X
16	2pcs	✓ Fuel tank side cover R/L @ \$155.00 ✓ SCR	Grazed/Broken	310.00	310.00 ✓
17	1pc	✓ Handle bar ✓ BT	Bent	122.00	122.00 ✓
18	2pcs	✓ Handle bar bracket R/L @ \$35.00 ✓ BT	Bent	70.00	70.00 ✓
19	1pc	✓ Headlamp assy ✓ CRA	Grazed/Broken	260.00	<del>260.00</del> 185 ✓
20	1pc	✓ Headlamp cowling ✓ BR	Broken	180.00	180.00 ✓
21	1pc	✓ Headlamp cowling bracket ✓ BT	Bent	122.00	122.00 ✓
22	1pc	✓ Headlamp cowling visor ✓ BR	Broken	98.00	98.00 ✓
23	1pc	✓ Headlamp cowling visor emblem ✓ NEC	Necessary	24.00	24.00 ✓
24	1pc	Headlamp switch X	Serviceable	78.00	- X
25	1pc	✓ Meter assy ✓ SCR/DM	Grazed/Damaged	450.00	450.00 ✓
26	1pc	✓ Meter bracket ✓ BT	Bent	68.00	68.00 ✓
27	2pcs	✓ Mirror R/L @ \$43.00 ✓ SCR/BT	Grazed/Bent	86.00	86.00 ✓
28	1pc	✓ Rear brake pedal ✓ SCR	Grazed/Bent	95.00	95.00 ✓
29	2pcs	✓ Rear footrest bracket R/L @ \$135.00 ✓ BT	Bent	270.00	270.00 ✓
30	2pcs	✓ Rear footrest R/L @ \$32.00 ✓ DD ✓ SCR	Dented/Grazed	64.00	64.00 ✓
31	1pc	✗ Rear mudguard X	Serviceable	125.00	- X
32	1pc	✓ Rear passenger seat handle bar ✓ BT ✓ TWI	Twisted	125.00	125.00 ✓
33	1pc	✓ Rear side cover set ✓ BR	Broken	220.00	220.00 ✓

**Instant Appraiser Services**

Our ref: CAS/17-10/026

Vehicle No: FBH 651E

No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<b>PARTS REPLACEMENT - LIST ITEMS (CONT'D)</b>					
34	2pcs	Rear signal lamp R/L @ \$32.00	Grazed/Broken	64.00	64.00 X
35	1pc	Rear top cover ✓ WP XNN	Broken	75.00	75.00 ✓
36	2pcs	Side cover R/L @ \$180.00 ✓ WP/BR	Broken	360.00	360.00 ✓
37	1pc	Steering stem ✓ BT	Broken	165.00	165.00 ✓
38	1pc	Taillamp assy	Bent	155.00	155.00 ✓
		Less 10%			
			Serviceable	6,846.00	6,063.00
				(684.60)	(606.30)
			Sub total	6,161.40	5,456.70
<b>PARTS REPLACEMENT - SPECIAL NETT ITEMS</b>					
1	1set	Body sticker set ✓ NEC	Necessary	180.00	180.00 ✓
2	1pc	Front fork oil ✓ NEC	Necessary	32.00	32.00 ✓
3	2pcs	Front fork oil seal R/L @ \$22.00 ✓ NEC	Necessary	44.00	44.00 ✓
4	1pc	Front no plate ✓ NEC	Necessary	25.00	25.00 ✓
5	1pc	Front wheel rim bearing ✓ NEC	Necessary	98.00	98.00 ✓
6	1set	Handle bar grip set ✓ LR	Necessary	66.00	66.00 ✓
7	1pc	Rear box ✓ BT	Torn	280.00	280.00 ✓
8	1pc	Rear box bracket ✓ BT	Grazed	165.00	165.00 ✓
9	1pc	Steering corn/bearing	Bent	165.00	165.00 ✓
			Sub total	7,216.40	6,511.70
<b>LABOUR &amp; MISC. CHARGES</b>					
1		To remove, reinstall electrical wiring harness, check lighting. (to FR) XNN		60.00	30.00 X
2		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		500.00	400.00 180
3		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		450.00	350.00 300
4		To Straighten body frame to the original position XNN		350.00	250.00 X
			Sub total	8,576.40	7,541.70
			Grand total		6,400.00

Recommended cost of lump sum repair (To its pre-accident condition)

\* 6 Working Days

**Constant Appraiser Services**

Vehicle No : FBH 651E

Our ref : CAS/17-10/026

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$6,400.00** on a contractual basis. Under normal circumstances, the repair period would be about **8 (Eight)** working days.

Yours faithfully,

**Constant Appraiser Services**



Liu Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2017		11 Sep 2017 17:40 <a href="#">Edit Adj Rpt</a>	<b>S\$5,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>				<a href="#">[Created by insurer]</a>					
<b>Insured:</b>	YSE GLOBAL PTE LTD, Co. Reg. No.: 199900728K								
<b>Main Claimant:</b>	LUCKY JOINT CONSTRUCTION PTE LTD, Co. Reg. No.: 198200882E								
<b>Vehicle Reg. No.:</b>	FBH651E	<b>Date of Loss:</b>	06/09/2017 07:00 - :59						
<b>Claim Type:</b>	TP / 529137	<b>Policy/Cover Note No.:</b>	A28984538MKC (TP, Fire & Theft) Coverage: 29/07/2017 - 28/07/2018						
<b>Vehicle Reg. No. (Insured):</b>	GZ6927S	<b>Policy No. (Claimant):</b>							
		<b>Excess:</b>							
<b>Repairer:</b>	Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:								
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 09/11/2017]								
<b>Driver/Custodian (Insured):</b>	RENKAR RANGANATHAN (), NRIC: G7769000Q, Tel: +6582214149								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>MSIG_SG (07/11/2017): Report Send Back Alerts - FBH651E (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

\*FBH651E (529137)  
[GZ6927S]

TP

LUCKY JOINT CONSTRUCTION PTE LTD

Sep 6 2017 7:00AM

[YSE GLOBAL PTE LTD]

Ong Motor Trading

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer <input type="checkbox"/>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	11/09/17 15:29	<b>Accident Statement</b> From:SC - Reg. No: GZ6927S, Claimant: YSE GLOBAL PTE LTD		Load HTM	<input type="checkbox"/>
2	11/09/17 15:29	<b>Addendum Sheet</b> From:SC - Reg. No: GZ6927S, Claimant: YSE GLOBAL PTE LTD		Load TIF	<input type="checkbox"/>
3	11/09/17 15:29	<b>Accident Statement Addm. #1</b> From:SC - Reg. No: GZ6927S, Claimant: YSE GLOBAL PTE LTD		Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/10/17 16:20	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>
2	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
32	13/10/17 16:20	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
33	13/10/17 16:21	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
34	13/10/17 16:21	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
35	13/10/17 16:21	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>

36	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
37	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
38	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
39	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
42	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
43	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
44	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
45	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
46	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
47	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
48	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
49	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
50	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
51	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
52	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
53	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
58	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
59	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
60	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
61	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
62	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
63	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
64	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
65	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
66	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
67	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
68	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
69	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
70	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
71	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
72	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
73	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
74	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
75	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
76	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
77	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
78	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
79	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
80	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
81	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
82	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
83	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
84	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
85	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
86	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
87	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
88	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
89	13/10/17 16:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

90	13/10/17 16:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
91	13/10/17 16:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
92	13/10/17 16:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
93	13/10/17 16:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
94	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
95	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
96	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
97	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
98	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
99	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
100	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
101	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
102	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
103	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
104	13/10/17 16:21	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	11/09/17 15:28	SJE disagreement email	1	Load PDF	
2	11/09/17 15:29	FBH651E GIA Rpt From: SC - Reg. No: G269275, Claimant: YSE GLOBAL PTE LTD	1	Load PDF	
3	11/09/17 17:41	Name of workshop email	1	Load PDF	
4	11/09/17 17:42	PRI	1	Load PDF	
5	11/09/17 17:44	LTA Search	1	Load PDF	
6	06/11/17 17:48	LOD	1	Load PDF	
7	06/11/17 17:48	Final Bill	1	Load PDF	
8	06/11/17 17:48	GIA Search, LTA Search, Towing Bill,	1	Load PDF	
9	06/11/17 17:48	TP Survey Report	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	11/12/17 11:26	PRS INVOICE	1	Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6644-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17017574/WTBS2-1  
Date: 11/12/2017

**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28984538MKC  
Claimant Vehicle No: FBH651E Insured Vehicle No: GZ6927S  
Date of Loss: 06/09/2017 Nature of Claim: TP Claim No: 529137

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: FBH651E Engine No: E3J2E005790  
Make & Model: YAMAHA YBR125, 124cc (M) Chassis No: LBPKE1782D0009143  
Reg. Date: 25/02/2013 (Man. Year: 2012) Odometer: 38969 km  
Colour: Red  
Engine Capacity: 124 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 2.75 18 Rear Tyre Size: 3.00 18  
Front Left Side: Michelin 2 mm Rear Left Side: Michelin 2 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,216.40	6,005.10	1,211.30	16.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	480.00	880.00	64.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,576.40</b>	<b>6,485.10</b>	<b>2,091.30</b>	<b>24.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,576.40</b>	<b>5,000.00</b>	<b>3,576.40</b>	<b>41.70</b>

**INSPECTION**

Date of Assignment: 11/09/2017  
Date Inspected: 12/09/2017 Inspected At: Ong Motor Trading (MACPHERSON RD)  
No. 464 Macpherson Road  
Singapore 368182  
Estimated Period of Repair: 6.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 11 Dec 2017)
<b>Parts:</b>	N/A YAMAHA YBR125 124cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBH651E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE LEVER	Broken	45.00 FL	*45.00 FL
2	1		*CLUTCH LEVER	Scratched	45.00 FL	*45.00 FL
3	1		*EXHAUST MUFFLER ASSY	Scratched / Dented	450.00 FL	*450.00 FL
4	1		*EXHAUST MUFFLER CHROME COVER	Scratched	78.00 FL	*78.00 FL
5	1		*EXHAUST MUFFLER PROTECTOR	Grazed	35.00 FL	*35.00 FL
6	1		*FRONT BRAKE DISC	Warped	280.00 FL	*280.00 FL
7	1		*FRONT FOOTREST BRACKET	Bent	104.00 FL	*104.00 FL
8	2		*FRONT FOOTREST RUBBER R/L	Torn	44.00 FL	*44.00 FL
9	2		*FRONT FORK ASSY R/L	Bent	900.00 FL	*700.00 FL
10	1		*FRONT FORK BRACKET BOTTOM	Bent	135.00 FL	*135.00 FL
11	1		*FRONT MUDGUARD	Cracked	85.00 FL	*85.00 FL
12	2		*FRONT SIGNAL R/L	Scratched	64.00 FL	*64.00 FL
13	1		*FRONT WHEEL RIM	Warped	485.00 FL	*350.00 FL
14	1		*FRONT WHEEL RIM SHAFT	Bent	85.00 FL	*85.00 FL
15	1		*FUEL TANK ASSY	Repair	425.00 FL	*- FL
16	2		*FUEL TANK SIDE COVER R/L	Scratched	310.00 FL	*310.00 FL
17	1		*HANDLE BAR	Bent	122.00 FL	*122.00 FL
18	2		*HANDLE BAR BRACKET R/L	Bent	70.00 FL	*70.00 FL
19	1		*HEADLAMP ASSY	Cracked	260.00 FL	*185.00 FL
20	1		*HEADLAMP COWLING	Broken	180.00 FL	*180.00 FL
21	1		*HEADLAMP COWLING BRACKET	Bent	122.00 FL	*122.00 FL
22	1		*HEADLAMP COWLING VISOR	Broken	98.00 FL	*98.00 FL
23	1		*HEADLAMP COWLING VISOR EMBLEM	Necessary	24.00 FL	*24.00 FL
24	1		*HEADLAMP SWITCH	Serviceable	78.00 FL	*- FL
25	1		*METER ASSY	Scratched / Damaged	450.00 FL	*450.00 FL
26	1		*METER BRACKET	Bent	68.00 FL	*68.00 FL
27	2		*MIRROR R/L	Scratched / Bent	86.00 FL	*86.00 FL
28	1		*REAR BRAKE PEDAL	Scratched	95.00 FL	*95.00 FL
29	2		*REAR FOOTREST BRACKET R/L	Bent	270.00 FL	*270.00 FL
30	2		*REAR FOOTREST R/L	Dented / Scratched	64.00 FL	*64.00 FL
31	1		*REAR MUDGUARD	Serviceable	125.00 FL	*- FL
32	1		*REAR PASSENGER SEAT HANDLE BAR	Bent / Twisted	125.00 FL	*125.00 FL
33	1		*SET REAR SIDE COVER	Broken	220.00 FL	*220.00 FL
34	2		*REAR SIGNAL LAMP R/L	Not Necessary	64.00 FL	*- FL
35	1		*REAR TOP COVER	Warped	75.00 FL	*75.00 FL
36	2		*SIDE COVER R/L	Warped / Broken	360.00 FL	*360.00 FL
37	1		*STEERING RIM	Bent	165.00 FL	*165.00 FL
38	1		*TAILLAMP ASSY	Serviceable	155.00 FL	*- FL
39	1		*SET BODY STICKER	Necessary	180.00 FS	*180.00 FS
40	1		*FRONT FORK OIL	Necessary	32.00 FS	*32.00 FS
41	2		*FRONT FORK OIL SEAL R/L	Necessary	44.00 FS	*44.00 FS
42	1		*FRONT NO PLATE	Necessary	25.00 FS	*25.00 FS
43	1		*FRONT WHEEL RIM BEARING	Necessary	98.00 FS	*98.00 FS
44	1		*SET HANDLE BAR GRIP	Torn	66.00 FS	*66.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR BOX (LOCAL REPAIR)	Grazed	280.00 FS	*200.00 FS
46	1		*REAR BOX BRACKET	Bent	165.00 FS	*165.00 FS
47	1		*STEERING CORN / BEARING	Necessary	165.00 FS	*165.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
<b>Sub Total (\$)</b>					<b>7,901.00</b>	<b>6,564.00</b>
- List Item Discount on L Items 10.00/10.00% (\$)					684.60	558.90
<b>Total Parts (\$)</b>					<b>7,216.40</b>	<b>6,005.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)	New	60.00	0.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	500.00	180.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	450.00	300.00
4	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.	New	350.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,360.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >