

ASS REC BN

RES CS/FWD17021396/Srb

Subject  
Meamen

Suburban

ASSIGNMENT (Office)

From (Person)

Belliana

FWD

Date/Time 8/11/2017 @ 5:44pm

Estimated Cost

Bill to

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG6984S

Insured

at Workshop m/s

Automotive Repair Centre

Tel:

64688834

of 38 woodlands Ind. Park E1, # 05-18, 757700

Policy No

PNPV2017-00007322

Claim No

1201700007395

Sum Insured

Excess

\$500

Make of Veh:

D.O.A

27/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

15.11.2017

H.O.D. Endorsement

Date/Time

9:07am @ 9/11/17

Person Contacted

Raymond

Vehicle IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SLG6984S - CS/FWD17021072 / Ggb - D.O.A: 27/10/2017
16/11/17	Market value check with Bryan change from \$117K to \$110K
	Submit prelim report & seek mandate
	mandate approved & inform Raymond.

Surveyor

## ASSIGNMENT

From:

Date: 15/11/17

Estimated Cost:

☒ OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLG 69843

at Workshop m/s

Automotive Repair Centre

of 38 woodlands Ind. Park E1, # 05-18, 75770

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

\$500.00


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

110K



Bal. or Market Value:

MV: \$117K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 69845

Yr Regn:

11/10/2016

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan X-Trail

cc 1997

Colour:

Blue

A/C:

Insured / Std / NI / NA

Op. Reading

15878

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1JANT3220002589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/55R19

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Good year

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/10/2017

D.O.I.

15/11/2017

Survey held at

ARC

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirm \$2085.00, 3 days

Red: \$1688.00, 35%.

RECEIVED 27 NOV 2017

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S+RS \$

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

OD - Meriman

Lump Sum / I.B.I. (\$

3085.00

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD17021396/Srb

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 09-11-2017



Code : FWD

1.

## Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLG 6984S
Policy No.	PNPV2017-00007322	Coverage (\$)	0.00
Claim No.	1201700007395	Excess (\$)	500.00
Assign From	MERIMEN (BELLIANA)	Assign Date	09/11/2017

2.

## Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3.

## Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

## Description of Damages

--	--

5.

## General Information

Accident Date	27/10/2017	Inspection Date	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		

5a.

## Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	08 Nov 2017 12:00	08 Nov 2017 13:18 <b>S\$4,773.00</b>	08 Nov 2017 17:44 <a href="#">Assign</a>			<b>New Assignment</b>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>HO SIN GIAN</b> , ID: S8137774Z, Tel: +6591152217, Email: MARINE_HO@YAHOO.COM		
Vehicle Reg. No.:	<b>SLG6984S</b>	Date of Loss:	27/10/2017 00:00 - :59
Claim Type:	<b>OD / 1201700007395</b>	Policy/Cover Note No.:	PNPV2017-00007322 (Comprehensive)
		Excess:	S\$500.00
Repairer:	<b>Automotive Repair Centre Pte Ltd (HQ)</b> 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834		
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Belliana</b> - 67275741]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561		
Driver/Custodian:	LEE POH CHOO, LINDA (LI BAOZHU) (38 / Female), NRIC: S7910707G, Tel: +6591152218		
Adj Asg. Remarks:	Auto-assignment adjuster same as linked case		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Belliana

Date: 16 Nov 2017

**Preliminary Advice**

Vehicle No	: SLG6984S	Accident Date	: 27/10/2017
Make	: NISSAN X-TRAIL	Policy No.	: PNPV2017-00007322
Assignment Date	: 08/11/2017	Excess	: S\$500.00
Date of Inspection	: 15/11/2017	Est. Duration of Repair	: 3.00
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,773.00
Revised Amount	:S\$	1,795.00
Check Items (Estimated)	:S\$	2,660.00
Total	:S\$	4,455.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	65,554.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,446.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Print Received Message

This mail is associated with :

**SLG6984S (1201700007395)**

OD

Oct 27 2017 12:00AM

[HO SIN GIAN]

Automotive Repair Centre Pte Ltd

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 16/11/2017 10:00 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4455.00) - SLG6984S - Claim Handler: Belliana

Approved:4455.00.

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Thursday, November 16, 2017 2:31 PM  
**To:** 'raymond@automotiverepaircentre.com.sg'  
**Cc:** shujuan@automotiverepaircentre.com.sg; SUR  
**Subject:** RE: OD / 1201700007395 , SLG6984S (FWD Singapore Pte Ltd)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLG 6984S (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** raymond@automotiverepaircentre.com.sg [mailto:raymond@automotiverepaircentre.com.sg]  
**Sent:** Thursday, November 16, 2017 9:16 AM  
**To:** clara.li@fwd.com; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** belliana@fwd.com; shujuan@automotiverepaircentre.com.sg  
**Subject:** RE: OD / 1201700007395 , SLG6984S (FWD Singapore Pte Ltd)

Hi All,

Kindly update us the status, as we required to inform owner the date of completion.

Thank you.

Best Regards,

Raymond Tan

**Automotive Repair Centre Pte Ltd**

**38 Woodlands Industrial Park E1**

**#05-18, Singapore 757700**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Singapore NRIC
Owner ID	7774Z
<b>Vehicle Details</b>	
Vehicle No.	SLG6984S
Vehicle to be Exported	No
Intended De-registration Date	16 Nov 2017
Vehicle Make	NISSAN
Vehicle Model	X-TRAIL 2.0 CVT ABS 4WD 5/R 7-STR
Primary Colour	Blue
Manufacturing Year	2016
Engine No.	MR20905927B
Chassis No.	JN1JANT32Z0002584
Maximum Power Output	106.0 kW (142 bhp)
Open Market Value	\$23,227.00
Original Registration Date	11 Oct 2016
First Registration Date	11 Oct 2016
Transfer Count	0
Actual ARF Paid	\$24,518.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	10 Oct 2026
PARF Rebate Amount	\$18,388.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	10 Oct 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$53,001.00
COE Rebate Amount	\$47,166.00
<b>Total Rebate Amount</b>	<b>\$65,554.00</b>

The information contained herein is correct as at 16 Nov 2017

OK







Dickson Automobile

Posted: 18-Oct-2017

Tags: 2016 Nissan X-Trail, 2016 Nissan X-Trail, Nissan X-Trail, Nissan X-Trail, Nissan, X-Trail, X-Trail, Used Nissan

[Details](#)

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

60 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Nissan X-Trail, Nissan X-Trail Singapore, used Nissan X-Trail Singapore, used Nissan X-Trail, used vehicles Singapore or even buy used Nissan X-Trail Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- [Home](#)
- [New Car](#)
- [Used Car](#)
- [Sell Car](#)
- [Motoring Directory](#)
- [Products Guide](#)
- [Article](#)
- [Forum](#)
- [Tool & Tip](#)

- [About Us](#)
- [Careers](#)
- [Contact Us](#)
- [Sitemap](#)

© 2004-2017 sgCarMart. All rights reserved.

- [Terms of Service](#)
- [Privacy Policy](#)
- [Personal Data Protection Statement](#)

[Compare](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/11/2017 17:35
Date Of Accident	27/10/2017 15:00
Exact Location Of Accident	CHONG PANG CAMP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG6984S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HO SIN GIAN
NRIC No	S8137774Z
Email Address	MARINE_HO@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91152217
Alternative Phone No	OTHERS-91152217

### Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNOV2017-00007322
Cover Note Number	10/10/2017 TO 10/10/2018

### Driver

Name of Driver	LEE POH CHOO,LINDA (LI BAOZHU)
NRIC No	S7910707G
Date Of Birth	04/04/1979
Occupation	INDOOR
Date Of Driving Pass	11/11/2002
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91152218
Fax Number	
Contact Number	
Email Address	HOLEE0598@GMAIL.COM

Address	23 FERNVALE LANE #19-29 (S) 797501
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

refer with attach.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX2553M
Vehicle Make/Model/Colour	KIA
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

## Accident Sketch Plan Pg. 1


### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time: 02/11/17

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 2 NOV 17

  
Reporting Centre Personnel Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



A: SLG 6984 S

B: SJX 2553 M


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was turning out from the carpark lot, I banged on the car no 2553 SJX 2553 M (rear left)


Insurance Co.	FWD Insurance
Vehicle No	SLG 6984 S
Date of Accident	22/10/17
<input checked="" type="checkbox"/> Reporting Only	
<input type="checkbox"/> Own Damage Claim	
<input type="checkbox"/> Third Party Claim	
<input type="checkbox"/> Other Workshop	

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 02/11/17

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: bpm 2/NOV/17

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No:



A-Assurance  
Assurance in Insurance

**Car Insurance Expiring?**  
We get you the cheapest insurance renewal

Click to get quote

Username / Email Add  
password  
Connect » Sign Up New Account.  
» Forgot Password

nissan x trail Price Range Depreciation 2016 Vehicle Type

Advanced  
Search

Home » Used Cars » Top Marque Auto » Nissan X-Trail 2.0A 7-Seater

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Tyres



Nissan X-Trail 2.0A 7-Seater

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

<b>Price</b>	<b>\$115,999</b>	
<b>Depreciation</b>	\$11,790 /yr View models with similar depreciation	?
<b>Reg Date</b>	02-Sep-2016 (8yrs 9mths 16days COE left)	
<b>Manufactured</b>	2016	?
<b>Mileage</b>	19,000 km (15.8k /yr)	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,997 cc	
<b>Road Tax</b>	\$1,210 /yr	?
<b>Power</b>	106.0 kW (142 bhp) View specs of the Nissan X-Trail (2014)	
<b>Curb Weight</b>	1,626 kg	?
<b>Features</b>	Refined And Smooth Nissan 2.0L DOHC Engine, Xtronic CVT, All Mode 4x4-I, Power Tailgate, Cruise Control, Multi Function Steering, Keyless Entry/Start.	
<b>Accessories</b>	Sunroof, All-Mode 4x4-i, LED DRL, Around View Monitor, Keyless Entry And Start/Stop, Auto Climate Control, Auto Tailgate, Bluetooth, Roof-rail.	
<b>Description</b>	A Popular, Spacious And Accessories Packed Family SUV That Seats 7 Person Comfortably. Well Maintained And Routinely Serviced At Tan Chong Motor By Current First Owner. Existing Warranty Of 4 Years Left. Sound Proofing Done On All 4 Doors And Rear Tyre. Routine Body Coating Done By Its Current Owner. Owner Upgrading Thus Selling. Flexible Financing Available. Contact Us Today For Viewing Appointment!	
<b>COE</b>	\$56,500	?
<b>OMV</b>	\$23,227	?
<b>ARF</b>	\$24,518	?
<b>Dereg Value</b>	\$68,093 as of today (change)	?
<b>No. of Owners</b>	1	?
<b>Type of Veh</b>	SUV	
<b>Category</b>	PARF Car	
<b>Availability</b>	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 27-Oct-2017 | Last Updated on: 27-Oct-2017

Tags: Nissan X-Trail, Nissan X-Trail, 2016 Nissan X-Trail, 2016 Nissan X-Trail, Nissan, X-Trail, X-Trail, Used Nissan



Seller Information

<b>Company</b>	<b>Top Marque Auto</b> » dealer's pricelist » 3 vehs sold   13 vehs available
<b>Address</b>	31 Woodlands Close #04-02 Search cars nearby this location
<b>Location</b>	Woodlands Horizon
<b>Contact Person(s)</b>	Fabian Teo 91887128

Useful Services

**STA** Make sure of this car condition with STA Evaluation.  
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.  
Free Valuation

Upfront Payment

» more Financial info

**Automotive Repair Centre Pte Ltd** (Co.Reg.No:201312913C)

38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Tel: 64688834 Fax: 64622278 Email: raymond@automotiverepaircentre.com.sg

INSURER:

**FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	PNOV2017-00007322	Date of Loss:	27/10/2017
Vehicle Reg. No.:	SLG6984S	Driveable?	
Driver Age/Info:	38 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HO SIN GIAN	Contact No:	+6591152217
Driver:	LEE POH CHOO, LINDA (LI BAOZHU)		
Make/Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Vehicle Reg. Date:	11/10/2016
Vehicle Colour:	Blue	Chassis No:	JN1JANT32Z0002584
Engine No:	MR20905927B		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Remarks: VEHICLE NOT IN WORKSHOP. REQUESTING FOR DESKTOP SURVEY. OWNER HAS FIXED A TEMPORARY NON-COMPLIANCE LICENSE PLATE. FORGOTTEN TO TAKE ODOMETER READING AND THE GENERAL VIEW OF THE VEHICLE FROM 6 DIFFERENT VIEWS, WILL DO SO WHEN THE VEHICLE IS IN THE WORKSHOP FOR REPAIR.

Present Location: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	3,853.00
Miscellaneous Items	0.00
Labour	920.00
Paintwork Labour	0.00
Towing	0.00
<b>Calculated Gross Total (S\$)</b>	<b>4,773.00</b>
<b>- Excess (S\$)</b>	<b>500.00</b>
<b>(S\$)</b>	<b>4,273.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>299.11</b>
<b>Nett Amount (S\$)</b>	<b>4,572.11</b>

This claim is handled by: SHUJUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 08 Nov 2017)  
**Parts:** N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** Automotive Repair Centre Pte Ltd/SLG6984S/08/11/2017 13:18  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ✓ CRK	0.00	0.00	*320.00 F
2	1		*FRONT BUMPER ALUMINIUM DEFUSER ✓ MS	0.00	0.00	*680.00 F
3	1		*FRONT BUMPER ALUMINIUM DEFUSER SCREW X2 ✓ NEC X NN	0.00	0.00	*10.00 F
4	1		*FRONT BUMPER CHROME MOULDING TRIM ✓ CRK	0.00	0.00	*110.00 F
5	1		*FRONT BUMPER CLIPS X10 ✓ NEC	0.00	0.00	*20.00 F
6	1		*FRONT BUMPER RETAINER RH ?	0.00	0.00	*20.00 F
7	1		*FRONT BUMPER RETAINER LH ?	0.00	0.00	*20.00 F
8	1		*FRONT BUMPER TOWING COVER X	0.00	0.00	*18.00 F
9	1		*FRONT BUMPER UNDERCOVER ?	0.00	0.00	*280.00 F
10	1		*FRONT REINFORCEMENT ? X NN	0.00	0.00	*280.00 F
11	1		*FRONT SPONGE ?	0.00	0.00	*185.00 F
12	1		*FRONT GRILLE ?	0.00	0.00	*320.00 F
13	1		*FRONT LOWER GRILLE ?	0.00	0.00	*145.00 F
14	1		*FRONT FOGLAMP LH ?	0.00	0.00	*225.00 F
15	1		*FRONT FOGLAMP GARNISH LH ?	0.00	0.00	*65.00 F
16	1		*FRONT HEAD LAMP LH ? ✓ SK	0.00	0.00	*1,100.00 F 1300
17	1		*FRONT HEAD LAMP BRACKET LH ? X NN	0.00	0.00	*20.00 F
18	1		*FRONT LICENSE PLATE WITH FRAME ✓ CRK	0.00	0.00	*35.00 F 30

F=Franchise part.

Total Parts (S\$) 3,853.00

Automotive Repair Centre Pte Ltd/SLG6984S/08/11/2017 13:18. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOTAL PAINT LABOUR AND MATERIAL	New	300 400.00
2	REMOVE, REFIT AND REPAIR AFFECTED ACCIDENT AREA	New	300 500.00
3	CHECK AND RECTIFY ELECTRICAL WIRING	New	20.00 ✓
Gross Labour Cost (\$\$)			920.00

Automotive Repair Centre Pte Ltd/SLG6984S/08/11/2017 13:18. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 days.

Sebastian  
15/11/2017.

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint
- Revert
- Excess : \$ 500

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

(SUPPLEMENTARY)

INSURER:

FWD Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00007322	Date of Loss:	27/10/2017
Vehicle Reg. No.:	SLG6984S	Driveable?	
Driver Age/Info:	38 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HO SIN GIAN	Contact No:	+6591152217
Driver:	LEE POH CHOO, LINDA (LI BAOZHU)		
Make/Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Vehicle Reg. Date:	11/10/2016
Vehicle Colour:	BLUE	Chassis No:	JN1JANT32Z0002584
Engine No:	MR20905927B		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Present Location: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)

**COST OF CLAIMS**

	Amount
Parts	
Miscellaneous Items	1,300.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	1,300.00
+ GST 7.00% (S\$)	91.00
Nett Amount (S\$)	1,391.00
+ Previous Estimates (S\$)	4,572.11
Claim Total (S\$)	5,963.11

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 21 Nov 2017)  
**Parts:** N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** Automotive Repair Centre Pte Ltd/SLG6984S/21/11/2017 10:55  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEAD LAMP LH / SLR (R)	0.00	0.00	*1,300.00 F
Total Parts (\$\$)						1,300.00

Automotive Repair Centre Pte Ltd/SLG6984S/21/11/2017 10:55. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

**UKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Automotive Repair Centre Pte Ltd/SLG6984S/21/11/2017 10:55. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**Janice Lee (LKKAuto)**

---

**From:** Sebastian Yeang (LKK Auto)  
**Sent:** Friday, November 24, 2017 5:59 PM  
**To:** raymond@automotiverepaircentre.com.sg; Janice Lee (LKKAuto)  
**Cc:** SUR  
**Subject:** RE: OD / 1201700007395 , SLG6984S (FWD Singapore Pte Ltd)  
**Attachments:** SLG\_6984\_S\_ESTIMATE\_REPLY.pdf

Dear Raymond

Please refer to attachment for the finalization.

Part : \$ 2430  
S/Nett : \$ 35  
Labour : \$ 620  
Excess : - \$500  
Total : \$2585 @ 3 days.

Thank You

Best Regards,

**Sebastian** | Automotive Assessor

**LKK Auto Consultants**

phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** raymond@automotiverepaircentre.com.sg [mailto:raymond@automotiverepaircentre.com.sg]  
**Sent:** Tuesday, 21 November 2017 10:56 AM  
**To:** Janice Lee (LKKAuto); Sebastian Yeang (LKK Auto)  
**Cc:** shujuan@automotiverepaircentre.com.sg; SUR  
**Subject:** RE: OD / 1201700007395 , SLG6984S (FWD Singapore Pte Ltd)

Dear Sebastian / Janice,

Please find attached before paint photos, completion photos and parts invoices for your verification.

Note: We have reloaded the headlamp LH to merimen as supplementary.  
(reason: price adjusted due to last piece sold therefore our supplier take from agent)

Thank you.

Best Regards,

Raymond Tan

Automotive Repair Centre Pte Ltd

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: +65 64688834

Fax: +65 64622278

**Automotive Repair Centre Pte Ltd** (Co.Reg.No:201312913C)

38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Tel: 64666534 Fax: 64622278 Email: raymond@automotiverepaircentre.com.sg

INSURER:

FWD Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	PNOV2017-00007322	Date of Loss:	27/10/2017
Vehicle Reg. No.:	SLG6984S	Driveable?	
Driver Age/Info:	38 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HO SIN GIAN	Contact No:	+6591152217
Driver:	LEE POH CHOO, LINDA (LI BAOZHU)		
Make/Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Vehicle Reg. Date:	11/10/2016
Vehicle Colour:	Blue		
Engine No:	MR20905927B	Chassis No:	JN1JANT32Z0002584
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	VEHICLE NOT IN WORKSHOP. REQUESTING FOR DESKTOP SURVEY. OWNER HAS FIXED A TEMPORARY NON-COMPLIANCE LICENSE PLATE. FORGOTTEN TO TAKE ODOMETER READING AND THE GENERAL VIEW OF THE VEHICLE FROM 6 DIFFERENT VIEWS, WILL DO SO WHEN THE VEHICLE IS IN THE WORKSHOP FOR REPAIR.		
Present Location:	AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	3,853.00
Miscellaneous Items	0.00
Labour	920.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	4,773.00
- Excess (S\$)	500.00
(S\$)	4,273.00
+ GST 7.00% (S\$)	299.11
Nett Amount (S\$)	4,572.11

This claim is handled by: SHUJUAN

Generated using Merimen e-Claims internet Estimation &amp; Adjusting System

## REPAIR DETAILS

### Reference

Part Source: (Last Synchronised: 08 Nov 2017)

Parts: N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Automotive Repair Centre Pte Ltd/SLG6984S/08/11/2017 13:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ✓ CRK	0.00	0.00	*320.00 F ✓
2	1		*FRONT BUMPER ALUMINIUM DEFUSER ✓ MS	0.00	0.00	*680.00 F ✓
3	1		*FRONT BUMPER ALUMINIUM DEFUSER SCREW X2 ✓ XAN	0.00	0.00	*10.00 F ✓
4	1		*FRONT BUMPER CHROME MOULDING TRIM ✓ CRK	0.00	0.00	*110.00 F ✓
5	1		*FRONT BUMPER CLIPS X10 ✓ NUC	0.00	0.00	*20.00 F ✓
6	1		*FRONT BUMPER RETAINER RH ? NA	0.00	0.00	*20.00 F
7	1		*FRONT BUMPER RETAINER LH ?	0.00	0.00	*20.00 F
8	1		*FRONT BUMPER TOWING COVER ×	0.00	0.00	*18.00 F
9	1		*FRONT BUMPER UNDERCOVER ?	0.00	0.00	*280.00 F
10	1		*FRONT REINFORCEMENT ?	0.00	0.00	*280.00 F
11	1		*FRONT SPONGE ?	0.00	0.00	*185.00 F
12	1		*FRONT GRILLE ? NA	0.00	0.00	*320.00 F
13	1		*FRONT LOWER GRILLE ?	0.00	0.00	*145.00 F
14	1		*FRONT FOGLAMP LH ?	0.00	0.00	*225.00 F
15	1		*FRONT FOGLAMP GARNISH LH ?	0.00	0.00	*65.00 F
16	1		*FRONT HEAD LAMP LH ?	0.00	0.00	*1,100.00 F 1/300
17	1		*FRONT HEAD LAMP BRACKET LH ?	0.00	0.00	*20.00 F
18	1		*FRONT LICENSE PLATE WITH FRAME ✓ CRK	0.00	0.00	*35.00 F
Total Parts (\$\$)						3,853.00

F=Franchise part.

Automotive Repair Centre Pte Ltd/SLG6984S/08/11/2017 13:18. Not valid without Reference section.  
Generated using Merlimen e-Claims IEAS

Parts : \$ 2430  
S/Nett : \$ 35  
Labour : \$ 620  
Excess : \$ 3085  
Total : \$ 2585 @ 3 days.



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TOTAL PAINT LABOUR AND MATERIAL	New	300 400.00
2	REMOVE, REFIT AND REPAIR AFFECTED ACCIDENT AREA	New	300 500.00
3	CHECK AND RECTIFY ELECTRICAL WIRING	New	20.00
<b>Gross Labour Cost (\$)</b>			<b>920.00</b>

Automotive Repair Centre Pte Ltd/SLG69845/08/11/2017 13:18. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 days.

Sebastian  
15/11/2017

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint
- Revert
- Excess : \$ 500

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date:



日美汽車私人有限公司

**JAE AUTO PTE LTD**

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AUTOMOTIVE REPAIR CENTRE PTE LTD  
38 WOODLANDS INDUSTRIAL PARK #1 #05-18

SINGAPORE 757700  
TEL: 64688834 FAX: 64622278  
ATTN: CHIN TIONG 94554198 RAYMOND 98197718

WIPER BLADE  
Dept Direct: 6417 8791 / 8745 9636



Dept Direct: 6326 9810



Dept Direct: 6417 8794



Wiper blade: NYS (Peppan Wiper blades, Silver (Made in Korea))  
Forn (Made in Germany)

Spark plug: Japan Denso, NGK (Made in Japan)

TAX INVOICE AR201711-09360  
DATE 16/11/2017  
CUSTOMER ID AU1075  
VEH REG. NO. SLG6984S  
TERMS 90 days  
PO NO.  
PAGE NO. Page 1 of 1  
CURR S\$

SO STOCKID	DESCRIPTION	StdLoo	QTY	U/PRICE	AMOUNT
1. N62022-4CB0H T32 X-TRAIL	FRT BUMPER	SG G4-5	1	320.00	320.00

SUB-TOTAL 320.00  
ADD GST 7.00 % 22.40

FACE TOTAL AMOUNT S\$ 342.40

[P] 16/11/2017 12:17:28PM

[E] 16/11/2017 11:58:00AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.

Sales Executive: GUAN

This is computer generated document.

No signature is required.



\* AR201711-09360 \*

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Depot Direct: 8417 9791 / 9740 9038



Depot Direct: 8425 9610

Depot Direct: 8425 9611

Depot Direct: 8417 9792

Depot Direct: 8417 9793

Depot Direct: 8417 9794

Depot Direct: 8417 9795

Depot Direct: 8417 9796

Wiper blades: NWB (Nissan Wiper blades, Super (Made in Korea))

Ford (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AUTOMOTIVE REPAIR CENTRE PTE LTD  
38 WOODLANDS INDUSTRIAL PARK E1 #05-18

SINGAPORE 757700

TEL: 64688834 FAX: 64622278

ATTN: CHIN TIONG 94554198, RAYMOND 98197718

TAX INVOICE AR201711-02501

DATE 16/11/2017

CUSTOMER ID AUT075

VEH REG. NO. SLG6984S

TERMS 90 days

PO NO.

PAGE NO. Page 1 of 1

CURR S\$

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1 NG5890-4CE0A/4CE00	FRT BUMPER SPOILER (LOWER)	SG	1	680.00	680.00
T32		V1-4			

SUB-TOTAL 680.00

ADD GST 7.00 % 47.60

E & OE TOTAL AMOUNT S\$ 727.60

[P] 16/11/2017 1:56:07PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on Over/Due Account(s).

[E] 16/11/2017 1:52:36PM

JAE Auto Pte. Ltd.

Sales Executive: GUAN

This is computer generated document.

No signature is required.



\*A4201711-09401\*

Goods Received in Good Order

*[Signature]*

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO. M2-0119201-3 CO. REG. NO. 129307741M

**AUTOMOTIVE REPAIR CENTRE PTE LTD**

38 WOODLANDS INDUSTRIAL PARK E1 #05-18

SINGAPORE 757700

TEL : 64688834 FAX : 64622278

ATTN : CHIN TIONG 94554198, RAYMOND 98197718

(copy)

Arrange By: \_\_\_\_\_  
Driver: \_\_\_\_\_  
Dept Direct: 6417 9791 / 6745 9636



Wiper blade: NWB (Nippon Wiper blade), Slicer (Made in Korea),  
Forth (Made in Germany)

**TAX INVOICE : AR201711-09365**

DATE : 16/11/2017

CUSTOMER ID : AUT075

VEH REG. NO. : SLG6984S

TERMS : 90 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	N01553-09611	CLIP BUMPER TOP, GRILLE CLIPN16 5 PES	MO	10	2.00	20.00
2.	B15 N16 P11 K12 N62072-4BA0A T32	MLD - FRT BUMPER	2A27 MO SUPPLIER	1	110.00	110.00
3.	N26075-4CA5C/D/6D T32	HEAD LAMP LH	MO SUPPLIER	1	1300.00	1,300.00

SUB-TOTAL : 1,430.00  
ADD GST 7.00 % 100.10

E. & O.E

TOTAL AMOUNT S\$ : 1,530.10

[P] 16/11/2017 2:40:22PM

[E] 16/11/2017 12:00:58PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : GUAN



\* A R 2 0 1 7 1 1 - 0 9 3 6 5 \*

Goods Received in Good Order

Signature / Co Stamp / Date

This is computer generated document.

No signature is required.

ORIGINAL

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2017 12:00 <a href="#">Sendback Est</a>	08 Nov 2017 13:18 <b>S\$4,773.00</b>	08 Nov 2017 17:44 <a href="#">Edit Adj Rpt</a>	<b>S\$3,085.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,085.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	21 Nov 2017 10:31	21 Nov 2017 10:55 <b>S\$1,300.00</b>	21 Nov 2017 10:55			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
<b>Insured:</b> HO SIN GIAN, ID: S8137774Z, Tel: +6591152217, Email: MARINE_HO@YAHOO.COM									
<b>Vehicle Reg. No.:</b> SLG6984S		<b>Date of Loss:</b>	27/10/2017 00:00 - :59						
<b>Claim Type:</b> OD / 1201700007395		<b>Policy/Cover Note No.:</b>	PNPV2017-00007322 (Comprehensive)						
		<b>Excess:</b>	S\$500.00						
<b>Repairer:</b> Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834									
<b>Handling Insurer:</b> FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by <b>Belliana</b> - 67275741]									
<b>Adjuster:</b> LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... [Final Rpt due 17/11/2017]									
<b>Driver/Custodian:</b> LEE POH CHOO,LINDA (LI BAOZHU) (38 / Female), NRIC: S7910707G, Tel: +6591152218									
<b>Adj Asg. Remarks:</b> Auto-assignment adjuster same as linked case									
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
• FWD_SG (16/11/2017): Alert - Adj Mandate Approved (S\$4455.00) - SLG6984S - Claim Handler: Belliana									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SLG6984S (1201700007395)  
 OD  
 Oct 27 2017 12:00AM  
 [HO SIN GIAN]  
 Automotive Repair Centre Pte Ltd

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">Use Viewer</a> ▼	
<b>Assessment Reports</b>				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	08/11/17 13:18	Repairer Estimates	1	Load HTM	
2	21/11/17 10:55	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	16/11/17 09:44	Adjuster Immediate Advice	1	Load HTM	
<b>Photos/Images</b>				3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	08/11/17 13:03	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
2	08/11/17 13:03	Tyre Size	1	Load JPG	<input checked="" type="checkbox"/>
3	08/11/17 13:03	Tyre Brand	1	Load JPG	<input checked="" type="checkbox"/>
4	08/11/17 13:03	Engine Compartment	1	Load JPG	<input checked="" type="checkbox"/>
5	08/11/17 13:03	Accident Scene Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	08/11/17 13:03	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
7	08/11/17 13:03	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
8	08/11/17 13:03	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
9	08/11/17 13:03	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
10	08/11/17 13:03	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	16/11/17 09:56	General View	1	Load JPG	<input checked="" type="checkbox"/>

24	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
25	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
26	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
27	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
28	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
29	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
30	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
31	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
32	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
33	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
34	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
35	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
36	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
37	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
38	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
39	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
40	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
41	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
42	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
43	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
44	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
45	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
46	16/11/17 09:56	General View		Load JPG	<input checked="" type="checkbox"/>
47	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	24/11/17 18:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	24/11/17 18:08	PHOTO BEFORE PAINT		Load JPG	<input checked="" type="checkbox"/>
57	24/11/17 18:08	PHOTO BEFORE PAINT		Load JPG	<input checked="" type="checkbox"/>
58	24/11/17 18:08	PHOTO BEFORE PAINT		Load JPG	<input checked="" type="checkbox"/>
59	24/11/17 18:08	PHOTO BEFORE PAINT		Load JPG	<input checked="" type="checkbox"/>
60	24/11/17 18:08	PHOTO BEFORE PAINT		Load JPG	<input checked="" type="checkbox"/>
61	24/11/17 18:08	PHOTO BEFORE PAINT		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/11/17 09:58	ESTIMATE		Load PDF	
2	12/12/17 08:21	Parts Invoice		Load PDF	
3	12/12/17 08:23	Supplementary		Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				

**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986

Our File No: CS/FWD17021396/SRBE2

Date: 12/12/2017

### REFERENCE

Insured/Claimant: HO SIN GIAN Policy No: PNPV2017-00007322  
Date of Loss: 27/10/2017 Nature of Claim: OD Claim No: 1201700007395

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG6984S  
Make & Model: NISSAN X-TRAIL, 2.0 CVT (A) Engine No: MR20905927B  
Reg. Date: 11/10/2016 (Man. Year: 2016) Chassis No: JN1JANT32Z0002584  
Colour: Blue Odometer: 15878 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: S\$110,000.00  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,153.00	2,465.00	2,688.00	52.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	620.00	300.00	32.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,073.00</b>	<b>3,085.00</b>	<b>2,988.00</b>	<b>49.20</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>5,573.00</b>	<b>2,585.00</b>	<b>2,988.00</b>	<b>53.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>390.11</b>	<b>180.95</b>	<b>209.16</b>	<b>53.62</b>
<b>Nett Amount (S\$)</b>	<b>5,963.11</b>	<b>2,765.95</b>	<b>3,197.16</b>	<b>53.62</b>

### INSPECTION

Date of Assignment: 08/11/2017 Present Location: Automotive Repair Centre Pte Ltd (HQ)  
Date Inspected: 15/11/2017 Inspected At: 38 Woodlands Industrial Park E1, #05-18  
Singapore 757700

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 12 Dec 2017)	
<b>Parts:</b>	N/A	NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG6984S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Cracked	320.00 F	*320.00 F
2	1	*FRONT BUMPER ALUMINIUM DEFUSER	Missing	680.00 F	*680.00 F
3	1	*FRONT BUMPER ALUMINIUM DEFUSER SCREW X2	Not Necessary	10.00 F	*- F
4	1	*FRONT BUMPER CHROME MOULDING TRIM	Cracked	110.00 F	*110.00 F
5	1	*FRONT BUMPER CLIPS X10	Necessary	20.00 F	*20.00 F
6	1	*FRONT BUMPER RETAINER RH	Not Necessary	20.00 F	*- F
7	1	*FRONT BUMPER RETAINER LH	Not Necessary	20.00 F	*- F
8	1	*FRONT BUMPER TOWING COVER	Not Necessary	18.00 F	*- F
9	1	*FRONT BUMPER UNDERCOVER	Not Necessary	280.00 F	*- F
10	1	*FRONT REINFORCEMENT	Not Necessary	280.00 F	*- F
11	1	*FRONT SPONGE	Not Necessary	185.00 F	*- F
12	1	*FRONT GRILLE	Not Necessary	320.00 F	*- F
13	1	*FRONT LOWER GRILLE	Not Necessary	145.00 F	*- F
14	1	*FRONT FOGLAMP LH	Not Necessary	225.00 F	*- F
15	1	*FRONT FOGLAMP GARNISH LH	Not Necessary	65.00 F	*- F
16	1	*FRONT HEAD LAMP LH	Scratched	1,100.00 F	*1,300.00 F
17	1	*FRONT HEAD LAMP BRACKET LH	Not Necessary	20.00 F	*- F
18	1	*FRONT LICENSE PLATE WITH FRAME	Cracked	35.00 F	*35.00 FS
<b>Supplementary #1</b>					
19	1	*FRONT HEAD LAMP LH	Repeated	1,300.00 F	*- F
F=Franchise part. S=SpcNett.					
<b>Total Parts (S\$)</b>				<b>5,153.00</b>	<b>2,465.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOTAL PAINT LABOUR AND MATERIAL	New	400.00	300.00
2	REMOVE, REFIT AND REPAIR AFFECTED ACCIDENT AREA	New	500.00	300.00
3	CHECK AND RECTIFY ELECTRICAL WIRING	New	20.00	20.00
Gross Labour Cost (S\$)			920.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >