

4/10/2008

ASS. REC. BY

REF: CS/FCI17021429/Ggbr

Special Instruction

Surveyor

GB

ASSIGNMENT (Office)

CNS

From (Person): Eugene Jaw

of FCI

Date/Time: 2:25pm @ 9/11/17

Estimated Cost:

Bill to:

OD (IP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA8252B

Insured:

SHC73972

at Workshop m/s

Volkswagen

Tel:

81214693

of

1 Kampong Ampat, MacPherson Rd 368314

Policy No:

D-15072702MFSH

Claim No:

D17010410MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/11/2017

CA / REV / REP. / REV 24 HRS

(wp)

10/11/17 @ 3pm owner waiting

R.O.D. Endorsement

Date/Time:

2:48pm @ 9/11/17

Person Contacted:

William

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKA8252B-x

SHC73972-x

14/11/17 @ 5:10pm revised to Eugene Jaw by email.

29/11/17 @ 4:21pm confirmed with Germaine final fig \$3157.68, 3 days.
(Red \$2480, 44%.)

Surveilling

XHL

REF: FCI

ASSIGNMENT

From: Date: 10/11/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKA 8252 B

at Workshop m/s Volkswagen

of 1 Kampong Ampert, Macpherson Rd 368314

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

3pm @ Owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKA 8252 B Yr Regn: 06 Apr 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta cc 1390

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 22738 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ 168 GM 017134

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 10-11-17

3:40pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 NOV 2017

Date/Time, File Pass to?

12/11/2017

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

☐ : S + RS, ☐ SI

☐ : Photos

☐ : Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 3157.68)

140
50
50
21
261



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021429/Gqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7397Z	Veh. Inspected	SKA 8252B
Policy No.		Coverage (\$)	0.00
Claim No.	D17010410MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	09/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/11/2017	Inspection Date	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Cathie): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Cao Dong): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓		
---	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓		
✓		
✓		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓		
---	--	--

Check By:

[Signature] 29/11/17

Case Handler

Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	08-11-2017	Our Ref No. D17010410MFSH
Accident Date	06-11-2017	Claim Type. Third Party
Insured Vehicle	SHC7397Z	Third Party Vehicle. SKA8252B
Survey Location	1 KAMPONG AMPAT	
Contact Person.	WILLIAM TAN	
Contact No.	65156560/ 81214693	Fax No. 68618225
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VOLKSWAGEN CENTRE SINGAPORE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229972)



PRI Documents



Close



PRI Header Details

Claim No	D17010410MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & VOLKSWA (MACPHERSON)
Workshop Name	VOLKSWAGEN CENTRE SINGAPORE (Contact Person : WILLIAM TAN)	Survey Location & Contact Details	1 KAMPONG AMPAT Mobile: 81214693 , Phone: 65156560 , Fax: 6861822! EmailId: WILLIAM.TAN@VW.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7397Z	TP Vehicle No	SKA8252B
PRI Recieved Date	08-11-2017 05:24:42 PM	Surveyor Appointed Date	09-11-2017 02:24:35 PM	Surveyor Accept Date	09-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 29 November, 2017 4:21 PM
To: Ong, Germaine (VWG Singapore)
Cc: Admin A; CS A Team; SUR; Tan, William (VWG Singapore); Tang, Shu Shi (VWG Singapore)
Subject: RE: FINALISATION SKA8252B

Dear Germaine,

Confirm final fig \$3,157.68 before GST and 3 repair days.

Kindly send the relevant documents to First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 29 November, 2017 3:40 PM
To: SUR <sur@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: FW: FINALISATION SKA8252B

CS/FCI17021429/Gqb

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong, Germaine (VWG Singapore) [<mailto:Germaine.ong@vw.com.sg>]
Sent: Wednesday, 29 November, 2017 3:23 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: Tan, William (VWG Singapore) <william.tan@vw.com.sg>; Tang, Shu Shi (VWG Singapore) <shushi.tang@vw.com.sg>
Subject: FINALISATION SKA8252B

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 14 November, 2017 5:10 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010410MFSH/1
Attachments: CSFCI17021429Gqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKA 8252B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 9 November, 2017 2:50 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010410MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 9 November, 2017 2:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010410MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010410MFSH
Our Ref: CS/FC117021429/Gqb

Date: 14 November 2017

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKA 8252B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/11/2017 at the premises of M/s VOLKSWAGEN , and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,637.68</u> .
Revised Estimate Amount	: S\$ <u>3,157.68</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

Enquire Transfer Fee

Vehicle Details

Vehicle No.	SKA8252B
Vehicle Type	P10 - Passenger Motor Car
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	VOLKSWAGEN
Vehicle Model	JETTA GP 1.4 TSI 90 A/T HL HID 1634G5
Chassis No.	WVWZZZ16ZGM017134
Propellant	Petrol
Engine No.	CAXF83746
Engine Capacity	1390 cc
Maximum Power Output	90.0 kW (120 bhp)
Maximum Laden Weight	1870 kg
Unladen Weight	1417 kg
Year Of Manufacture	2015
Original Registration Date	06 Apr 2016
Lifespan Expiry Date	-
COE Category	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium	\$45,504.00
COE Expiry Date	05 Apr 2026
Road Tax Expiry Date	05 Apr 2018
PARF Eligibility Expiry Date	05 Apr 2026
Inspection Due Date	05 Apr 2019
Intended Transfer Date	14 Nov 2017
CO2 Emission	138.00 (g/km)
CEVS Rebate Utilised Amount	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	

Amount Payable

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------	------------------	------------------------



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

VW DRIVEEASY
Comprehensive

Certificate No. A 28720121 AVW

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SKA8252B

2. Name of Policyholder
Tan Canny

3. Effective Date of the Commencement of Insurance for the purposes of the Act
06/04/2017

4. Date of Expiry of Insurance
05/04/2018

5. Persons or Classes of Persons entitled to drive*

Tan Canny

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

Sketch Plan #4 Pg. 1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8005334G



Name
CANNY TAN
陳凱妮

Religion
CHINESE

Date of Birth
26-02-1980

Country of Birth
SINGAPORE

Sex
F

DRUG ALLERGY
Gempaglitazar - ischaemic heart disease




REPUBLIC OF SINGAPORE DRIVING LICENCE



NAME
CANNY TAN

Issue Date
05 Feb 1990

Valid Until
11 Mar 2004

0011578119

9313592



NRIC No: S8005334G



Hand Group Date of issue
26-02-2003

97 PASIR RIS HEIGHTS #01-26
SINGAPORE 519280
NRIC No: S8005334G Date: 05/11/2017

YOU ARE ENTITLED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

CLASS DATE
11 Mar 2004

NP 428A

Licence No: S8005334G



PDI TUAS



3 Days.

before parts photo's

Gue Qing - 888082

10/11/17

PDI TUAS

CANNY TAN
81 LORONG K TELOK KURAU
#03-03
Singapore, 425711
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV033290
Quote No. SER/QUO/1701859
Quote Date 07/11/17
Salesperson Goh Terry
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	22,302	Tan William
License No.	VIN	Initial Registration	Sales Advisor
SKA8252B	WVWZZZ16ZGM017134	06/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F83746	1634G7

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	3	UNIT		2,520.00
P B&P MACP PAINT	SPRAY PAINT	2	UNIT		1,600.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		280.00
	Sum Labor				4,400.00
P 5C6807421H GRU	REAR BUMPER / <i>re</i>	1	Pieces		1,023.60
	Predecessor 5C6807417J GRU				
P 5C6919493A	REAR BUMPER SENSOR BRACK /	1	Pieces		53.52
P 5C6919493B	REAR BUMPER SENSOR BRACK /	1	Pieces		53.52
P 5C6919494A	REAR BUMPER SENSOR BRACK /	1	Pieces		53.52
P 5C6919494B	REAR BUMPER SENSOR BRACK /	1	Pieces		53.52
	Sum Item				1,237.68

Sum Labor 4,400.00
Sum Item 1,237.68

Total SGD 5,637.68
7% GST 394.64
Total SGD Incl. GST 6,032.32

Explanations

P = Proportionately Charged

Payment Terms

Signature: No Credit

Date:

Payments to:

- BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO: 17IP3133

CUSTOMER NO.: CV033290

CUSTOMER NAME: CANNY TAN

TELEPHONE NO.:

ADDRESS: 81 LORONG K TELOK KURAU #03-03

Singapore

VEH No.: SKA8252B

Order Date: 21/11/17

Reg Date: 06/04/16

KM: 23,894

VIN NO.: WVVZZZ16ZGM017134

ENGINE NO:

SA: Tan William

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	280		280
2	B&P MACP LABOUR LABOUR	1	UNIT	840		840
3	B&P MACP PAINT SPRAY PAINT	1	UNIT	800		800
4	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
5	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
6	5C6807421H GRU REAR BUMPER	1	PCS	1,023.60		1,023.60
7	5C6919493A REAR BUMPER SENSOR BRACKET	1	PCS	53.52		53.52
8	5C6919493B REAR BUMPER SENSOR BRACKET	1	PCS	53.52		53.52
9	5C6919494B REAR BUMPER SENSOR BRACKET	1	PCS	53.52		53.52
10	5C6919494A REAR BUMPER SENSOR BRACKET	1	PCS	53.52		53.52

Remarks : DIRECT SETTLEMENT (FIRST CAP)

DOA 06/11/2017

SURVEY BY LKK

TP VEHICLE NO SHC7397Z

Claim number : D17010410MFSH

*Officer-in-Charge : LURENE

Service Order Confirmation

SERVICE ORDER NO: 17IP3133

CUSTOMER NO.: CV033290

CUSTOMER NAME: CANNY TAN

TELEPHONE NO.:

ADDRESS: 81 LORONG K TELOK KURAU #03-03
Singapore

VEH No.: SKA8252B

Order Date: 21/11/17

Reg Date: 06/04/18 KM: 23,894

VIN NO.: WVVZZZ16ZGM017134 ENGINE NO:

SA: Tan William

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	3,157.68
GST AMOUNT	221.04
TOTAL AMOUNT	3,378.72

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021429/Gqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-11-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7397Z	Veh. Inspected	SKA 8252B	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17010410MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	09/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WWZZZ16ZGM017134	Colour	BLACK	
Odometer	22738	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/11/2017	Inspection Date	10/11/2017	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 8252B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	1,023.60	1,023.60
1	REAR BUMPER SENSOR BRACK (SN)	NECESSARY	53.52	53.52
1	REAR BUMPER SENSOR BRACK (SN)	NECESSARY	53.52	53.52
1	REAR BUMPER SENSOR BRACK (SN)	NECESSARY	53.52	53.52
1	REAR BUMPER SENSOR BRACK (SN)	NECESSARY	53.52	53.52
			1,237.68	1,237.68
LABOUR				
LABOUR.			2,520.00	840.00
SPRAY PAINT.			1,600.00	800.00
PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.			280.00	280.00
			4,400.00	1,920.00
GRAND TOTAL			5,637.68	3,157.68
RECOMMENDED COST OF REPAIRS				3,157.68

Report Ref No. CS/FCI17021429/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.