Type MCGP M Cycle / Bus / Van Nov S \$ \$ \$ 666 D	91		ASSIGNMENT	= .59 N		
Similario Cost Ditp Wis TP RES OD RES EVA INV MV		620	Mah No	SJS1666 D	Yr Regn. 2011	Nov
Truck / Trailler or Make: And I A6			100001000			
Asker Colour Black Action Insured Issured Sp. Reading 57486 TiRadio Insured Istal Ins			LAW LATER IN			
Colour Black AIC: Insured / Std / Ni / NA spreading 57486. TRadio: Insured / Std / Ni / NA spreading 57486. TRadio: Insured / Std / Ni / NA spreading 57486. TRadio: Insured / Std / Ni / NA EngNo: CNo: WALZZZZGGCO 3720 Gen. Cond. Good / Fair / Poor / Burnt Steering: Insured / Jammed / Leaked / Burnt or Walter of Vehr: Policy Condition	1000	200 (20	Make:	Audi A6	c.c	2995
Sp. Reading S7486. TiRadio: Insured / Std / NI / NA natured / Na			Colour	Black.	A/C: Insured / St	td / NI / NA
Eng No: C/No: WAU 222464 CNO 5 3 720 Color 1 85 6 5 Color 1 8 6 7 Color 1 8 6 5 Color 1 8 6 7 Color 1 8 6 5 Color 1 8 6 7 Color 1 8 7			Sp.Reading	57486.	T/Radio: Insured / S	td / NI / NA
CNO: CALLERY I REP. 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction Date / Time File Return 107 Prelia Report RECEIVED Days Of Repair: 3 Pass Survey Fee: 100 Instruction (S Prelia Report) Final Report RECEIVED Days Of Repair: 3 Pass Survey Fee: 100 Instruction (S Prelia Report) Instruction (S Prelia Report) Press Date / Time Action / Instruction Act						
Gen. Cond. Good / Fair / Poor / Burnt Sum Insured: Excess: (1400 10 11) Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nill (SRIP) / STD ARIM or Tyre Size: F: 255 35 R20 Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: 100 K IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No LUM Sum: 96 3 Val.: Yes or No CA / REP / REP. / 24 HRS Date: Person Contacted: Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Date / Time Action / Instruction DO A / G. Survey held at Consistent? Yes or No Date / Time Action / Instruction DO A / G. Survey held at Consistent? Yes or No Date / Time Action / Instruction DO A / G. Survey held at Consistent? / Survey / G. Do A / G. Survey held at Consistent? / Survey / G. Do A / G. Survey held at Consistent? / Survey / G. Do A / G. Survey / G. Date / Time / G. Date / G. Date / Time / G. Date	MSV/IIqt//iii	7100778565		WAU 2224	64CNO53720)
Sum Insured: Excess: 1/400 (0/1/2) Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nill (SiRtin / STD A/Rtim or Modi: Nill (SiRtin / STD A/Rtim or Tyre Size: F: 255 3 5 R 20 R: 355 3 5 R 2		07307111456	Gen, Cond: G	oed / Fair / Poor / Bur	nt	
Brake: Inorder / Jammed / Leaked / Burnt or		11/0	0/u// Steering: Inor	der / Jammed / Leake	d / Burnt or	
Modi: NIII (SRIM) or Tyre Size: F: 255 35 R20 Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: 100 K IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No UBal. of mm RBal. of		W. Oskarotto	Brake: Inor	der / Jammed / Leake	d / Burnt or	
Policy Condition Remark: The veh had commenced its repair at the time of inspection. Nis Ois BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU (FIR)/SUMI/ TOYO/YOKO or Bal. or Market Value: 100 K.			Modi: Nil(
Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: IDAC Accident Roport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 3 Val.: Yes or No LUB Survey held at Date / Time Action / Instruction Date / Time Action / Instruction DA A C. SURVEY REP. I 24 HRS Date / Time Action / Instruction DA A C. SURVEY REP. I Consistent Repairs: Date / Time Action / Instruction DA A C. SURVEY REP. I CONSTRUCT REPAIRS R			Tyre Size:			
Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: 100 K DAC Accident Rport: Consistent?: Yes or No DAC Accident Rport: Consistent?: Yes or No Est. Repairs: 03 KMs days Res.: Yes or No LUBAL 96 mm LUBAL 96 mm LUBAL 96 mm LUBAL 96 mm LUBAL 96 mm LUBAL 96 mm LUBAL 96 mm	(Policy Cond	lition)		R: ⊅≤≤	35R20	
Ball or Market Value: 100 K IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 03 M/S days Res.: Yes or No LUBAL 06 mm R/Bal. 06 mm D.O.A. D.O.I. 09 1417 Ball 06 mm LUBAL 06 mm D.O.A. D.O.I. 09 1417 Ball 06 mm R/Bal. 06 mm R/Bal. 06 D.O.I. 07. 105 107	(8)	W (CONTRACTOR	O/S BS / DUN / E	XNOVA / GY / FS / LIZ	A / MIC / OHTSU (PIR) / S	SUMI /
DAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 03 / 6 / days Res.: Yes or No Lum Sum: 96 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN/OUT Date / Time Action / Instruction OD A (9. S. 3.3 Logo Paramed P	repa	ir at the time of inspection.	TOYO / YOF	KO or		
DAC Accident Roport: SIA / PR Seen: Consistent?: Yes or No Est. Repairs: 03 / M/S' days Res.: Yes or No LUM SUM: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time	Bal. or Market	Value: 100K	Front		Rear	
Est. Repairs: 03 M/s days Res.: Yes or No Lum Sum: // % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN/OUT Date / Time Action / Instruction DA A (S.	DAC Acciden	t Rport: Consistent? : Yes or No	R/Bal.	6 mm	- 09	mm
Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN/OUT Date/Time Action/Instruction OV A(G. SJ3 1660 - C3 / Ath 1600 Atto / Ago 2 Io 1174 @ 3.33 m Informed Premium the Boy Free Fig. By 1916 Bo, 3 days. CREOL & U.S. A. Configured With Mr Boy Free Fig. By 1916 Bo, 3 days. CREOL & U.S. A. Configured With Mr Boy Free Fig. By 1916 Bo, 3 days. CREOL & U.S. A. Configured With Mr Boy Free Fig. By 1916 Bo, 3 days. CREOL & U.S. A. Configured With Mr Boy Free Fig. By 1916 Bo, 3 days. CREOL & U.S. A. Configured Mr Memory. Date/Time, Fie Pass 10? Date/Time, Fie Pass 10? Preli. Report RECEIVED Days Of Repair: 20 Add Fee: Site Insp (\$) S+RS_SI Interview (\$) Photos	GIA / PR Se	en: Consistent? : Yes or No		mm		-
Date: Person Contacted: Vehicle: IN/OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision Date / Time	Est. Repairs:	03 Mb' days Res.: Yes or No	D.O.A.	o		417
Date: Person Contacted: Vehicle: IN/OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision Date / Time	Lum Sum:	/ % 3 Val.: Yes or No				
Date / Time Action / Instruction OP A(G. ST3 16660 - CC3 A 161600 9160 Agb C2 DCA: 170516 10 11 12 12 12 12 12 12	CA / REV			ages (Frt) Rear / O/	S / N/S / U/C / Roofto	op or
DOP ALG. STO 1660 - CC3 /ALG 600 9410 / Ago 2 10 11/12 @ 5.37 m Informed Premium Ext & 1400 by email. 14/11/12 @ 3.09 m vount to Michar Via Marinnen. 14/11/12 @ 3.33 m Victor informed elle via Marinen. 15/11/12 @ 11.51 an Informed Premium C/A TO EX: & 1400 by email. 15/11/12 @ 11.51 an Confirmed with his Bod finel fig & 12916.80, 3 days. Check & (4892.70, 547.) Daterlime, File Pass 107 13/1 Michar : Preli. Report RECEIVED Days Of Repair: 2 Add Fee: Site Insp (\$) _S-RS_SI 10 Interview (\$) Photos	Date:		AND LOCATION IN CO.	/ Chassis frame / Bo	ody Structure affected d	ue to collision
STO 1660 - CC3 /A 16100 9410 / Agb C2 10 11/14 @ 5.37 M Informed Premium the By Games. 14/11/17 @ 3.33 M Victor Informed CLA Marianen. 14/11/17 @ 3.33 M Victor Informed CLA Marianen. 15/11/19 @ 11.41 M Informed Premium C/A TO EX. B/400 by emori. 14/11/18 @ 11.51 M Confirmed with her boo fire! Fig & 12916.80, 3 days. CRed & (4892.20, 347.) Date/Time. File Pass 10? 13/1 Minh : Final Report RECEIVED Days Of Repair: 13/1 Minh : Final Report RECEIVED Days Of Repair: 13/1 Minh : Final Report RECEIVED Days Of Repair: 13/1 Minh : Final Report RECEIVED Days Of Repair: 13/1 Minh : Final Report RECEIVED Days Of Repair: 13/1 Minh : Final Report RECEIVED Days Of Repair: 13/1 Minh : Survey Fee: 200 10 Interview (\$) _s-RS_SI	Date / Time					
14/11/17 P 3.33 M Victor Informed CIA Warman. 15/11/19 P 11.41 Informed Premium C/A B EX: 80/400 by emer! 15/11/19 P 11.51 Confirmed With Mr Boo Fire! Fig 6 12916.80, 3 days. CRed 6 (4892.70, 547.) Date/Time, File Pass 10? 13/11 Mish : Final Report RECEIVED Days Of Repair: 13/11 Mish : Final Report Resurvey No. of Trip: Survey Fee: 200 Transportation 10 Add Fee: : Site Insp (\$)S+RSSI		OD A(9.	Could /hJ-sh		Dra : 120511	п
14/11/17 P 3.33 M Victor Informed CIA Warman. 15/11/19 P 11.41 Informed Premium C/A B EX: 80/400 by emer! 15/11/19 P 11.51 Confirmed With Mr Boo Fire! Fig 6 12916.80, 3 days. CRed 6 (4892.70, 547.) Date/Time, File Pass 10? 13/11 Mish : Final Report RECEIVED Days Of Repair: 13/11 Mish : Final Report Resurvey No. of Trip: Survey Fee: 200 Transportation 10 Add Fee: : Site Insp (\$)S+RSSI	ielulia	@ = 220 10 Dormed Pan	nun EX: 81	400 by en	nst.	
14/11/17 @ 3.33 M Victor Informed EIB Na Warman. 15/11/19 @ 11.41 Informed Premium C/A 10 EX: 80/400 by emer! 24/11/18 @ 11.51 an Confirmed with Mr Boo Finel Fig 6 12916.80, 3 days. CRED 6 (4892.70, 547.) Date/Time, File Pass 10? 13/11 Mish : Final Report RECEIVED Days Of Repair: 2 Resurvey No. of Trip: Survey Fee: 200 Transportation 10 Add Fee: : Site Insp (\$)S+RSSI	14/11/12	@ 3.07m round to Vich	w Va Merion	en.		
DaterTime, File Return to? Add Fee: Site Insp (\$) Photos 15 17 18 18 18 18 18 18 18	11.11.11	@ 222. Victor informed	CIA VIG	region,		
Date/Time, File Pass 10? Date/Time, File Return to? Add Fee: Site Insp (\$)	11.11	a 11 Alan Intorned Pren	widn C/A 10	Ex. D1400	by emeral.	
Date/Time, File Pass to? 1) 31 Moth : Preli. Report RECEIVED Days Of Repair: 3 1) 31 Moth : Final Report Resurvey No. of Trip: Survey Fee: 200 1) Cate/Time, File Return to? Add Fee: : Site Insp (\$)s.+Rssi 2) Add Fee: : Interview (\$) Photos	24/1/180	@ 11.51 an confirmed with	Mr Boo fine	el fry 6 1291	6.80, 3 day	3.
1) 31 1 Milh : Final Report Resurvey No. of Trip: Survey Fee: 200 Transportation 10 State File Return to? Add Fee: Site Insp (\$)S.+RSSI Interview (\$) Photos	. 1 1	The state of the s	I de la companya della companya della companya de la companya della companya dell		uk to hardler fr	Il in con
1)31 1 Mish: : Final Report : Resurvey No. of Trip: Survey Fee: 200 Date/Time, File Return to? Cleaned At RECEIVED 0 State 2018 Transportation. 10	Date/Time, File	Pass to? : Preli, Report RECE	Days Of Re	pair: 3		
Date/Time, File Return to? Cecened File RECEIVED 0 5 FEB 2018 Transportation. 10	31/1 /				Survey Fee:	200
Interview (\$) Photos	Date/Time, File	10.			Transportation	10
Interview (\$) Photos	2)	A	dd Fee: Site	Insp (\$)S.+RSSI	
Report Format : Tech, Invs (\$) Others Lump Sum / I.B.I: (\$ (2816 - 89) : Weekend (\$)	15.0-11.51	Long to the	: Inte	rview (\$) Photos	
Lump Sum / I.B.I: (\$ /28/6-89 : Weekend (\$)	Report Fo	ormat: WER-OD	: Tec	h. Invs (\$) Others	
	1 4 4 14 14 14 1	COLUMN CO	- Participant -			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Claim No. Assign From 2. Make & Model Engine No. Chassis No. Odometer Brakes General 3. R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre 4. Accident Date 03/	ANCE PTE LTD	Pof . 000/AI0/700/	
CHARTIS BUILDING SINGAPORE 079120 1.		Ref : CC3/AIG17021	1433/Aqb
Insured Veh. Policy No. 210 Claim No. Assign From 2. Make & Model Engine No. Hill Chassis No. Odometer Brakes General 3. Siz R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre 4. 5. Accident Date 03/	i	Date: 09-11-2017	
Policy No. 216 Claim No. Assign From 2. Make & Model Engine No. Hill Chassis No. Odometer Brakes General 3. R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre L.H Rear Tyre	Policy Part	ticulars :- OWN DAMAGE	
Claim No. Assign From 2. Make & Model Engine No. Chassis No. Odometer Brakes General 3. R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre 4. Accident Date 03/	Victoria de la companya del companya de la companya del companya de la companya d	Veh. Inspected	SJS 1666D
Assign From 2. Make & Model Engine No. Hill Chassis No. Odometer - Brakes General 3. R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre L.H Rear Tyre	00278565	Coverage (\$)	0.00
Make & Model Engine No. Hill Chassis No. Odometer Brakes General B. Siz R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 03/		Excess (\$)	0.00
Make & Model Engine No. Hill Chassis No. Odometer Brakes General S. Siz R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 03/		Assign Date	09/11/2017
Engine No. HID Chassis No. Odometer - Brakes General R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 03/	Vehicle F	Particulars & Condition	
Chassis No. Odometer Brakes General Siz R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 03/		c.c	0
Odometer - Brakes General B. R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 03/	DDEN	Year of Reg.	
Brakes General Siz R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 03/		Colour	***
General Siz R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre Accident Date 03/		Steering	
R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre		Modification	
R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 03/	7.5		
R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L. Accident Date 03/	Cor	nditions of Tyres	PENG TYPE BURNESS
L/H Front Tyre R/H Rear Tyre L/H Rear Tyre . Accident Date 03/	e	Make	Balance
R/H Rear Tyre L/H Rear Tyre . Accident Date 03/			mm
L/H Rear Tyre			mm
Accident Date 03/			mm
Accident Date 03/			mm
Accident Date 03/	Desc	ription of Damages	
	Ger	neral Information	
	11/2017	Inspection Date	09/11/2017
	EMIUM AUTOMOBILES	EAST-MANUFACTURE CONTRACTOR	25450 F.C. (1/550 D.C.) (1/5)
	UBI ROAD 1 . IGAPORE 408699		
Sa.	AND LANGUE TO SERVICE	Remarks	

Réference No. Ce3/ACE/TONES Agb
Policy Type OD/TP / TP RES / TL / EVA): Case handler to make sure all Information created by the assignment team are ACCURATE. Admin (Y-Date N-Date Y-Date N-Date (1) Office Assign Form Reference No. C Customer Code C Assign From N Assign Date C Veh No (Inspected) C Veh No (Insured) C C D.O.A Policy No C C Claim No Insurance Authorisation (CA /REV/REP) C Report Type C C Weekend Charges Survey held at/Repairer N C Excess Adana): Case handler to make sure the surveryor completed all required information. Surveyor ((1) Assignment Form Vehicle No Regn Month/Year C Vehicle Type Make & Model N Engine Capacity. (C.C) C N Colour Odometer. (Sp.Reading) C Chassis No C General Condition Steering N Brake N Modification (Modi) N Tyre Size C Tyre Make N Tyre Balance C Date of Inspection C Survey held N Des.of Damages N (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases C Estimate Repair Cost for PRI (RSI, TMI, MSIG) C Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uplo ded

Case Handler

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 24 January 2018 11:51 AM

To:

Boo seng yak; SUR; Carrine Leong; Nora Khai

Subject:

RE: FINAL REVISION - SJS1666D - OD AIG - SURVEYED 9 NOV 17

Dear Mr Boo,

Confirm final fig \$12,916.80 before excess \$1,400.00 & GST and 3 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Friday, 22 December 2017 3:01 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong

<carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION - SJS1666D - OD AIG - SURVEYED 9 NOV 17

Hi Adrian and all,

Revised estimate is attached.

Kindly confirm repair cost of \$12,916.80 @ 3 days of repairs.

Your colleague, Mr. Wilson conducted a re-inspection on 13 Nov 17.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 15 November, 2017 11:41 AM

To:

'Claims Department'

Subject:

RE: VEHICLE SJS 1666D (DOA: 03/11/2017)

Attachments:

SJS1666 EST 2.pdf; SJS1666 SUPP.pdf

Dear Sir/Madam,

As instructed by our client AIG, please proceed to repair the insured vehicle SJS 1666D (Excess \$1,400/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Friday, 10 November, 2017 5:37 PM

To: 'Claims Department' <claims@premiumauto.com.sg>

Subject: VEHICLE SJS 1666D (DOA: 03/11/2017)

Dear Sir/Madam,

Please be informed that the excess of above vehicle is \$1,400.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

	AUDIT TRAIL		Remarks	By
1	07 Nov 2017	Clm Veh Model	(202954) AUDI A6 3.0 TFSI quattro S-Line (C7) (A).	[] Merimen Administrato
2	18:54 07 Nov 2017 18:54	Clm Created	Reg No: SJS1666D. Policy No: 2100278565-05000. Acct Date: 2017/11/03. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA117147582	[I] Merimen Administrato
3	09 Nov 2017 16:52	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	09 Nov 2017 16:52	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	09 Nov 2017 16:52	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	09 Nov 2017 16:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/20	[A] CATHERINE CHONG KAI LING
7	09 Nov 2017 16:52	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	09 Nov 2017 16:52	Clm Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	09 Nov 2017 16:52	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
10	10 Nov 2017 09:57	Adj Rpt Initiated		[A] SHIAU CHAN
11	10 Nov 2017 09:57	Clm Details Notified		[A] SHIAU CHAN
12	10 Nov 2017 11:24	Clm Registration Modified	Init,Est.:->7,000 - 8,000, Excess: -> 1400.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Mohd Zawaye, Norsazani
13	10 Nov 2017 11:24	Label Added	(20226):Coverage Confirmed.	[A] Merimer Administrate
14	14 Nov 2017 15:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/20	[A] SHIAU CHAN
15	15:06	Auj Manuate Request	Cur.Req:15414.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] SHIAU CHAN
	14 Nov 2017 15:33		Next Rpt:Final Rpt.Due Date:2017/11/20. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
17	, 14 Nov 2017 15:33	Adj Mandate Set	Approved: 15414.00: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK

ACTIVITY

No record

erimen Billin	g for this case -	Transaction	History				
BIII Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1635228	10/11/2017 09:57	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJS1666D		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Mohd Zawaye, Norsazani

Date:

14 Nov 2017

Preliminary Advice

Vehicle No

: SJS1666D

Accident Date

: 03/11/2017

Make

Policy No.

: 2100278565-05000

: AUDI A6

Assignment Date

: 09/11/2017

Excess

: S\$1,400.00

Date of Inspection

: 09/11/2017

Est. Duration of Repair

: 3.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (HQ)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,809.00 (ESTIMATE \$27,736.00 + SUPPLEMENTARY \$73.00)
Revised Amount	:S\$	15,114.00
Check Items (Estimated)	:S\$	300.00
Total	:S\$	15,414.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	86,247.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,753.00

Remarks

let us have your authorisation.	
let de llave your additions allow	

9 -1)	The vehicle i	s uneconomical	to	be repaired,	you are	advised	to	invi	te t	tender	for	the	wrec	k
------	---	---------------	----------------	----	--------------	---------	---------	----	------	------	--------	-----	-----	------	---

Other comments:

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 10 November, 2017 5:37 PM

To:

'Claims Department'

Subject:

VEHICLE SJS 1666D (DOA: 03/11/2017)

Dear Sir/Madam,

Please be informed that the excess of above vehicle is \$1,400.00.

Best Regards,

Shiau Chan (Ms) | Case Handler


LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type	Company	
Owner ID	1891C	
Vehicle Details		
Vehicle No.	SJS1666D	
Vehicle to be Exported	No	
Intended De-registration Date	10 Nov 2017	
Vehicle Make	AUDI	
Vehicle Model	A6 3.0 TFSI QU (LED)	
Primary Colour	Black	
Manufacturing Year	2011	
Engine No.	CGW024305	
Chassis No.	WAUZZZ4G4CN053720	
Maximum Power Output	220.0 kW (295 bhp)	
Open Market Value	\$82,506.00	
Original Registration Date	18 Nov 2011	
First Registration Date	18 Nov 2011	
Transfer Count	0	
Actual ARF Paid	\$82,506.00	
Intended PARF Rebate Details		
PARF Eligibility	Yes	
PARF Eligibility Expiry Date	17 Nov 2021	
PARF Rebate Amount	\$57,754.00	
Intended COE Rebate Details		
COE Expiry Date	17 Nov 2021	
COE Category	B - Car (1601cc & above)	
COE Period(Years)	10	
QP Paid	\$70,890.00	
COE Rebate Amount	\$28,493.00	
Total Rebate Amount	\$86,247.00	

The information contained herein is correct as at 10 Nov 2017





EMPLOYMENT PASS

Employment of Foreign Manpower Act (Chapter 91A) Republic of Singapore

LAKEVIEW INVESTMENTS PTE. LTD.



Name DAI XIN PERSONNEL ASSISTANT

G6270011X

10-05-2019

04-04-2017 Date of Issue 28-04-2017 Date of Expiry



L7885395

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

EFFECTIVE DATE

Motor Cars=< 3000kg with =<7 passengers, exclusive 17 Jun 2009 of the driver; and other motor vehicles =< 2500kg Class 3

NP 428A



VISIT PASS Immigration Regulations

Name DAI XIN



Date of Birth Sex

O1-07-1981 M CHINESE
FIN Date of Issue Date of Expiry

G6270011X 28-04-2017 10-05-2019

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED. OR WHEN A NEW CARD IS ISSUED TO YOU.





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.4

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100278565-05000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$1400.00 (1) WINDSCREEN EXCESS S\$100.00

SUM INSURED Market Value INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

LAKEVIEW INVESTMENTS PTE LTD

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT

18 Nov 2016

SJS1666D

4) DATE OF EXPIRY OF INSURANCE

17 Nov 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION : All Age Condition

Any person who is driving on the Insured's order or with their permission. This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions. A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in additional to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

1. AUGI CUSIONER SERVICE CERIER - 35 OUR ROBE 1 (16: 63602525)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgre Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service

Centre

* NAMED DRIVER NA

HIRE PURCHASE COMPANY MayBank

/EMPLOYER'S LOAN *Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in Singapore 28 Oct 2016

504125-200 PREMIUM LEASING - AP 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

AIG Asia Pacific Insurance Pte. Ltd.

ORIGINAL

SSCSYK



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.4

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100278565-05000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$1400.00 (1) WINDSCREEN EXCESS S\$100.00

SUM INSURED Market Value INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

LAKEVIEW INVESTMENTS PTE LTD

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT

18 Nov 2016

SJS1666D

4) DATE OF EXPIRY OF INSURANCE

17 Nov 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION: All Age Condition

Any person who is driving on the Insured's order or with their permission. This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions. A Young and/or inexperienced Driver Excess ("YIDR") of S\$3,000.00, in additional to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

1. Audi Customer Service Center - 55 Util Road 1 (1 6: 63952323)
APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)
2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)
4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
10. SME Motor - 1 Kaki Bukit Ave 6 Rik D. (Tel: 67478406)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service

Centre

* NAMED DRIVER NA

HIRE PURCHASE COMPANY MayBank

/EMPLOYER'S LOAN *Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in Singapore 28 Oct 2016


504125-200 PREMIUM LEASING - AP 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCSYK



EMPLOYMENT PASS

Employment of Foreign Manpower Act (Chapter 81A) Republic of Singapore

LAKEVIEW INVESTMENTS PTE. LTD.

DAI XIN PERSONNEL ASSISTANT

G6270011X

Date of Application

04-04-2017

Date of Issue 28-04-2017 Date of Expiry 10-05-2019

L7885395

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Motor Cars=< 3000kg with =<7 passengers, exclusive 17 Jun 2009 of the driver; and other motor vehicles =< 2500kg

Licence No: G6270011X

Name

DAI XIN

Date of Birth Sex Nationality

01-07-1981 M CHINESE FIN Date of Issue Date of Expiry

VISIT PASS Immigration Regulations

G6270011X 28-04-2017 10-05-2019

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

NP 428A



AIG Asia Pacific Insurance Pte. Ltd AIG Building 78 Shenton Way #07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME	: Dat Xin
VEHICLE NUMBER	: 828 1980
DATE/ TIME OF ACCIDENT	: 3/11/17
PLACE OF ACCIDENT	: Paya Labor towards PIE
THIRD PARTY VEHICLE (IF ANY)	: SHD 1295 T
**************************************	WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?
I start my journey	from my home to Airport to pick up
my colleague	
- No	XTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?
WERE YOU OR YOUR PASSENGER/S INJURED FOR INVESTIGATION? — NO	D? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE
***	***

NAME: Dai Vin

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

UNDERTAKING

1. Dai Xin	, (NRIC No. 6627001)X), hereby
confirm that the Singapore	Accident Statement lodged by me on
ASSESSMENT OF THE PARTY OF THE	I was the driver are true and accurate to the best of my
knowledge, information and	
I acknowledge that my insur a breach of policy terms and	ers are not liable under the contract of insurance if there is deconditions.
	ed/unreported third party property or injury claim arises or
	that there is a breach of policy terms and conditions, I
	bsolve my insurer from all liability under the contract of
	to re-pay any sums paid by my insurers pursuant to the
contract of insurance upon i	receipt of written demand by my insurers.
Signature	: 鼓(
Name of Insured / Driver	Dai Xin
Nric No.	G 6270011 X
Date	1
Signature	: - THE WEST MENTS
Name of Policyholder	: Lakevieles Investments Pte Ltd
Nric No.	:
Date	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate Accident Repairs Workshop Ubi Road 1 6366 2323 Contact No

6841 1183 Fax No

Reference PA/OD/1108/2017/TF

8-Nov-17 Date

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Vehicle No

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

LAKEVIEW INVESTMENTS PTE LTD Owner's Name

101 THOMSON ROAD Address

#28-05 UNITED SQUARE

Singapore 307591

HP +65 9652 7776 Telephone Own Damage Claims Type of Claim

2100278565-05000 Policy No. SIS 1666 D

Audi A6 C7 3.0T FSI QU Model Code

Model / Year Nov-11

CGW 024305 **Engine No**

Chassis No WAUZZZ4G4CN053720

Mileage

6-Nov-17 Date In

Liability **Excess Cost**

Johnny Boo / Allan Wu Estimated By

Accident Date 3-Nov-17

PAYA LEBAR TOWARDS PIE Place of Accident

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 1666 D.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire hardness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	/
2	To dismantle and renew front bumper and both front headlights. Re-organise front crash management components.Reinstall all parts removed.		\$ 2,100.00	500
3	To respray front bumper.		\$ 900.00	550
4	To carry out diagnostic check.	S/N	\$ 192.00	/
	TOTAL LABOUR CHARGES		\$ 3,672.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SSJS 1666 D.

S/N	Parts Description		Damage Parts & Prices S/NETT REMARKS
1 2	FRONT BUMPER Delomed FRNT RADIATOR GRILLE Crucles	\$	2,513.00 7010.40 1,134.00 407.20
3	FRONT BUMPER AIR GRILLE - LH /RH / 2	\$	474.00 ±
4	FRONT BUMEPER AIR GRILLE COVER - RH	\$	42.00 + 33.44
5	FRONT BUMPER LOWER CENTER GRILLE and	\$	106.00 84.40
6	FRONT BUMPER SUPPORT ~ 2	\$	20.00 ~
7	FRONT BUMPER GUIDE PIECE - LH /RH	\$	62.00
8	FRONT BUMPER TOP COVER Couled	\$	100.00 - 79.60
9	CAUTION STICKER HE	\$	12.00 - 9.04
10	FRONT BUMPER FOAM	\$	193.00 + 154
11	FRONT HEADLIGHT - LH /RH LH coulced	\$	18,908.00 9494 75t3.2
12	FRONT HEADLIGHT MOUNTION - LH / RH 2	\$	200.00 7 79.44
13	SUNDRIES NO	\$	300.00 7 24.08
	TOTAL SPARE PARTS	\$	24,064.00
	TOTAL LABOUR CHARGES	\$	3,672.00
	GRAND TOTAL	\$	27,736.00
		S.	90876

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Authorised Pyris, 03 Days.

LKK Auto Consultants her an inty the Repairer of the following

. Third party survey is on a "Without Prejudice" basis.

 Supplementary item(s) must be removeyed and is subject to final approval from insurance Company

. To resurvey before/after spray painting To display damaged part(s) during resurvey. · Parts prices are subject to confernation

No illegal modification(s) is allowed.

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323 : 6841 1183

Fax No Reference

PA/OD/1108/2017/TF

Date

8-Nov-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Hi Adrian 3 days - ok - jb - 22 Dec 17

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

LAKEVIEW INVESTMENTS PTE LTD

Address

101 THOMSON ROAD

#28-05 UNITED SQUARE

Singapore 307591

Telephone

HP +65 9652 7776

Type of Claim

Own Damage Claims

Policy No.

2100278565-05000

Vehicle No

SJS 1666 D

Model Code

Audi A6 C7 3.0T FSI QU

Model / Year

Nov-11

CGW 024305

Engine No

Chassis No

WAUZZZ4G4CN053720

Mileage

Date In

6-Nov-17

Liability

Excess Cost

Estimated By

Johnny Boo / Allan Wu

Accident Date

3-Nov-17

Place of Accident

PAYA LEBAR TOWARDS PIE

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 1666 D.

S/N	Nature of Jobs		Nature of Jobs		Nature of Jobs Estimated Charges			irveyor's mmendation
1	To remove and transfer front wire hardness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$	480.00	\$	480.00		
2	To dismantle and renew front bumper and both front headlights. Re-organise front crash management components.Reinstall all parts removed.		\$	2,100.00	\$	750.00		
3	To respray front bumper.		\$	900.00	\$	550.00		
4	To carry out diagnostic check.	S/N	\$	192.00	s	192.00		
	TOTAL LABOUR CHARGES	:	\$	3,672.00	\$	1,972.00		

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SSJS 1666 D.

					Damage Parts & Prices				
Parts Description		S	NETT RE	MAR	KS				
V. 3 UP. 200000 1-50 M. UBEPPO SPORK		•	2 513 00	c	2,010.40				
FRONT BUMPER					Figures were				
FRNT RADIATOR GRILLE		\$	1,134.00	\$	907.20				
FRONT BUMPER AIR GRILLE - LH /RH	2	\$	474.00						
FRONT BUMEPER AIR GRILLE COVER - RH		\$	42.00	\$	33.44				
FRONT BUMPER LOWER CENTER GRILLE		\$	106.00	\$	84.40				
FRONT BUMPER SUPPORT	2	\$	20.00						
FRONT BUMPER GUIDE PIECE - LH /RH	2	\$	62.00						
FRONT BUMPER TOP COVER		\$	100.00	\$	79.60				
CAUTION STICKER		\$	12.00	\$	9.04				
FRONT BUMPER FOAM		\$	193.00	\$	154.00				
	2	\$	18,908.00	\$	7,563.20				
	2	\$	200.00	\$	79.44				
		\$	300.00	\$	24.08				
A TO COURT OF THE PROPERTY OF		\$	24,064.00	\$	10,944.80				
		\$	3,672.00	\$	1,972.00				
		\$	27,736.00	\$	12,916.80				
	FRONT BUMPER FRNT RADIATOR GRILLE FRONT BUMPER AIR GRILLE - LH /RH FRONT BUMPER AIR GRILLE COVER - RH FRONT BUMPER LOWER CENTER GRILLE FRONT BUMPER SUPPORT FRONT BUMPER GUIDE PIECE - LH /RH	FRONT BUMPER FRNT RADIATOR GRILLE FRONT BUMPER AIR GRILLE - LH /RH FRONT BUMEPER AIR GRILLE COVER - RH FRONT BUMPER LOWER CENTER GRILLE FRONT BUMPER SUPPORT FRONT BUMPER GUIDE PIECE - LH /RH FRONT BUMPER TOP COVER CAUTION STICKER FRONT BUMPER FOAM FRONT HEADLIGHT - LH /RH SUNDRIES TOTAL SPARE PARTS TOTAL LABOUR CHARGES	FRONT BUMPER FRNT RADIATOR GRILLE FRONT BUMPER AIR GRILLE - LH /RH FRONT BUMPER AIR GRILLE COVER - RH FRONT BUMPER LOWER CENTER GRILLE FRONT BUMPER SUPPORT FRONT BUMPER GUIDE PIECE - LH /RH FRONT BUMPER TOP COVER CAUTION STICKER FRONT BUMPER FOAM FRONT HEADLIGHT - LH /RH SUNDRIES TOTAL SPARE PARTS TOTAL LABOUR CHARGES	FRONT BUMPER \$ 2,513.00 FRNT RADIATOR GRILLE \$ 1,134.00 FRONT BUMPER AIR GRILLE - LH /RH 2 \$ 474.00 FRONT BUMEPER AIR GRILLE COVER - RH \$ 42.00 FRONT BUMPER LOWER CENTER GRILLE \$ 106.00 FRONT BUMPER SUPPORT 2 \$ 20.00 FRONT BUMPER GUIDE PIECE - LH /RH 2 \$ 62.00 FRONT BUMPER TOP COVER \$ 100.00 CAUTION STICKER \$ 12.00 FRONT BUMPER FOAM \$ 193.00 FRONT HEADLIGHT - LH /RH 2 \$ 18,908.00 FRONT HEADLIGHT MOUNTION - LH / RH 2 \$ 200.00 SUNDRIES \$ 300.00 TOTAL SPARE PARTS \$ \$ 24,064.00 TOTAL LABOUR CHARGES \$ 3,672.00	FRONT BUMPER \$ 2,513.00 \$ FRNT RADIATOR GRILLE \$ 1,134.00 \$ FRONT BUMPER AIR GRILLE - LH /RH				

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1108/2017/TF

Date

11-Nov-17

Service Advisor Pages

Jeffery Tan

Regn No

SJS 1666 D

Model No

Audi A6 C7 3.0T FSI QU

Quantity	Description	Unit Price	Amoun
Parts 1 2	Fog light back cover - RHS (MA MA Radiator grille cover (MA	\$ 42.00 \$ 31.00	+
	,	\$ 73.00	
	TOTAL	\$ 73.00	

For Premium Automobiles Pte Ltd

Adria G 86/2. 13/11/12.

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183



Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date 11-Nov-17
Service Advisor Jeffery Tan
Pages 1
Regn No SJS 1666 D
Model No Audi A6 C7 3.0T FSI QU

Quantity	Description	Unit Price	Amount
Parts 1 2	Fog light back cover - RHS Radiator grille cover	\$ 42.00 \$ 31.00	un =
		\$ 73.00	
	TOTAL	\$ 73.00	

For Premium Automobiles Pte Ltd

Adrian Lis Sefs.

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

:

Surveyed Date

**

Authorised Date

*

Excess Cost Liability

2

Remarks

- 2

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SJS 1666 D Norah Khai 6768 9911 6841 1183

Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/1108/2017/MAS

29 Jan 2018

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref Your Ref Date

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SJS 1666 D, Audi A6 C7 3.0T FSI QU

With reference to the above-mentioned vehicle, no SJS 1666 D, claimant, Lakeview Investments Pte Ltd, please find the related document per attached.

- A copy of the Original invoice no. 85012085 S\$12,322.98
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SJS 1666 D

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj F	Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	10 Nov 2017 09:57		09 Nov 2017 16:52 Edit Adj Rpt	S\$12,9 Edit Esti		5\$12,916.80 View Rpt		Pending for Survey Report Cancel Case	
	Main	Refer	ence	Cla	im Detai	is]	Documents	Show All	
CLAIM S	UBFOLDER DET	AILS					[Created by i	nsurer]	
Insured:		LAKEVIEW IN	VESTMENTS PT	ELTD, C	o. Reg. N	o.: 200701891C			
Vehicle F	Reg. No.:	SJS1666D		D	ate of Lo	55:	03/11/2017 22	:00 - :59	
Claim Ty		OD / 07307	7114SG	Policy/Cover		over Note No.: 2100278565		05000 (Comprehensive)	
		1.55.4.50.50.00		E	Excess:		S\$1,400.00		
Repairer	1	Premium Aut	omobiles Pte Lt	d (UBI) 5	5 Ubi Roa	d 1, 408699 Ubi	Tel: 67689828/	9827/9911	
Handling	Insurer:	Norsazani] No	rsazani.Zawaye@	Daig.com			. [Handled by Mo		
Adjuster	1	20/11/2017		d (HQ) - T	el: 6256-	3561 [Handled	by ADRIAN LIN	IG] [Final Rpt due	
Driver/C	Custodian:	DAI XIN (36 /	Male), NRIC: G	6270011X,	, Tel: +	6596527776			
ASSOCI	ATED MAIL REC	EIVED					View All	Compose Case Mail	
AIG_S	G (14/11/2017): G (10/11/2017): SOCIATED TASK	Alert - Adj Mand SJS1666D / OD	late Approved (/ 03/11/2017	S\$15414. / Coverag	ge & Exco	51666D - Claim ess update	· 00,000000		
Due Da	ste Priority		oup Subject	Handle			mpleted On	Created On Done?	

Claim Documents

*SJS1666D (0730717114SG) OD Nov 3 2017 10:30PM [LAKEVIEW INVESTMENTS PTE LTD] Premium Automobiles Pte Ltd

_	Upload Documents				1 per	nage 🔻	V
	essment Reports		Dt- 134 (UO)		1 per p	Thumbnail	Print
No	Finalized On 14/11/17 15:06	Adjuster Immediate A	A SA A S		0	Load HTM	
1	14/11/17 13.00	Aujuster zimilediate A					
ho	tos/Images				3 per j	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants	Pte Ltd (HQ)			Thumbnail	Print
1	14/11/17 14:59	General View			0	Load JPG	7
2	14/11/17 14:59	Chassis Number			0	Load JPG	1
3	14/11/17 14:59	General View			0	Load JPG	V
4	14/11/17 14:59	General View			0	Load JPG	1
5	14/11/17 14:59	General View			0	Load JPG	1
6	14/11/17 14:59	General View			0	Load JPG	7
7	14/11/17 14:59	General View			0	Load JPG	V
8	14/11/17 14:59	General View			0	Load JPG	1
9	14/11/17 14:59	General View			0	Load JPG	V
10	14/11/17 14:59	General View			0	Load JPG	V
11	14/11/17 14:59	General View			0	Load JPG	V
12	14/11/17 14:59	General View			0	Load JPG	V
13	14/11/17 14:59	General View			0	Load JPG	V
14	14/11/17 14:59	General View			0	Load JPG	V
	14/11/17 14:59	General View			0	Load JPG	V
15		General View			0	Load JPG	7
16	14/11/17 14:59	General View			0	Load JPG	V
17	14/11/17 14:59				0	Load JPG	V
18	14/11/17 14:59	General View			0	Load JPG	V
19	2 Chiefen Chambrid 19 South	General View			0	Load JPG	7
20	y the second visits and are	General View			0	Load JPG	V
21		General View			0	Load JPG	7
22		General View			0		7
23	14/11/17 14:59	Reinspection Photo			-	Load JPG	
24	14/11/17 14:59	Reinspection Photo			0	Load JPG	V
25	14/11/17 14:59	Reinspection Photo			0	Load JPG	7
26	14/11/17 14:59	Reinspection Photo			0	Load JPG	0
27	14/11/17 14:59	Reinspection Photo			0	Load JPG	7
28	14/11/17 14:59	Reinspection Photo			0	Load JPG	V
29	14/11/17 14:59	Reinspection Photo			0	Load JPG	1
30	14/11/17 14:59	Reinspection Photo			0	Load JPG	V
31	14/11/17 14:59	Reinspection Photo			0	Load JPG	V
32	14/11/17 14:59	Reinspection Photo			0	Load JPG	7
33	14/11/17 14:59	Reinspection Photo			0	Load JPG	V
34		Reinspection Photo			0	Load JPG	V
35		Reinspection Photo			0	Load JPG	V
36		Reinspection Photo			0	Load JPG	V
37		Reinspection Photo			0	Load JPG	V

38	14/11/17 14:59	Reinspection Photo	6	Load JPG	1
39	14/11/17 14:59	Reinspection Photo	0	Load JPG	J
40	14/11/17 14:59	Reinspection Photo	0	Load JPG	V
41	14/11/17 14:59	Reinspection Photo	0	Load JPG	7
42	14/11/17 14:59	Reinspection Photo	0	Load JPG	7
43	14/11/17 14:59	Reinspection Photo	0	Load JPG	7
Dor	umentation		1 per	page 🔻	J
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/11/17 09:52	Singapore Accident Statement	0	Load PDF	
2	10/11/17 09:52	Certificate of Insurance	0	Load PDF	
3	10/11/17 09:52	Drivers Driving License	0	Load PDF	
4	10/11/17 09:52	AIG INTERVIEW FORM	0	Load PDF	
5	10/11/17 09:52	AIG UNDERTAKING FORM	0	Load PDF	
6	10/11/17 09:52	WORKSHOP ESTIMATE	0	Load PDF	
7	14/11/17 14:58	LATEST WORKSHOP ESTIMATE	0	Load PDF	
8	14/11/17 14:58	SUPPLEMENTARY LIST	0	Load PDF	
9	05/02/18 11:30	WORKSHOP INVOICE	0	Load PDF	
10	05/02/18 11:30	DISCHARGE VOUCHER	0	Load PDF	
	The state of the s	The state of the s	0	Load PDF	

Linked Accident Report Documents

			v	iew Use Viewe	
Ass	essment Report	s	1 per	page 🔻	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	07/11/17 18:54	Accident Statement	0	Load HTM	
Pho	Photos/Images		3 per	page 🔻	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	07/11/17 18:30	Accident Photo	0	Load JPG	V
2	07/11/17 18:30	Accident Photo	0	Load JPG	J
3	07/11/17 18:30	Accident Photo	0	Load JPG	V
4	07/11/17 18:30	Accident Photo	0	Load JPG	V
5	07/11/17 18:30	Accident Photo	0	Load JPG	V
6	07/11/17 18:30	Accident Photo	0	Load JPG	V
7	07/11/17 18:30	Accident Photo	0	Load JPG	V
8	07/11/17 18:30	Accident Photo	0	Load JPG	V
9	07/11/17 18:30	Accident Photo	0	Load JPG	V
Doc	cumentation		1 per	page 🔻	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	07/11/17 18:18	Sketch Plan	0	Load JPG	V
2	07/11/17 18:18	Sketch Plan #2	0	Load JPG	0

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
	•	
	-	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120

Our File No:

CC3/AIG17021433/AQBN2

Date:

05/02/2018

REFERENCE

Date of Loss:

Insured/Claimant: LTD

LAKEVIEW INVESTMENTS PTE

Policy No:

2100278565-

05000 OD

Nature of Claim:

Claim No:

Chassis No: WAUZZZ4G4CN053720

57486 km

Engine No: CGW024305

0730717114SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

03/11/2017

Reg No:

SJS1666D

Make & Model: Reg. Date:

AUDI A6, 3.0 TFSI quattro S-Line (C7) (A)

18/11/2011 (Man. Year: 2011)

Colour:

2995 cc

Market Value/New Car Price:

S\$100,000.00 Market Value/New Car Price

Sum Insured (S\$):

Engine Capacity:

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Front Right Side:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Odometer:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

Rear Tyre Size: 255/35 R20 Pirelli 6 mm Pirelli 6 mm

Rear Left Side: Rear Right Side: 255/35 R20 Pirelli 6 mm

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,137.00	10,944.80	13,192.20	54.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,672.00	1,972.00	1,700.00	46.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00 0.00	0.00		
Calculated Gross Total (S\$)	27,809.00	12,916.80	14,892.20	53.55
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	26,409.00	11,516.80	14,892.20	56.39
+ GST 7.00/7.00% (S\$)	1,848.63	806.18	1,042.45	56.39
Nett Amount (S\$)	28.257.63	12,322.98	15,934.65	56.39

INSPECTION

Date of Assignment:

09/11/2017

Date Inspected:

09/11/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

	City Faith	lo. Particulars	Condition	Repairer's	Amount
	1	*FRONT BUMPER	Deformed	2,513.00 FS	*2,010.40FS
	1	*FRONT RADIATOR GRILLE	Cracked	1,134.00 FS	*907.20 FS
	2	*FRONT BUMPER AIR GRILLE-LH/RH *FRONT BUMPER AIR GRILLE COVER-RH	Not Necessary Necessary	474.00 FS 42.00 FS	*- FS *33.44 FS
5	1 2	*FRONT BUMPER LOWER CENTER GRILLE *FRONT BUMPER SUPPORT	Cracked Not Necessary	106.00 FS 20.00 FS	*84.40 FS *- FS
	2	*FRONT BUMPER GUIDE PIECE-LH/RH	Not Necessary	62.00 FS	*- FS
3	1	*FRONT BUMPER TOP COVER	Cracked	100.00 FS	*79.60 FS
)	1	*CAUTION STICKER	Necessary	12.00 FS	*9.04 FS
0	1	*FRONT BUMPER FOAM	Cracked	193.00 FS	*154.00 FS
11	1	*FRONT HEADLIGHT-LH/RH *FRONT HEADLIGHT MOUNTION-LH/RH	N/s Cracked N/s Cracked	18,908.00 FS 200.00 FS	*7,563.20 FS
13	1	*SUNDRIES	Necessary	300.00 FS	*24.08 FS
14	1	*FOG LIGHT BACK COVER-RHS	Not Necessary	42.00 FS	*- FS
15	1	*RADIATOR GRILLE COVER	Not Necessary	31.00 FS	*- F8
=Frai	nchise part. S=	SpcNett.	Total Parts (S\$)	24,137.00	10,944.80

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		Section 4.	
1	TO REMOVE AND TRANSFER FRONT WIRE HARDN FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AS AND FRONT PARKING AID		480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH FRONT HEADLIGHTS.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL PARTS REMOVED		2,100.00	750.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		3,672.00	1,972.00
	Report was unsubmitte	d during this print-out.		

< END OF ESTIMATES >