

ASS. REQ BY

REF CS3/MSG17021439/WB22

range

Supplier

ASSIGNMENT (Office)

From (Person)

Katherine Wong

MSIG

Date/Time

9/11/17 @ 3:01pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLH 6424L

Insured

SKT 9633D

at Workshop m/z

Lush Automotive

Tel

8777 2345

of No. 8 Kaki Bkt Ave 4 # 03-47 Premier

Policy No 28855403 QMY

Claim No

536076

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

7/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

10/11/17 @ After 2pm

H.O.D. Endorsement

Date/Time

3:17pm @ 9/11/17

Person Contacted

Rizal

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLH 6424L - X

SKT 9633D - X

Dismantle Part: 13.11.2017

After repair: 20.11.2017

281177 7:17pm Email to Katherine Wong thru Merimen.



## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**(2) System - (Views/Merimen)**

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

**(3) Workshop Estimate/Assignment Form**

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


**(4) System - (Views/Merimen)**

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17021439/Wb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 09-11-2017



Code : MSG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKT 9633D	Veh. Inspected	SLH 6424L
Policy No.	28855403QMY	Coverage (\$)	0.00
Claim No.	536076	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	09/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	07/11/2017	Inspection Date	10/11/2017
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Nov 2017		09 Nov 2017 15:01 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Chen Dazhi, ID: S8200739C		
Main Claimant:	Li Qingqing, ID: S7969703F		
Vehicle Reg. No.:	SLH6424L	Date of Loss:	07/11/2017 23:00 - :59
Claim Type:	TP / 536076	Policy/Cover Note No.:	28855403QMY Coverage: 21/11/2016 - 20/11/2017
Vehicle Reg. No. (Insured):	SKT9633D	Policy No. (Claimant):	
		Excess:	
Repairer:	LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4,, #03-47 Premier@Kaki Bukit,, 415875 Kaki Bukit - Tel: 86662345		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/11/2017]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2017 17:20
Date Of Accident	07/11/2017 23:45
Exact Location Of Accident	PRINSEP STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH6424L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LI QINGQING
NRIC No	S7969703F
Email Address	QINGQING100528@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91705072
Alternative Phone No	OTHERS-91705072

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 1.5X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC16A00462200
Cover Note Number	

### Driver

Name of Driver	LI QINGQING
NRIC No	S7969703F
Date Of Birth	30/07/1979
Occupation	INDOOR
Date Of Driving Pass	12/12/2001
Driving Experience	15 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91705072
Fax Number	
Contact Number	OTHERS-91705072
EMail Address	QINGQING100528@GMAIL.COM

Address	BLK 242 KIM KEAT LINK #03-167
Postcode	310242
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT9633D
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	CHEN DAZHI
NRIC/Passport Number	S8200739C
Contact Number	97301972
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 8/11/17  
16:38

Driver's Signature

(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature

Name: ELAINE SOON  
NRIC/FIN No.: 88029144B



# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened on 07/11/2017 @ 2346HRS at Junction of Prinsep Street and Prinsep link.

I'm driving a HONDA VEZEL, color: CHAMPAGNE GOLD bearing veh no: SLH6424L and while I was making a left turn into Prinsep link from Prinsep street a car (Black Honda Civic) veh no: SKT9633D which was stationary at left side road (zig-zag line) suddenly move out hitting my rear left door and dented it.

No bodily injuries onto the other party driver and myself at the time of accident.

I have a video recorder on my vehicle and have an eye-witness on the accident.

My Eye witness detail as follow:-

MR WEE KENG JUAN.

TEL NO: 97310027.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 8/11/17

1650

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## View Sent Message

This mail is associated with :

**\*SLH6424L (536076)**  
**[SKT9633D]**

TP  
Li Qingqing  
Nov 7 2017 11:00PM  
[Chen Dazhi]  
LUSH AUTOMOTIVE PTE LTD

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 28/11/2017 19:19 PM.  
**To** MSI\_WCS  
**Subject** Pre-repair Inspection

Dear Katherine,

Refer to your assignment on 09.11.2017 at 3.01PM.

Please be informed that we have inspected the vehicle SLH 6424L on 10.11.2017 at 2.46PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Nov 2017		09 Nov 2017 15:01 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Chen Dazhi, ID: S8200739C		
Main Claimant:	Li Qingqing, ID: S7969703F		
Vehicle Reg. No.:	SLH6424L	Date of Loss:	07/11/2017 23:00 - :59
Claim Type:	TP / 536076	Policy/Cover Note No.:	28855403QMY Coverage: 21/11/2016 - 20/11/2017
Vehicle Reg. No. (Insured):	SKT9633D	Policy No. (Claimant):	
		Excess:	
Repairer:	LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4,, #03-47 Premier@Kaki Bukit,, 415875 Kaki Bukit - Tel: 86662345		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 10/11/2017]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date   Priority   Type   Task Group   Subject   Handler   Assigned By   Completed On   Created On   Done?

No results.

## Claim Documents

\*SLH6424L (536076)  
[SKT9633D]  
TP  
Li Qingqing  
Nov 7 2017 11:00PM  
[Chen Dazhi]  
LUSH AUTOMOTIVE PTE LTD

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/11/17 09:23	<b>Video - Accident (Front) - TP</b> From:SC - Reg. No: SKT9633D, Claimant: CHEN DAZHI	Load MOV	
2	10/11/17 09:23	<b>Video - Accident (Back)- TP</b> From:SC - Reg. No: SKT9633D, Claimant: CHEN DAZHI	Load MOV	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/18 16:37	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
2	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	09/03/18 16:37	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
4	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	09/03/18 16:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	09/03/18 16:37	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
23	09/03/18 16:37	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
24	09/03/18 16:37	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
25	09/03/18 16:37	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
26	09/03/18 16:37	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
27	09/03/18 16:37	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
28	09/03/18 16:37	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>

29	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
30	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
31	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
32	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
33	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
34	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
35	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
36	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
37	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
38	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
39	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
40	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
41	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
42	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
43	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
44	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
45	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
46	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
47	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
48	09/03/18 16:37	Photographs of Damaged Parts	1	Load JPG	✓
49	09/03/18 16:38	Photo After Spray	1	Load JPG	✓
50	09/03/18 16:38	Photo After Spray	1	Load JPG	✓
51	09/03/18 16:38	Photo After Spray	1	Load JPG	✓
52	09/03/18 16:38	Photo After Spray	1	Load JPG	✓
53	09/03/18 16:38	Photo After Spray	1	Load JPG	✓
54	09/03/18 16:38	Photo After Spray	1	Load JPG	✓
55	09/03/18 16:38	Photo After Spray	1	Load JPG	✓
<b>Documentation</b>				1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/11/17 15:01	TP disagree on SJE & workshop details	1	Load PDF	
2	10/11/17 09:23	SLH6424L E FILE REPORT. From:SC - Reg. No: SKT9633D, Claimant: CHEN DAZHI	1	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021439/WBS2  
 Date: 12/03/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28855403QMY  
 Claimant Vehicle No: SLH6424L Insured Vehicle No: SKT9633D  
 Date of Loss: 07/11/2017 Nature of Claim: TP Claim No: 536076

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLH6424L Engine No: L15B4405693  
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Chassis No: RU11205693  
 Reg. Date: 14/11/2016 (Man. Year: 2016) Odometer: 5982 km  
 Colour: Brown  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm  
 Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 09/11/2017  
 Date Inspected: 10/11/2017 Inspected At: LUSH AUTOMOTIVE PTE LTD (HQ)  
 No. 8 Kaki Bukit Avenue 4, #03-47 Premier@Kaki  
 Bukit,  
 Singapore 415875  
 Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



3/12/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLH6424L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >