

Surveyor  
Mullmen

REF: CS3 / MSG17021468 / Wvbe2

Special Instruction:  
US: \$ 6802.00

From (Person): TeLaine Ngu of MSCG Date/Time: 27-11-2017  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

ASSIGNMENT (Office)


Third Parties:  
Claimant:  
Surveyor: HJL Auto  
Workshop: Auto Best Motor

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: 6X 3699E Insured: YK 4020L  
at Workshop m/s Auto Best Motor Tel: 6745 8932  
of Blk 3006 Ubi Rd 1 #01-362  
Policy No: 77086168TMV Claim No: 536136  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
Make of Veh: \_\_\_\_\_ D.O.A. 08-11-2017  
(Client's Record)

DO Not Finalize  
H.O.D. Endorsement/Date: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT  
Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 9 days)  
Date/Time: 15/1/18 Submit Final Fig LS 4150, 6 days (Red \$ 2650 / 39 %; Original 9 days)

Date/Time	Action/Instruction
	6X 3699E - NA / ENCL11015627 / ji
	YK 4020L - X
	W. / son
	PIS 200 my remarks
	
	11/1/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 15 JAN 2018

Para(3) : Nett Value

Not: Market Value : 9500 (EST)  
LTA Salvage Value : 6520  
Nett Value : 2980

Inspected/  
Evaluated by:

Fee Charged:	Date:
Basic & Add	
Transport	
Photos	
Others	
Total	

- 1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_
- 2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_
- 4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_
- 6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

PRS & PS

23/05/2017

ASS. REC. REF:

REF: C83/MSG17021468/Wb

Special Instruction:

Surveyor: Wilson

ASSIGNMENT (Office)

Menmen

From (Person): Elaine Ngu

of MSIG

Date/Time: 9/11/17 @ 5:27pm

Estimated Cost:

Bill no:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GX 3699E

Insured: YK4020L

at Workshop m/s Auto Best Motor Services

Tel: 67456932

of Blk 3006 Ubi Rd 1 # 01-362, 408700

Policy No: 27086168 TMV

Claim No: 536136

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 8/11/17

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement:

Date/Time: 10/11/17 @ 9:09am

Person Contacted:

Mr. Lee

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>GX 3699E - NA / INC 110 / SC 07 / 1 - D.O.A. : 4/08/2011</u>
	<u>YK 4020L - X</u>
	<u>Dismantle Part : 13.11.2017</u>
	<u>After repair : 16.11.2017</u>



## Survey Department Check List (Case Handler)

Reference No. : CS3 / MSG No 21468 / Wvd  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** \_\_\_\_\_ **)**: Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** \_\_\_\_\_ **)**: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded				

Check By: VERON 15/1/18  
 Case Handler Date



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17021468/Wvb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 10-11-2017



Code : MSG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YK 4020L	Veh. Inspected	GX 3699E
Policy No.	27086168TMV	Coverage (\$)	0.00
Claim No.	536136	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	10/11/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	08/11/2017	Inspection Date	10/11/2017
Survey held at	AUTO BEST MOTOR SERVICES BLK 3006 UBI ROAD 1 #01-362 SINGAPORE 408700		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Paper Survey

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Nov 2017		09 Nov 2017 17:27 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]																					
<b>Insured:</b>	ALSTERN TECHNOLOGIES SINGAPORE PTE LTD, Co. Reg. No.: 200406842Z																						
<b>Main Claimant:</b>	ACCLAIM SYSTEMS PTE LTD, Co. Reg. No.: 199202237G																						
<b>Vehicle Reg. No.:</b>	GX3699E	<b>Date of Loss:</b>	08/11/2017 20:00 - :59																				
<b>Claim Type:</b>	TP / 536136	<b>Policy/Cover Note No.:</b>	27086168TMV (Third Party Only) Coverage: 06/05/2017 - 05/05/2018																				
<b>Vehicle Reg. No. (Insured):</b>	YK4020L	<b>Policy No. (Claimant):</b>																					
<b>Repairer:</b>	Auto Best Motor Services (HQ) BLK 3006 UBI ROAD 1, #01-362, 408700 Ubi - Tel:																						
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Slau Mei - 6594 2540]																						
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 10/11/2017]																						
<b>Adj Asg. Remarks:</b>	Please contact and liaise with the workshop directly to arrange for the pre-repair survey of our client's damaged vehicle and obtain the requisite documents from them. Workshop Auto Best Motor Services Address Blk 3006 Ubi Road 1 #01-362 Singapore 408700 Contact Person Mr Lee Tel No. 67456932																						
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>																				
There are no mail for this case.																							
<b>ALL ASSOCIATED TASKS</b>																							
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>				Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?														
No results.																							

D.O.A → 8/11/2017

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>				
Owner ID Type:	Company	14	04 <sup>12</sup>	2018 <sup>8</sup>
Owner ID:	2237G	08	11	2017
<b>Vehicle Details</b>				
Vehicle No.:	GX3699E	06	05	1
Vehicle to be Exported:	Yes	(Bal → 0.2 month)		
Intended De-registration Date:	15 Jan 2018			
Vehicle Make:	TOYOTA	Bal → 1 yr 5.2 month		
Vehicle Model:	LITEACE 5DR	→ 17.2 month		
Primary Colour:	White			
Manufacturing Year:	2004	* Average Depreciation		
Engine No.:	3C3988613	→ \$7000 / yrs		
Chassis No.:	CR425008375	→ \$583 / month		
Maximum Power Output:	-			
Open Market Value:	\$18,689.00	→ 17.2 month x \$583 / month		
Original Registration Date:	16 Apr 2004			
First Registration Date:	16 Apr 2004	→ \$10,027 / =		
Transfer Count:	1			
Actual ARF Paid:	\$935.00			
<b>Intended PARF Rebate Details</b>				
PARF Eligibility:	No			
PARF Eligibility Expiry Date:	-			
PARF Rebate Amount:	\$0.00			
<b>Intended COE Rebate Details</b>				
COE Expiry Date:	15 Apr 2019			
COE Category:	C - Goods Vehicle & Bus			
COE Period(Years):	5			
PQP Paid:	\$26,082.00			
COE Rebate Amount:	\$6,520.00			
<b>Total Rebate Amount:</b>	<b>\$6,520.00</b>			

Message  
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 15 Jan 2018

\* M.V → OK → \$9500

## Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

**New 5 Year Coe Renewal Honda Stream 1.8A RSZ**



\$2800 Downpayment Monthly  
From \$738 Onwards. Lowest  
3.68%PA@GV Cars Financing.  
GV Credit Pte Ltd StarAd

**Lake View Credit Pte Ltd** [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Sort by Date Posted 40 results/page

5 vehicles

toyota liteace

Basic Search Submit

Price Any price Depre Any depre  
 Fuel Any fuel Mileage Any  
 Category All categories Scheme All schemes  
 Reg Date 2014 to 2018 Eng Cap Any Veh Type All types  
 OMV Any Gear Any Gear Past Owners Any  
 Dealer Any Dealer Location Any Status Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

**Toyota Liteace GL**  
**Fuel Type:** Petrol  
 Low Fuel Consumption And Hassle Free Japanese Petrol Commercial Van. Most Convenient Compact Van And Low Maintenance. Price Is GST Inclusive.  
 Think One Automobile & Trading  
 Posted: 15-Jan-2018 Tags: Toyota Townace, 2017 Toyota Liteace, Toyota Liteace, Toyota, Liteace, Used Toyota

**Toyota Liteace**  
**Fuel Type:** Petrol  
 One Of The Most Reliable Japanese Compact Van In The Market! Low Fuel Consumption And Low Maintenance! Hassle Free Experience For Your Everyday Drive! Loan And Trade In Available. Call Now To Enquire ...  
 Net Link Partners Pte Ltd  
 Posted: 02-Jan-2018 Tags: Toyota Townace, 2017 Toyota Liteace, Toyota Liteace, Toyota, Liteace, Used Toyota

**Toyota Liteace**  
**Fuel Type:** Petrol  
 One Of The Most Reliable Japanese Compact Van In The Market! Low Fuel Consumption And Low Maintenance! Hassle Free Experience For Your Everyday Drive! Loan And Trade In Available. Call Now To Enquire ...  
 Net Link Partners Pte Ltd  
 Posted: 29-Dec-2017 Tags: Toyota Townace, 2017 Toyota Liteace, Toyota Liteace, Toyota, Liteace, Used Toyota

**Toyota Liteace GL**  
**Fuel Type:** Petrol  
 Selling On Behalf Of Private Owner, Please Call To Arrange Before Viewing!  
 Posted: 15-Dec-2017 Tags: Toyota Townace, 2017 Toyota Liteace, Toyota Liteace, Toyota, Liteace, Used Toyota

Car Buying Car Selling Car Aftermarket  
 Car Ownership On The Move Lifestyle

12233E **Ballfed Capplates For Sale!**

**Toyota Liteace GL**  
**Fuel Type:** Petrol  
 Low Fuel Consumption And Hassle Free Japanese Petrol Commercial Van. Most Convenient Compact Van And Low Maintenance.  
 Think One Automobile & Trading  
 Posted: 20-Nov-2017 Tags: Toyota Townace, 2017 Toyota Liteace, Toyota Liteace, Toyota, Liteace, Used Toyota

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

40 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota liteace, toyota liteace Singapore, used toyota liteace Singapore, used vehicles Singapore or even buy used toyota liteace Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance

	<b>Toyota Liteace (COE till 11/2018)</b> Fuel Type: Diesel In House Loan Available, Can Use For Early Turnover Scheme. Well Kept.	\$11,800	\$14,080 /yr	18-Nov-2003	2,184 cc	-	Van	Available
	<b>Toyota Liteace (New 5-yr COE)</b> Fuel Type: Diesel 3 Careful Owners. New Paintwork. Regular Servicing.	\$28,800	\$5,760 /yr	29-Nov-2003	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 01/2019)</b> Fuel Type: Diesel The Most Reliable Van In Town, Original Condition, Regular Serviced And Maintained, Price Negotiable For Sincere Buyer, View By Appointment Only.	\$10,500	\$10,740 /yr	06-Jan-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 02/2019)</b> Fuel Type: Diesel Reliable Compact Van! High Loan! Low Interest! Superb Engine And Gearbox Condition! Price Negotiable! COE Rise, But Our Price Remain! Fast, Hassle Free And Easy Approve Loan! Call Our Team Of Special...	\$18,800	\$15,030 /yr	26-Feb-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 03/2019)</b> Fuel Type: Diesel Cheapest In The Market. Engine And Gearbox In Wonderful Condition. Most Reliable Model In The Market. Loan And Trade In Are Most Welcome. Sell As Per Condition. Call Us Now To Arrange For Viewing.	\$10,800	\$9,080 /yr	26-Mar-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 04/2019)</b> Fuel Type: Diesel Engine Gearbox Condition Top! Nice And Clean Interior! ETS Available! Low Mileage! New Fan Belt And Clutch Pack. See To Believe! Call Us Now To Arrange Door Step View!	\$13,800	\$10,760 /yr	29-Apr-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 07/2019)</b> Fuel Type: Diesel Full Glass Panel. Excellent Condition. Toyota Liteace, 5 Doors Van, Excellent And Clean Condition, High Loan, Low Down Payment Available. Trade In Available, Call Now For Viewing Appointment! Hurry Ca...	\$14,999	\$9,940 /yr	21-Jul-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 07/2024)</b> Fuel Type: Diesel Well Maintained In Good Condition. Original Paintwork And Stock Condition. Price Is Negotiable. View To Appreciate	\$40,000	\$6,130 /yr	23-Jul-2004	2,184 cc	120,000 km	Van	Available
	<b>Toyota Liteace (COE till 08/2019)</b> Fuel Type: Diesel Auto Diesel Liteace! 1 Month Warranty! Engine And Gearbox In Excellent Condition. Low Fuel Consumption, Best For Businesses Doing Delivery Or Even Own Personal Usage. Do Not Miss Out This Loan And Hi...	\$16,800	\$10,430 /yr	27-Aug-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 07/2019)</b> Fuel Type: Diesel Rare Auto Diesel Transmission. Get Back LTA Rebate Of At Least \$20000. Drive For Free For 18 Mths. Superb Condition, Reliable. Able To Renew 5 More Years. Newly Changed Battery (Since 15 Feb 2017) And...	\$14,800	\$9,610 /yr	27-Aug-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 04/2019)</b> Fuel Type: Diesel Excellent Cond. Glass Panel. Wear And Tear All Replaced. Flexible In House Loan Available. View To Believe.	\$21,800	\$16,930 /yr	30-Sep-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 07/2019)</b> Fuel Type: Diesel Still In Good Condition.	\$14,800	\$9,610 /yr	27-Oct-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 12/2019)</b> Fuel Type: Diesel Engine And Gearbox In Excellent Condition. Low Fuel Consumption, Best For Businesses Doing Delivery Or Even Own Personal Usage. Do Not Miss Out This Loan And High Trade In Available. Hurry Before Its...	\$15,800	\$9,410 /yr	03-Dec-2004	2,184 cc	-	Van	Available
	<b>Toyota Liteace (COE till 07/2019)</b> Fuel Type: Diesel Toyota Liteace, 5 Doors Van, Excellent And Clean Condition, No Repair Needed, High Loan And Trade In Available, Call Now For Viewing Appointment!	\$21,800	\$14,160 /yr	17-Jan-2005	2,184 cc	-	Van	Available

**SINGAPORE ACCIDENT STATEMENT**

*Handwritten signature*

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 09/11/2017 10:18  
Date Of Accident 08/11/2017 20:00  
Exact Location Of Accident KAKI BUKIT AVE 3 / KAKI BUKIT RECREATION CENTRE  
Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number GX3699E  
**Insured/Policyholder**  
Name Of Registered Owner ACCLAIM SYSTEMS PTE LTD  
Co Reg No 199202237G  
Email Address NOEMAIL  
Mobile Phone No  
Alternative Phone No OFFICE-62990798  
**Vehicle Particulars**  
Manufacturer TOYOTA  
Model LITEACE 5DR  
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSES  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category COMMERCIAL VEHICLE  
**Insurance Company**  
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 5062163996-04  
Cover Note Number  
**Driver**  
Name of Driver RAJENDRAN RAJARAMAN  
Passport No/FIN G2274767W  
Date Of Birth 03/05/1991  
Occupation OUTDOOR  
Date Of Driving Pass 07/08/2014  
Driving Experience 3 YEARS AND 3 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-96640853  
Fax Number  
Contact Number  
EEmail Address NOEMAIL

Address 171 KAKI BUKIT AVENUE 1 SHUN LI INDUSTRIAL PARK  
 Postcode 416020  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS TRAVELLING STRAIGHT ON A SINGLE LANE ROAD, ALONG KAKI BUKIT AVENUE 3. AS I WAS DRIVING PASS KAKI BUKIT RECREATION CENTRE OPEN-SPACED CARPARK, SUDDENLY I FELT AN IMPACT FROM THE LEFT. VEHICLE B BEARING REGN NO. YK4020L FAILED TO STOP AT THE STOP-LINE AND HIT ONTO THE LEFT PORTION OF MY VEHICLE. THAT'S ALL.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number YK4020L  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver LAKSHMANAN RAMARAJAN  
 NRIC/Passport Number 034547211  
 Contact Number 97190591  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver) 1

**Details of Witness**

Name  
 Phone Number  
 Email Address

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



JOO HAK KEE AUTO PTE LTD  
Blk 3007 Ubi Road 1 #01-406  
Singapore 408701  
Blk 3014 Ubi Road 1 #01-324  
Singapore 408702


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

A = GTX3649E  
B = YK4020L




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to statement*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

JOO HAK KEI AUTO PTE LTD  
 Blk 3007 Ubi Road 1 #01-406  
 Singapore 408701  
 Blk 3014 Ubi Road 1 #01-324  
 Singapore 408702  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

# HJL AUTO APPRAISER SERVICES

Business Registration No. 53065865L  
Postal Address: 120 Ang Mo Kio Avenue 3 #04-1833 Singapore 560120  
Tel / Fax: 6618 2621 Handphone: 9855 0756  
Email Address: hjlautoappraiser@hotmail.com

## AUTOMOBILE INSPECTION REPORT

M/s ACCLAIM SYSTEMS PTE LTD C/o BLK 3006 UBI ROAD 1 #01-362 SINGAPORE 408700	Our Reference : TP/AB/T1711169/GX3699E Date : 12 November 2017
---	---

### REFERENCE PARTICULARS

Vehicle No.	: GX3699E	Policy No.	: N.A
Type of Claim	: Third Party	Claim No.	: Not Advised
Date of Accident	: 08-11-2017	Sum Insured	: N.A
Date of Assignment	: 09-11-2017	Excess	: N.A
Date of Inspection	: 09-11-2017	Assigned By	: Owner
Date of Re-Inspection	: 11-11-2017		

Name of Workshop : AUTO BEST MOTOR SERVICES

### PARTICULARS OF DAMAGED VEHICLE

Registration No.	: GX3699E	Engine No.	: Concealed
Make / Model	: Toyota Liteace	Chassis No.	: CR42-5008375
Year of Registration	: 2004	Engine Capacity	: 2184
Colour	: Grey/Red	Odometer Reading	: 337148


### CONDITION OF TYRES

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Nearside	: Journey	165R13	8mm
Front Offside	: Journey	165R13	13mm
Rear Nearside	: Condor	165R13	6mm
Rear Offside	: Bridgestone	165R13	2mm

### PRE-ACCIDENT CONDITION (STATIC CHECK ONLY)

General Condition	: Good	Footbrake	: Serviceable
Paintwork	: Good	Handbrake	: Serviceable
Modification to Engine	: No	Steering	: Serviceable

### POINT OF IMPACT



The vehicle sustained damages at the nearside portion.  
For details, refer to schedule and photographs attached.

### REMARKS

Under normal circumstances, the estimated repair working day(s) required is Nine ( 9 ) days.

Please note that the survey was conducted strictly on a **Without Prejudice Basis** and we Have Not authorise the repairs.

# HJL AUTO APPRAISER SERVICES

Business Registration No. 53065865L

Postal Address: 120 Ang Mo Kio Avenue 3 #04-1833 Singapore 560120

Tel / Fax: 6618 2621 Handphone: 9855 0756

Email Address: hjlautoappraiser@hotmail.com

Our Reference No. : TP/AB/T1711169/GX3699E  
Vehicle No. : GX3699E

## GENERAL REMARKS

The survey was conducted at Blk 3006 Ubi Road 1, #01-362, Singapore 408700.

We have thoroughly inspected the damaged vehicle and examined each and every part(s) listed in the repairer's estimate against the damages found on the vehicle. We have list the breakdown, findings and our recommendation as per schedule attached.

Generally, the vehicle sustained impact at the nearside portion and the damages appeared to be consistent as per the accident report form. Please see the attached schedule and photographs for details.

### Assessment / Recommendation

The repairer has submitted a repair estimate of S\$11,741.50. Our assessment for a reasonable repair cost is at S\$8,515.00.

However, taking into consideration the availability of OEM and/or second hand parts and to economise repairs, ~~we would recommend the repairs to be carried out on a Lump Sum Basis.~~

### Conclusion

The repairer has agreed to undertake the repairs at a Lump Sum Basis of S\$6,800.00 Nett (subject to GST if applicable).

We hereby revert the matter to you for your decision.

Assuring you of our best services always.

Yours faithfully,



---

Danny Ho - MSAE, MSAAA, AMIMI

# HJL AUTO APPRAISER SERVICES

Business Registration No. 53065865L

Postal Address: 120 Ang Mo Kio Avenue 3 #04-1833 Singapore 560120

Tel / Fax: 6618 2621 Handphone: 9855 0756

Email Address: hjlautoappraiser@hotmail.com

Our Reference : TP/AB/T1711169/GX3699E

Policy Number : N.A.

Vehicle No : GX3699E

Claim Number : Not Advised

QTY	DESCRIPTIONS	COMMENTS / CONDITIONS	REPAIRER'S ESTIMATE (\$\$)	ADJUSTED AMOUNT (\$\$)
<b>Parts Replacement - List Item(s)</b>				
01 pc	Front fender LH <i>R</i>	To repair	702.00	0.00 <i>X</i>
01 pc	Side view mirror LH <i>✓CRA</i>	Scraped/Cracked	409.00	<del>409.00</del> <i>280</i>
01 pc	Front door glass LH <i>✓SCR</i>	Scraped	495.00	<del>495.00</del> <i>225</i>
01 pc	Front door LH <i>✓DDIBUC</i>	Dented/Buckled	1,087.00	<del>1,087.00</del> <i>897</i>
01 pc	Front door outer handle LH <i>✓CRA</i>	Scraped/Cracked	165.00	165.00 <i>✓</i>
01 pc	Front door lock LH <i>✓JM</i>	Seized/Twisted	391.00	<del>391.00</del> <i>250</i>
01 pc	Front door weatherstrip LH <i>✓NEC</i>	Deformed	256.00	<del>256.00</del> <i>180</i>
01 pc	Front door glass regulator assy LH <i>✓BT</i>	Bent/Twisted	251.00	251.00 <i>✓</i>
01 pc	Center pillar LH <i>R</i>	Dented/Buckled	980.00	<del>980.00</del> <i>X 992</i>
01 pc	Sliding door LH <i>✓DDIBUC</i>	Dented/Buckled	1,450.00	<del>1,450.00</del> <i>992</i>
01 pc	Sliding door outer handle LH <i>✓DDIBUC</i>	Scraped	163.00	<del>163.00</del> <i>✓</i>
01 pc	Sliding door weatherstrip LH <i>✓NEC</i>	Deformed	345.00	<del>345.00</del> <i>290</i>
01 pc	Rear body panel LH <i>✓R</i>	To repair	1,480.00	0.00 <i>X</i>
			<u>8,174.00</u>	<u>5,992.00</u>
		Less 25%	2,043.50	1,498.00 <i>3683</i>
		List Total	6,130.50	4,494.00
<b>Special Nett Item(s)</b>				
01 pc	Front fender company advertisement LH <i>✓NEC</i>	Torn/Necessary	350.00	<del>250.00</del> <i>120</i>
01 pc	Front door company label LH <i>✓NEC</i>	Necessary	25.00	15.00 <i>✓</i>
01 pc	Front door company advertisement LH <i>✓NEC</i>	Scraped/Necessary	750.00	<del>500.00</del> <i>250</i>
01 set	Front door inner trim board clip LH <i>✓NEC</i>	Necessary	38.00	28.00 <i>✓</i>
01 pc	Sliding door company advertisement LH <i>✓NEC</i>	Scraped/Necessary	750.00	<del>500.00</del> <i>200</i>
01 set	Sliding door inner trim board clip LH <i>✓NEC</i>	Necessary	38.00	28.00 <i>✓</i>
01 pc	Rear body panel company advertisement LH <i>✓NEC</i>	Scraped/Necessary	500.00	<del>350.00</del> <i>180</i>
		Parts Total	<u>8,581.50</u>	<u>6,165.00</u> <i>8211</i>
<b>Labour and Miscellaneous</b>				
	To check wiring for proper function. <i>✓</i>		60.00	30.00 <i>✓</i>
	To transfer LH front door components from old to new.		100.00	60.00 <i>✓</i>
	To transfer LH sliding door components from old to new.		100.00	60.00 <i>✓</i>
	To remove & refit LH front seat assy, floor carpet, upholstery, etc to facilitate repairs. <i>XNN</i>		150.00	100.00 <i>X</i>
		Balance C/f	8,991.50	6,415.00

: revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damage(s) should be notified to the company within 7 days of the date hereof. Otherwise the adjusted amount should be deemed as valid.

# HJL AUTO APPRAISER SERVICES

Business Registration No. 53065865L  
 Postal Address: 120 Ang Mo Kio Avenue 3 #04-1833 Singapore 560120  
 Tel / Fax: 6618 2621 Handphone: 9855 0756  
 Email Address: hjlautoappraiser@hotmail.com

Our Reference : TP/AB/T1711169/GX3699E      Policy Number      : N.A.  
 Vehicle No      : GX3699E      Claim Number      : Not Advised

	REPAIRER'S ESTIMATE (\$)	ADJUSTED AMOUNT (\$)	
QTY DESCRIPTIONS	COMMENTS / CONDITIONS		
	8,991.50	6,415.00	
	150.00	<del>100.00</del>	60.
	1,300.00	<del>1,000.00</del>	600.
	1,300.00	<del>1,000.00</del>	✓ 800
<b>Grand Total</b>	<b>11,741.50</b>	<b>8,515.00</b>	<b>1460</b>

**Special Remarks**

The repairer has agreed to undertake the repairs at a Lump Sum Basis of S\$6,800.00, corresponding to labour charges, spray painting and replacement of parts.

Parts (List)	\$ 3683.00
Discount 25%	- \$ 920.75
	\$ 4603.75
Parts (Special Qty)	+ \$ 821.00
	\$ 5424.75
Labour	\$ 1460.00
	\$ 6884.75
Discount 20% (Lump)	- \$ 1376.95
	\$ 5507.80
* Lump Sum → \$ 5500 6 Repair Days.	

revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damage(s) should be notified to the company within 7 days of the date hereof. Otherwise the adjusted amount should be deemed as valid.

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Nov 2017		09 Nov 2017 17:27 <a href="#">Edit Adj Rpt</a>	<b>S\$4,150.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,150.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured: **ALSTERN TECHNOLOGIES SINGAPORE PTE LTD**, Co. Reg. No.: 200406842Z

Main Claimant: **ACCLAIM SYSTEMS PTE LTD**, Co. Reg. No.: 199202237G

Vehicle Reg. No.:	<b>GX3699E</b>	Date of Loss:	08/11/2017 20:00 - :59
Claim Type:	<b>TP / 536136</b>	Policy/Cover Note No.:	27086168TMV (Third Party Only) Coverage: 06/05/2017 - 05/05/2018
Vehicle Reg. No. (Insured):	<b>YK4020L</b>	Policy No. (Claimant):	
		Excess:	

Repairer: **Auto Best Motor Services (HQ)** BLK 3006 UBI ROAD 1, #01-362, 408700 Ubi - Tel:

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Elaine Ngu Siau Mei** - 6594 2540]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **Teo Cheng Ming Wilson**] ...  
[Imm.Advice due 10/11/2017]

Adj Asg. Remarks: Please contact and liaise with the workshop directly to arrange for the pre-repair survey of our client's damaged vehicle and obtain the requisite documents from them. Workshop Auto Best Motor Services Address Blk 3006 Ubi Road 1 #01-362 Singapore 408700 Contact Person Mr Lee Tel No. 67456932

---

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- MSIG\_SG (09/01/2018): Paper survey report

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GX3699E (536136)

[YK4020L]

TP

ACCLAIM SYSTEMS PTE LTD

Nov 8 2017 8:00PM

[ALSTERN TECHNOLOGIES SINGAPORE PTE LTD]

Auto Best Motor Services

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>		
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
2	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
3	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
4	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
27	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
28	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
29	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
30	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
31	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
32	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
33	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
34	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
35	29/11/17 08:17	General View		Load JPG	<input checked="" type="checkbox"/>

36	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
60	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
61	29/11/17 08:17	General View	1	Load JPG	<input checked="" type="checkbox"/>
62	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
63	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
64	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
65	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
66	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
67	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
68	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
69	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
70	29/11/17 08:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
71	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
72	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
73	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
74	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
75	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
76	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
77	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
78	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
79	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
80	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
81	29/11/17 08:22	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
82	29/11/17 08:24	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
83	29/11/17 08:24	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
84	29/11/17 08:24	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
85	29/11/17 08:24	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>

86	29/11/17 08:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
87	29/11/17 08:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	27/11/17 18:22	HJL AUTO APPRAISER SERVICES REPORT - GX3699E.		Load PDF	
2	27/11/17 18:22	HJL AUTO APPRAISER SERVICES REPORT 2 - GX3699E		Load PDF	
3	27/11/17 18:22	HJL AUTO APPRAISER SERVICES PRICE LIST- GX3699E		Load PDF	
4	27/11/17 18:22	THIRD PARTY SURVEY PHOTO - GX3699E.		Load PDF	
5	27/11/17 18:22	THIRD PARTY SURVEY PHOTO 2 - GX3699E		Load PDF	
6	27/11/17 18:22	THIRD PARTY SURVEY PHOTO 3 - GX3699E.		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	15/01/18 13:50	PHOTO		Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p style="text-align: right;">   </p> <p><b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>
---

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CS3/MSG17021468/WBE2

Date: 15/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 27086168TMV
Claimant Vehicle No : GX3699E	Insured Vehicle No : YK4020L
Date of Loss: 08/11/2017	Nature of Claim: TP
	Claim No: 536136

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GX3699E</b>	Engine No:	3C3988613
Make & Model:	TOYOTA LITEACE, 2.2 D CR42 (M)	Chassis No:	CR425008375
Reg. Date:	16/04/2004 (Man. Year: 2004)	Odometer:	337148 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165 R13	Rear Tyre Size:	165 R13
Front Left Side:	Journey 4 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Journey 4 mm	Rear Right Side:	Bridgestone 2 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,581.50	3,583.25	4,998.25	58.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,610.00	1,550.00	49.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,741.50</b>	<b>5,193.25</b>	<b>6,548.25</b>	<b>55.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,741.50</b>	<b>4,150.00</b>	<b>7,591.50</b>	<b>64.66</b>

INSPECTION

Date of Assignment:	09/11/2017		
Date Inspected:	10/11/2017	Inspected At:	Auto Best Motor Services (HQ) BLK 3006 UBI ROAD 1, #01-362 Singapore 408700

Estimated Period of Repair: 6.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

**Part Source:** (Last Synchronised: 15 Jan 2018)  
**Parts:** N/A TOYOTA LITEACE 2.2 D CR42 (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for GX3699E)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER LH	Repair	702.00 FL	*- FL
2	1	*SIDE VIEW MIRROR LH	Cracked	409.00 FL	*280.00 FL
3	1	*FRONT DOOR GLASS LH	Scratched	495.00 FL	*225.00 FL
4	1	*FRONT DOOR LH	Dented / Buckled	1,087.00 FL	*897.00 FL
5	1	*FRONT DOOR OUTER HANDLE LH	Cracked	165.00 FL	*165.00 FL
6	1	*FRONT DOOR LOCK LH	Jammed	391.00 FL	*250.00 FL
7	1	*FRONT DOOR WEATHERSTRIP LH	Necessary	256.00 FL	*180.00 FL
8	1	*FRONT DOOR GLASS REGULATOR ASSY LH	Bent	251.00 FL	*251.00 FL
9	1	*CENTER PILLAR LH	Repair	980.00 FL	*- FL
10	1	*SLIDING DOOR LH	Dented / Buckled	1,450.00 FL	*982.00 FL
11	1	*SLIDING DOOR OUTER HANDLE LH	Dented	163.00 FL	*163.00 FL
12	1	*SLIDING DOOR WEATHERSTRIP LH	Necessary	345.00 FL	*290.00 FL
13	1	*REAR BODY PANEL LH	Repair	1,480.00 FL	*- FL
14	1	*FRONT FENDER COMPANY ADVERTISEMENT LH	Necessary	350.00 FS	*120.00 FS
15	1	*FRONT DOOR COMPANY LABEL LH	Necessary	25.00 FS	*15.00 FS
16	1	*FRONT DOOR COMPANY ADVERTISEMENT LH	Necessary	750.00 FS	*250.00 FS
17	1	*SET FRONT DOOR INNER TRIM BOARD CLIP LH	Necessary	38.00 FS	*28.00 FS
18	1	*SLIDING DOOR COMPANY ADVERTISEMENT LH	Necessary	750.00 FS	*200.00 FS
19	1	*SET SLIDING DOOR INNER TRIM CLIP LH	Necessary	38.00 FS	*28.00 FS
20	1	*REAR BODY PANEL COMPANY ADVERTISEMENT LH	Necessary	500.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,625.00</b>	<b>4,504.00</b>
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,043.50	920.75
<b>Total Parts (\$\$)</b>	<b>8,581.50</b>	<b>3,583.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING FOR PROPER FUNCTION	New	60.00	30.00
2	TO TRANSFER LH FRONT DOOR COMPONENTS FROM OLD TO NEW	New	100.00	60.00
3	TO TRANSFER LH SLIDING DOOR COMPONENTS FROM OLD TO NEW	New	100.00	60.00
4	TO REMOVE & REFIT LH FRONT SEAT ASSY, FLOOR CARPET, UPHOLSTERY, ETC TO FACILITATE REPAIRS	New	150.00	0.00
5	CAVITY PRESERVATION ON ALL AFFECTED AREAS	New	150.00	60.00
6	TO REPLACE, REPAIR, STRAIGHTEN & RE-ALIGN ALL DAMAGED PARTS	New	1,300.00	600.00
7	TO SPRAY PAINT ON ALL AFFECTED AREAS	New	1,300.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>3,160.00</b>	<b>1,610.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >