

20/03/2007

ASS. REQ. BY:

REF: CS3/MSG17021485/Wber

range

Special Instructions:

Survivor:  
Merimen

Wilson

ASSIGNMENT (Office)

From (Person): Irene Tan

of

MSG

Date/Time: 10/11/17 @ 11.55am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 2537A

Insured:

GBBG742T

at Workshop m/s

N-51 Automotive

Tel:

68420051

of BIK 2 Kaki Bukit, # 01-17/18 417921

Policy No:

28707879MKC

Claim No:

536223

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 8/11/2017

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

12.32pm @ 10/11/17

Person Contacted:

Sabrina

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

XD 2537A-X

GBBG742T-CC3/AIG09025145/Tijg1n-D.O.A: 5/11/2009

Dismantle Part: 17.11.2017

After repair: 22.11.2017

01.12.17 166pm Email to Irene Tan thru Merimen.

PRG

# ASSIGNMENT

From: W-1201 Date: 10/4/2008  
 Estimated Cost: 2537 A  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV:  
 To Inspect Vehicle No: 2537 A  
 at Workshop no: N 51  
 of: 2 Kaki Bukit Ave. 2 #01-17  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured: Excess:  
 (Client's Record):  
 Make of Ven:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: XD 2537 A Regn: 10/4/2008  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Nissan CC: 13074  
 Colour: Gold AC Insured / Std / NI / NA  
 Sp. Reading: 287214 T. Radio: Insured / Std / NI / NA  
 Eng No:  
 C.No: CWB4CLP00083  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 295/80 R22.5  
Rear: 275/70 R22.5 (D)  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or BY S 98 (F)  
 Front: Double Happiness (middle) Mable  
 R/Bal: 5 mm R/Bal: 4 mm  
 L/Bal: 5 mm L/Bal: 4 mm  
 D.O.A: 8/11/2017 D.O.I: 14/11/2017  
 Survey held at: N-51 Automotive @ 4:52pm  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
left fty  
 The U/C / Chassis frame / Body Structure affected due to collision.

Tyre Size Rear: 275/70 R22.5  
 Brand: Sport Trak  
 Depthness: 3mm

Range \$4000 - \$5000

RECEIVED 04 APR 2018

Date/Time File Pass to: ☐ : Preli. Report

1: 03042018 ☐ : Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1. S - R \$

Photo

Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Monty  
13/4/2018



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17021485/Wb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 10-11-2017	
		Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	GBB 6742T	Veh. Inspected	XD 2537A
Policy No.	28707879MKC	Coverage (\$)	0.00
Claim No.	536223	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	10/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	08/11/2017	Inspection Date	14/12/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Nov 2017		10 Nov 2017 11:55 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YU YEE ENGINEERING PTE LTD, Co. Reg. No.: 198203631K		
Main Claimant:	MULTIFORM DEVELOPMENTS & CONSTRUCTION PTE LTD, Co. Reg. No.: 199409263D		
Vehicle Reg. No.:	XD2537A	Date of Loss:	08/11/2017 07:00 - :59
Claim Type:	TP / 536223	Policy/Cover Note No.:	28707879MKC (Comprehensive) Coverage: 05/04/2017 - 04/04/2018
Vehicle Reg. No. (Insured):	GBB6742T	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/11/2017]		
Driver/Custodian (Insured):	HALIM ABDUL ( / Male), NRIC: G7789685L		

### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor** ( ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2017 20:51
Date Of Accident	08/11/2017 07:40
Exact Location Of Accident	CHOA CHU KANG WAY TOWARDS KJE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD2537A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MULTIFORM DEVELOPMENTS & CONSTRUCTION PTE LTD
Co Reg No	199409263D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82599454
Alternative Phone No	OFFICE-82599454

### Vehicle Particulars

Manufacturer	NISSAN
Model	CWB45A
Exact Purpose for which vehicle was being used at time of accident	WORKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5075747442-01
Cover Note Number	

### Driver

Name of Driver	ZHENG GUOHUI
Passport No/FIN	G5315815W
Date Of Birth	29/01/1982
Occupation	OUTDOOR
Date Of Driving Pass	17/02/2014
Driving Experience	3 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82599454
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NO 3 SUNGEI KADUT DRIVE SINGAPORE
Postcode	756229
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB6742T
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	HALIM ABDUL
NRIC/Passport Number	G7789685L
Contact Number	97362240
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	



# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 05/11/2017 / 10:00hrs

Reporting Centre Person's Signature

Name: KIM SUT  
NIC/FIN No: 25520244



# Sketch Plan #2

## SKETCH PLAN



A-102837A

D-668672T

93

DELTA CHU KANG WAY  
TOWARDS KSC

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along lane one when vehicle B change lane abruptly and collide against my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Publicholder's Signature  
(Date & Time)

郭國輝

Driver's Signature  
(If driver is not the publicholder)

Date & Time: 2022/02/10/10:37

Reporting Centre Personnel's Signature

Name: Yikson

Signature No: 50514628

## View Sent Message

This mail is associated with :

**\*XD2537A (536223)**  
**[GBB6742T]**

TP  
MULTIFORM DEVELOPMENTS & CONSTRUCTION PTE LTD  
Nov 8 2017 7:00AM  
[YU YEE ENGINEERING PTE LTD]  
N-51 Automotive Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **01/12/2017 13:56 PM**.  
**To** MSI\_ITAN  
**Subject** Pre-repair Inspection

Dear Irene,

Refer to your assignment on 10.11.2017 at 11.55AM.

Please be informed that we have inspected the vehicle XD 2537A on 14.11.2017 at 4.52PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Nov 2017		10 Nov 2017 11:55 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	YU YEE ENGINEERING PTE LTD, Co. Reg. No.: 198203631K								
Main Claimant:	MULTIFORM DEVELOPMENTS & CONSTRUCTION PTE LTD, Co. Reg. No.: 199409263D								
Vehicle Reg. No.:	XD2537A	Date of Loss:	08/11/2017 07:00 - :59 [114 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 536223	Policy/Cover Note No.:	28707879MKC (Comprehensive) Coverage: 05/04/2017 - 04/04/2018						
Vehicle Reg. No. (Insured):	GBB6742T	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 11/11/2017]								
Driver/Custodian (Insured):	HALIM ABDUL ( / Male), NRIC: G7789685L								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*XD2537A (536223)

[GBB6742T]



































TP



















































**MULTIFORM DEVELOPMENTS & CONSTRUCTION PTE LTD**






















Nov 8 2017 7:00AM

[YU YEE ENGINEERING PTE LTD]

N-51 Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser		
Assessment Reports								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	10/11/17 11:55	Accident Statement From:SC - Reg. No: GBB6742T, Claimant: YU YEE ENGINEERING PTE LTD						 Load HTM		
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
2	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
3	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
4	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
5	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
6	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
7	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
8	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
9	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
10	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
11	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
12	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
13	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
14	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
15	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
16	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
17	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
18	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
19	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
20	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
21	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
22	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
23	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
24	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
25	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
26	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
27	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
28	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
29	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
30	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
31	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
32	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	
33	03/04/18 15:58	General View						 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/04/18 15:58	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	03/04/18 15:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	03/04/18 15:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	03/04/18 15:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	03/04/18 15:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	03/04/18 15:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	03/04/18 15:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	03/04/18 15:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	03/04/18 15:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/11/17 11:55	PRI	 Load PDF	
2	10/11/17 11:55	EMAIL to TP reject their list of surveyor	 Load PDF	
3	10/11/17 11:55	TP GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021485/WBE2

Date: 09/04/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28707879MKC

Claimant Vehicle No : XD2537A

Insured Vehicle No : GBB6742T

Date of Loss: 08/11/2017

Nature of Claim: TP

Claim No: 536223

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: XD2537A

Make &amp; Model: NISSAN CWB45CLPHNB, 13.1 D (M)

Engine No: GE13334335B

Reg. Date: 10/04/2008 (Man. Year: 2007)

Chassis No: CWB4CLP00083

Colour: Gold

Odometer: 287214 km

Engine Capacity: 13074 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: BYS 98 5 mm

Rear Left Side: Sport Pak 3/3 mm

Front Right Side: BYS 98 5 mm

Rear Right Side: Sport Pak 3/3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 10/11/2017

Date Inspected: 14/11/2017 Inspected At:

N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI  
BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 09 Apr 2018)	
<b>Parts:</b>	N/A	NISSAN CWB45CLPHNB 13.1 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XD2537A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >