


REF: CS / FCL17021B83 / G9b n2
 ASSIGNMENT (Office)
 From (Person): Serene Ler FCI Date: 11:31am @ 10/11/17
 Estimated Cost: Bill to
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: FBH 2472S Insured: SH 9419A
 At Workshop no: Kivile Enterprise Tel: 67488645
 of 31k3007 4bi Rd 1 # 61-408
 Policy No: D15077701MFSH Claim No: D17010238MFSH
 Sum Insured: Excess:
 Make of Veh: D.O.A 31/10/2017
 (Client's Record)
 CA / REV / REP. / REV 24 HRS 'wp'
 Date/Time: 11:34am @ 10/11/17 Person Contacted: Irene Toh Veh: IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	FBH 2472S - NA / msh 17021034 / k4	D.A: 31-10-17
	SH 9419A - x	
28/12/17 @ 2:38pm	revised to Serene by email.	

Surveys Nhl REF: FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: Kivile
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: FBH 2472S Yr Regn: 13 Apr 2009
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or: _____
 Make: Honda wave cc 125
 Colour: yellow/white A/O: Insured / Std / NI / NA
 Sp. Reading: 1433 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NF 125ST 00 23271
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NH / S/Rim / STD A/Rim or
 Tyre Size: F: 80/90-17
 R: 90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or TIMSUN

Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 10-11-17
 Survey held at w/s 4:15pm
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
Wed 12/1/10 \$1500 with Inex. (Rad \$1187, 44%)

RECEIVED 31 JAN 2010

Date/Time, File Pass to? ☐ : Preli. Report
31/1/10 ☐ : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 3
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS: _____
 Photos: _____
 Others: _____

110
50
30
TOTAL
190

Report Format: TP
 Lump Sum / I.B.I. (\$) 1500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021583/Gqb

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 13-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9419A	Veh. Inspected	FBH 2472S
Policy No.		Coverage (\$)	0.00
Claim No.	D17010238MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	10/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	31/10/2017	Inspection Date	10/11/2017
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010238MFSH
Our Ref: CS/FCI17021583/Gqb

Date: 28 December 2017

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBH 2472S.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/11/2017 at the premises of M/s KIVILE ENTERPRISE, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,687.00 .
Revised Estimate Amount	: S\$ 1,913.90 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front portion and o/s body.



Yours faithfully

Guo Qiang
Automotive Assessor

21/05/2014

MOTOR SURVEY ASSIGNMENT

Date	02-11-2017	Our Ref No. D17010238MFSH
Accident Date	31-10-2017	Claim Type. Third Party
Insured Vehicle	SH9419A	Third Party Vehicle. FBH2472S
Survey Location	BLK 3007 UBI ROAD 1 #01-408	
Contact Person.	IRENE TOH	
Contact No.	67488645/ 0	Fax No. 67482533
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KIVILE ENTERPRISE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229757)



PRI Documents



Close



PRI Header Details

Claim No	D17010238MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & KIVILE EN
Workshop Name	KIVILE ENTERPRISE (Contact Person : IRENE TOH)	Survey Location & Contact Details	BLK 3007 UBI ROAD 1 #01-408 Mobile: 0 , Phone: 67488645 , Fax: 67482533 EmailId: KIVILEPC@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM T		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9419A	TP Vehicle No	FBH2472S
PRI Recieved Date	09-11-2017 06:07:26 PM	Surveyor Appointed Date	10-11-2017 11:31:08 AM	Surveyor Accept Date	10-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	10-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 December, 2017 2:38 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010238MFSH/1
Attachments: CSFCI17021583Gqb.pdf

Dear Serene,

Enclosed herewith preliminary advice of FBH 2472S.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 10 November, 2017 11:37 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010238MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 10 November, 2017 11:31 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010238MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Foreign Identification Number
Owner ID	1649L
Vehicle Details	
Vehicle No.	FBH2472S
Vehicle to be Exported	No
Intended De-registration Date	15 Nov 2017
Vehicle Make	HONDA
Vehicle Model	WAVE 125X A
Primary Colour	White
Manufacturing Year	2008
Engine No.	NF125STE0023271
Chassis No.	NF125ST0023271
Maximum Power Output	-
Open Market Value	\$1,873.00
Original Registration Date	13 Apr 2009
First Registration Date	13 Apr 2009
Transfer Count	6
Actual ARF Paid	\$281.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	12 Apr 2019
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$1,053.00
COE Rebate Amount	\$148.00
Total Rebate Amount	\$148.00

The information contained herein is correct as at 15 Nov 2017

OK



吉维利企业 KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

VEHICLE NO: FBH24725 MODEL: HONDA WAVE 125R A

FRONT RIM / Dis	350 /
FRONT DISC / BT	95 /
FRONT BRAKE PUMP X NN	115 X
FRONT WHEEL SHAFT / BT	85 /
FRONT FORK / BT	180 /
FORK UNDER BRACKET / BT	120 /
STEERING BEARING / MC	80 /
FRONT FENDER / Cut	75 /
FRONT NUMBER PLATE / Cut	12 /
HANDLE BAR / BT	105 /
HANDLE GRIP X NN	25 X
BRAKE LEVER / Cut	32 /
SIDE MIRROR / Cut	32 /
FOOTREST / Cut	25 /
BRAKE PEDAL / Cut	32 /
MUFFLER / Cut	350 /
TAIL BOX / Cut	98 /
TAIL BRACKET X NN	60 X
BODY ALIGNMENT	200 150
IU UNIT X NN	156 X
TRANSPORT(WITH RECEIPT)	110 /
LABOUR	350 150
	2687

1671
10%: 1503.9
1913.9
20%: 1500

3 Days.

Lumpsum repair

After repair photos

Guo Qiang - 8288 0282

10/11/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021583/Gqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9419A	Veh. Inspected	FBH 2472S	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010238MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	10/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA WAVE	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	NF125ST0023271	Colour	YELLOW / WHITE	
Odometer	1433	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	TIMSUN	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	TIMSUN	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/10/2017	Inspection Date	10/11/2017	
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 2472S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RIM	DISTORTED	350.00	350.00
1	FRONT DISC	BENT	95.00	95.00
1	FRONT BRAKE PUMP	NOT NECESSARY	115.00	-
1	FRONT WHEEL SHAFT	BENT	85.00	85.00
1	FRONT FORK	BENT	180.00	180.00
1	FORK UNDER BRACKET	BENT	120.00	120.00
1	STEERING BEARING	NECESSARY	80.00	80.00
1	FRONT FENDER	CUT	75.00	75.00
1	FRONT NUMBER PLATE	CUT	12.00	12.00
1	HANDLE BAR	BENT	105.00	105.00
1	HANDLE GRIP	NOT NECESSARY	25.00	-
1	BRAKE LEVER	CUT	32.00	32.00
1	SIDE MIRROR	CUT	32.00	32.00
1	FOOTREST	CUT	25.00	25.00
1	BRAKE PEDAL	CUT	32.00	32.00
1	MUFFLER	CUT	350.00	350.00
1	TAIL BOX	CUT	98.00	98.00
1	TAIL BRACKET	NOT NECESSARY	60.00	-
	LESS 10% DISCOUNT		-	-167.10
			1,871.00	1,503.90
<u>SPECIAL NETT ITEMS</u>				
1	IU UNIT (SN)	NOT NECESSARY	156.00	-
			156.00	-
<u>LABOUR</u>				
	BODY ALIGNMENT.		200.00	150.00
	TRANSPORT (WITH RECEIPT).		110.00	110.00
	LABOUR.		350.00	150.00
			660.00	410.00
GRAND TOTAL			2,687.00	1,913.90

Report Ref No. CS/FCI17021583/Gqbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00
---	--	--	----------

Report Ref No. CS/FCI17021583/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.