

22/03/2002

ASS. REC. BY:

REF:

CS3 / GA17021590 / Wbe2

Special Instruction:

range k days.

Surveyor:

Wilson.

ASSIGNMENT (Office)

From (Person):

Sharon Ng

of

GAL

Date/Time:

12.11.2017 3:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRD 7101

Insured:

SLN 9775 Y

at Workshop m/s

Asia Motorsport

Tel:

6745 3811

of

568 Geylang Rd

Policy No:

Claim No:

CLM0MVC000001535

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07.11.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

13.11.17 10:25am

Person Contacted:

Mr. Loo

Vehicle: IN / OUT

Date/Time

Action/Instruction (X) Estimate

JRD 7101 - X

SLN 9775Y - X

Dismantle Part: 15.11.2017

After repair: 20.11.2017

01.12.17 20:1pm

Call Mr. Loo get log card & GAL, they don't have

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV:
 To inspect Vehicle No: JRD7101
 at Workshop m/s: Asia Motorsports
 of: S65, Conlang Rd.
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 JDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: JRD7101 Yr Regn: No Available
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha CC: Holder
 Colour: Black AC: Insured / Std / NI / NA
 Sp. Reading: 26185 T Ratio: Insured / Std / NI / NA
 Eng No: _____
 C/No: PM Yu G04101F
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 75/90-17
 R: 80/90-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 2 mm R/Bal: 2 mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A: _____ D.O.I: 13/4/12-17@
 Survey held at: As Above 4:38pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

No Accident Report Given

Range - \$2900 - \$3900

4 days

[Signature]
 9/4/2018

RECEIVED 11 APR 2018

Date/Time File Pass to:

10042018

Date/Time File Return to:

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

100

100

100

100

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

PRS

100




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS3/GAI17021590/Wb	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 13-11-2017	
			Code : GAI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLN 9775Y	Veh. Inspected	JRD 7101	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	SHARON NG	Assign Date	12/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/11/2017	Inspection Date	13/11/2017	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Catherine Chong (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Sunday, 12 November, 2017 3:15 PM
To: Asia Motorsports Solution Pte Ltd
Cc: Nivitha (LKK Auto); SUR
Subject: RE: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - CALL FOR PRE-REPAIR INSPECTION

WITHOUT PREJUDICE

Dear Sir

In accordance to the state court's practice direction, we put on notice that we will also conduct a post-repair inspection once the vehicle has been repaired and before returned to your client.

Cc: LKK – please conduct the pre-repair inspection within 2 days and follow-up with Asia Motorsports for the post repair inspection.

Regards
Sharon

From: Ng, Sharon
Sent: Sunday, November 12, 2017 11:32 AM
To: 'Asia Motorsports Solution Pte Ltd' <asiamotorsports@hotmail.com>
Cc: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - CALL FOR PRE-REPAIR INSPECTION

WITHOUT PREJUDICE

Dear Sir

We have informed LKK for the pre-repair inspection. Kindly arrange with them and let them have the police report and necessary document.

Regards
Sharon Ng
Great American

From: Asia Motorsports Solution Pte Ltd [<mailto:asiamotorsports@hotmail.com>]
Sent: Friday, November 10, 2017 5:32 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>; Customer Service <Customer.Service@sg.gaig.com>; General Claims <GeneralClaims@sg.gaig.com>
Subject: Re: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - CALL FOR PRE-REPAIR INSPECTION

Your Ref:

Our Ref: JRD 7101

10 November 2017

Great American Insurance Company, Singapore Branch
3 Temasek Avenue
#16-01
Centennial Tower
Singapore 039190

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Attn: Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - CALL FOR PRE-REPAIR INSPECTION

Thank you so much for your reply dated 10 November 2017. Unfortunately, we are unable to reach a compromise on the appointment of a Single Joint Expert. As such, we will be appointing one motor surveyor from our proposed list to conduct the survey on our client's damaged vehicle.

We are also sending out this letter as a call for pre-repair inspection to your kind office.

As we/our client are unable to wait indefinitely, kindly note that if we do not hear from you by **14 November 2017 (Tuesday), 1800H**, we will proceed with the necessary repair on our client's damaged vehicle.

Thank you and we hope to hear from you soonest.

Regards,

Asia Motorsports

568 Geylang Road

Singapore 389514

6745 3811

6746 5110 (fax)

asiamotorsports@hotmail.com

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>

Sent: Friday, November 10, 2017 4:57 PM

To: Asia Motorsports Solution Pte Ltd

Subject: RE: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

WITHOUT PREJUDICE

Dear Sir

Since we are unable to agree to SJE, we will appoint our surveyors LKK Auto Consultants to survey your client's vehicle.

Please let us have your client's police report asap.

Regards

Sharon Ng

Great American

From: Asia Motorsports Solution Pte Ltd [<mailto:asiamotorsports@hotmail.com>]

Sent: Thursday, November 09, 2017 1:40 PM

To: Ng, Sharon <Sharon.Ng@sg.gaig.com>; Customer Service <Customer.Service@sg.gaig.com>; General Claims <GeneralClaims@sg.gaig.com>

Subject: Re: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Your Ref:

Our Ref: JRD 7101

9 November 2017

Great American Insurance Company, Singapore Branch
3 Temasek Avenue
#16-01
Centennial Tower
Singapore 039190

Attn: Claims Department

Dear Sir/Mdm,

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Thank you so much for your reply dated 9 November 2017. However, we regret to inform that we will not be selecting or appointing any motor surveyors from your proposed list.

As required by the new regulations, please find appended below our counter proposed list of motor surveyors for your appointment as Single Joint Expert:

Forensic Consultants Pte Ltd
HJL Auto Appraiser Services
KTO Automobile Assessors
Mc-Coy Appraiser Pte Ltd
YB Lim Appraisal Services
LCW Appraiser Pte Ltd
Treasures Appraisal Services
Pal's Appraiser Pte Ltd
Sincere Appraisal Services
Prudent Adjustors Services

We will appreciate if your kind office can revert by **13 November 2017 (Monday), 1400H** on your selection from the above list, failing which we will appoint a motor surveyor from our list after **13 November 2017 (Monday), 1400H**.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Thursday, November 9, 2017 11:48 AM
To: Asia Motorsports Solution Pte Ltd
Subject: RE: NOTICE OF ACCIDENT: ACCIDENT INVOLVING JRD 7101 & SLN9775Y ON 7 NOVEMBER 2017

WITHOUT PREJUDICE

Dear Sir

Liability is clear.

Please confirm on SJE and if your repair estimate is available, please forward to us together with your reply on the selected SJE for the purpose of direct settlement.

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Regards
Sharon Ng
Great American

From: Asia Motorsports Solution Pte Ltd [<mailto:asiamotorsports@hotmail.com>]
Sent: Wednesday, November 08, 2017 4:10 PM
To: Customer Service <Customer.Service@sg.gaig.com>; General Claims <GeneralClaims@sg.gaig.com>
Subject: NOTICE OF ACCIDENT: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017

Your Ref:
Our Ref: JRD 7101

8 November 2017

Great American Insurance Company, Singapore Branch
3 Temasek Avenue

**PROPERTY CLAIM
(WITHOUT PREJUDICE)**

#16-01
Centennial Tower
Singapore 039190

TO: Any Personal Injury
Claims)

Attn: Claims Department

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017

We are instructed to notify you of a road traffic accident on **7 November 2017** at about **12.00 am** at **Pan Island Expressway towards Tuas, before Adams Road Exit** involving our client's vehicle registration number **JRD 7101** and vehicle registration number **SLN 9775 Y** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **10 November 2017 (Friday), 1630H**, we will be forwarding **our proposed list of 10 motor surveyors for your appointment**, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports Solution Pte Ltd
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Catherine Chong (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Tuesday, 10 April, 2018 3:48 PM
To: Catherine Chong (LKK Auto)
Cc: 'assignments'
Subject: RE: RE: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

CLMOMVC000001535

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Tuesday, April 10, 2018 3:46 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: 'assignments' <assignments@lkkauto.com>
Subject: [External] RE: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Dear all,

Kindly assist.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, 1 December, 2017 2:02 PM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>
Cc: 'assignments' <assignments@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Dear Sharon,

Kindly provide us the claim number.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, 10 November, 2017 5:09 PM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; 'assignments' <assignments@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING JRD 7101 & SLN 9775 Y ON 7 NOVEMBER 2017 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No				
C Claim No				
C Insurance Authorisation (CA /REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition				
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair				
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded				
---------------------------	--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS3/GAI17021590/Wbe2 Date: 11-04-2018 Code: GAI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLN 9775Y	Veh. Inspected	JRD 7101
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000001535	Excess (\$)	0.00
Assign From	SHARON NG	Assign Date	12/11/2017
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	PMYUG0410F	Colour	BLACK
Odometer	26185 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90-17	YOKOHAMA	2 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	YOKOHAMA	2 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.			
5. General Information			
Accident Date	07/11/2017	Inspect Date / Time	13/11/2017 (04:38 PM)
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,900-\$3,900			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/GAI17021590/Wbe2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.