

ASS. REC. BY:

REF: C03 /MSH17021592/Wbez

Special Instruction:

Range

Surveyor

Willson

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSU

Date/Time:

13-11-2017 10:14am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 2847H

Insured:

STN 8676C

at Workshop m/s

3 Motorwerkz

Tel:

9797 2800

of

25 Kaki Bukit Rd 4 # 01-40

Policy No:

28782168A/W

Claim No:

536138

Sum Insured:

Excess:

Make of Veh:

D.O.A.

0811207

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

13-11-17 10:51am

Person Contacted:

Jay

Vehicle IN/OUT

Date/Time

Action/Instruction ( x ) Estimate

SLB 2847H - x

STN 8676C - x

Dismantle Part: 16.11.2017

After repair: 28.11.2017

27-11-17 4:27pm

Email to Catherine Thia thru mesimen

PRS  
Wilson

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV:  
To inspect Vehicle No: SLB 284TH  
at Workshop no: 3 Motorworldz  
of 25 Lakehurst Rd 4, #31-40  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record): \_\_\_\_\_  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Est. or Market Value: \_\_\_\_\_  
JDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Veh No: SLB284TH Regn: 31/3/2016  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Subaru Forester cc: 1995  
Colour: Blue Insured / Std / NI / NA  
Sp Reading: 18496 T Rad: Insured / Std / NI / NA  
Eng No: \_\_\_\_\_  
C No: 3F15J5KC54G069142  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size F: 225/65 R17  
R: 225  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Geolandar (F) / (R)  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R.Bal: 4 mm R.Bal: 4 mm  
L.Bal: 4 mm L.Bal: 4 mm  
D.O.A: 8/11/2017 DOI: 13/11/2017  
Survey held at: As Above @ 3:51pm  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Range \$5900 - \$6000

*[Signature]*  
9/4/2018

RECEIVED 09 APR 2018

Date Time File Pass to: 07042018  
Date Time File Return to: \_\_\_\_\_  
☐ : Preli. Report  
☐ : Final Report

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp \$  
☐ Inter. by \$  
☐ Tech. Insp \$  
☐ Weekend \$

Report Format: FRS  
Lump Sum / I.B.I: (\$)

Survey Fee	120
Transporter	50
Food	10
Other	
TOTAL	180



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG17021592/Wb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 13-11-2017	
			Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SFN 8676C	Veh. Inspected	SLB 2847H	
Policy No.	28782168AVW	Coverage (\$)	0.00	
Claim No.	536138	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	13/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	08/11/2017	Inspection Date	13/11/2017	
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2017		13 Nov 2017 10:14 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
<b>Insured:</b>	SEAH YE PENG, ID: S7637814B, Tel: +6596935751								
<b>Main Claimant:</b>	CHAN CHEE HOE, ID: S7139504I								
<b>Vehicle Reg. No.:</b>	SLB2847H	<b>Date of Loss:</b>	08/11/2017 15:00 - :59						
<b>Claim Type:</b>	TP / 536138	<b>Policy/Cover Note No.:</b>	28782168AVW (Comprehensive) Coverage: 24/06/2017 - 23/06/2018						
<b>Vehicle Reg. No. (Insured):</b>	SFN8676C	<b>Policy No. (Claimant):</b>							
		<b>Excess:</b>	S\$500.00						
<b>Repairer:</b>	3 Motorwerkz Concepts Pte Ltd (HQ) 25 Kaki Bukit Road 4, Synergy @ KB #01-40, 417800 Kaki Bukit - Tel: 97972800								
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/11/2017]								
<b>Driver/Custodian (Insured):</b>	CHING TENG HONG (), NRIC: S7805035G, Tel: +6596916016								
<b>ASSOCIATED MAIL RECEIVED</b>		View All Compose Case Mail							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No.
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor** ( ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**(2) System - (Views/Merimen)**

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

**(3) Workshop Estimate/Assignment Form**

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


**(4) System - (Views/Merimen)**

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2020

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/11/2017 17:48
Date Of Accident	08/11/2017 15:30
Exact Location Of Accident	SLIP ROD OF BRADDELL ROAD TOWARDS TOA PAYOH LOR 8
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB2847H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHAN CHEE HOE
NRIC No	S7139504I
Email Address	TIETB@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-90477398
Alternative Phone No	OFFICE-90477398

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER 2.0I-L
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01003517
Cover Note Number	

### Driver

Name of Driver	CHAN CHEE HOE
NRIC No	S7139504I
Date Of Birth	27/10/1971
Occupation	INDOOR
Date Of Driving Pass	23/03/1995
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90477398
Fax Number	
Contact Number	OFFICE-90477398
EMail Address	TIETB@YAHOO.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

UPON REACHING AT THE MENTIONED SLIP ROAD, I WAS SLOWING DOWN IN ORDER FOR ME TO CHECK THE TRAFFIC CONDITION ON THE MAJOR ROAD. OUT OF A SUDDEN, I FELT AN HUGE IMPACT FROM MY REAR AND DISCOVER VEHICLE B HAD COLLIDED ONTO MY VEHICLE REAR PORTION. AFTER THE IMPACT, WE ALIGHTED TO EXCHANGE DETAILS AND TOOK SOME PHOTOS BEFORE WE MOVE OFF FROM THE SCENE. THERE IS NO INJURIES INVOLVED. HOWEVER, I WILL SEEK FOR MEDICAL ATTENTION IF NEEDED.

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING VIDEO FROM INSURED

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFN8676C

Vehicle Make/Model/Colour VOLKSWAGEN/GOLF VARIANT

Details Of Properties

Name of Driver CHING TENG HONG

NRIC/Passport Number S7805035G

Contact Number 96916016

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

### Details of Witness

Name

Phone Number




## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GA Records Management Centre established by the General Insurance Association of Singapore (GA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
9/11/2017  
Policyholder's Signature / Date & Time

  
9/11/2017 3:45 PM  
Driver's Signature (if driver is not the policyholder) / Date & Time

VERIFIED BY AJAK MARS  
REPORTING OFFICER  
EUGENE KOH  
Witnessed by Reporting Centre  
Personnel

#### Sketch Plan





ACCIDENT STATEMENT (2000 characters)

UPON REACHING AT THE MENTIONED SLIP ROAD, I WAS SLOWING DOWN IN ORDER FOR ME TO CHECK THE TRAFFIC CONDITION ON THE MAJOR ROAD. OUT OF A SUDDEN, I FELT AN HUGE IMPACT FROM MY REAR AND DISCOVER VEHICLE B HAD COLLIDED ONTO MY VEHICLE REAR PORTION. AFTER THE IMPACT, WE ALIGHTED TO EXCHANGE DETAILS AND TOOK SOME PHOTOS BEFORE WE MOVE OFF FROM THE SCENE. THERE IS NO INJURIES INVOLVED. HOWEVER, I WILL SEEK FOR MEDICAL ATTENTION IF NEEDED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
EUGENE KOH YEW KIAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 November 2017 at 3:35 PM

Date/Time:

9 November 2017 at 3:35 PM

## View Sent Message

This mail is associated with :

**\*SLB2847H (536138)**  
**[SFN8676C]**

TP  
CHAN CHEE HOE  
Nov 8 2017 3:00PM  
[SEAH YE PENG]  
3 Motorwerkz Concepts Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 29/11/2017 16:27 PM.  
**To** MSI\_TSY  
**Subject** Pre-repair Inspection

Dear Catherine,

Refer to your assignment on 13.11.2017 at 10.14AM.

Please be informed that we have inspected the vehicle SLB 2847H on 13.11.2017 at 3.51PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2017		13 Nov 2017 10:14 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	SEAH YE PENG, ID: S7637814B, Tel: +6596935751	
Main Claimant:	CHAN CHEE HOE, ID: S71395041	
Vehicle Reg. No.:	SLB2847H	Date of Loss: 08/11/2017 15:00 - :59 [19 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 536138	Policy/Cover Note No.: 28782168AVW (Comprehensive) Coverage: 24/06/2017 - 23/06/2018
Vehicle Reg. No. (Insured):	SFN8676C	Policy No. (Claimant):
		Excess: S\$500.00
Repairer:	3 Motorwerkz Concepts Pte Ltd (HQ) 25 Kaki Bukit Road 4, Synergy @ KB #01-40, 417800 Kaki Bukit - Tel: 97972800	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 14/11/2017]	
Driver/Custodian (Insured):	CHING TENG HONG (), NRIC: S7805035G, Tel: +6596916016	
































ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		




























  

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*SLB2847H (536138)  
[SFN8676C]  
TP  
CHAN CHEE HOE  
Nov 8 2017 3:00PM  
[SEAH YE PENG]  
3 Motorwerkz Concepts Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	13/11/17 11:24	Accident Statement From: OD - Reg. No: SFN8676C, Claimant: SEAH YE PENG						Load HTM	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
2	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
3	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
4	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
5	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
6	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
7	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
8	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
9	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
10	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
11	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
12	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
13	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
14	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
15	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
16	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
17	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
18	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
19	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
20	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
21	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
22	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
23	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
24	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
25	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
26	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
27	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
28	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
29	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
30	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
31	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
32	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	
33	09/04/18 16:27	Photo After Spray						Load JPG <input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	09/04/18 16:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/18 16:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 16:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	09/04/18 16:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	09/04/18 16:28	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
81	09/04/18 16:28	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
82	09/04/18 16:28	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
83	09/04/18 16:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
85	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
86	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
87	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
88	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
89	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
90	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
91	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
92	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
93	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
94	09/04/18 16:28	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/11/17 10:15	Email to TP to appoint LKK		Load PDF	
2	13/11/17 10:16	PRI		Load PDF	
3	13/11/17 11:24	TP GIA Report From:OD - Reg. No: 5FN8676C, Claimant: SEAH YE PENG		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021592/WBE2

Date: 10/04/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28782168AVW

Claimant Vehicle No : SLB2847H

Insured Vehicle No : SFN8676C

Date of Loss: 08/11/2017

Nature of Claim: TP

Claim No: 536138

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLB2847H

Make &amp; Model: SUBARU FORESTER, 2.0 2.0i-L CVT AWD SR (A)

Engine No: FB20Y226736

Reg. Date: 31/03/2016 (Man. Year: 2016)

Chassis No: JF1SJ5KC5GG069142

Colour: Blue

Odometer: 18496 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: GEOLANDAR 4 mm

Rear Left Side: GEOLANDAR 4 mm

Front Right Side: GEOLANDAR 4 mm

Rear Right Side: GEOLANDAR 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 13/11/2017

Date Inspected: 13/11/2017 Inspected At:

3 Motorwerkz Concepts Pte Ltd (HQ)  
25 Kaki Bukit Road 4, Synergy @ KB #01-40  
Singapore 417800

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,900.00 - \$6,800.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
<b>Parts:</b>	M1-SUV	SUBARU FORESTER 2.0 2.0I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB2847H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >