

21.03.2012

PASS REC.BY:

REF:

CS/MSG17021629/RHbe2

Special Instruction:

Surveyor

RAGUL

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSLH

Date/Time: 13-11-2017 11:07am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 5650G

Insured:

GBG 2561Z

at Workshop m/s

Borneo Motor

Tel:

9336 6875

of

2 Pandan Crescent

Policy No:

28983269MKE

Claim No:

536398

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

13-11-2017 1207pm

Person Contacted:

Shashiv

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 5650G - x

GBG 2561Z - x

14/11/17 @ 4.33pm Reuses to Lionel Tan via Memmen.

Part by PAH \$10,060.54 (Red: 3157.51 / 23%)

Signature: *Rame*

REF:

15694


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: **SLH 56506**
at Workshop m/s: **Borneo Motor**
of _____
Insured: **MSK/UP**
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

sumu

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLH 56506** Yr Regn: **2016** **NOV**
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **TOYOTA COROLLA ALTIS 1.6 cc 1598**
Colour: **RED** A/C: Insured / Std / NI / NA
Sp. Reading: **16601** T/Radio: Insured / Std / NI / NA
Eng No: _____
C/No: **M R053 RCH 104 554939**
Gen. Cond: Good / ☒ Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: Nil / ☒ S Rim / STD A/Rim or
Tyre Size: F: **215/45R18**
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. **6** mm R/Bal. **6** mm
L/Bal. **6** mm L/Bal. **6** mm
D.O.A. **10/11/17** D.O.I. **13/11/17**
Survey held at: **Borneo**
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?
4/12 Typist
Date/Time: File Return to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **8**
Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation: _____ \$ - RS _____ \$
Photos: _____
Others: _____

Report Format: **TP**
Lump Sum / I.B. (\$): **10,000.54**

300
10
310

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17021629/R1tb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 2561Z	Veh. Inspected	SLH 5650G
Policy No.	28983269MKC	Coverage (\$)	0.00
Claim No.	536398	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	13/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

4.

5. General Information

Accident Date	10/11/2017	Inspection Date	13/11/2017
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2017		13 Nov 2017 11:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured: CNC GENERAL CONTRACTORS (PTE) LTD, Co. Reg. No.: 200917807R																								
Main Claimant: HE YA PENG, ID: S8061569H																								
Vehicle Reg. No.: SLH5650G																								
Claim Type: TP / 536398																								
Vehicle Reg. No. (Insured): GBG2561Z																								
Date of Loss: 10/11/2017 18:00 - :59																								
Policy/Cover Note No.: 28983269MKC (Comprehensive) Coverage: 03/07/2017 - 02/07/2018																								
Policy No. (Claimant):																								
Excess: S\$600.00																								
Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857																								
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/11/2017]																								
Driver/Custodian (Insured): SOH ENG LYE (), NRIC: S1044750Z, Tel: +6596835751																								
Adj Asg. Remarks: Please contact SHASHI @ 9336 6878 / 6631 1864 to arrange for survey.																								
View All Compose Case Mail																								
ASSOCIATED MAIL RECEIVED																								
There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 14 Nov 2017

Preliminary Advice

Insured Vehicle No	: GBG2561Z	Accident Date	: 10/11/2017
TP Vehicle No	: SLH5650G	Assignment Date	: 13/11/2017
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 8.00
Date of Inspection	: 13/11/2017		
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,218.05
Revised Amount	:S\$	11,031.05
Check Items (Estimated)	:S\$	907.00
Total	:S\$	11,938.05

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: Slashi

MOTOR ACCIDENT REPORT

Date Of Report: 11 NOV 2017

Time: 08:44

Date Of Accident: 10 NOV 2017

Time: 18:06

Exact Location Of Accident: Tuas road before PIE

Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLH 5650 G

Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S8061569H

Name Of Registered Owner: HE YA PENG

Mobile Number: 90066081

Alternative No: 90052996

Email Address: risealex@hotmail.com / yangshuai99@gmail.com

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model:

Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):

Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒

Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: AIG

Any In-Car Camera? (applicable for United Overseas Insurance Limited insured only): Yes ☒ (please attach photo) No ☐

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐

Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: 2100489460

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: YANG SHUAI

NRIC/ Passport / FIN No: S8373610J

Date Of Birth: 28 Feb 1983

Occupation: Indoor ☒ Outdoor ☐

Date Of Driving Pass: 25 NOV 2015

Gender: Male ☐ Female ☒

Mobile Number: 90052996

Fax No:

Alternative No:

Postal Code:

Address: BLK 11 WOODLANDS DR 72 #03-32 S78094

Email Address: yangshuai99@gmail.com

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: Spouse

Vehicle Registration Number of Driver's Own Vehicle (if applicable): NO

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Rear collision

Number of Passengers in the above vehicle (Including Driver): 1

Weather Conditions: Clear ☐ Raining ☒ Others ☐ (If others, please state condition):

Road Surface: Wet ☒ Dry ☐ Others ☐ (If others, please state condition):

Was any body injured in the Accident? No ☒ Yes ☐

Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: GBG 2561 Z Vehicle type: Lorry

Was any other material or property (e.g. other vehicle) damaged? No ☐ Yes ☒

Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒

Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):

Was notice of intended Prosecution given? No ☐ Yes ☐ (If yes, please state against whom):

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: GBG 2561 Z

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver: Soh Eng Yee

NRIC/Passport/FIN Number: S1044750Z

Contact Number: 9683 5751

Address: BLK 730 Jurong West Street 72 #04-39 Singapore Postal Code: 640730

Insurance Company Name:

Nature Of Damage: No. Of Passenger (Including Driver): 1

DETAILS OF ACCIDENT INDEPENDANT WITNESS

Name:

Name:

Phone Number:

Phone Number:

Email Address:

Email Address:

DETAILS OF INJURED PERSON 1 (Please fill Annex A if more person injured)

Name:

Approximate Age:

Postal Code:

Address:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? No ☐ Yes ☐

Were injured conveyed to hospital by ambulance? No ☐ Yes ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 11 NOV 2017
Policyholder's Signature / Date & Time

 11 NOV 2017
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

slow down due to ~~two~~ car in front hit at the back.


Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

TOYOTA AUTO PROTECTOR (2-YEAR)
CERTIFICATE NO. 2100489460-00000
(The below excess is subject to GST)
OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00
(Windscreen excess is waived if the repair is done at Borneo Motors Workshop.)

SUM INSURED Market Value
INSURING WITH COE/PAF Yes

SLH5650G

He Yapeng

10 Nov 2016

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

9 Nov 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION : All Age Condition

a) The insured.
b) Any other person who is driving on the insured's order or with his permission.
This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.
A Young and/or inexperienced Driver Excess ("YIDER") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the insured's business.
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pacemaking, reliability trial speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / TOYOTA AUTHORISED REPAIRERS

1. Borneo Motors (S)

2. Pandan Crescent (Tel: 6631 1188)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

4. Ethos - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 DeLu Lane 12 (Tel: 67479560) 7. Lai Hui (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Move Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 BIK D (Tel: 67476106)

LOSS OF USE Loss of Use 15 Days (1500 - 1600cc) - Refer to policy wordings for details

* NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD

EMPLOYER'S LOAN

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AIG Asia Pacific Insurance Pte. Ltd.

Issued in Singapore 15 Nov 2016

030210-153
INCHCAPE AUTO TOYOTA-LK2DW
33 LENG KEE ROAD
SINGAPORE 159102

AUTHORISED REPRESENTATIVE

ORIGINAL

IASDLS

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16 Singapore 079120

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg 25 Nov 2015
< 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals =< 2500kg



NP 428A

4797738



NRIC No. S8373610J



Date of issue
24-11-2011

Address

11 WOODLANDS DRIVE 72
#03-32
SINGAPORE 738094

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8373610J
Name:

YANG SHUAI



Birth Date: 28 Feb 1983
Issue Date: 25 Nov 2015



SG
50

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8373610J



Name

YANG SHUAI

杨 帅

Race

CHINESE

Date of birth

28-02-1983

Sex

F

Country of birth

CHINA

S8373610J

Labour	Parts
50	56.27
154	56.27
308	328.61
134	45.3
2412	45.3
2224	89.84
160	49.55
5442	89.84
	49.55
	458.91
	33.1
	551.82
	91.37
	115.6
	144.67
	603.58
	328.61
	199.15
	3.9
	50.74
	33.74
	37.48
	200.68
	291.21
	312.71
	54.48
	136.51
	159.75
	4618.54

Total

10060.54



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingsapore.com.sg

Toyota Bollycar Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

ESTIMATECo Reg No : 196700086Z
GST Reg No : MR-8500000-9Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr He Yapeng
	Document No	11 Woodlands Drive 72
	0	#03-32
	Document Date	Singapore 738094
	11/11/2017	Mobile: 90066081

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	10/11/2016	SLH5650G	0	28293 .6TP/SLH5650G/11111'
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104554939	1ZRX586974	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TPCLAIM TP VEH NO.:GBG2561 ACC DATE:10/11/117 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB CHECK WIRING AND CONDUCT LEAK TEST				154.00
3	B	BP-LAB TRANSFER BOOT LID MECHANISM				308.00
4	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR				154.00
5	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALLILGN ACC AFF AREA				2412 2772 3696.00
6	B	BP-RES RESRPAY ACC AFF AREA				2224 2530.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				160.00
8	1	S52182-02160 ARM, RR BUMPER LH	1.00	66.20	56.27	66.20
9	2	S52181-02190 ARM, RR BUMPER RH	1.00	66.20	56.27	66.20
10	3	S52023-02190 REINFORCEMENT, RR	1.00	386.60	328.61	386.60
11	4	S52592-02300 SEAL, RR BUMPER LH	1.00	53.30	45.30	53.30
12	5	S52591-02301 SEAL, RR BUMPER RH	1.00	53.30	45.30	53.30
13	6	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70	89.74	105.70
14	7	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30	49.55	58.30
15	8	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70	89.74	105.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3541519

TO SECURITY GUARD

3541519

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 11/11/2017
TIME 09:39VEHICLE NO
SLH5650G

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr He Yapeng 11 Woodlands Drive 72 #03-32 Singapore 738094 Mobile: 90066081
	Document No	
	Document Date	
	0	
	11/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	10/11/2016	SLH5650G	0	28293 :6TP/SLH5650G/11111'
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104554939	1ZRX586974	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	9	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30	49.55	58.30
17	0	S52159-02904 COVER, RR BUMPER	1.00	539.90	458.91	539.90
18	1	S52161-OK040 PIECE, RR BUMPER	10.00	3.90	33.10	39.00
19	2	S58307-02380 PANEL, LAMP LOWER	1.00	649.20	551.82	649.20
20	3	S61697-02913 HOUSING, QUARTER	1.00	107.50	91.37	107.50
21	4	S64503-02181 ARM SUB-ASSY, LUG CO	2.00	68.00	115.60	136.00
22	5	S64461-02220 WEATHERSTRIP, LUGGAGE	1.00	170.20	144.67	170.20
23	6	S64401-02B71 PANEL, LUGGAGE DOOR	1.00	710.10	603.58	710.10
24	7	S64600-02080 LOCK ASSY, LUGGAGE	1.00	386.60	328.61	386.60
25	8	S58387-02240 PLATE, RR FLOOR	1.00	234.30	199.15	234.30
26	9	T90467-08186 CO CLIP	2.00	2.30	3.90	4.60
27	0	S75431-02090 LUGGAGE COMP EMBLEM,	1.00	59.70	50.74	59.70
28	1	S75442-02330 PLATE, LUGGAGE COMPT	1.00	39.70	33.74	39.70
29	2	S75442-02340 PLATE, LUGGAGE COMPT	1.00	44.10	37.48	44.10
30	3	S76801-02E30 GARNISH SUB-ASSY	1.00	236.10	200.63	236.10
31	4	S81580-02550 R/REAR BOOT LAMP	1.00	342.60	291.21	342.60
32	5	S81590-02550 LAMP ASSY, RR LH RH	1.00	342.60	291.21	342.60
33	6	S81550-02780 LAMP ASSY, RR COMB RH	1.00	367.90	312.71	367.90
34	7	S81560-02780 LAMP ASSY, RR COMBIN	1.00	367.90	312.71	367.90
35	8	T81270-OD120 LAMP ASSY, LICENSE	1.00	64.10	54.48	64.10
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3541520

3541520

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 11/11/2017
TIME 09:39

VEHICLE NO SLH5650G

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr He Yapeng 11 Woodlands Drive 72 #03-32 Singapore 738094 Mobile: 90066081
	Document No	
	Document Date	
	0	
	11/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	10/11/2016	SLH5650G	0	28293 :6TP/SLH5650G/11111'
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104554939	12RX586974	60		Shashitharan	--/--/----	0.00 --/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
36	9	T89997-30070 ELECTRICAL ANTENNA,	1.00	160.60	136.51	160.60
37	0	SP2061-12021 26 BACK SENSOR (3R3) 310A	1.00	159.75	159.75	159.75
<i>Rasul</i> <i>hp 90010068</i> <i>8 days</i> <i>13/11/17 @ 1445</i> <i>Reg 50 print</i> <i>22/11/17</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	13,218.05
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	925.26
		Labour	6,116.05	
		Materials	7,102.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
		0.00	Amount Due	14,143.31

PLEASE TEAR ALONG PERFORATED LINE

3541521

3541521

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 11/11/2017
TIME 09:39

VEHICLE NO SLH5650G

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 30/11/2017	Mr He Yapeng 11 Woodlands Drive 72 #03-32 Singapore 738094 Mobile: 90066081

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	10/11/2016	SLH5650G	8388	28293 :6TP/SLH5650G/11111'
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053REH104554939 1ZRX586974 60 Shashitharan 21/11/2017 8.00 30/11/2017 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TPCLAIM TP VEH NO.:GBG2561 ACC DATE:10/11/117 DATE-IN:21/11/17 DATE SURVEY:13/11/17 NO OF REPAIR DAYS:8 BY:RASUL AUTHORIZED ON:21/11/17	*			50.00
2	B	BP-LAB CHECK WIRING AND CONDUCT LEAK TEST	*			154.00
3	B	BP-LAB TRANSFER BOOT LID MECHANISM	*			308.00
4	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR	*			134.00
5	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALLIGN ACC AFF AREA	*			2412.00
6	B	BP-RES RESRPAY ACC AFF AREA	*			2224.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				160.00
8	1	S52023-02190 REINFORCEMENT, RR	1.00	386.60	15.00	328.61
9	2	S52592-02301 SEAL, RR BUMPER LH	1.00	53.30	15.00	45.30
10	3	S52591-02301 SEAL, RR BUMPER RH	1.00	53.30	15.00	45.30
11	4	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70	15.00	89.84
12	5	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30	15.00	49.55
13	6	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70	15.00	89.84
14	7	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30	15.00	49.55
15	8	S52159-02904 COVER, RR BUMPER	1.00	539.90	15.00	458.91

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

354415

354415

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/11/2017
TIME 08:40

VEHICLE NO SLH5650G

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1100

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 30/11/2017	Mr He Yapeng 11 Woodlands Drive 72 #03-32 Singapore 738094 Mobile: 90066081

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	10/11/2016	SLH5650G	8388	28293 :6TP/SLH5650G/11111'
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MRO53REH104554939	1ZRX586974	60	Shashitharan	21/11/2017	8.00	30/11/2017	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
16	9	S52161-0K040	PIECE, RR BUMPER	10.00	3.90	15.00	33.10
17	0	S58307-02380	PANEL, LAMP LOWER	1.00	649.20	15.00	551.82
18	1	S61697-02913	HOUSING, QUARTER	1.00	107.50	15.00	91.37
19	2	S64503-02181	ARM SUB-ASSY, LUG CO	2.00	68.00	15.00	115.60
20	3	S64461-02220	WEATHERSTRIP, LUGGAGE	1.00	170.20	15.00	144.67
21	4	S64401-02B71	PANEL, LUGGAGE DOOR HG	1.00	710.10	15.00	603.58
22	5	S64600-02080	LOCK ASSY, LUGGAGE	1.00	386.60	15.00	328.61
23	6	S58387-02240	PLATE, RR FLOOR	1.00	234.30	15.00	199.15
24	7	T90467-08186 CO	CLIP	2.00	2.30	15.00	3.90
25	8	S75431-02090	EMBLEM, LUGGAGE COMP	1.00	59.70	15.00	50.74
26	9	S75442-02330	PLATE, LUGGAGE DOOR	1.00	39.70	15.00	33.74
27	0	S75442-02340	PLATE, LUGGAGE DR	1.00	44.10	15.00	37.48
28	1	S76801-02E30	GARNISH SUB-ASSY	1.00	236.10	15.00	200.68
29	2	S81550-02780	LAMP ASSY, RR COMB RH	1.00	367.90	15.00	312.71
30	3	T89997-30070	ANTENNA, ELECTRICAL	1.00	160.60	15.00	136.51
31	4	SP2061-12021 26	BACK SENSOR (3R3) 310A	1.00	159.75		159.75
32	5	S81580-02550	LAMP ASSY, RR RH	1.00	342.60	15.00	291.21
33	6	T81270-0D120	LAMP ASSY, LICENSE	1.00	64.10	15.00	54.48
34	7	S52181-02190	ARM, RR BUMPER RH	1.00	66.20	15.00	56.27
35	8	S52182-02160	ARM, RR BUMPER LH	1.00	66.20	15.00	56.27
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.							

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour 4,618.54 Materials 5,442.00 Lubrication/Fluid 0.00 Others 0.00	10,060.54
			GST 7.00% 704.24
			Less 0.00
			Amount Due 10,764.78

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/11/2017
TIME 08:40

VEHICLE NO SLH5650G

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2017		13 Nov 2017 11:07 Edit Adj Rpt	S\$10,060.54 Edit Estimates	S\$10,060.54 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: CNC GENERAL CONTRACTORS (PTE) LTD, Co. Reg. No.: 200917807R
Main Claimant: HE YA PENG, ID: S8061569H
Vehicle Reg. No.: SLH5650G
Claim Type: TP / 536398
Vehicle Reg. No. (Insured): GBG2561Z
Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/12/2017]
Driver/Custodian (Insured): SOH ENG LYE (), NRIC: S1044750Z, Tel: +6596835751
Adj Asg. Remarks: Please contact SHASHI @ 9336 6878 / 6631 1864 to arrange for survey.

Date of Loss: 10/11/2017 18:00 - :59
Policy/Cover Note No.: 28983269MKC (Comprehensive)
 Coverage: 03/07/2017 - 02/07/2018
Policy No. (Claimant):
Excess: S\$600.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH5650G (536398)
[GBG2561Z]
TP
HE YA PENG
Nov 10 2017 6:00PM
[CNC GENERAL CONTRACTORS (PTE) LTD]
Borneo Motors (S) Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View Use Viewer		
Letters/Correspondences									1 per page		☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail		Print	
1	13/11/17 10:47	Non Reporting Letter to OI						1 Load HTM			
									1 per page		☒
Assessment Reports											
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail		Print	
1	15/11/17 11:03	Accident Statement From:OD - Reg. No: GBG2561Z, Claimant: CNC GENERAL CONTRACTORS (PTE) LTD						1 Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	14/11/17 16:33	Adjuster Immediate Advice						1 Load HTM			
									3 per page		☒
Photos/Images											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	04/12/17 15:15	General View						1 Load JPG		☒	
2	04/12/17 15:15	General View						1 Load JPG		☒	
3	04/12/17 15:15	General View						1 Load JPG		☒	
4	04/12/17 15:15	General View						1 Load JPG		☒	
5	04/12/17 15:15	General View						1 Load JPG		☒	
6	04/12/17 15:15	General View						1 Load JPG		☒	
7	04/12/17 15:15	General View						1 Load JPG		☒	
8	04/12/17 15:15	General View						1 Load JPG		☒	
9	04/12/17 15:15	General View						1 Load JPG		☒	
10	04/12/17 15:15	General View						1 Load JPG		☒	
11	04/12/17 15:15	General View						1 Load JPG		☒	
12	04/12/17 15:15	General View						1 Load JPG		☒	
13	04/12/17 15:15	General View						1 Load JPG		☒	
14	04/12/17 15:15	General View						1 Load JPG		☒	
15	04/12/17 15:15	General View						1 Load JPG		☒	
16	04/12/17 15:15	General View						1 Load JPG		☒	
17	04/12/17 15:15	General View						1 Load JPG		☒	
18	04/12/17 15:15	General View						1 Load JPG		☒	
19	04/12/17 15:15	General View						1 Load JPG		☒	
20	04/12/17 15:15	General View						1 Load JPG		☒	
21	04/12/17 15:15	General View						1 Load JPG		☒	
22	04/12/17 15:15	General View						1 Load JPG		☒	
23	04/12/17 15:15	General View						1 Load JPG		☒	
24	04/12/17 15:15	General View						1 Load JPG		☒	
25	04/12/17 15:15	General View						1 Load JPG		☒	
26	04/12/17 15:15	General View						1 Load JPG		☒	
27	04/12/17 15:15	General View						1 Load JPG		☒	
28	04/12/17 15:15	General View						1 Load JPG		☒	
29	04/12/17 15:15	General View						1 Load JPG		☒	
30	04/12/17 15:15	General View						1 Load JPG		☒	

Merimen e-Claims

31	04/12/17 15:15	General View		Load JPG	☒
32	04/12/17 15:15	General View		Load JPG	☒
33	04/12/17 15:15	General View		Load JPG	☒
34	04/12/17 15:15	General View		Load JPG	☒
35	04/12/17 15:15	General View		Load JPG	☒
36	04/12/17 15:15	General View		Load JPG	☒
37	04/12/17 15:15	General View		Load JPG	☒
38	04/12/17 15:15	General View		Load JPG	☒
39	04/12/17 15:15	General View		Load JPG	☒
40	04/12/17 15:15	General View		Load JPG	☒
41	04/12/17 15:15	General View		Load JPG	☒
42	04/12/17 15:15	General View		Load JPG	☒
43	04/12/17 15:15	General View		Load JPG	☒
44	04/12/17 15:15	General View		Load JPG	☒
45	04/12/17 15:15	General View		Load JPG	☒
46	04/12/17 15:15	General View		Load JPG	☒
47	04/12/17 15:15	General View		Load JPG	☒
48	04/12/17 15:15	General View		Load JPG	☒
49	04/12/17 15:15	General View		Load JPG	☒
50	04/12/17 15:15	General View		Load JPG	☒
51	04/12/17 15:15	General View		Load JPG	☒
52	04/12/17 15:15	General View		Load JPG	☒
53	04/12/17 15:15	General View		Load JPG	☒
54	04/12/17 15:15	General View		Load JPG	☒
55	04/12/17 15:15	General View		Load JPG	☒
56	04/12/17 15:15	General View		Load JPG	☒
57	04/12/17 15:15	General View		Load JPG	☒
58	04/12/17 15:15	General View		Load JPG	☒
59	04/12/17 15:15	General View		Load JPG	☒
60	04/12/17 15:15	General View		Load JPG	☒
61	04/12/17 15:15	General View		Load JPG	☒
62	04/12/17 15:15	General View		Load JPG	☒
63	04/12/17 15:15	General View		Load JPG	☒
64	04/12/17 15:15	General View		Load JPG	☒
65	04/12/17 15:15	General View		Load JPG	☒
66	04/12/17 15:15	General View		Load JPG	☒
67	04/12/17 15:15	General View		Load JPG	☒
68	04/12/17 15:15	General View		Load JPG	☒
69	04/12/17 15:15	General View		Load JPG	☒
70	04/12/17 15:15	General View		Load JPG	☒
71	04/12/17 15:15	General View		Load JPG	☒
72	04/12/17 15:15	General View		Load JPG	☒
73	04/12/17 15:15	General View		Load JPG	☒
74	04/12/17 15:15	General View		Load JPG	☒
75	04/12/17 15:15	General View		Load JPG	☒
76	04/12/17 15:15	General View		Load JPG	☒
77	04/12/17 15:15	General View		Load JPG	☒
78	04/12/17 15:15	General View		Load JPG	☒
79	04/12/17 15:15	General View		Load JPG	☒
80	04/12/17 15:15	General View		Load JPG	☒
81	04/12/17 15:15	General View		Load JPG	☒

82	04/12/17 15:32	Reinspection Photo		Load JPG	☒
83	04/12/17 15:32	Reinspection Photo		Load JPG	☒
84	04/12/17 15:32	Reinspection Photo		Load JPG	☒
85	04/12/17 15:32	Reinspection Photo		Load JPG	☒
86	04/12/17 15:32	Reinspection Photo		Load JPG	☒
87	04/12/17 15:32	Reinspection Photo		Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Load PDF	
1	13/11/17 10:52	Pre-Repair Survey		Load PDF	
2	13/11/17 10:52	TPD SLH5650G - GIA REPORT		Load PDF	
3	13/11/17 10:52	TPD SLH5650G - ESTIMATE REPAIR		Load PDF	

Documents Checklist

		Reset	Save	Print
DOCUMENTS CHECKLIST				
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17021629/R1TBE2

Date: 04/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28983269MKC
Claimant Vehicle No :	SLH5650G	Insured Vehicle No :	GBG2561Z
Date of Loss:	10/11/2017	Nature of Claim:	TP
		Claim No:	536398

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH5650G	Engine No:	1ZRX586974
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104554939
Reg. Date:	10/11/2016 (Man. Year: 2016)	Odometer:	16601 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R18	Rear Tyre Size:	215/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,216.05	4,668.54	1,547.51	24.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,002.00	5,392.00	1,610.00	22.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,218.05	10,060.54	3,157.51	23.89
+ GST 7.00/7.00% (S\$)	925.26	704.24	221.02	23.89
Nett Amount (S\$)	14,143.31	10,764.78	3,378.53	23.89

INSPECTION

Date of Assignment:	13/11/2017	
Date Inspected:	13/11/2017	Inspected At:
		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Dec 2017)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLH5650G)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
2	1		*ARM, RR BUMPER LH	Bent	66.20 FS	*56.27 FS
3	1		*ARM, RR BUMPER RH	Bent	66.20 FS	*56.27 FS
4	1		*REINFORCEMENT, RR	Bent	386.60 FS	*328.61 FS
5	1		*SEAL, RR BUMPER LH	Necessary	53.30 FS	*45.30 FS
6	1		*SEAL, RR BUMPER RH	Necessary	53.30 FS	*45.30 FS
7	1		*RETAINER, RR BUMPER L	Necessary	105.70 FS	*89.84 FS
8	1		*RETAINER, RR BUMPER L	Necessary	58.30 FS	*49.55 FS
9	1		*RETAINER, RR BUMPER R	Necessary	105.70 FS	*89.84 FS
10	1		*RETAINER, RR BUMPER R	Necessary	58.30 FS	*49.55 FS
11	1		*COVER, RR BUMPER	Deformed	539.90 FS	*458.91 FS
12	10		*PIECE, RR BUMPER	Necessary	39.00 FS	*33.10 FS
13	1		*PANEL, LAMP LOWER	Buckled	649.20 FS	*551.82 FS
14	1		*HOUSING, QUARTER	Bent	107.50 FS	*91.37 FS
15	2		*ARM SUB-ASSY, LUG CO	Bent	136.00 FS	*115.60 FS
16	1		*WEATHERSTRIP, LUGGAGE	Necessary	170.20 FS	*144.67 FS
17	1		*PANEL, LUGGAGE DOOR	Bent	710.10 FS	*603.58 FS
18	1		*LOCK ASSY, LUGGAGE	Bent	386.60 FS	*328.61 FS
19	1		*PLATE, RR FLOOR	Deformed	234.30 FS	*199.15 FS
20	2		*CLIP	Necessary	4.60 FS	*3.90 FS
21	1		*LUGGAGE COMP EMBLEM	Necessary	59.70 FS	*50.74 FS
22	1		*PLATE, LUGGAGE COMPT	Necessary	39.70 FS	*33.74 FS
23	1		*PLATE, LUGGAGE COMPT	Necessary	44.10 FS	*37.48 FS
24	1		*GARNISH SUB-ASSY	Cracked	236.10 FS	*200.68 FS
25	1		*R/REAR BOOT LAMP	Serviceable	342.60 FS	*- FS
26	1		*LAMP ASSY, RR RH	Broken	342.60 FS	*291.21 FS
27	1		*LAMP ASSY, RR COMB RH	Broken	367.90 FS	*312.71 FS
28	1		*LAMP ASSY, RR COMBIN	Serviceable	367.90 FS	*- FS
29	1		*LAMP ASSY, LICENSE	Cracked	64.10 FS	*54.48 FS
30	1		*ELECTRICAL ANTENNA	Cracked	160.60 FS	*136.51 FS
31	1		*BACK SENSOR (3R3) 310A	Not Working	159.75 FS	*159.75 FS
Total Parts (\$\$)					6,216.05	4,668.54

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND CONDUCT LEAK TEST	New	154.00	154.00
2	TRANSFER BOOT LID MECHANISM	New	308.00	308.00
3	DRILL HOLE AND INSTALL REVERSE SENSOR	New	154.00	134.00
4	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	3,696.00	2,412.00
5	RESPRAY ACC AFF AREA	New	2,530.00	2,224.00
6	SUPPLY SEALANT (NETT) 2 PANEL	New	160.00	160.00
Gross Labour Cost (S\$)			7,002.00	5,392.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >