

22/03/2002

ASS. REC. BY:

REF:

CS/LCR17021707/Am27

Special Instruction:

Supervisor:
Munim

Adrian

ASSIGNMENT (Office)

From (Person):

Ashley Chan

of

LCR

Date/Time:

14.11.2017 1033am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GY 8757H

Insured:

SLL 263C

at Workshop m/s

Liang Hee Motor

Tel:

9762 7752

of

Blk 1 Kaki Bukit Ave 6 #01-62

Policy No:

Claim No:

6345526905SG003.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09.11.2017

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

14.11.2017 11:00am

Person Contacted:

David

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GY 3757H - RU / (TEL) 012153 / Rlpb3
	SLL 263C - X
	Confirm L/S \$5800, 6 days
	Red - \$8,753.00, 60%.

REF:

ASSIGNMENT

14/11/09.
2009, NOV

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G48757H. Yr Regn: _____
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Starex. C.C. 2497
 Colour: Silver. A/C: Insured / Std / NI / NA
 Sp. Reading: 259274. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMFWBX7JMAW192976.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: (Nil) / S/Rim / STD A/Rim orTyre Size: F: 215/65R16CR: 215/65R16C.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 14/11/17.

Survey held at

Liang HeeDes. of Damages Ex / Rear / O/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : _____ Action / Instruction

TPA16.MV: 20KPV: 3.5KNett: 16.5K.

RECEIVED

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 61) tpa☒

Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation:

2) _____

Add Fee:

☐

Site Insp (\$)

) S + RS SI

☐

Interview (\$)

) Photos

☐

Tech. Invs (\$)

) Others

☐

Weekend (\$)

)

Report Format : TPLump Sum / 4B.I. (\$) 5800

TOTAL

270




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/LCR17021707/Arb	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 14-11-2017	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLL 263C	Veh. Inspected	GY 8757H
Policy No.		Coverage (\$)	0.00
Claim No.	6345526905SG003	Excess (\$)	0.00
Assign From	ASHLEY CHAN	Assign Date	14/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/11/2017	Inspection Date	14/11/2017
Survey held at	LIANG HEE MOTOR WORKSHOP 1 KAKI BUKIT AVE 6 #01-62 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

- Pre repair inspection request - GY8757H VS SLL263C (OI) DOA 9/11/2017

From: Chan, Yoke Shi
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Loo, Kar Yong, Fan, Winnie-LW
Sent: Tuesday, 14 November, 2017 10:33:53 AM
Attachments:  Fax7168.TIF

Hi,

Please refer to the enclosed request from **Atkins Law Corporation**.

Claim no : 6345526905SG003
Case Owner : JUSTIN WONG KEN YU

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Atkins Law Corporation [mailto:atkinslawcorp@gmail.com]
Sent: Tuesday, November 14, 2017 10:02 AM
To: Chan, Yoke Shi
Subject: Fwd: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL263C AND GY8757H ON 9/11/2017

Dear Sir,

We refer to your email.

Our client is agreeable to appoint **Adrian Ling (LKK Auto Consultants Pte Ltd)** as a single joint expert.

Please be informed that our client 's motor vehicle is available for pre-repair inspection at the under-stated Workshop:-

Liang Hee Motor Workshop
1 Kaki Bukit Ave 6 #01-62
Singapore 417883
Tel : 9752 7252 (David) / 6747-4416. Fax : 6747-2935

Regards,

Atkins Law Corporation.

On Mon, Nov 13, 2017 at 9:11 PM, <general@atkinslaw.com.sg> wrote:

From: Chan, Yoke Shi [mailto:yokeshi.chan@aig.com]
Sent: Monday, November 13, 2017 2:58 PM
To: general@atkinslaw.com.sg
Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Loo, Kar Yong <KarYong.Loo@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL263C AND GY8757H ON 9/11/2017

Without Prejudice

Your Reference : AL/GY8757H/L.HEE

Our Reference :6345526905SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

--
Sent for and on behalf of
Atkins Law Corporation

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

--
Sent for and on behalf of
Atkins Law Corporation

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

**ATKINS LAW CORPORATION****Advocates & Solicitors****Notary Public • Commissioner for Oaths**

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone: (65) 6506-0944, 6506-0940 Facsimile: (65) 6506-0949

E-mail: general@atkinslaw.com.sgNot for service of Court Documents

Our Ref: AL/GY8757H/L.HEE

Your Ref: SLL263C

13 November 2017

LCRF PTE LTD
60 ANSON ROAD #11 - 01
MAPLETREE ANSON
SINGAPORE 079914

By Post Only

AIG Asia Pacific Insurance Pte Ltd
Singapore

By Fax: 6835 7416 Only

Dear Sir

ACCIDENT INVOLVING GY8757H & SLL263C ON 9-11-2017

We act for the owner of vehicle no. GY8757H.

We hereby notify you of a road traffic accident on 9 November 2017 at about 1635 hrs, at Jalan Eunus involving our client's vehicle and vehicle registration no, SLL263C driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

Atkins Law Corporation (Registration No. 201110148W) is a law corporation with limited liability

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/11/2017 15:53
Date Of Accident	09/11/2017 16:35
Exact Location Of Accident	ALONG JLN EUNOS TOWARDS MARINE PARADE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY8757H
Insured/Policyholder	
Name Of Registered Owner	Y.X. VEGETARIAN FOOD
Co Reg No	52908170M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90093957
Alternative Phone No	OFFICE-90093957
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	H-1 STAREX-2.5 D CRDI (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1548991702
Cover Note Number	

Driver

Name of Driver	LEE ENG YIOW
NRIC No	S2629220D
Date Of Birth	13/02/1964
Occupation	OUTDOOR
Date Of Driving Pass	15/09/2000
Driving Experience	17 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90093957
Fax Number	
Contact Number	OFFICE-90093957
EMail Address	NOEMAIL

Address BLK 14, UPPER BOON KENG ROAD
#04-955

Postcode 380014

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLL263C

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number S1664283E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage


No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address



- ① 875714
② ~~875714~~ SL 263C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Jln Enns towards Manne
Parade direction

I was on lane 1 while I was driving
a vehicle SL 263C, suddenly cut into
my lane and collided onto my vehicle.
After collision the car continue to move
and force my vehicle to hit the road
divider.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature


(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





Vote for your favourite car!

All

Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?

Sell it on Marketplace. Posting an advertisement is FREE!

Username / Email Add

password

Connect » Sign Up New Account » Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

2007 Lexus RX400h AWD \$55K



2007 Lexus RX400h AWD
 2007 Lexus RX400h AWD
 Direct Owner

HIN LUNG AUTO
 HoBee Group

30 years of car sale

One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

1 vehicles

Starex

	Make	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Starex		Any	Any	2009	Any	Any	Any	Available
	Hyundai Starex 2.5A		\$16,800	\$12,940 /yr	04-Mar-2009	2,497 cc	-	Van	Available
	Fuel Type: Diesel								
	Good For Short Term Use, Well Maintained By Owner, Wear And Tear Parts Fully Replaced, Call For Appointment Now!								
	ABWIN (1994) Pte Ltd								
	Posted: 08-Nov-2017 Tags: 2009 Hyundai Starex, 2009 Hyundai Starex, Hyundai Starex, Hyundai Starex, Hyundai, Starex, Starex, Used Hyundai								
	Details								

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	-----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Starex, Starex Singapore, used Starex Singapore, used Starex, used vehicles Singapore or even buy used Starex Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	8170M

Vehicle Details

Vehicle No.	GY8757H
Vehicle to be Exported	Yes
Intended De-registration Date	14 Nov 2017
Vehicle Make	HYUNDAI
Vehicle Model	H1 STAREX VAN 2.5 CRDI
Primary Colour	Silver
Manufacturing Year	2009
Engine No.	D4CB9562848
Chassis No.	KMFWBX7JMAU192976
Maximum Power Output	-
Open Market Value	\$22,854.00
Original Registration Date	14 Nov 2009
First Registration Date	14 Nov 2009
Transfer Count	0
Actual ARF Paid	\$1,143.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	13 Nov 2019
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$16,989.00
COE Rebate Amount	\$3,395.00
Total Rebate Amount	\$3,395.00

The information contained herein is correct as at 14 Nov 2017

OK

TP KR.

Janice

GY8757H.

Hyundai Starex

KMFWBX7JMAU182976.

Front Bumper Upper } Deformed

Front Bumper Lower

Front Bumper Clips.

Front Bumper Side Holder x 02

Front Bumper Reinforcement

Front Bumper Sponge

Headlamp x 02

Bonnet

Bonnet Lock.

Front Fender x 02

Front Fender Inner Shield x 02

Front Fender Inner Shield Clips.

Front LH Wing Mirror

Front Support Panel

Front Shock Absorber x 02

Front Lower Arm x 02

Front Knuckle Arm x 02

424 ✓

355 ✓

30 ✓

46x2=92 ✓

249 X

92 X

425x2=850 ✓

1345 ✓

215 X.

~~556x2=1112~~ 556

~~158x2=316~~ 158

~~60~~ 30


394 X

1050 ✓

255x2=510 X

275x2=550 ✓

824x2=648 ✓



GY8757H.

Front Knuckle Arm Bearing x 02

125 x 2 = 250

Front Steering Rack and Pinion.

1795

Front Wheel Rim x 02

200 x 2 = 400 (SN)

Front Tyre x 02

250 x 2 = 500 (SN)

Stickers.

50 (SN)

6338

5070.40

2.1.450

Panel Beating
Spray Painting.
Wiring.

~~1200~~ 600
~~1200~~ 600
~~50~~ 30
~~150~~

To undersent

To remove condenser, radiator }
and to re-gec

~~180~~ 120

To remove front Lt and Rt undercarriages.

~~760~~ 400

To perform wheel alignment

~~150~~ 80 1830
14,553.00

+ 7350.40.

h/s: 5.8K. 14974

06hys

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Nov 2017 Edit Reg		14 Nov 2017 00:00 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: NA		
Main Claimant:	Y.X. VEGETARIAN FOOD, Co. Reg. No.: 52908170M		
Vehicle Reg. No.:	GY8757H	Date of Loss:	09/11/2017 16:00 - :59
Claim Type:	TP / 6345526905SG	Policy/Cover Note No.:	0999995010 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL263C	Policy No. (Claimant):	
		Excess:	
Repairer:	Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 67474416		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wong, Justin] Justin.Wong@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/11/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (15/11/2017): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GY8757H (6345526905SG)**
[SLL263C]

































TP

Y.X. VEGETARIAN FOOD

Nov 9 2017 4:00PM

[LCRF Pte Ltd]

Liang Hee Motor Workshop

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser		
Assessment Reports										1 per page		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail	Print	
1	15/11/17 10:14	Accident Statement From:SC - Reg. No: SLL263C, Claimant: LCRF PTE LTD								 Load HTM		
Photos/Images										3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
2	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
3	08/01/18 09:27	Chassis Number								 Load JPG	<input checked="" type="checkbox"/>	
4	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
5	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
6	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
7	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
8	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
9	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
10	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
11	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
12	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
13	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
14	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
15	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
16	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
17	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
18	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
19	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
20	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
21	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
22	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
23	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
24	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
25	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
26	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
27	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
28	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
29	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
30	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	
31	08/01/18 09:27	General View								 Load JPG	<input checked="" type="checkbox"/>	

32	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	08/01/18 09:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
68	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
69	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
70	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
71	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
72	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
73	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
74	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
75	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
76	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
77	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
78	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
79	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
80	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
81	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

82	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
83	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
84	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
85	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
86	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
87	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
88	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
89	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
90	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
91	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
92	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
93	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
94	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
95	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
96	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
97	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
98	08/01/18 09:27	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR17021707/ARBE2

Date: 12/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995010
 Claimant Vehicle No: GY8757H Insured Vehicle No: SLL263C
 Date of Loss: 09/11/2017 Nature of Claim: TP Claim No: 6345526905SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GY8757H
 Make & Model: HYUNDAI H-1 STAREX, 2.5 D CRDi (A) Engine No: D4CB9562848
 Reg. Date: 14/11/2009 (Man. Year: 2009) Chassis No: KMFWBX7JMAU192976
 Colour: Silver Odometer: 259274 km
 Engine Capacity: 2497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/65 R16C Rear Tyre Size: 215/65 R16C
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,287.00	5,520.40	5,766.60	51.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	1,830.00	1,860.00	50.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,977.00	7,350.40	7,626.60	50.92
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	14,977.00	5,800.00	9,177.00	61.27

INSPECTION

Date of Assignment: 14/11/2017
 Date Inspected: 14/11/2017 Inspected At: Liang Hee Motor Workshop (HQ)
 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY
 @ KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER UPPER	Deformed	424.00 F	*424.00 FL
2	1		*FRONT BUMPER LOWER	Deformed	355.00 F	*355.00 FL
3	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
4	2		*FRONT BUMPER SIDE HOLDER	Necessary	92.00 F	*92.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	249.00 F	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	92.00 F	*- FL
7	2		*HEADLAMP	Cracked	850.00 F	*850.00 FL
8	1		*BONNET	Dented	1,345.00 F	*1,345.00 FL
9	1		*BONNET LOCK	Not Necessary	215.00 F	*- FL
10	1		*FRONT FENDER	O/S Repair / N/S Dented	1,112.00 F	*556.00 FL
11	1		*FRONT FENDER INNER SHIELD	N/S Torn	316.00 F	*158.00 FL
12	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 F	*30.00 FL
13	1		*FRONT LH WING MIRROR	Not Necessary	394.00 F	*- FL
14	1		*FRONT SUPPORT PANEL	Cracked	1,050.00 F	*1,050.00 FL
15	2		*FRONT SHOCK ABSORBER	Not Necessary	510.00 F	*- FL
16	2		*FRONT LOWER ARM	Bent	550.00 F	*550.00 FL
17	2		*FRONT KNUCKLE ARM	Bent	648.00 F	*648.00 FL
18	2		*FRONT KNUCKLE ARM BEARING	Necessary	250.00 F	*250.00 FL
19	1		*FRONT STEERING RACK AND PINION	Not Necessary	1,795.00 F	*- FL
20	2		*FRONT WHEEL RIM	Cut	400.00 FS	*400.00 FS
21	2		*FRONT TYRE	Not Necessary	500.00 FS	*- FS
22	1		*STICKERS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,287.00	6,788.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,267.60
Total Parts (\$\$)	11,287.00	5,520.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE CONDENSER, RADIATOR AND TO REGAS	New	180.00	120.00
6	TO REMOVE FRONT LH AND RH UNDERCARRIAGE	New	760.00	400.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			3,690.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >