

22/03/2002

SS. REC. BY:

REF:

CS/LCR17021710/Gqbs

Special Instruction:

Surveyor

Melimen

ASSIGNMENT (Office)

From (Person):

Loo Kar Yang

of

LCR

Date/Time:

14-11-2017 9:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FT 7706A

Insured:

SLJ 8907L

at Workshop m/s

Dirt Wheel Motor

Tel:

6783 3063

of

Blk 9004 Tampines 94 93 # 01-100

Policy No:

0999 995159

Claim No:

42834131785603.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28-10-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

14-11-2017 10:23am

Person Contacted:

Tangene

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FT 7706A - X

SLJ 8907L - X

REF: LCR

ASSIGNMENT

From: Date: 14/11/2017

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FT 7706A

at Workshop m/s Did Wheel motor

of Blk 9004 Tampines #93 #01-100

Insured: 91521077 - Eugene

Policy No. 96676280 - Mike

Claims No.

Sum Insured: 67833063 Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$3500.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FT 7706A Yr Regn: 15 Aug 2001

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KTM 200 EGS c.c. 193

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VBK GSA 2011.M 209106

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-17

R: 140/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 14-11-17

Survey held at W/S 4pm

Des. of Damages (Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/11 Total loss - Beyond repair.

~~\$2500 - \$4500~~

Finalized \$2800 with Eugene.

30/8/18 Submit Extensive total Loss Report.

RECEIVED 30 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1) 30/8 14/11

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐ : Site Insp (\$)

S + RS \$

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format: MER - TL-E

Lump Sum / I.B.I. (\$)

250

20

- Pre repair inspection request - FT7706A VS SLJ8907L (OI) DOA 28/10/2017

From: Loo, Kar Yong
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang
Sent: Tuesday, 14 November, 2017 9:17:12 AM
Attachments: 11263.17 - letter of authorisation.pdf 11263.17 - Assignment.pdf 5394220564SG_03_11_2017_LOSS NOTIFICATION_174054_001.tif

Hi,

Please refer to the enclosed request from Lee Shergill LLP.

Claim no : 4283413128SG003

Case Owner : Wilson Tan

If you have any queries/concerns, please let us know.
Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thank you.

Best Regards,
Loo Kar Yong
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services
AIG Shared Services (M) Sdn Bhd (887191-D)
Menara WorldWide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext 101 2246 | Fax +603 2719 6150
karyong.loo@aig.com | www.aig.com

Planned PTO: 20/11-28/11

-
-

From: Siti [<mailto:siti@leeshergill.com>]
Sent: Monday, November 13, 2017 5:24 PM
To: Tan, Wilson-KL
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/10/2017 [LSP ref: LSP/RSS/11263/17/si]

Dear Wilson,

We enclose herein scanned copies of the duly signed Assignment & Letter of authorization by the owner of motor vehicle no. FT 7706A for your attention.

Our client's repairer's order of preference is as follows:

- 1) Xing Guo Qiang - LKK Auto Consultants Pte Ltd
- 2) Mohamad Taufikh - LKK Auto Consultants Pte Ltd
- 3) Marcus Chua - LKK Auto Consultants Pte Ltd

Kindly arrange with our client's repairer for the pre-repair survey on an urgent basis.

Warmest Regards,

Siti Norfaein

Legal Executive
For **Raj Singh Shergill / Chia Aileen**
Lee Shergill LLP

Advocates & Solicitors
(In association with Bajwa & Co)

Tel: 6535 1376
Fax: 6535 5362
111 North Bridge Road
#07-07 Peninsula Plaza
Singapore 179098

Internet Email Confidentiality

Important : This message is intended for the recipient(s) addressed above.
It may contain privileged and confidential information. If you are not the intended recipient(s), kindly notify the sender immediately by replying to this message and then delete it from your system. You must not read, copy, use, or disseminate this communication in any form. Thank you.

From: Tan, Wilson-KL [<mailto:Wilson-KL.Tan@aig.com>]
Sent: Wednesday, November 08, 2017 2:27 PM
To: Siti <siti@leeshergill.com>
Cc: Loo, Kar Yong <KarYong.Loo@aig.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/10/2017 [LSP ref: LSP/RSS/11263/17/si]

AIG REF: 4283413128SG003

Dear Siti

Reference to your email dated 6 November, addressed to Kar Yong.

Please let us have the warrant to act, listing down the condition that the settlement sum be paid to the Third Party repairer directly, should there be any settlement and without prejudice to the cause of action for personal injury.

Wilson Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1753 | Fax +(65) 6835 7416

Wilson-KL.Tan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Loo, Kar Yong
Sent: Wednesday, November 08, 2017 10:59 AM
To: Tan, Wilson-KL
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/10/2017 [LSP ref: LSP/RSS/11263/17/si]
Importance: High

Hi Wilson ,

Could you advise on matter below ?

Thank you.

Best Regards,
Loo Kar Yong
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services
AIG Shared Services (M) Sdn Bhd (887191-D)
Menara WorldWide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext 101 2246 | Fax +603 2719 6150
karyong.loo@aig.com | www.aig.com

Planned PTO: 20/11-28/11

From: Siti [<mailto:siti@leeshergill.com>]

Sent: Wednesday, November 08, 2017 10:53 AM

To: Loo, Kar Yong

Cc: 'Kang Li'

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/10/2017 [LSP ref: LSP/RSS/11263/17/si]

Importance: High

Dear Kar Yong,

We refer to our email dated 6 November 2017.

Kindly let us hear from you at the soonest.

Warmest Regards,

Siti Norfaein

Legal Executive

For **Raj Singh Shergill / Chia Aileen**

Lee Shergill LLP

Advocates & Solicitors

(In association with Bajwa & Co)

Tel: 6535 1376

Fax: 6535 5362

111 North Bridge Road

#07-07 Peninsula Plaza

Singapore 179098

Internet Email Confidentiality

Important : This message is intended for the recipient(s) addressed above.

It may contain privileged and confidential information. If you are not the intended recipient(s), kindly notify the sender immediately by replying to this message and then delete it from your system. You must not read, copy, use, or disseminate this communication in any form. Thank you.

From: Siti [<mailto:siti@leeshergill.com>]

Sent: Monday, November 06, 2017 3:50 PM

To: 'Loo, Kar Yong' <KarYong.Loo@aig.com>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/10/2017

Importance: High

Dear Sir,

We refer to our letter dated 2 November 2017.

However we note that you did not revert to paragraph 3 of our letter dated 2 November 2017 which reads "The repairer is willing to agree on a Single Joint Expert if the property damage claim is settled directly and paid to the repairer, without prejudice to the cause of action for personal injury."

Whereas our client is prepared to consider appointing an SJE on your list, we would be grateful on the clarification on the above.

Kindly let us hear from you on an urgent basis.

Warmest Regards,

Siti Norfaein

Legal Executive
For **Raj Singh Shergill / Chia Aileen**
Lee Shergill LLP
Advocates & Solicitors
(In association with Bajwa & Co)

Tel: 6535 1376
Fax: 6535 5362
111 North Bridge Road
#07-07 Peninsula Plaza
Singapore 179098

Internet Email Confidentiality

Important : This message is intended for the recipient(s) addressed above.

It may contain privileged and confidential information. If you are not the intended recipient(s), kindly notify the sender immediately by replying to this message and then delete it from your system. You must not read, copy, use, or disseminate this communication in any form. Thank you.

From: Loo, Kar Yong [<mailto:KarYong.Loo@aig.com>]

Sent: Monday, November 06, 2017 9:14 AM

To: siti@leeshergill.com

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/10/2017

Importance: High

Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thank you.

Best Regards,

Loo Kar Yong

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara WorldWide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 ext 101 2246 | Fax +603 2719 6150

karyong.loo@aig.com | www.aig.com

Planned PTO: 20/11-28/11

From: Chan, Yoke Shi

Sent: Friday, November 03, 2017 2:31 PM

To: siti@leeshergill.com

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Loo, Kar Yong

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/10/2017

Hi,

Amend subject title with DOA 28/10/2017.

Thanks.

From: Chan, Yoke Shi

Sent: Friday, November 03, 2017 2:22 PM

To: siti@leeshergill.com

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Loo, Kar Yong

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ8907L AND FT7706A ON 28/9/2017

Without Prejudice

Your Reference : LSP/RSS/11263/17/si

Our Reference : SLJ8907L

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com



Virus-free. www.avast.com

Lee Shergill LLP

Advocates & Solicitors

Raj Singh Shergill LLB Hons (NUS) Chia Aileen LLB Hons (NUS)

Service of court documents by facsimile and/or email is not accepted

111 North Bridge Road
#07-07 Peninsula Plaza
Singapore 179098
Tel: +65 6535 1376
Fax: +65 6535 5362
URL:<http://www.leeshergill.com>

2 November 2017

IMMEDIATE ATTENTION**AIG Asia Pacific Insurance Pte Ltd**
Motor Claims Department
78 Shenton Way
#07-16 CHARTIS Building
Singapore 079120
Your Reference: SLJ 8907L**BY FAX & PDX**
FAX NO. : 6835 7416No. of page(s) including this page: 2 + encls
Our Reference: LSP/RSS/11263/17/si

Dear Sirs,

ACCIDENT INVOLVING FT 7706A & SLJ 8907L ALONG JUNCTION OF YISHUN AVENUE 7 & AVENUE 2 ON 28 OCTOBER 2017 AT 2350 HRS

We hereby give notice on behalf of the repairer – Dirt Wheel Motor & Credit Pte Ltd and/ or the owner of motorcycle registration no. **FT 7706A** that this motorcycle was involved in an accident on 28 October 2017 with motor vehicle registration no. SLJ 8907L the driver of which was insured with **AIG Asia Pacific Insurance Pte Ltd** and caused the accident by negligent driving/ control/ management. A copy of the Traffic Police report filed is enclosed.

Take Notice that the motorcycle is available for purpose of pre-repair survey if you are so minded, at Dirt Wheel Motor & Credit Pte Ltd premises.

The repairer is willing to agree on a Single Joint Expert if the property damage claim is settled directly and paid to the repairer, without prejudice to the cause of action for personal injury.

Kindly liaise with our Ms Siti (slt1@leeshergill.com) in respect of any inspection or survey.

Take Further Notice that in the event you fail to respond within **2 working days** (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice as to whether you wish to carry out or waive a pre-repair survey, the workshop will in due course proceed to repair the motorcycle and/ or have it surveyed as they deem fit, without further notice and without prejudice to the right to claim loss of use in accordance with the Pre-action Protocol for Non-Injury Motor Accident Cases.

Privileged/confidential information may be contained in this letter and is intended only for the use of the addressee. If you are not the addressee, or person responsible for delivering to the person addressed, you may not copy or deliver this to anyone else. If you receive this letter by mistake, please notify us immediately by telephone and destroy this. Thank you.

In association
with Bajwa & Co**B
&
C**

02/NOV/2017/THU 19:25

FAX No.

F. 002/006

Lee Shergill LLP

Advocates & Solicitors

Ref : LSP/RSS/11263/17/si

Yours faithfully


LEE SHERGILL LLP

Emails : raj@leeshergill.com; aileen@leeshergill.com
siti@leeshergill.com

cc **Dirt Wheel Motor & Credit Pte Ltd**
Blk 9004 Tampines Street 93
#01-100
Singapore 528838
(Person to contact: Mr Eugene 6783 3063)

By Fax No. 6788 1202 Only



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999



T/20171029/2083

1 of 4

Report No. T/20171029/2083

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/10/2017 19:51		Vide Report No.: F/20171029/0011		Station Diary No.: 108	
Informant's Particulars					
Name of Informant: LEE GEN MARCUS			Address: APT BLK 81 BEDOK NORTH ROAD #08-304 SINGAPORE 460081		
ID Type / ID No.: NRIC NO / S9509382E			Contact No.: Home/Office:		Mobile: 93686638
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 22	Date of Birth: 11/03/1995	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SAF SPECIALIST			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 28/10/2017 23:50	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 YISHUN AVENUE 7 YISHUN AVENUE 2 At the traffic light junction of Yishun Ave 7 and Yishun Avenue 2.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FT7706A	Motorcycle	KTM	200 EGS	Orange	Seriously Damaged	1
SLJ8907L	Car	MAZDA	MAZDA 3	Grey	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171029/2083

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 4

Report No. T/20171029/2083

CONTINUATION OF REPORT

Rider			
Name	LEE GEN MARCUS	ID No.	S9509382E
Related Vehicle	FT7706A (Motorcycle)	Contact No.	93686638
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	29/10/2017	Date Discharge	29/10/2017
No. of Days granted Medical Leave	14	Degree of Injury	Serious
Rider			
Name	SOH ZHEN HUI	ID No.	S9718596D
Related Vehicle	FT7706A (Motorcycle)	Contact No.	96441979
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	29/10/2017	Date Discharge	29/10/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 28.10.2017 at about 2340hrs to 2350hrs, I was riding my motorcycle bearing registration plate number FT 7706A with one pillion on board. I was travelling along Yishun Avenue 7 heading towards Gambas. I was travelling along the third lane out of the four lanes along Yishun Avenue 7. As I was approaching the traffic light junction of Yishun Avenue 7 and Yishun Avenue 2, the traffic light signal was green and I have the right of way. Therefore, I continued my journey heading straight and as I get nearer to the stopping line and crossed over, I saw a vehicle on the move from the opposite direction (Yishun Avenue 7) outside the right turn pocket making a right turn. The vehicle was directly near me, therefore, I applied emergency brake and swerved to the right to avoid collision, but it was unavoidable as the vehicle was too near. The collision was from my front to the vehicle rear portion. Due to the impact, both me and my pillion flew off from my motorcycle. The said vehicle moved off to the side and did not stay at the actual accident scene.

Thereafter, few other people who saw the accident came to assist me and my pillion. We moved to the side of the road and they assisted to call for the ambulance. While waiting for the ambulance, I talked to the driver of the vehicle who collided onto me. He is one Ranjit Singh S/O Mukhtiar singh, S1312390Z of Blk 116 Lengkong Tiga #08-183 S(410116) driving vehicle SLJ8907L (Mazda, grey in colour). I asked him what had happened that he did not wait for the oncoming vehicle, and he replied that a bus had blocked his view and he was unable to see my motorcycle, thus, the collision. The driver also brushed me off and did not offer any helping hand when me and my pillion was lying down helplessly.

My father was alerted after the accident occurred and came down immediately. The vehicle that collided onto me had removed his in-car camera and my father witnessed him removing his camera. However, I am unsure if the traffic police managed to capture the accident details since he had removed the data. The said driver was also ignorant to what had happened and did not show any sign of remorse towards



**SINGAPORE
POLICE FORCE**



T/20171029/2083

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 4

Report No. T/20171029/2083

CONTINUATION OF REPORT

what he had caused. His actions were irresponsible and did not assist me in the accident despite me being the victim. His actions of not giving way to oncoming vehicles heading straight was dangerous and furthermore, I was riding on the third lane visible to oncoming vehicles which were not blocked by any vehicles on the first lane (turn right only) and second lane (turn right and straight). Due to the accident, I suffered fracture on my right collarbone, abrasion on parts of my body and left knee injury. I was given 14 days (29.11.2017 to 11.11.2017) of hospitalization leave and will be reviewed for surgery after my swelling has subside. My pillion suffered left ankle injury and bad abrasion on the left leg and swelling on the lips. She was given 3 days of medical leave. My vehicle has already been towed away to Tampines bike shop (Dirt Wheel).

There are three witnesses to the accident, one is Johnny (passenger of the vehicle that collided onto me) HP: 88088514, Kenneth (a jogger) HP:98259584 and Afiq (another driver) HP: 83381547. That is all.



**SINGAPORE
POLICE FORCE**



T/20171029/2083

4 of 4

Report No. T/20171029/2083

Police Station Of Origin:
Yishun North N P C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report

F /

Staff Sgt NUR AFIDA BINTE MOHAMED AYUB

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

29/10/2017 19:51

Officer In Charge Of Case:

TP / GIT /

Staff Sgt WONG SIEU LUI


Contact No.: 65476423

Classification Of Case:

SN 085

Authentication Stamp

NP168



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	5767Z
Vehicle Details	
Vehicle No.	FT7706A
Vehicle to be Exported	No
Intended De-registration Date	21 Nov 2017
Vehicle Make	K.T.M.
Vehicle Model	200 EGS
Primary Colour	Orange
Manufacturing Year	2001
Engine No.	152309272
Chassis No.	VBKGSA2011M209106
Maximum Power Output	-
Open Market Value	\$6,002.00
Original Registration Date	15 Aug 2001
First Registration Date	15 Aug 2001
Transfer Count	17
Actual ARF Paid	\$901.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	31 Mar 2020
COE Category	D - Motorcycle
COE Period(Years)	10
PQP Paid	\$884.00
COE Rebate Amount	\$220.00
Total Rebate Amount	\$220.00

The information contained herein is correct as at 21 Nov 2017

OK

Vehicle Details

Vehicle Type:	Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	Scrambler
Make / Model:	K.T.M. / 200 EGS
Primary Colour:	Orange
Year of Manufacture:	2001
Maximum Laden Weight:	0 kg
Unladen Weight:	0 kg
No. Of Axles:	0
Engine No.:	152309272
Chassis No.:	VBKGSA2011M209106
Engine Capacity:	193 cc
Maximum Power Output:	-
IU Label No.:	714291507
Propellant:	Petrol
Passenger Capacity:	1
Original Registration Date:	15 Aug 2001
First Registration Date:	15 Aug 2001
Open Market Value:	\$6,002.00
Additional Registration Fee Rate:	15.00 %
Actual ARF Paid:	\$901.00
PARF Eligibility:	No
Minimum PARF Benefit:	-
COE No.:	2001040106000555D
COE Category:	D - Motorcycle
COE Expiry Date:	31 Mar 2020
Quota Premium (QP):	\$1,055.00
PQP Paid:	\$884.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$1,055.00
CO2 Emission:	-

[Previous](#)[OK](#)

商品

搜尋商品, 用戶或社團



Get

\$0 BLACK FRIDAY
BASE CHARGE

GET PROMO CODES



< Class 2B (/categories/motorbikes-108/motorbikes-for-sale-1592/class-2b-1595/)



KTM EGS 200

二手

fait.accompl (/fait.accompl/)

S\$4,000

Singapore

購買方式

面交

直接購買

私訊賣家 (/login/?next=/inbox/new/137557225/)

♥ 49

與朋友分享



(https://www.pinterest.com/pin/create/button/?

guid=ngOLrUbjUWH-

2&url=https%3A%2F%2Fcarousell.com%2Fp%2Fktm-

egs-

200-

137557225%2F%3Fref%3Dsearch%26ref_query%3Dktm%2520200%2520egs%26ref_referrer%3D%252Fsearch%252Fproducts%252F%253Fquery%253Dktm%252520200%2525done%20at%20ideal%20Motors.Monthly%20servicing%20done%20at%20trustable%20Ah%20Hua%20Motors%20in%20YishunBraap%20still%20as%20fresh%20as%20ever.Didr

biking%20under%20my%20car%20for%20viewing.%20Negotiable.%20Not%20trading%20though.%20Selling%20to%20get%20a%20A.%20Pass%20liao%20mah.%20But%20

KTM EGS 200

COE April 2020

Multiple items re-done at Ideal Motors.

Monthly servicing done at trustable Ah Hua Motors in Yishun

Braap still as fresh as ever.

Didn't bring her for dirt-biking under my care.

PM for viewing. Negotiable. Not trading though. Selling to get a 2A. Pass liao mah, But would still miss this beast for smoking any other bike for 10 lampposts after any red light.

Make: KTM

Bike Type: Scrambler

交易方式



面交

📍 Singapore

刊登於2017年11月9日

與賣家見面



Syazwan Rasidi

👤 9 🗣️ 0 📧 0

(/falt.accompl/)

其他瀏覽過的商品



Cbr15r

S\$3,800



juliannaxx

🕒 2 小時前

(/juliannaxx/)



Honda Phantom TA150

S\$2,200




apprentic...

🕒 53 分鐘前

(/apprenticesg/)

record purpose!

Dirt Wheel Motor & Credit
9004 Tampines Street 93, #01-100
Singapore 528838



Damage Report / Pro Forma Invoice

Invoice No. 0311201702

Date: 03-Nov-17

Description	Unit	Per Pc (SGD)	Total (SGD)
<u>Replacement of Parts</u>			
Front Fork Right + Left (Bent)	N/A	N/A	N/A
Front Fork Set (200 EXC 2005)	1	5,415.00	5,415.00
Top Triple Clamp (200 EXC 2005)	1	233.00	233.00
Bottom Triple Clamp (200 EXC 2005)	1	233.00	233.00
Steering Stem Needle Bearing	2	58.00	116.00
Steering Stem Lower Seal	1	27.00	27.00
Steering Stem Upper Seal	1	12.00	12.00
Front Fender (Broken)	1	70.00	70.00
Exhaust Pipe (Smashed)	1	633.00	633.00
Header O-ring (Deformed)	2	8.00	16.00
Muffler (Bent)	N/A	N/A	N/A
Muffler (200 EXC 2005)	1	593.00	593.00
Handbrake Cover (Scratched)	1	33.00	33.00
Handbrake Lever (Scratched)	1	82.00	82.00
Speedometer (Missing)	N/A	N/A	N/A
Speedometer (200 EXC 2005)	1	504.00	504.00
Speedometer Bracket (200 EXC 2005)	1	10.00	10.00
Wiring Harness (200 EXC 2005)	1	202.00	202.00
Front Wheel CPL (Out-of-True)	1	1,310.00	1,310.00
Front Wheel Axle (Out-of-True)	1	112.00	112.00
<u>Additional</u>			
Labour for Repairs of Parts	1	500.00	500.00
Survey/Storage/Administrative Fees	1	380.00	480.00

Grand Total: 10,581.00

9152 1077

Eugene.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2017 10:06 Edit Reg		14 Nov 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lion City Rentals Pte Ltd, Co. Reg. No.: NA				
Main Claimant:	-				
Vehicle Reg. No.:	FT7706A	Date of Loss:	28/10/2017 00:00 - :59 [194 Months and 13 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 4283413128SG	Policy/Cover Note No.:	0999995159 (Comprehensive)		
Vehicle Reg. No. (Insured):	SLJ8907L	Policy No. (Claimant):			
		Excess:			
Repairer:	Dirt Wheel Motor Trading (HQ) Blk 9004 Tampines Street 93, #01-100, 528838 Tampines - Tel: 67833063				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/11/2017]				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (15/11/2017): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***FT7706A (4283413128SG)**
[SLJ8907L]

TP

-

Oct 28 2017 12:00AM
[Lion City Rentals Pte Ltd]
Dirt Wheel Motor Trading

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)	Thumbnail	Print
1	15/11/17 15:40	Accident Statement From: SC - Reg. No: SLJ8907L, Claimant: LCRF PTE LTD	Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
2	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
3	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
4	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
5	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
6	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
7	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
8	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
9	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
10	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
11	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
12	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
13	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
14	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
15	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
16	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
17	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
18	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
19	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
20	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
21	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
22	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
23	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
24	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
25	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
26	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
27	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
28	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
29	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
30	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>
31	06/07/18 09:21	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	06/07/18 09:21	General View	Load JPG	✓
33	06/07/18 09:21	General View	Load JPG	✓
34	06/07/18 09:21	General View	Load JPG	✓
35	06/07/18 09:21	General View	Load JPG	✓
36	06/07/18 09:21	General View	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/18 11:07	TP POLICE REPORT	Load PDF	
2	30/08/18 14:02	LTA REBATE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR17021710/GQBS2

Date: 30/08/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999995159
Claimant Vehicle No :	FT7706A	Insured Vehicle No :	SLJ8907L
Date of Loss:	28/10/2017	Nature of Claim:	TP
		Claim No:	4283413128SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FT7706A	Engine No:	152309272
Make & Model:	KTM 200 EGS, 193cc (M)	Chassis No:	VBKGSA2011M209106
Reg. Date:	15/08/2001 (Man. Year: 2001)	Odometer:	0 km
Colour:	Orange		
Engine Capacity:	193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/11/2017	
Date Inspected:	14/11/2017	Inspected At: Dirt Wheel Motor Trading (HQ) Blk 9004 Tampines Street 93, #01-100 Singapore 528838
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE : \$3,500.00 (estimate)

LTA REIMBURSEMENT VALUE : \$220.00

NETT VALUE : \$3,280.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >