

22/03/2002

DAR & days.

ASS. REC. BY:

REF: CS3 / ATG 17021728 / RI bet Special Instruction:

Survivor:

Rasul

ASSIGNMENT (Office)

From (Person):

Ashley Chan

of

ATG

Date/Time: 14.11.2017 2:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Ym 6981P

Insured:

SLB 9248R

at Workshop m/s

A & L motor

Tel:

6362 7228.

of

11 Mandai Estate # 05-09

Policy No:

Claim No:

6168D1439856003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26.07.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 14.11.2017 2:58pm

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	Ym 6981P - X
	SLB 9248R - X
	Dismantle Part: 23.11.2017
	After repair: 27.11.2017

PRR

Inspection

REF:

ALH

ASSIGNMENT

Form:

Date:

23-11-2017

Vehicle:

YM 6981P

Yr Reg:

2007 Jul 18

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Corr / Taxi / Prime Mover

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

YM 6981P

Make:

MITSUBISHI FE83BE09RDEA 2977

at Workshop no:

A & L Motors

Colour:

WHITE

A/C Insured / Std / NI / NA

of:

11 Mandal Estate #05-09

Se Reading:

284472

T-Ratio: Insured / Std / NI / NA

Insured:

Eng No:

Policy No:

C No:

FE83BEA10130

Claims No:

Gen. Cond: Good / Pa / Poor / Burnt

Sum Insured:

Excess:

Steering: Order / Jammed / Leaked / Burnt or

(Client's Record)


Brake: Order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: CD / S/Rim / STD A/Rim or

(Policy Condition)

morning



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size

F:

7.00 -16

R:

175R14C

BS CDN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

6/6

mm

L/Bal:

7

mm

L/Bal:

6/6

mm

D/O.A.

26/07/17

D/O.A.

23/07/17 @ 11.20am

Survey held at:

A & L

Des. of Damages: Fnt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date Time Action / Instruction

RECEIVED 09 APR 2018

Date/Time File Pass to:



Prel. Report

Days Of Repair:

09/04/2018



Final Report

Resurvey No. of Trip:

Survey Fee

180

Date/Time File Return to:

Transportation

20

Report Format:

PRS

Lump Sum / I.B.H. / S

Add Fee:



Site/Inc S



Interview S



Tech. Insp S



/ As-ent S

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17021728/b

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 14-11-2017



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLB 9248R	Veh. Inspected	YM 6981P
Policy No.		Coverage (\$)	0.00
Claim No.	6168014398SG003	Excess (\$)	0.00
Assign From	ASHLEY CHAN	Assign Date	14/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/07/2017	Inspection Date
Survey held at	A&L MOTORS NO. 11 MANDAI ESTATE #05-09 ELDIX SINGAPORE 729908	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

/ - Pre repair inspection request - YM6981P VS SLB9248R (OI) DOA 26/7/2017

From: Chan, Yoke Shi
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Loo, Kar Yong
Sent: Tuesday, 14 November, 2017 2:43:27 PM
Attachments:  FaxB16A.TIF

Hi,

Please refer to the enclosed request from **M/s Ong & Shan LLC**.

Claim no : 6168014398SG003
Case Owner : CHAN KIAN CHUAN

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Ong & Shan LLC [mailto:ongshanllc@gmail.com]
Sent: Tuesday, November 14, 2017 2:36 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Loo, Kar Yong
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB9248R AND YM6981P ON 26/7/2017

Dear Sir/Madam,

We refer to the above matter and your email on the eve..

Our client confirmed appointed of **M/s LKK Auto Consultants Pte Ltd Mr. Marcus Chua** as the Single Joint Expert for this matter.

Name of workshop : M/s A&L Motors
Address : 11 Mandai Estate #05-09 ELDIX Singapore 729908
Contact person : Ms. Lynn
Telephone no : 6-3627228
Fax no : 6-3669708

If you fail to conduct the pre-repair inspection within the next two(2) working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

For Surveyor

From M/s AIG Asia Pacific Insurance Pte Ltd
Vehicle YM 6981P inspected as follows by Name:

Before repair	Parts removed	After repair
_____	_____	_____

Warmest Regards,

CM Chen

Signature:	Signature:	Signature:	M/s Ong & Shan LLC Block 184 Toa Payoh Central #02-364 Singapore 310184
Date/ Time:	Date/ Time:	Date/ Time:	

Tel: 6224 9847 Fax : 6254 7261

Email: ongshanllc@gmail.comOn Tue, Nov 14, 2017 at 2:14 PM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:Without PrejudiceYour Reference : SRSTP.8050.17.CM

Our Reference : 6168014398SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

14-11-'17 12:05 FROM- ONG & SHAN LLC

6562547261

T-963 P0001/0005 F-897

ONG & SHAN LLC

ADVOCATES & SOLICITORS
COMMISSIONERS FOR OATHS
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:
Lawyer : ongshanllc@gmail.com
Secretary :

Please send all correspondences to:

- ☐ 2 Kallang Avenue #08-19 Singapore 339407
Tel: 6444 7845 | Fax: 6444 5847
- ☐ 101 Upper Cross Street #06-15B Singapore 058357
Tel: 6536 7991 | Fax: 6536 7995
- ☒ 184 Toa Payoh Central #02-364 Singapore 310184
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.8050.17.CM

Your Ref : Your insured vehicle SLB 9248R

14th November 2017

Lim Chee Han
c/o AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Department)
78, Shenton way
#08-16, AIG Building
Singapore 079120

BY FAX: 6-835-7416

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
(NIMA) ROAD TRAFFIC ACCIDENT INVOLVING YM 6981P & SLB 9248R ON 26.07.2017
ALONG GEYLANG EAST CENTRAL @ 0740 HRS**

We are instructed by our client's repairer workshop M/s A&L Motors to notify you of a road traffic accident on 26.07.2017 at about 0740hrs along Geylang East Central involving our client's customer's vehicle registration number YM 6981P and vehicle registration number SLB 9248R driven by you at the material time. A copy of the Police report filed is enclosed.

As the result of the accident, our client's/ customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,



Ong & Shan LLC

cc: M/s A&L Motors (63669708)

ONG & SHAN LLC

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE (S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

Survey Department Check List (Case Handler)

Reference No.:

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/08/2014

VAN / LORRY (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	DM	✓	
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket	BT	✓	
1140	993632	Rear Number Plate Lamp	CUT	✓	
1141	992958	Rear Bumper	AS	✓	
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement	DD	✓	
2045	993081	Rear Bumper Step Panel	DD	✓	
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish	BT		
1165	993859	Rear LH Taillamp Panel	BT	✓	
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish	SCR		
1168	993859	Rear RH Taillamp Panel	BT	✓	
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge	SCR		
1352	995307	Rear RH Door Hinge	SCR		
1301	993261	Rear LH Door Lock	DD	✓	
1362	993261	Rear RH Door Lock	DD	✓	
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

Vehicle No: YM 6981 P

[illegible]

IPRI12932204 / NTUC Income Insurance Co-operative Ltd - HQ
ENTRY DATE & TIME: 27/07/2017 17:37

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 28/07/2017 09:15

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/07/2017 17:37
Date Of Accident 26/07/2017 07:40
Exact Location Of Accident ALONG GEYLANG EAST CENTRAL
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YM6981P
Insured/Policyholder
Name Of Registered Owner A&L LEASING PRIVATE LIMITED
Co Reg No 201026256R
Email Address LYNN@ANL.SG
Mobile Phone No (LOCAL) +65-97779689
Alternative Phone No OFFICE-97779689

Vehicle Particulars
Manufacturer MITSUBISHI
Model FE83
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY
Fleet Policy YES

Policy Number 5069320211-02
Cover Note Number THIRD PARTY

Driver
Name of Driver THIAGU S/O SELVARAJOO

NRIC No S8903513I
Date Of Birth 23/01/1989

Occupation OUTDOOR
Date Of Driving Pass 03/05/2013

Driving Experience 4 YEARS AND 2 MONTHS
Gender MALE

Mobile Number (LOCAL) +65-97924468

Fax Number

Contact Number

Email Address PREMKUMARTRADING2308@GMAIL.COM

Address BLK 633 ANG MO KIO AVENUE 6
#04-5155
Postcode 560633
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Refer to Sketch Plan

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLB9248R
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LIM CHEE HIAN
NRIC/Passport Number S7523229B
Contact Number 97680226
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver) 2

Details of Witness

Name
Phone Number
Email Address

Sketch Plan

NINE Estate Motor Service Centre

Vehicle No: YN2081P

Report Date & Start Time: 27/07/17 12:25

Report Ref: MAT

O.A. No: 265932612
Time: 07:00pm

Make & Model: MITSUBISHI L200

Reporting Type: TP

Est. Time: 12:25

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policeholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renege their policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the members of the CMA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and full copies of this report will be made available upon application by interested parties.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA):
I understand, acknowledge, agree and warrant that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, enter, disclose and/or process my personal data/ personal information set out in this Form and any other personal information provided by me or purchased by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/firm, the Monetary Authority of Singapore and any relevant government department(s) (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims, including the settlement of my claims and any necessary investigations relating to the claims;
(ii) finalizing the accident and/or my claims;
(iii) settling out and/or dealing with my obligations or responding to any enquiries by me;
(iv) administering my claims including the making of correspondence, statements, affidavits, reports or findings to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of correspondence packages; and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, respectively the "Purposes";
(b) all Insurers who have insured my vehicle involved in this accident and the Insurers' Lawyer/firm, workshop recruited to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/firm), which may be used outside of Singapore, for one or more of the above Purposes.

27/07/17 12:25
Insured Person's Signature/ Date & Time

27/07/17 12:25
Driver's Signature/ Date & Time

Thomas Goh (S202890)
Customs & Excise Executive
Motor Service Centre
Witnessed by Recovery Centre Personnel

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident

My vehicle was stationary as the Traffic light was red. Suddenly, Vehicle B hit me at the back of my vehicle.

Declaration

I hereby declare that foregoing particulars are true in every respect.




7/27/2017 17:35

Police Officer's Signature / Date & Time



Police Officer's Signature / Date & Time



Thomas Chan (5096890)
Customer Care Executive
Motor Service Centre

Authorized by Reporting Party's Personal

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Nov 2017 Edit Reg		14 Nov 2017 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Lim Chee Hian (Lin ZhiXian) , ID: S7523229B									
Main Claimant: A&L LEASING PRIVATE LIMITED , Co. Reg. No.: 201026256R									
Vehicle Reg. No.: YM6981P		Date of Loss: 26/07/2017 07:00 - :59 [120 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6168014398SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLB9248R		Policy No. (Claimant):							
		Excess:							
Repairer: A&i Motors (HQ) No. 11 Mandai Estate #05-09 Eldix, 729908 Mandai - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/11/2017]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (15/11/2017): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YM6981P (6168014398SG)**
[SLB9248R]
TP
A&L LEASING PRIVATE LIMITED
Jul 26 2017 7:00AM
[Lim Chee Hian (Lin ZhiXian)]
A&I Motors

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Photos/Images										3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	06/04/18 16:26	Odometer Reading								Load JPG	
2	06/04/18 16:26	Chassis Number								Load JPG	
3	06/04/18 16:26	General View								Load JPG	
4	06/04/18 16:26	General View								Load JPG	
5	06/04/18 16:26	General View								Load JPG	
6	06/04/18 16:26	General View								Load JPG	
7	06/04/18 16:26	General View								Load JPG	
8	06/04/18 16:26	General View								Load JPG	
9	06/04/18 16:26	General View								Load JPG	
10	06/04/18 16:26	General View								Load JPG	
11	06/04/18 16:26	General View								Load JPG	
12	06/04/18 16:26	General View								Load JPG	
13	06/04/18 16:26	General View								Load JPG	
14	06/04/18 16:26	General View								Load JPG	
15	06/04/18 16:26	General View								Load JPG	
16	06/04/18 16:26	General View								Load JPG	
17	06/04/18 16:26	General View								Load JPG	
18	06/04/18 16:26	General View								Load JPG	
19	06/04/18 16:26	General View								Load JPG	
20	06/04/18 16:26	General View								Load JPG	
21	06/04/18 16:26	General View								Load JPG	
22	06/04/18 16:26	General View								Load JPG	
23	06/04/18 16:26	General View								Load JPG	
24	06/04/18 16:26	General View								Load JPG	
25	06/04/18 16:26	General View								Load JPG	
26	06/04/18 16:26	General View								Load JPG	
27	06/04/18 16:26	Reinspection Photo								Load JPG	
28	06/04/18 16:26	Reinspection Photo								Load JPG	
29	06/04/18 16:26	Reinspection Photo								Load JPG	
30	06/04/18 16:26	Reinspection Photo								Load JPG	
31	06/04/18 16:26	Reinspection Photo								Load JPG	
32	06/04/18 16:26	Reinspection Photo								Load JPG	
33	06/04/18 16:29	Photo After Spray								Load JPG	
34	06/04/18 16:29	Photo After Spray								Load JPG	
35	06/04/18 16:29	Photo After Spray								Load JPG	
36	06/04/18 16:29	Photo After Spray								Load JPG	
37	06/04/18 16:29	Photo After Spray								Load JPG	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/04/18 16:29	Photo After Spray	 Load JPG	☒
39	06/04/18 16:29	Photo After Spray	 Load JPG	☒
40	06/04/18 16:29	Photo After Spray	 Load JPG	☒
41	06/04/18 16:29	Photo After Spray	 Load JPG	☒
42	06/04/18 16:29	Photo After Spray	 Load JPG	☒
43	06/04/18 16:29	Photo After Spray	 Load JPG	☒
44	06/04/18 16:29	Photo After Spray	 Load JPG	☒
45	06/04/18 16:29	Photo After Spray	 Load JPG	☒
46	06/04/18 16:29	Photo After Spray	 Load JPG	☒
47	06/04/18 16:29	Photo After Spray	 Load JPG	☒
48	06/04/18 16:29	Photo After Spray	 Load JPG	☒
49	06/04/18 16:29	Photo After Spray	 Load JPG	☒
50	06/04/18 16:29	Photo After Spray	 Load JPG	☒
51	06/04/18 16:29	Photo After Spray	 Load JPG	☒
52	06/04/18 16:29	Photo After Spray	 Load JPG	☒
53	06/04/18 16:29	Photo After Spray	 Load JPG	☒
54	06/04/18 16:29	Photo After Spray	 Load JPG	☒
55	06/04/18 16:29	Photo After Spray	 Load JPG	☒
56	06/04/18 16:29	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/11/17 09:23	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17021728/R1BE2
 Date: 10/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
 Claimant Vehicle No: YM6981P Insured Vehicle No: SLB9248R
 Date of Loss: 26/07/2017 Nature of Claim: TP Claim No: 6168014398SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YM6981P**
 Make & Model: MITSUBISHI FE83BE6SRDEA, 3.0 D (A)
 Reg. Date: 18/07/2007 (Man. Year: 2007) Engine No: 4M42A42790
 Colour: White Chassis No: FE83BEA10130
 Engine Capacity: 2977 cc Odometer: 284472 km
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 7.00-16 Rear Tyre Size: 195 R14C (D)
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 6/6 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 6/6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/11/2017
 Date Inspected: 23/11/2017 Inspected At: A&I Motors (HQ)
 No. 11 Mandai Estate #05-09 Eldix
 Singapore 729908
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Damaged	0.00 F	*- F
2	1		*REAR NUMBER PLATE BRACKET	Bent	0.00 F	*- F
3	1		*REAR NUMBER PLATE LAMP	Cut	0.00 F	*- F
4	1		*REAR BUMPER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*REAR BUMPER STEP PANEL	Dented	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
8	1		*REAR LH TAILLAMP PANEL	Bent	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP PANEL	Bent	0.00 F	*- F
11	1		*REAR LH DOOR LOCK	Dented	0.00 F	*- F
12	1		*REAR RH DOOR LOCK	Dented	0.00 F	*- F
13	1		*REAR STEPER	Bent	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >