

ASS. REF. BY:

REF:

OS/EG17021735 /Tlg

Special Instruction

call only vehicle not at workshop, call only

Surveyor: Tauhin

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of EGT

Date/Time: 13/11/17 @ 6:06pm

Estimated Cost:

Bill to:

OD-TP-WS-TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

GBD 9025A

Insured

GBF2442P

at Workshop m/s

Goldbell Engineering (Pvt) Ltd

142

88/6-2798

of

Bilik Panduan Loop Ind. Est. # 01-12/128230

Policy No:

Claim No.

GBF2442P/SE/p

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A. 04/11/2017

CA / REV / REP. / REV 24 HRS

1 up 2

20.11.2017 @ 3pm-4pm

H.G.D. Erdemeneh

Date/Time: 10.06am

14.11.2017

Person Contacted

Andy Ooi

Vehicle IN OUT

[illegible]

Tanpin

EGI

Date 20/11/17

GBD 9025A

Reg 2011 April

Estimated Cost

CD (TP) NS (TP) RES CD RES (EVA) (NV) (V)

To inspect vehicle GBD 9025A

at Workshop Goldbell Engineering

of Blk k pandan hoop Ind. Est # 01-12, 128 230

Insured

Policy No

Claims No

Sum Insured

Excess


Offerts Record

Make of Veh

3pm - 4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value

ICAD Accident Report Consistent? : Yes or No

GIA / PP Seen Consistent? : Yes or No

Est. Repairs days Res? Yes or No

Lump Sum \$3,000 Yes or No

CA / REV / REP / 24 HRS

lup

Date Person Contacted

Venue IN/OUT

Truck / Trailer

Make Nissan Urvan

2453

Colour White

Insured Std N/A

St Reading 2388 77

Insured Std N/A

Eng No

C No

SNIT64E2570790491

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt

Brake: Inorder / Jammed / Leaked / Burnt

Mod: N/A S Rim / STD A Rim

Tyre Size F

R

195/115

ES / RUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI

TOYO / YOKO

Front

R Bal

6

L Bal

6

D.O.A.

Rear

R Bal

6

L Bal

6

D.O.A.

20/11/17 C/SES

Survey held at

(Goldbell) Eng Pandan

Des. of Damages Fr Rear O.S. N.S. U.C. Rooftop

Fvt o/s

The U.C. / Chassis frame Body Structure affected due to collision

Date Time Action Instruction

21/11/17 email preli to Per Li.

16/1/2018 - confirmed Lumpsum \$1,000.00

Due Time For Report



Prelim. Report

Final Report

Days Of Repair

3 days

Resurvey No. of Trips

Survey Fee

Due Time For Report

16/1/2018 - typist

Add Fee:



Preli Fee

Final Fee


Travel Fee

Other Fee

Receipt Printed

T/P

Receipt Signed



250

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17021735/T1gb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 14-11-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 2442P	Veh. Inspected	GBD 9025A
Policy No.		Coverage (\$)	0.00
Claim No.	GBF2442P/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	14/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/11/2017	Inspection Date
Survey held at	BLK K PANDAN LOOP IND EST #01-12	
Repairer	GOLDBELL LEASING PTE LTD	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBF2442P/SE/pl

Date: 21-10-2017

Our Ref: CS/EG117021735/T1gb

The Motor Claims Department
Ergo Insurance Pte Ltd

Without Prejudice

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBD 9025A.


We thank you for the instruction on 13-11-2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20-11-2017 at the premises of M/s GOLDBELL LEASING and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,558.08</u>
Revised Estimate Amount	: S\$ <u>1,281.71</u>
"Check" Items Amount	: S\$ <u>331.94</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/ Present Status:

Damages Consistent.
03 days of repair.

Yours faithfully

Mohamed Taufikh
Automotive Assessor

Reference No. : CS/EGL/17021735/T/gb
Policy Type: OD / TP / TP RES / TL / EVA

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

<u>Y-Date</u>	<u>N-Date</u>
/	
//	
//	
/	
/	
//	
//	
/	
/	
//	
/	
.	
/	

(1) Assignment Form

C	Vehicle No			
C	Regn Month/Year			
N	Vehicle Type			
N	Make & Model			
C	Engine Capacity. (C.C)			
N	Colour			
C	Odometer. (Sp.Reading)			
C	Chassis No			
N	General Condition			
N	Steering			
N	Brake			
N	Modification (Modi)			
C	Tyre Size			
N	Tyre Make			
C	Tyre Balance			
C	Date of Inspection			
N	Survey held			
N	Des.of Damages			

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

*C: Critical *N: Non-Critical

Norrita (LKKAuto)

From: Norrita (LKKAuto)
Sent: Tuesday, 16 January 2018 3:41 PM
To: 'andyooilk@goldbell.com.sg'
Cc: SUR
Subject: Re : Confirmed Finalised Amount for Veh - GBD 9025A

Dear Andy

Confirmed Finalised Lump sum repair at \$1,000.00 before GST with 3 working days.

Thank you

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Norrita (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 16 January 2018 3:01 PM (Taufikh.)
To: SUR
Subject: FW: PLEASE CONFIRMED FINALISED AMOUNT -GBD9025A
Attachments: GBD9025A-FINALISED.pdf; CIMG3418.JPG; CIMG3419.JPG; CIMG3420.JPG; CIMG3421.JPG; CIMG3422.JPG; CIMG3423.JPG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Andy Ooi Lee Keong [mailto:AndyOoiLK@goldbell.com.sg]
Sent: Tuesday, 16 January 2018 2:53 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: PLEASE CONFIRMED FINALISED AMOUNT -GBD9025A

Hi Taufikh,

Lump sum repair at \$1000.00 b4 GST with 3 working days .

Thank & regards



GOLDBELL
ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6458 9596 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230

Sales | Leasing | Financing | Insurance | Fuel Card | Advanced Fleet Management System

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Tuesday, 21 November, 2017 12:31 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBF2442P / TP : GBD9025A/LKK / DOA : 04.11.2017
Attachments: GBD 9025A.pdf

Dear Pei Li,

Enclosed herewith preliminary advise of GBD 9025A.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 14 November, 2017 10:10 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBF2442P / TP : GBD9025A/LKK / DOA : 04.11.2017

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 13 November, 2017 6:06 PM
To: admin-d@lkkauto.com
Subject: OI : GBF2442P / TP : GBD9025A/LKK / DOA : 04.11.2017

Dear Catherine,

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 13 November, 2017 6:06 PM
To: admin-d@lkkauto.com
Subject: OI : GBF2442P / TP : GBD9025A/LKK / DOA : 04.11.2017
Attachments: GBD9025A - ESTIMATE n SAS.pdf; GBD9025A - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **GOLDBELL ENGINEERING PTE LTD (PANDAN)**.

ADDRESS : BLK K PANDAN LOOP INDUSTRIAL ESTATE
#01-12
SINGAPORE 128230

PERSON TO CONTACT : ANDY OOI @ 6458 9596 / 8816 2798

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most
affordable prices available in the market.

ERGO
TravelProtect

Your Global Safety Net

TravelProtect is underwritten by ERGO Insurance plc Ltd

 **BUY NOW**

ERGO

Date: 13.11.2017
Our Reference: GBF 2442P/SE/pl
Your Reference: GBD 9025A

Sent via Fax

or

Email

AndyOoiLK@goldbell.com.sg

To: GOLDBELL ENGINEERING PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBD 9025A
Insured's Vehicle: GBF 2442P
Date Of Accident: 04.11.2017


We acknowledge receipt of your request for PRS on: 13.11.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* Lkk Auto Consultants Pte Ltd

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2017 16:11
Date Of Accident	04/11/2017 08:30
Exact Location Of Accident	CLEMENTI WEST AVE 2 BLK 722 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD9025A
Insured/Policyholder	
Name Of Registered Owner	PC LEASING
Co Reg No	52986061M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94288126

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN-2.5 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092619527
Cover Note Number	

Driver

Name of Driver	LAM PAK YEAN
NRIC No	F7173476P
Date Of Birth	05/08/1972
Occupation	OUTDOOR
Date Of Driving Pass	17/05/2003
Driving Experience	14 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLANS

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF2442P
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

PC LEASING



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

Accident scene: Clementi West ^{St 2} car park:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at Blk 722 HDB Car park
at Clementi West St 2.

After parking my van, a vehicle No GBF 2442 P
hit on to the right front side of my vehicle
while my making a left turn in front of my
vehicle.

DECLARATION

DECLARATION
PC LEASING
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



GOLDBELL

GOLDBELL

ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

* 10 Tadas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 10/11/2017

TO : ERGO INSURANCE

ATTN :

OFFICE / MOBILE :

EMAIL ADDRESS :

FROM : GOLDBELL PANDAN

ATTN : ANDY OOI

OFFICE / MOBILE : 88162798

FAX NO. :

VEHICLE NO. : GBD9025A

MODEL NO. : NISSAN MICROBUS 3.0 4DR

CHASSIS NO. : JN1TG4E25Z0790491

ENGINE NO. : ZD30279041K

REG. DATE : 20/4/2011

REF. NO. : GBE/SVC/SALES-

D.O.A. : 4/11/2017


POLICY NO. : 5092619527

CLAIM TYPE : TP CLAIM - ERGO INSURANCE

WORKSHOP : BLK K PANDAN LOOP IND EST
#01-12 SINGAPORE 128230

S/N	PART NO.	DESCRIPTION	QUANTITY	LIST PRICE
1		FRONT BUMPER <i>CR</i>	1	\$ 654.60 ✓
2		FRONT BUMPER SIDE LAMP RH <i>ms</i>	1	\$ 90.70 ✓
3		FRONT CORNER PANEL RH <i>RP</i>	1	\$ 535.50 X
4		HEADLAMP RH <i>7 m</i>	1	\$ 474.20 X

SUB-TOTAL :	\$ 1,754.40
PART LESS-30% :	\$ 526.32
BALANCE :	\$ 1,228.08



bizSAFE
S T R



ACCREDITED
CERTIFICATION
BODY

Cert No: 05-1999-04
Member of the IAF MLA for QMS



Cert No: AJA01/3054

GOLDBELL

GOLDBELL

ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

SPECIAL-NETT ITEMS

1	FRONT DOOR COMPANY ADDRESS STICKER RH	1	\$	30.00 ✓
---	---------------------------------------	---	----	---------

PARTS TOTAL :	\$	1,258.08
---------------	----	----------

LABOUR CHARGES

1 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	1	\$	550.00
--	---	----	--------

2 TO CHECK & RECTIFY WIRING FAULT	1	\$	100.00
-----------------------------------	---	----	--------

3 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC, AFFECTED AREAS	1	\$	650.00
--	---	----	--------

LABOUR TOTAL :	\$	1,300.00
----------------	----	----------

GRAND TOTAL :	\$	2,558.08 SD
---------------	----	-------------

PREPARED BY : ANDY OOI

DATE / TIME : 20/11/12 @ 1550

SURVEYOR : Tanpin

MOBILE NO. : 97495740

OFFICE FAX NO. :

EMAIL ADDRESS : suv@lkkands.com / tanpin@lkkands.com

[Signature]
22/11/12

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 3

REMARKS :

bizSAFE
S T R



Certificate No: AJA(S)01/Q1243

Certificate No: AJA01/3054

GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

SPECIAL-NETT ITEMS

1	FRONT DOOR COMPANY ADDRESS STICKER RH	1	\$	30.00
---	---------------------------------------	---	----	-------

PARTS TOTAL :

\$ 1,258.08

LABOUR CHARGES

1	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	1	\$	550.00
---	--	---	----	--------

2	TO CHECK & RECTIFY WIRING FAULT	1	\$	100.00
---	---------------------------------	---	----	--------

3	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC, AFFECTED AREAS	1	\$	650.00
---	--	---	----	--------

LABOUR TOTAL :

\$ 1,300.00

GRAND TOTAL :

\$ 2,558.08

PREPARED BY : ANDY OOI

DATE / TIME : 20/11/2015 1550

SURVEYOR : Tanjun

MOBILE NO. : 92445744

OFFICE FAX NO. :

EMAIL ADDRESS : suv@lkhant.com / tanjun@lkhant.com

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 3

REMARKS :

FINALISED

1281.70 - 20%

45 1000.00

bizSAFE
S T A R



Certificate No: AJA/SJ01/Q1243

Certificate No: AJA01/0054

GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 10/11/2017

TO : ERGO INSURANCE

ATTN :

OFFICE / MOBILE :

EMAIL ADDRESS :

FROM : GOLDBELL PANDAN

ATTN : ANDY OOI

OFFICE / MOBILE : 88162798

FAX NO. :

VEHICLE NO. : GBD9025A

MODEL NO. : NISSAN MICROBUS 3.0 4DR

CHASSIS NO. : JN1TG4E25Z0790491

ENGINE NO. : ZD30279041K

REG. DATE : 20/4/2011

REF. NO. : GBE/SVC/SALES-

D.O.A. : 4/11/2017

POLICY NO. : 5092619527

CLAIM TYPE : TP CLAIM - ERGO INSURANCE

WORKSHOP : BLK K PANDAN LOOP IND EST
#01-12 SINGAPORE 128230

<u>S/N</u>	<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>QUANTITY</u>	<u>LIST PRICE</u>
1		FRONT BUMPER <i>err</i>	1	\$ 654.60
2		FRONT BUMPER SIDE LAMP RH <i>m.s</i>	1	\$ 90.70
3		FRONT CORNER PANEL RH <i>RP</i>	1	\$ 535.50
4		HEADLAMP RH <i>?</i>	1	\$ 474.20
SUB-TOTAL :				\$ 1,754.40
PART LESS-30% :				\$ 526.32
BALANCE :				\$ 1,228.08

745-30-30%

= 521-70

bizSAFE
S T A R



Certificate No: AJA(S)1/Q1243

Certificate No: AJA(S)1/Q1243




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17021735/T1nbe2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 17-01-2018		
Code : EGI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 2442P	Veh. Inspected	GBD 9025A	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBF2442P/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	13/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JN1TG4E25Z0790491	Colour	WHITE	
Odometer	238877	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/11/2017	Inspection Date	20/11/2017	
Survey held at	BLK K PANDAN LOOP IND EST #01-12			
Repairer	GOLDBELL LEASING PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 9025A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	654.60	654.60
1	FRONT BUMPER SIDE LAMP RH	MISSING	90.70	90.70
1	FRONT CORNER PANEL RH	TO REPAIR SEE LABOUR	535.50	-
1	HEADLAMP RH	NOT NECESSARY	474.20	-
	LESS 30% DISCOUNT		-526.50	-223.59
			1,228.50	521.71
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMPANY ADDRESS STICKER RH (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL RH.		550.00	300.00
	TO CHECK & RECTIFY WIRING FAULT.		100.00	30.00
	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC, AFFECTED AREAS.		650.00	400.00
			1,300.00	730.00
	GRAND TOTAL		2,558.50	1,281.71
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CS/EGI17021735/T1nbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.