

12/03/2001

ASS' REC BY

REF: CS/FCI7021746 / Arb<sup>N2</sup>

Special Instruction

Surveyor:

Adrian

ASSIGNMENT (Office)

CWS

May Chua

of FCI

Date/Time 9.26am @ 14/11/17

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 5647U

Insured: SHD 6990L

at Workshop m/s

MG Solution

Tel:

of 23 kaki Bukit Ave 4 #02-03

Policy No:

Claim No:

D17010559MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A 12/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

1 wp

H.O.D. Endorsement

Date/Time:

9.35am @ 14/11/17

Person Contacted:

Ms. Wong

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SJL 5647U-CC4 / AXA 17005654 / Ahb392-D.O.A: 16/03/2017

SHD 6990L-X

REF: FCI

## ASSIGNMENT

02/12/08

From:

Date: 14/11/17

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 5647 U

at Workshop m/s MG Solution

of 23 kaki Bkt Ave 4 # 02-03

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJL5647U. Yr Regn: 2008 Dec

Type: ☒ M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1799

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

201771

T/Radio: Insured / Std / NI / NA

Eng/No:

JHMFD16309S201076.

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 225/45 R17.

R: 225/45 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/11/17.

Survey held at

MG Solution.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP / 1st Cap.

19/12

Admion confirmed LS RHTDOP with repainer. (Red. 7166.75, 612.)

MV: 22.5K

PV: 14.5K.

Nett: 8K.

RECEIVED 14/12/2017

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 4400)

170 + 15

50

50

63

348

# Survey Department Check List (Case Handler)

Reference No. : CS/FC217021746/Arb.  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( Catherine ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

|   |                                       | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No.                         | ✓      |        |        |        |
| C | Customer Code                         | ✓      |        |        |        |
| N | Assign From                           | ✓      |        |        |        |
| C | Assign Date                           | ✓      |        |        |        |
| C | Veh No (Inspected)                    | ✓      |        |        |        |
| C | Veh No (Insured)                      | ✓      |        |        |        |
| C | D.O.A                                 | ✓      |        |        |        |
| C | Policy No                             |        |        |        |        |
| C | Claim No                              | ✓      |        |        |        |
| C | Insurance Authorisation (CA /REV/REP) |        |        |        |        |
| C | Report Type                           | ✓      |        |        |        |
| C | Weekend Charges                       |        |        |        |        |
| N | Survey held at/Repairer               | ✓      |        |        |        |
| C | Excess                                |        |        |        |        |

**Surveyor** ( Adrian ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

|   |                        |   |  |  |  |
|---|------------------------|---|--|--|--|
| C | Vehicle No             | ✓ |  |  |  |
| C | Regn Month/Year        | ✓ |  |  |  |
| N | Vehicle Type           | ✓ |  |  |  |
| N | Make & Model           | ✓ |  |  |  |
| C | Engine Capacity. (C.C) | ✓ |  |  |  |
| N | Colour                 | ✓ |  |  |  |
| C | Odometer. (Sp.Reading) | ✓ |  |  |  |
| C | Chassis No             | ✓ |  |  |  |
| N | General Condition      | ✓ |  |  |  |
| N | Steering               | ✓ |  |  |  |
| N | Brake                  | ✓ |  |  |  |
| N | Modification (Modi)    | ✓ |  |  |  |
| C | Tyre Size              | ✓ |  |  |  |
| N | Tyre Make              | ✓ |  |  |  |
| C | Tyre Balance           | ✓ |  |  |  |
| C | Date of Inspection     | ✓ |  |  |  |
| N | Survey held            | ✓ |  |  |  |
| N | Des.of Damages         | ✓ |  |  |  |

## (2) System - (Views/Merimen)

|   |                                      |   |  |  |  |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ |  |  |  |
|---|--------------------------------------|---|--|--|--|

## (3) Workshop Estimate/Assignment Form

|   |                                               |   |  |  |  |
|---|-----------------------------------------------|---|--|--|--|
| N | ALL Parts condition                           | ✓ |  |  |  |
| C | Market Value for OD cases                     |   |  |  |  |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) |   |  |  |  |
| C | Days of repair                                | ✓ |  |  |  |
| C | Finalised Amount                              | ✓ |  |  |  |
| C | Re-inspection Cases to Finalize within 5 Days |   |  |  |  |

## (4) System - (Views/Merimen)

|   |                         |   |  |  |  |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ |  |  |  |
|---|-------------------------|---|--|--|--|

Check By: Catherine 19/05/14  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                    |                          |            |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|--------------------------|------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                            |                                                                                                                    | Ref : CS/FCI17021746/Arb |            |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                                                                    | Date : 14-11-2017        |            |
|                                                                                                                                        |                                                                                                                    | Code : FCI2              |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                    |                          |            |
| Insured Veh.                                                                                                                           | SHD 6990L                                                                                                          | Veh. Inspected           | SJL 5647U  |
| Policy No.                                                                                                                             |                                                                                                                    | Coverage (\$)            | 0.00       |
| Claim No.                                                                                                                              | D17010559MFSH                                                                                                      | Excess (\$)              | 0.00       |
| Assign From                                                                                                                            | CWS (MAY CHUA)                                                                                                     | Assign Date              | 14/11/2017 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                    |                          |            |
| Make & Model                                                                                                                           |                                                                                                                    | c.c                      | 0          |
| Engine No.                                                                                                                             | HIDDEN                                                                                                             | Year of Reg.             |            |
| Chassis No.                                                                                                                            |                                                                                                                    | Colour                   |            |
| Odometer                                                                                                                               | -                                                                                                                  | Steering                 |            |
| Brakes                                                                                                                                 |                                                                                                                    | Modification             |            |
| General                                                                                                                                |                                                                                                                    |                          |            |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                    |                          |            |
|                                                                                                                                        | Size                                                                                                               | Make                     | Balance    |
| R/H Front Tyre                                                                                                                         |                                                                                                                    |                          | mm         |
| L/H Front Tyre                                                                                                                         |                                                                                                                    |                          | mm         |
| R/H Rear Tyre                                                                                                                          |                                                                                                                    |                          | mm         |
| L/H Rear Tyre                                                                                                                          |                                                                                                                    |                          | mm         |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                    |                          |            |
|                                                                                                                                        |                                                                                                                    |                          |            |
| <b>5. General Information</b>                                                                                                          |                                                                                                                    |                          |            |
| Accident Date                                                                                                                          | 12/11/2017                                                                                                         | Inspection Date          | 14/11/2017 |
| Survey held at                                                                                                                         | MG SOLUTION PTE LTD<br>23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                          |            |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                    |                          |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                    |                          |            |

**MOTOR SURVEY ASSIGNMENT**

|                           |                                                 |                                      |
|---------------------------|-------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 13-11-2017                                      | <b>Our Ref No.</b> D17010559MFSH     |
| <b>Accident Date</b>      | 12-11-2017                                      | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHD6990L                                        | <b>Third Party Vehicle.</b> SJL5647U |
| <b>Survey Location</b>    | 23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03 |                                      |
| <b>Contact Person.</b>    | SU WONG                                         |                                      |
| <b>Contact No.</b>        | 62431373/ 0                                     | <b>Fax No.</b> 62431376              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:       |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                    |                                      |
| <b>Contact Person</b>     | NA                                              | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                              |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                     |                                |
|--------------------------|---------------------|--------------------------------|
| <b>Cc : Workshop</b>     | MG SOLUTION PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                  | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | MAY CHUA            |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230156)



PRI Documents



Close



## PRI Header Details

|                   |                                                   |                                   |                                                                                                                                  |                      |              |
|-------------------|---------------------------------------------------|-----------------------------------|----------------------------------------------------------------------------------------------------------------------------------|----------------------|--------------|
| Claim No          | D17010559MFSH                                     | Policy No                         | D-15072701MFSH                                                                                                                   | Claimant S.No & Name | 1 & MG SOLU7 |
| Workshop Name     | MG SOLUTION PTE LTD<br>(Contact Person : SU WONG) | Survey Location & Contact Details | 23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03<br>Mobile: 0 , Phone: 62431373 , Fax: 62431376<br>EmailId: MG3SOLUTION@GMAIL.COM |                      |              |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                      | Instructions To Surveyor          | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:                                                                                        |                      |              |
| Insured Name      | COMFORT TRANSPORTATION PTE LTD                    | Insured Vehicle No                | SHD6990L                                                                                                                         | TP Vehicle No        | SJL5647U     |
| PRI Recieved Date | 13-11-2017 09:40:17 PM                            | Surveyor Appointed Date           | 14-11-2017 09:25:14 AM                                                                                                           | Surveyor Accept Date | 14-11-2017 1 |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 14-11-2017 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                      |                |                       |         |                      |
|-----------|----------------------|----------------|-----------------------|---------|----------------------|
| Make      | Please Select Make ▼ | Model          | Please Select Model ▼ | Year    | Select Year ▼        |
| Chasis No | <input type="text"/> | Engine No      | <input type="text"/>  | Mileage | <input type="text"/> |
| Color     | <input type="text"/> | Cubic Capacity | <input type="text"/>  |         |                      |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                          |
|-------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>    |                          |
| Owner ID Type                       | Company                  |
| Owner ID                            | 9223D                    |
| <b>Vehicle Details</b>              |                          |
| Vehicle No.                         | SJL5647U                 |
| Vehicle to be Exported              | Yes                      |
| Intended De-registration Date       | 14 Nov 2017              |
| Vehicle Make                        | HONDA                    |
| Vehicle Model                       | HONDA CIVIC 1.8L 5AT     |
| Primary Colour                      | White                    |
| Manufacturing Year                  | 2008                     |
| Engine No.                          | R18A14006037             |
| Chassis No.                         | JHMF16309S201076         |
| Maximum Power Output                | 103.0 kW (138 bhp)       |
| Open Market Value                   | \$24,871.00              |
| Original Registration Date          | 02 Dec 2008              |
| First Registration Date             | 02 Dec 2008              |
| Transfer Count                      | 3                        |
| Actual ARF Paid                     | \$24,871.00              |
| <b>Intended PARF Rebate Details</b> |                          |
| PARF Eligibility                    | Yes                      |
| PARF Eligibility Expiry Date        | 01 Dec 2018              |
| PARF Rebate Amount                  | \$13,679.00              |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date                     | 01 Dec 2018              |
| COE Category                        | B - Car (1601cc & above) |
| COE Period(Years)                   | 10                       |
| QP Paid                             | \$8,301.00               |
| COE Rebate Amount                   | \$869.00                 |
| <b>Total Rebate Amount</b>          | <b>\$14,548.00</b>       |

The information contained herein is correct as at 14 Nov 2017

OK





**Honda Civic 1.8A VTI-S**      **\$21,800**      **\$10,310 /yr**      **14-Nov-2008**      **1,799 cc**      -      **Sedan**      **Available**

\$0 Down Payment! Free Road Tax, Insurance & Unlimited! High Trade-In! Powerful Yet Fuel Efficient, Allow The All Time Favorite Honda Civic To Convince You With Its Driving Performance And Reliability....

Dickson Automobile

Posted: 01-Nov-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic Type R 2.0M 3DR**      **\$29,000**      **\$12,840 /yr**      **19-Nov-2008**      **1,998 cc**      **160,000 km**      **Sports**      **Available**

Down Payment \$3k, Gruppe M Carbon Fiber Open Pod Air Filter, Accident Free, Excellent Condition Interior And Exterior, No Gimmicks, Low Down Payment, Balloon Scheme Available, Bank/In House Loan Avail...

Posted: 08-Nov-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic 1.8A VTI-S**      **\$27,800**      **\$15,120 /yr**      **21-Nov-2008**      **1,799 cc**      -      **Sedan**      **Available**

Reliable And Fuel Efficient Sedan! Popular Model For Honda. Only \$2,780 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package W...

Classic Credit Pte Ltd

Posted: 18-Oct-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic 1.8A VTI-S GL**      **\$22,800**      **\$12,300 /yr**      **21-Nov-2008**      **1,799 cc**      **82,000 km**      **Sedan**      **Available**

Ex OPC Converted. Low Mileage. One And Only In The Market! Ment To Be Pampered And Renew Another 10 Years! View To Appreciate! Facelift Model With Octagon Tail Lamps! Call For Appointment Before It's ...

Posted: 22-Sep-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic 1.6A VTI**      **\$20,288**      **\$9,910 /yr**      **25-Nov-2008**      **1,595 cc**      **116,000 km**      **Sedan**      **Available**

Regular Servicing Done At 115,000km, Car Is Maintenance Free, Ideal For COE Renewal, Well Maintained By Fussy Owner. No Repairs Needed, Low Petrol Consumption Of 11km/L Based On City Driving. Call For...

Posted: 09-Nov-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic Hybrid 1.3A**      **\$20,800**      **\$10,150 /yr**      **09-Dec-2008**      **1,339 cc**      -      **Sedan**      **Available**

**Fuel Type:** Petrol-Electric

Only 1 Careful Owner, New Facelift Model, Very Well Kept Condition, Accident Free! High PARF Value, Fuel Efficient And Yet Low On Road Tax. Call Now For Viewing.

Posted: 10-Nov-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic Type R 2.0M**      **\$37,000**      **\$19,920 /yr**      **09-Dec-2008**      **1,998 cc**      -      **Sports**      **Available**

No Modifications Done, Full Stock Maintained Engine Producing 225Bhp, Stock Condition Interior, Enthusiast Owner. Never Track, Daily Driven But Never Abused. Ideal For COE Renewal. Do Text Me For Gene...

Posted: 09-Oct-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic 1.8A VTI-S**      **\$25,800**      **\$11,810 /yr**      **13-Dec-2008**      **1,799 cc**      **178,000 km**      **Sedan**      **Available**

1.8L (A), High OMV. Leather Seats, Changed Tires And Rims, SRS Airbags, Regular Servicing. Original HID Headlight Kit. DVD Player, Strictly No Dealers!

Posted: 13-Nov-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic 2.0A Si**      **\$33,800**      **\$18,150 /yr**      **13-Dec-2008**      **1,998 cc**      **121,000 km**      **Sedan**      **Available**

Best Selling 2.0 Auto Civic. Beautiful Black. Fully Original Factory Condition. Well Service And Maintain. Easy Handling And Spacious Interior. Best Buy Guarantee View By Appointment Only.

Posted: 09-Oct-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic 1.8A VTI-S**      **\$25,800**      **\$11,250 /yr**      **13-Dec-2008**      **1,799 cc**      **155,000 km**      **Sedan**      **Available**

New Arrival! Most Valued Buy! Beautiful Brown Unit With Original Condition! Peace Of Mind! Serviced Regularly. Accident Free! Seller Selling Due To Upgrading. One Of The Most Popular And Reliable Seda...

Posted: 02-Oct-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic Type R 2.0M**      **\$41,888**      **\$26,370 /yr**      **15-Dec-2008**      **1,998 cc**      **123,000 km**      **Sports**      **Available**

J's Exhaust With Certification, Volks Racing Rims With 4 Pieces New P54 Tyre, Alcon BBK, Open Pod, Carbon Fibre Bonnet, Supertech Retainer, New Engine Mounting, Hondata ECU, New API Coilover And Strai...

Posted: 13-Nov-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)



**Honda Civic 1.8A VTI-S**      **\$25,800**      **\$11,520 /yr**      **15-Dec-2008**      **1,799 cc**      **110,000 km**      **Sedan**      **Available**

Premium Dealer 2013 To 2017! 1 Owner Unit, \$2000 Down Payment, Lowest Depreciation, Excellent Condition, Very Well Kept, In House, Balloon Scheme And Bank Loan All Available! Call/Sms/Whatsapp Now For...

Posted: 12-Nov-2017    Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

[Details](#)

**Honda Civic 1.8A VTI-S**      **\$23,800**      **\$9,960 /yr**      **16-Dec-2008**      **1,799 cc**      -      **Sedan**      **Available**



# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

|                                 |                                   |          |                         |
|---------------------------------|-----------------------------------|----------|-------------------------|
| TO                              | : FIRST CAPITAL INSURANCE LIMITED | DATE     | : 13-Nov-17             |
| ATTENTION                       | : MOTOR CLAIMS DEPT               | JOB TYPE | : T/P CLAIM             |
| ESTIMATE REPORT                 | :                                 |          |                         |
| <u>VEHICLE DETAILS</u>          |                                   |          |                         |
| VEHICLE NO                      | : SJL5647U                        |          |                         |
| MODEL                           | : HONDA CIVIC 1.8L                |          | <i>Twice</i>            |
| CHASSIS NO                      |                                   |          | <i>JHMF76309S201076</i> |
| <u>ACCIDENT DETAILS</u>         | DATE : 12-Nov-17                  |          |                         |
|                                 | TIME : 77:30HRS                   |          |                         |
| THIRD PARTY REQUESTOR / CONTACT | : JACK LI                         |          |                         |

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                | QTY | UNIT LIST PRICE | TOTAL LIST PRICE                |
|-----|--------------------------------------------|-----|-----------------|---------------------------------|
| 1   | BOOTLID <i>Beeked</i>                      | 1   | \$ 755.30       | \$ <del>755.30</del> <i>698</i> |
| 2   | BOOTLID LOGO <i>new</i>                    | 1   | \$ 82.00        | \$ <del>82.00</del> <i>48</i>   |
| 3   | BOOTLID INSULATOR <i>new</i>               | 1   | \$ 162.00       | \$ 162.00 <i>+</i>              |
| 4   | BOOTLID KEYLOCK <i>new</i>                 | 1   | \$ 135.00       | \$ 135.00 <i>+</i>              |
| 5   | BOOTLID HINGE <i>Not new</i>               | 2   | \$ 72.00        | \$ 144.00 <i>+</i>              |
| 6   | BOOTLID HINGE COVER <i>Not new</i>         | 2   | \$ 92.30        | \$ 184.60 <i>+</i>              |
| 7   | BOOTLID REFLECTOR <i>Not new</i>           | 2   | \$ 266.30       | \$ 532.60 <i>+</i>              |
| 8   | BOOTLID INNER STOPPER <i>new</i>           | 2   | \$ 35.80        | \$ 71.60 <i>+</i>               |
| 9   | BOOTLID LOCK <i>new</i>                    | 1   | \$ 211.30       | \$ 211.30 <i>+</i>              |
| 10  | BOOTLID LOCK CATCH <i>new</i>              | 1   | \$ 89.60        | \$ 89.60 <i>+</i>               |
| 11  | BOOTLID WEATHERSTRIP <i>new</i>            | 1   | \$ 155.30       | \$ 155.30 <i>+</i>              |
| 12  | REAR NUMBER PLATE LAMP <i>new</i>          | 2   | \$ 64.90        | \$ 129.80 <i>+</i>              |
| 13  | REAR NUMBER PLATE LAMP GARNISH <i>new</i>  | 1   | \$ 168.50       | \$ 168.50 <i>+</i>              |
| 14  | REAR BUMPER <i>Beeked</i>                  | 1   | \$ 688.90       | \$ 688.90 <i>+</i>              |
| 15  | REAR BUMPER SIDE RETAINER <i>new</i>       | 2   | \$ 62.50        | \$ <del>125.00</del> <i>64</i>  |
| 16  | REAR TAIL LAMP <i>combined</i>             | 2   | \$ 366.20       | \$ 732.40 <i>+</i>              |
| 17  | REAR TAIL LAMP PANEL <i>new</i>            | 2   | \$ 103.50       | \$ 207.00 <i>+</i>              |
| 18  | REAR TAIL LAMP LOWER BRACKET <i>Beeked</i> | 2   | \$ 62.00        | \$ <del>124.00</del> <i>24</i>  |

|    |                                          |   |             |                      |               |
|----|------------------------------------------|---|-------------|----------------------|---------------|
| 19 | REAR FENDER INNER TRIM LH <i>new bon</i> | 1 | \$ 189.20   | \$ 189.20            | +             |
| 20 | REAR FENDER AIR VENT DUCT <i>new</i>     | 2 | \$ 85.90    | \$ 171.80            | +             |
| 21 | REAR END PANEL <i>Rehnd</i>              | 1 | \$ 540.50   | \$ <del>540.50</del> | <i>300.80</i> |
| 22 | REAR END PANEL TOP GARNISH <i>Rehnd</i>  | 1 | \$ 138.60   | \$ 138.60            | -             |
| 23 | REAR FLOOR PANEL <i>Rpr</i>              | 1 | \$ 1,088.30 | \$ 1,088.30          | +             |
| 24 | REAR FLOOR PANEL TOP BOARD <i>Rehnd</i>  | 1 | \$ 322.30   | \$ <del>322.30</del> | ✓             |
| 25 | SPARE TYRE TOOL SPONGE <i>new</i>        | 1 | \$ 106.30   | \$ 106.30            | +             |
| 26 | REAR EXHAUST CHROME PIPE <i>Best</i>     | 1 | \$ 865.00   | \$ <del>865.00</del> | <i>614.20</i> |

4187

3349.60

TOTAL PRICE \$ 8,120.90

LESS 20% \$ 1,624.18

SUB TOTAL PRICE \$ 6,496.72

#### SPECIAL NETT ITEMS

| S/N | DESCRIPTION                                       | QTY | UNIT S/NETT | TOTAL S/NETT         |           |
|-----|---------------------------------------------------|-----|-------------|----------------------|-----------|
| 1   | REAR NUMBER PLATE <i>new</i>                      | 1   | \$ 50.00    | \$ 50.00             | +         |
| 2   | BOOTLID SEALANT <i>new</i>                        | 1   | \$ 60.00    | \$ 60.00             | +         |
| 3   | REAR BUMPER CLIP (SET) <i>new</i>                 | 1   | \$ 20.00    | \$ 20.00             | ✓         |
| 4   | TAILLAMP PANEL SEALANT <i>new</i>                 | 2   | \$ 60.00    | \$ 120.00            | +         |
| 5   | REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>     | 1   | \$ 20.00    | \$ 20.00             | -         |
| 6   | REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i> | 1   | \$ 20.00    | \$ <del>20.00</del>  | <i>10</i> |
| 7   | REAR END PANEL INSULATION SEAL <i>new</i>         | 1   | \$ 150.00   | \$ <del>150.00</del> | <i>60</i> |
| 8   | REAR FLOOR PANEL INSULATION SEAL <i>new</i>       | 1   | \$ 200.00   | \$ 200.00            | +         |
| 9   | REVERSE SENSOR <i>new</i>                         | 1   | \$ 220.00   | \$ 220.00            | -         |

330

TOTAL \$ 860.00

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

|    |                                                                 |                                       |            |  |
|----|-----------------------------------------------------------------|---------------------------------------|------------|--|
| 1  | PANEL BEATING, REMOVAL AND REPLACING PARTS                      | \$ 1,600.00                           | <i>800</i> |  |
| 2  | TO SPRAY PAINT AFFECTED AREA                                    | \$ 1,400.00                           | <i>800</i> |  |
| 3  | TUFF COAT                                                       | \$ 250.00                             | <i>60</i>  |  |
| 4  | WIRING CHECK                                                    | \$ 180.00                             | <i>30</i>  |  |
| 5  | REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO     | <i>Facilitate repair</i><br>\$ 180.00 | <i>60</i>  |  |
| 6  | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING            | \$ 80.00                              | <i>50</i>  |  |
| 7  | TRANSFER BOOTLID MECHANISM                                      | \$ 80.00                              | <i>1</i>   |  |
| 8  | CONDUCT WATER LEAKAGE TEST                                      | \$ 80.00                              | <i>1</i>   |  |
| 9  | REMOVE AND REFIX REAR EXHAUST PIPE                              | \$ 180.00                             | <i>80</i>  |  |
| 10 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET | \$ 180.00                             | <i>1</i>   |  |

memories to specification etc  
TOTAL

\$4,210.00

1880

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,356.72

TOTAL LABOUR COST : \$ 4,210.00

TOTAL REPAIR COST : \$ 11,566.72

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian L  
L/S 14/11/12

06 days.

total: 5559.60  
L/S: 4.41K. ✓



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                                                    |                            |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                                                    | Ref : CS/FCI17021746/Arbn2 |            |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                                                    | Date : 22-12-2017          |            |  |
|                                                                                                                                                                                        |                                                                                                                    | Code : FCI2                |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                                                    |                            |            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHD 6990L                                                                                                          | Veh. Inspected             | SJL 5647U  |                                                                                     |
| Policy No.                                                                                                                                                                             | D-15072701MFSH                                                                                                     | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                                                                              | D17010559MFSH                                                                                                      | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                                                                            | MAY CHUA                                                                                                           | Assign Date                | 14/11/2017 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                                                    |                            |            |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA CIVIC                                                                                                        | c.c                        | 1799       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                                             | Year of Reg.               | 2008       |                                                                                     |
| Chassis No.                                                                                                                                                                            | JHMF16309S201076                                                                                                   | Colour                     | WHITE      |                                                                                     |
| Odometer                                                                                                                                                                               | 201771                                                                                                             | Steering                   | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                                           | Modification               | SPORTS RIM |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                                               |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                                                    |                            |            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                                               | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 225/45 R17                                                                                                         | CONTINENTAL                | 6 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 225/45 R17                                                                                                         | CONTINENTAL                | 6 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 225/45 R17                                                                                                         | CONTINENTAL                | 6 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 225/45 R17                                                                                                         | CONTINENTAL                | 6 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                                                    |                            |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                                                             |                                                                                                                    |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                                                    |                            |            |                                                                                     |
| Accident Date                                                                                                                                                                          | 12/11/2017                                                                                                         | Inspection Date            | 14/11/2017 |                                                                                     |
| Survey held at                                                                                                                                                                         | MG SOLUTION PTE LTD<br>23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                                                    |                            |            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                    |                            |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                                                    |                            |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                                                    | 6 Working Days             |            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5647U

| Qty                         | Description of Parts                  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                       |                      |                           |                   |
| 1                           | BOOTLID                               | BUCKLED              | 755.30                    | 698.00            |
| 1                           | BOOTLID LOGO                          | NECESSARY            | 82.00                     | 48.00             |
| 1                           | BOOTLID INSULATOR                     | NOT NECESSARY        | 162.00                    | -                 |
| 1                           | BOOTLID KEYLOCK                       | NOT NECESSARY        | 135.00                    | -                 |
| 2                           | BOOTLID HINGE @\$72.00                | NOT NECESSARY        | 144.00                    | -                 |
| 2                           | BOOTLID HINGE COVER @\$92.30          | NOT NECESSARY        | 184.60                    | -                 |
| 2                           | BOOTLID REFLECTOR @\$266.30           | NOT NECESSARY        | 532.60                    | -                 |
| 2                           | BOOTLID INNER STOPPER @\$35.80        | NOT NECESSARY        | 71.60                     | -                 |
| 1                           | BOOTLID LOCK                          | DAMAGED              | 211.30                    | 211.30            |
| 1                           | BOOTLID LOCK CATCH                    | NOT NECESSARY        | 89.60                     | -                 |
| 1                           | BOOTLID WEATHERSTRIP                  | CUT                  | 155.30                    | 155.30            |
| 2                           | REAR NUMBER PLATE LAMP @\$64.90       | NOT NECESSARY        | 129.80                    | -                 |
| 1                           | REAR NUMBER PLATE LAMP GARNISH        | NOT NECESSARY        | 168.50                    | -                 |
| 1                           | REAR BUMPER                           | DEFORMED             | 688.90                    | 688.90            |
| 2                           | REAR BUMPER SIDE RETAINER @\$62.50    | NECESSARY            | 125.00                    | 64.00             |
| 2                           | REAR TAIL LAMP @\$366.20              | CRACKED              | 732.40                    | 732.40            |
| 2                           | REAR TAIL LAMP PANEL @\$103.50        | TO REPAIR SEE LABOUR | 207.00                    | -                 |
| 2                           | REAR TAIL LAMP LOWER BRACKET @\$62.00 | BENT                 | 124.00                    | 24.00             |
| 1                           | REAR FENDER INNER TRIM LH             | TORN                 | 189.20                    | 189.20            |
| 2                           | REAR FENDER AIR VENT DUCT @\$85.90    | NOT NECESSARY        | 171.80                    | -                 |
| 1                           | REAR END PANEL                        | DENTED               | 540.50                    | 300.80            |
| 1                           | REAR END PANEL TOP GARNISH            | DEFORMED             | 138.60                    | 138.60            |
| 1                           | REAR FLOOR PANEL                      | TO REPAIR SEE LABOUR | 1,088.30                  | -                 |
| 1                           | REAR FLOOR PANEL TOP BOARD            | DEFORMED             | 322.30                    | 322.30            |
| 1                           | SPARE TYRE TOOL SPONGE                | NOT NECESSARY        | 106.30                    | -                 |
| 1                           | REAR EXHAUST CHROME PIPE              | BENT                 | 865.00                    | 614.20            |
|                             | LESS 20% DISCOUNT                     |                      | -1,624.18                 | -837.40           |
|                             |                                       |                      | 6,496.72                  | 3,349.60          |

Report Ref No. CS/FCI17021746/Arbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                                                                              | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                  |               |                           |                   |
| 1   | REAR NUMBER PLATE (SN)                                                                                            | NOT NECESSARY | 50.00                     | -                 |
| 1   | BOOTLID SEALANT (SN)                                                                                              | NOT NECESSARY | 60.00                     | -                 |
| 1   | SET REAR BUMPER CLIP (SN)                                                                                         | NECESSARY     | 20.00                     | 20.00             |
| 2   | TAILLAMP PANEL SEALANT @\$60.00 (SN)                                                                              | NOT NECESSARY | 120.00                    | -                 |
| 1   | SET REAR FENDER INNER TRIM CLIPS (SN)                                                                             | NECESSARY     | 20.00                     | 20.00             |
| 1   | SET REAR END PANEL TOP GARNISH CLIPS (SN)                                                                         | NECESSARY     | 20.00                     | 10.00             |
| 1   | REAR END PANEL INSULATION SEAL (SN)                                                                               | NECESSARY     | 150.00                    | 60.00             |
| 1   | REAR FLOOR PANEL INSULATION SEAL (SN)                                                                             | NOT NECESSARY | 200.00                    | -                 |
| 1   | REVERSE SENSOR (SN)                                                                                               | DAMAGED       | 220.00                    | 220.00            |
|     |                                                                                                                   |               | 860.00                    | 330.00            |
|     | <b><u>LABOUR</u></b>                                                                                              |               |                           |                   |
|     | PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL AND REAR FLOOR PANEL. |               | 1,600.00                  | 800.00            |
|     | TO SPRAY PAINT AFFECTED AREA.                                                                                     |               | 1,400.00                  | 800.00            |
|     | TUFF COAT.                                                                                                        |               | 250.00                    | 60.00             |
|     | WIRING CHECK.                                                                                                     |               | 180.00                    | 30.00             |
|     | REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR.                                     |               | 180.00                    | 60.00             |
|     | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.                                                             |               | 80.00                     | 50.00             |
|     | TRANSFER BOOTLID MECHANISM.                                                                                       | NOT NECESSARY | 80.00                     | -                 |
|     | CONDUCT WATER LEAKAGE TEST.                                                                                       | NOT NECESSARY | 80.00                     | -                 |
|     | REMOVE AND REFIX REAR EXHAUST PIPE.                                                                               |               | 180.00                    | 80.00             |
|     | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.                    | NOT NECESSARY | 180.00                    | -                 |
| -   |                                                                                                                   |               | -                         | -                 |
| -   |                                                                                                                   |               | -                         | -                 |
| -   |                                                                                                                   |               | -                         | -                 |
|     |                                                                                                                   |               | 4,210.00                  | 1,880.00          |
|     | <b>GRAND TOTAL</b>                                                                                                |               | <b>11,566.72</b>          | <b>5,559.60</b>   |

Report Ref No. CS/FCI17021746/Arbn2



|                                                                         |  |  |          |
|-------------------------------------------------------------------------|--|--|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |  | 4,400.00 |
|-------------------------------------------------------------------------|--|--|----------|

Report Ref No. CS/FCI17021746/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.