

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER Date: 18-04-2018

FIVE SINGAPORE 038985

ERGO INSURANCE PTE LTD

18-04-2018

CS3/EGI17021762/Wbe2

Page No.:1 of 1

			Code: EGI			
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SGY 1040M	Veh. Inspected	SLK 5008X		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	DSMPC1702634/RH/sa	Excess (\$)	0.00		
	Assign From	SITI A'THIKAH	Assign Date	14/11/2017		
2.	Vehicle Particulars & Condition					
	Make & Model	PEUGEOT 5008	c.c	1560		
	Engine No.	HIDDEN	Year of Reg.	2016		
	Chassis No.	VF30EBHZTGS166031	Colour	LIGHT GREY		
	Odometer	24747 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	215/50 R17	MICHELIN	3 mm		
	L/H Front Tyre	215/50 R17	MICHELIN	3 mm		
	R/H Rear Tyre	215/50 R17	MICHELIN	3 mm		
	L/H Rear Tyre	215/50 R17	MICHELIN	3 mm		
4.	Description of Damages					
	THE VEHICLE SU					
5. General Information						
	Accident Date	10/11/2017	Inspect Date / Time	15/11/2017 ( 03:18 PM )		

	Consul Information						
	5.	General Information					
		Accident Date	10/11/2017	Inspect Date / Time	15/11/2017 ( 03:18 PM )		
		Survey held at	BLK 2 KAKI BUKIT AVE 2 #02-25, 417921				
		Repairer	H S AUTOMOTIVE SERVICES				
1							

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900-\$4,900

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/EGI17021762/Wbe2

Inspected By

**WILSON TEO CHENG MING** 

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.