

REF:

NS/INC17021792 / Sep 2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 736E

Yr Regn:

11/7/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

CC 1798

Colour:

Maroon

A/C

Insured / Std / NI / NA

Sp. Reading

445861

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN36UX05747159

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size:

F: 195/55R15

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/11/2017

D.O.A.

14/11/2017

Survey held at

SMART

Des. of Damages: Fnt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 736E - NKA / LEP16001555 / Y

DCA: 240116

TAX / 11/17/2018

FY 4059C - X

LKK.

NTUC.

US \$ 1450, 4 days (Cred \$ 5096.54, 78%)

RECEIVED 29 NOV 2017

Date/Time File Pass to?

☐

Preli. Report

29/11/2017

☐

Final Report

Date/Time File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S - RS - \$

) Photos

) Other

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Weekend (\$

Report Format:

Tp

Lump Sum / LEP: (\$

1450

TOTAL

160
35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17021792/Sqb

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 15-11-2017
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FY 4059C	Veh. Inspected	SHB 736E
Policy No.	5094749859	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/11/2017	Inspection Date	14/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Reference No. : 05/NCI707799/SUB
Policy Type: OD / TP / TP RES / TL / EVA

Typist

(1) Office Assign Form

[illegible]

(1) Assignment Form

C	Vehicle No		
C	Regn Month/Year		
N	Vehicle Type		
N	Make & Model		
C	Engine Capacity. (C.C)		
N	Colour		
C	Odometer. (Sp.Reading)		
C	Chassis No		
N	General Condition		
N	Steering		
N	Brake		
N	Modification (Modi)		
C	Tyre Size		
N	Tyre Make		
C	Tyre Balance		
C	Date of Inspection		
N	Survey held		
N	Des.of Damages		

C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

✓	
✓	

C Resurvey photo Uploaded

--	--	--	--

Case Handler 29/11/17 Date

21/05/2014

Denise Tay (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Wednesday, 29 November, 2017 12:43 PM
To: Denise Tay (LKKAuto)
Subject: REQUEST CLAIM NUMBER

Hi,

All claims created.

Samsia
Senior Admin Assistant, Motor Insurance
www.income.com.sg



From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, November 29, 2017 10:51 AM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

Dear Sir,

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date
1	MT/0971613-001	SMRT TAXIS PTE LTD	SHB 535T	FBG 907Z	
2	MT/0971616-001	SMRT TAXIS PTE LTD	SHC 4736Z	SJA 2764S	
3	MT/0969589-002	SMRT TAXIS PTE LTD	SHB 736E	FY 4059C	
4	MT/0971621-001	SMRT TAXIS PTE LTD	SHB 5261A	FY 8785M	
5	MT/0965908-003	SMRT TAXIS PTE LTD	SHF 210J	SJQ 586T	

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5094749859	SALMON BARIS UJYARMUNAVAR	S9175966G	GMC	Third Party	FY4059C	FY4059C	03/10/2017	02/10/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2017 09:29
Date Of Accident	12/11/2017 19:35
Exact Location Of Accident	JUNCTION OF WOODLANDS AVE 1 & CHAMPIONS WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB736E
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	
Driver	
Name of Driver	KOK MON KIT
NRIC No	S8080402D
Date Of Birth	29/03/1980
Occupation	OUTDOOR
Date Of Driving Pass	13/06/2001
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ
Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/2017112/7006 On 12/11/2017 at about 1936hrs, I was at Woodlands Avenue 1 junction to Champions Way and Woodlands Avenue 4 trying to make a U-turn towards Avenue 2. As I was approaching the traffic light, it was red light however there was a green turn right light. I then signalled right and wanted to make a U-turn. As I was making the U-turn, a motor bike FY4059C that was behind me suddenly moved forward and collided onto my right passenger door. After the collision, he did not fall down and managed to stay on his bike. I then moved the vehicle to the side and exchange particulars with the rider. The rider informed me that he felt pain on his right leg however does not require ambulance. I wish to inform that I am not injured in the process.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: FILE TOO LARGE
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FY4059C
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver SALMON BARIS UJYARMUNAVAR
NRIC/Passport Number S9175966G
Contact Number
Address
Postcode
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

SALMCN BARIS UJYARMUNAVAR

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FY4059C

Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171112/7006

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171112/7006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/11/2017 20:31		Vide Report No.:		Station Diary No.:	
Name of Informant: KOK MON KIT		Address: APT BLK 876 WOODLANDS AVENUE 9 #04-254 SINGAPORE 730876			
ID Type / ID No.: NRIC NO / S8080402D		Contact No.: Home/Office:		Mobile: 97771495	
Nationality: SINGAPORE CITIZEN		Email: Kennykok80@yahoo.com			
Sex: Male	Age: 37	Date of Birth: 29/03/1980		Type of Informant: Driver	
Race: Chinese		Language: English		Institution / School Name:	
Occupation: TAXI DRIVER		Driving Licence Information: Class: 2B,3		Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/11/2017 19:36	Type of Location: X-Junction
Location: CHAMPIONS WAY Junction of Champions Way and Woodlands Avenue 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

FY4059C	Motorcycle	HONDA	PHANTOM		Slightly Damaged	0
SHB736E	Car	TOYOTA	PRIUS		Slightly Damaged	0

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171112/7006

2 of 3

Report No. T/20171112/7006

CONTINUATION OF REPORT

Name	SALMON BARIS UJJARMUNAVAR		ID No.	S9175966G
Related Vehicle	FY4059C (Motorcycle)		Contact No.	81112540
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	
Name	KOK MON KIT		ID No.	S8080402D
Related Vehicle	SHB736E (Car)		Contact No.	97771495
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 12/11/2017 at about 1936hrs, I was at Woodlands Avenue 1 junction to Champions way and Woodlands avenue 4 trying to make a U turn towards Avenue 2.

As i was approaching the traffic light, it was red light however there was a green turn right light. I then signalled right and wanted to make a U turn. As i was making the U turn, a motor bike FY4059C that was behind me suddenly moved forward and collided onto my right passenger door. After the collision, he did not fall down and manage to stay on his bike. I then moved the vehicle to the side and exchange particulars with the rider. The rider informed me that he felt pain on his right leg however does not require ambulance.

I wish to inform that i am not injured in the process.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171112/7006

3 of 3

Report No. T/20171112/7006

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
LEE SOON LYE
Contact No.: 65476239

Authentication Stamp
NP158

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
12/11/2017 20:31

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	5369K
Vehicle Details	
Vehicle No.	SHB736E
Vehicle to be Exported	No
Intended De-registration Date	15 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2014
Engine No.	2ZR6098897
Chassis No.	JTDKN36UX05747159
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$32,920.00
Original Registration Date	16 Jul 2014
First Registration Date	16 Jul 2014
Transfer Count	0
Actual ARF Paid	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	15 Jul 2022
PARF Rebate Amount	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date	15 Jul 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$53,269.00
COE Rebate Amount	\$31,073.00
Total Rebate Amount	\$37,139.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Nov 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 13 Oct 2017 at 07:07 PM

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB736E
Ref. No : TAX/11/17/2078
Reg. Date : 16/07/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : KOK MON KIT
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 12/11/2017 07:36:00 PM
Accident Reported Date / Time : 13/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 12/11/2017
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093063
Special Instruction to ARC.if any :
TOWED \$50 / FY4059C
Prepared Date : 13/11/2017 10:00:06 AM



Sebastian.
14/11/2017.
- Lump Sum Repair.
- Question Mark Item Photo
- Photo After Paint.


22/11/17

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX05747159

Mileage

0

Work Shop :

Repair Completed Date / Time :


Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,014.00	0.00
Total Spray Painting Charges	1,494.00	0.00
Total Material Charges	1,634.26	2,094.34
Other Charges	780.00	0.00
TOTAL	4,922.26	0.00
Lum Sum Total	4,900.00	0.00
No. of Repair Days	6.00	0.00 3 days
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	13/11/2017 05:20:48 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks :

Prepared Date : 13/11/2017 05:20:04 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 X
TO RESPRAY REAR FENDER RH	378.00	0.00 200
RESPRAY WHEEL CAP	180.00	0.00 X
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR DOOR RH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	780.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Repair	Replace	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace	No
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace	No
42602-47060		6505676	CAP SUB-ASSY, WHEEL	1	174.10	25.00	130.57	Replace	Replace	No
TOTAL MATERIALS								2,042.84	2,617.93	
TOTAL MATERIALS(Discounted)								1,634.26	2,094.34	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



Attached
Supplementary
Information

+10M

17.11.17 / 12.51
17.11.17 / 16.51

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

14.11.17 / 16.51

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB736E
Ref. No : TAX/11/17/2078
Reg. Date : 16/07/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : KOK MON KIT
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 12/11/2017 07:36:00 PM
Accident Reported Date / Time : 13/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 12/11/2017
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093063
Special Instruction to ARC, if any :



Shore -

TOWED \$50 / FY4059C - NTUC IDAC
AFTER PAINT PHOTO, LUMP SUM REPAIR, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121

Prepared Date : 13/11/2017 10:00:06 AM

E ① 12 F
KM 445859

Vehicle to Wega Date In: 15/11/17 Towing: _____
Time In: 1155 Driver: Gwa
Wega Job No: 13931/11
Vehicle sent to SMRT Date In: 16/11/17 Towing: _____
Time In: 1615 Driver: Chd
Received by (SMRT): _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX05747159

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	400.00
Total Spray Painting Charges	: 1,494.00	500.00
Total Material Charges	: 515.38	805.27
Other Charges	: 700.00	-255.27
TOTAL	: 3,723.38	1,450.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	4.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 13/11/2017 05:20:48 AM	14/11/2017 04:51:03 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/11/2017 05:20:04 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1711-0488

Invoice No :

Quotation Date : 21/11

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,014.00	400.00 /
Total Labour	1,014.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY REAR FENDER RH	378.00	200.00 /
RESPRAY WHEEL CAP	180.00	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00 /
TO RESPRAY REAR DOOR RH	378.00	200.00 /
Total Spray Painting & Panel Beating	1,494.00	500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	60.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-335.27
Total Other Costs	700.00	-255.27

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52159-47905		6505548	BUMPER REAR	0	458.60	25.00	0.00	Replace	Not given	No	X
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace	No	/
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	0	94.80	25.00	0.00	Replace	Not given	No	X
61604-47090			FENDER RR/RH	1	766.80	100.00	0.00	Repair	Repair	No	R
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	/
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	/
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace	No	/
75851-47900			MOULDING BODY, RH	1	673.60	100.00	0.00	Replace	Repair	No	R
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No	X
42602-47060		6505676	CAP SUB-ASSY, WHEEL	0	174.10	25.00	0.00	Replace	Not given	No	X
TOTAL MATERIALS							805.28	805.27			
TOTAL MATERIALS(Discounted)							515.38	805.27			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

805.27
+ 400.00
+ 580.00

1785.27

- 209

1428.22

L/S \$1450/-
6546.54

Sebastian
29/11/2017



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHB 736E

INSPECTION





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H






National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHB 736E

RE-INSPECTION



**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17021792/Sqbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Date: 04-12-2017



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FY 4059C	Veh. Inspected	SHB 736E
Policy No.	5094749859	Coverage (\$)	0.00
Claim No.	MT/0969589-002	Excess (\$)	0.00
Assign From		Assign Date	14/11/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36UX05747159	Colour	MAROON
Odometer	445861	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/11/2017	Inspection Date	14/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 736E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR RR/RH (DISC 25%)	DENTED	954.50	715.87
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	BUMPER REAR	NOT NECESSARY	458.60	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	TYRE	NOT NECESSARY	126.74	-
1	CAP SUB-ASSY,WHEEL	NOT NECESSARY	174.10	-
1	FENDER RR/RH	TO REPAIR	766.80	-
1	MOULDING BODY,RH	TO REPAIR	673.60	-
			3,338.54	805.27
LABOUR				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,454.00	460.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,594.00	500.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,208.00	980.00
GRAND TOTAL			6,546.54	1,785.27
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,450.00

Report Ref No. NS/INC17021792/Sqbn2

YEANG WAI KEEN
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.