

22/03/2002

ASS. REC. BY:

REF: CS/A9M7021845/Tigberz

Special Instruction:

Survivor: Taufikah.

ASSIGNMENT (Office)

Smart claim

From (Person):

Kitty Teo

of

AXA

Date/Time: 15-11-2017 3:44pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

STV 6602P

Insured:

at Workshop m/s

ETH02

Tel:

6654 7520

of

30Bukit Batok Crescent

Policy No:

Claim No:

87M0045E

Sum Insured:

Excess:

\$ 900.00

Make of Veh:

D.O.A. 10-11-2017

(Client's Record):

16.11.2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15-11-2017 4:16 pm

Person Contacted:

Lee

Vehicle: IN ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	STV 6602P - X 16/11/17 @ 10:44am Kitty informed SA if damages consistent with SC claim
17/11/17 @ 9:44am	Informed Chen Sim C/O S EX: \$ 900 by email.
17/11/17 @ 11:10am	revised to Kitty Teo via Smart Claim.
16/11/18 @ 4:16pm	2nd revised to Kitty via Smart Claim (Complementary).

ASSIGNMENT

From: _____ Date: 16/11/17
 Estimated Cost: _____
☒ TP WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJV 6602P
 at Workshop m/s: Ethoz
 of: 30, Bukit Batok Crescent
 Insured: _____
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: \$900.00
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$239K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: Lee

Vehicle: IN / OUT

Veh No: SJV6602P Yr Regn: 2010 Feb
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Wish C.C. 1797
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 331565 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 2GE200025625
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 275/45 R17
 R: 275/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 16/11/17 @ 1445

Survey held at Ethoz Bkt Bkt

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2145, 6 days E-mail to Lee
(Red @ 3060, 59%)
Parts supplied by AXA @ 1635
no lump sum

29/1/2018

Date/Time, File Pass to? ☐ : Preli. Report

30/1/2018 ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation: _____

) S + RS: _____

) Photos _____

) Others _____

TOTAL: 150

Report Format: Smart Claim

Lump Sum / I.B.I. / S: 2145

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17021845/T1qb

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 15-11-2017



Code : AXA2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJV 6602P
Policy No.	Coverage (\$)	0.00
Claim No. S7M0045E	Excess (\$)	900.00
Assign From SMART CLAIM (KITTY TEO)	Assign Date	15/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 10/11/2017	Inspection Date 16/11/2017
Survey held at ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No.: C8/ASM/7071845/1196
 Policy Type: OD / TP / TP RES / TL / EVA

SJU6602P

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		

Surveyor (Taufik): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

☒			
-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

☒			
☒			
☒			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

☒			
-------------------------------------	--	--	--

Check By: [Signature] 26/1/18
 Case Handler Date



Service Request Details

Claim

S7M0045E

Reference

None

Loss Date

November 10, 2017

Request Date

November 15, 2017

Due Date

November 22, 2017

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJV6602P

Make

TOYOTA

Service Address

30 Bukit Batok Crescent, , , 658075

Primary Contact

AHAMADI BIN KAMSIDIN
92778918
madi190655@gmail.com

Claim Handler

Kitty TEO
6568804602
kitty.teo@axa.com.sg

Additional Instructions

EXCESS \$400+\$500(NAMED YOUNG DRIVER)=\$900

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

11/15/17 3:50 PM

FROM

Kitty TEO

SUBJECT

SKA5206E - Car @ Ethoz(BB)

BODY

Hi WP survey and get estimate. Thanks.





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S7M0045E

Date: 26th January 2018

Our Ref: CS/ASM17021845/T1qb

The Motor Claims Department
AXA Insurance Singapore Pte L td

Attn: Kitty

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SJV 6602P


We thank you for the instruction on 15/11/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/11/2017 (2.40pm) at the premises of M/s ETHOZ and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 5,205.00 (ESTIMATE \$4,905.00 + SUPPLEMENTARY \$300.00).</u>
Revised Estimate Amount	: <u>S\$ 2,145.00 (INCLUSIVE OF SUPP).</u>
"Check" Items Amount	: <u>S\$ -</u>
Total	: <u>S\$ 2,145.00</u>
Market Value	: <u>S\$ 39,000.00</u>
LTA Reimbursement Value	: <u>S\$ 17,006.00</u>
Nett Value	: <u>S\$ 21,994.00</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Part supplied by AXA \$1,635.00.

We have authorised the repairs.

Yours faithfully

Taufikh
Automobile Assessor

« PRELIMINARY ADVICE OF VEHICLE SJV 6602P

Type

🔗 Question

Message

Repairer's Estimate (Gross): \$4,905.00 Revised Amount: \$3,410.00 Check Items (Estimated): \$360.00 Total: \$3,770.00 Pre-Accident Value: \$39,000.00 COE / PARF Rebate: \$17,006.00 Margin for Repair: \$21,994.00
Date & time of survey: 16-11-2017 @ 2.40pm. Damages Consistent. Repair Cost Economical. We have authorised repair on 17/11/2017 at 9.44am. Recommend 06 Repair days. - Shiau Chan

Reply

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 17 November, 2017 9:44 AM
To: Lee Chen Sin
Cc: SUR; Toh Khar Kian; Leon Lim
Subject: RE: SJV-6602-P TOYOTA WISH (OD)(AXA) - SEEK FOR AUTHORIZE REPAIR

Dear Chen Sin,

As instructed by our client AXA Insurance, please proceed to repair the insured vehicle **SJV 6602P (Excess \$900/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee Chen Sin [<mailto:ChenSin.Lee@ethozgroup.com>]
Sent: Friday, 17 November, 2017 9:35 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Toh Khar Kian <KharKian.Toh@ethozgroup.com>; Leon Lim <Leon.Lim@ethozgroup.com>
Subject: SJV-6602-P TOYOTA WISH (OD)(AXA) - SEEK FOR AUTHORIZE REPAIR

Hi,

Above mention vehicle had authorize repair?

Thanks you.

Warmest Regards,
Lee Chen Sin

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

Mobile: (65) 8822 8339/ DID: 6654 7520 / Fax: 6654 7542

Website: www.ethozgroup.com



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	6088B
Vehicle Details	
Vehicle No.	SJV6602P
Vehicle to be Exported	No
Intended De-registration Date	15 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	WISH 1.8X A
Primary Colour	White
Manufacturing Year	2009
Engine No.	2ZR0473067
Chassis No.	ZGE200025625
Maximum Power Output	106.0 kW (142 bhp)
Open Market Value	\$21,545.00
Original Registration Date	04 Feb 2010
First Registration Date	04 Feb 2010
Transfer Count	0
Actual ARF Paid	\$21,545.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Feb 2020
PARF Rebate Amount	\$12,927.00
Intended COE Rebate Details	
COE Expiry Date	03 Feb 2020
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$19,000.00
COE Rebate Amount	\$4,079.00
Total Rebate Amount	\$17,006.00

The information contained herein is correct as at 15 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2017 12:32
Date Of Accident	10/11/2017 19:00
Exact Location Of Accident	KM12 JALAN JOHOR BHARU KOTA TINGGI
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV6602P
Insured/Policyholder	
Name Of Registered Owner	AHAMADI BIN KAMSIDIN
NRIC No	S1206088B
Email Address	MADI190655@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92778918
Alternative Phone No	OFFICE-92778918
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	TRAVELLING TO SHOPPING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA012858/1
Cover Note Number	
Driver	
Name of Driver	AHAMADI BIN KAMSIDIN
NRIC No	S1206088B
Date Of Birth	19/06/1955
Occupation	OUTDOOR
Date Of Driving Pass	11/02/1977
Driving Experience	40 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92778918
Fax Number	
Contact Number	OFFICE-92778918
Email Address	MADI190655@GMAIL.COM

Address BLK 346 BUKIT BATOK STREET 34 #03-212
Postcode 650346
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? YES
Foreign Vehicle Registration Number JKF9386 (PRIVATE CAR)
Was any body injured in the Accident? NO
Was any other material or property damaged? NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name 10 UBI AVENUE 3
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Please refer to Police report

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

13/11/17 12:48 hrs


CHARMC SketchPlanForm_V3

Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

[Signature]

Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.		- Reporting Only
	✓	- Claim OD
		- Claim TP
		- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's signature
Date & Time

13/11/17
12:45 HRS

Driver's Signature
(if driver not the policyholder)
Date & Time

[Signature]

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.



**SINGAPORE
POLICE FORCE**



T/20171111/2151

1 of 2

POLICE REPORT (NP299)

Report No. T/20171111/2151


Police Station Of Origin
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Date/Time Report Made 11/11/2017 18:51	Vide Report No.	Station Diary No.
Name Of Informant AHAMADI BIN KAMSIDIN	Address APT BLK 346 BT BATOK ST 34 #03-212 HDB-BUKIT BATOK SINGAPORE 650346	
ID Type / ID No. NRIC NO / S1206088B	Contact No. Home/Office Mobile 92778918	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Building and construction project manager	Sex Male	Age 62
Institution/School Name	Date of Birth 19/06/1955	Race Javanese
Date/Time Of Incident 10/11/2017 19:00 - 10/11/2017 19:00	Location Of Incident KM 12 JOHOR BHARU KOTA TINGGI MALAYSIA	

Brief details.

ON 10/11/2017 AT ABOUT 1900HRS AT JOHOR BAHRU,

I WAS TRAVELLING FROM TEBRAU HEADING TO ULU TIRAM IN MY VEHICLE: ' SJV6602P'. WHEN I REACHED KM 12 JOHOR BAHRU KOTA TINGGI IN HEAVY TRAFFIC SITUATION, SUDDENLY A CAR, 'JKF9386' FROM BEHIND BANG MY CAR. THERES SERIOUS DAMAGE TO THE REAR OF MY VEHICLE. I HAVE SENT MY CAR TO THE WORKSHOP. THEY MENTIONED THAT THEY WILL

Signature Of Officer Recording The Report: TP / LEE KWANG HONG KENDRICK	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 11/11/2017 18:51
Officer In-Charge Of Case: TP / Traffic Police Division HQ / Sr Staff Sgt NORASHIKIN BINTE DAUD Contact No.: 65476439	Classification Of Case:  SINGAPORE POLICE FORCE
Authentication Stamp	Signature: 



**SINGAPORE
POLICE FORCE**



T/20171111/2151

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. T/20171111/2151

UPDATE ME IF FURTHER DAMAGES ARE FOUND ON THE VEHICLE.

THIS REPORT IS FOR RECORD PURPOSES.

Signature Of Officer Recording The Report:

TP / LEE KWANG HONG KENDRICK

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

TP / Traffic Police Division HQ /

Sr Staff Sgt NORASHIKIN BINTE DAUD

Contact No.: 65476439

Authentication Stamp

Signature Of Informant:

Date/Time:

11/11/2017 18:51

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: _____



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK JOHOR BAHRU(S) **Pegawai Penyiasat** : R112169
Daerah : J/BAHRU SELATAN **No Repot Bersangkut** : TRAFIK JOHOR BAHRU (S)/026108/17
Kontinjen : JOHOR
No Repot : TRAFIK JOHOR BAHRU(S)/026157/17
Tarikh : 11/11/2017
Waktu : 1545 PM
Bahasa Diterima : B. Malaysia

Butir-butir Penerima Repot

Nama : CELVIN BIN JEFRDIN **No Personel** : R193839 **Pangkat** : KONST
Butir-butir Jurubahasa (Jika Ada)
Nama : — **No K/P (Baru)** : — **No Polis/Tentera** : —
No Paspot : — **Bahasa Asal** : —
Alamat : —

Butir-butir Pengadu

Nama : AHAMADI BIN KAMSIDIN
No K/P (Baru) : — **No Polis/Tentera** : — **No Paspot** : S1206088B
No Sijil Beranak : —
Jantina : Lelaki **Tarikh Lahir** : 19/06/1955 **Umur** : 62 tahun 4 bulan
Keturunan : Melayu **Warganegara** : Singapore
Pekerjaan : SWASTA
Alamat Tempat Tinggal : APT BLK 346 BUKIT BATOK STREET 34 , SINGAPORE, 650346
Alamat Ibu/Bapa : —
Alamat Pejabat : —
No Tel (Rumah) : — **No Tel (Pejabat)** : — **No Tel (HP)** : 92778918

Pengadu Menyatakan:-

PADA 10/11/2017 JAM LEBIH KURANG 1900HRS SEMASA SAYA MEMANDU M/KAR NO. SJV6602P DARI TEBRAU HENDAK PERGI KE ULU TIRAM. APABILA SAYA SAMPAI DI KM 12 JALAN JOHOR BHARU KOTA TINGGI DALAM KEADAAN KESESAKAN LALULINTAS TIBA - TIBA ADA SEBUAH M/KAR NO. JKF9386 DARI ARAH BELAKANG TELAH MELANGGAR M /KAR SAYA. KEROSAKAN PADA BAHAGIAN MURDGUARD BELAKANG ROSAK, BUMPER BELAKANG ROSAK, LAMPU BELAKANG PECAH, PANEL ROSAK, BONET BELAKANG ROSAK, LAIN - LAIN KEROSAKAN TIDAK PASTI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu : **Tandatangan Jurubahasa(Jika ada)** : **Tandatangan Penerima Repot** :

ID Pencetak | Tarikh @ Masa Cetak : R2120133 | 13/11/2017 09:22:52 AM



KETUA POLIS DAERAH
IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN
80250 JOHOR BAHRU
JOHOR


Tel : 072237977 Samb :

No. Pengaduan : TRAFIK JOHOR BAHRU(S)/026108/17

Tarikh Cetak : 13/11/2017

Dicetak Oleh : R2120133

(Rajah Kasar Tidak Mengikut Skala)





redefining / insurance

AXA Insurance Pte Ltd
☎ 1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
☎ (65) 6880 4740
✉ customer.care@axa.com.sg
🌐 www.axa.com.sg

Certificate of Insurance

account number
04247

-Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules 1960 - Road Transport Act 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules 1959 (Malaysia)

Policy details

Policyholder name	AHAMADI BIN KAMSIDIN	Certificate number	GA012858 / 1
Cover	Comprehensive	Chassis number	ZGE200025625
Plan name	Private MPV APW	Engine number	2ZR0473067
NCD applicable	0%		
Vehicle registration number	SJV6602P		
Period of insurance	from 04/02/2017 to 03/02/2018 (both dates inclusive)		
Finance loan company	OCBC BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade, or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings

EXCESS Basic Own Damage Excess
Windscreen Excess

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy renewal certificate endorsement etc.

REPUBLIC OF SINGAPORE

DRIVING LICENCE

License Number: **S1206088B**

AHAMADI BIN KAMSIDIN

Birth Date: **19 Jun 1955**

Issue Date: **27 Jan 2003**

000153726C



S1206088B



AHAMADI BIN KAMSIDIN

JAVANESE

Date of birth: **19-06-1955** Sex: **M**

Country of birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

		PASS DATE
Class 2	Motorcycles exceeding 400 cc	09 Feb 1977
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	11 Feb 1977
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	04 Jan 1979
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	11 Jun 1988

NP 428A



Licence No: **S1206088B**



4590099

NRIC No: **S1206088B**



Date of issue: **19-06-2010**

Address

**APT BLK 346 BUKIT BATOK STREET 34
#03-212
SINGAPORE 650346**

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	TAILGATE	435 450.00	bt ✓
1	TAILGATE EMBLEM CENTRE	25 28.00	ner ✓
1	REAR WINDSCREEN MOULDING	60 100.00	ner ✓
1	TAILGATE EMBLEM "VALVE MATIC"	25 22.00	ner ✓
1	TAILGATE LOCK	115 125.00	ddl ✓
1	TAILGATE INNER TRIM (LOWER)	750 120.00	? cat ✓ pufin
1	TAILGATE RUBBER	50 90.00	ner ✓
1	TAILGATE LAMP LH	50 60.00	ner ✓
1	TAILGATE LAMP RH	60.00	X an

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE CHROME GARNISH	70 70.00	de -
1	REAR LAMP OUTER LH	85 80.00	an -
1	REAR LAMP OUTER RH	80.00	Xun
1	REAR BUMPER	160 190.00	de -
10	REAR BUMPER CLIPS	15 15.00	ne -
1	REAR BUMPER SIDE RETAINER LH	20 25.00	ne -
1	REAR BUMPER SIDE RETAINER RH	20 25.00	ne -
1	REAR BUMPER INNER BRACKET LH	20 25.00	ne -
1	REAR BUMPER INNER BRACKET RH	20 25.00	ne -
1	REAR BUMPER REFLECTOR LH	25.00	Xun

Date : 15/11/2017

To : **AXA INSURANCE PTE LTD**

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN

: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER REFLECTOR RH	25.00	} <i>un</i>
1	REAR BUMPER ARM LH	25.00	
1	REAR BUMPER ARM RH	25.00	
1	REAR END PANEL	130 140.00	} <i>un</i>
1	REAR END PANEL TOP GARNISH	95 95.00	
1	REAR FENDER INNER LOWER TRIM (LH)	420.00	} <i>un</i>
1	REAR FENDER INNER LOWER TRIM (RH)	280.00	
1	SPARE TYRE PANEL	RESTORE	} <i>R</i>
1	REAR FENDER LH	RESTORE	
1	REAR FENDER RH	RESTORE	

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	2625.00	
	Add 0% On Parts	0.00	
	<u>Special Nett Item</u>		
1	REAR NUMBER PLATE	35.00	bt
1	REVERSE SENSOR	200.00	mm
1	WINDSCREEN SEALANT	60.00	her
	Sub Total	295.00	295
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT REAR REPAIR	800.00	700
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	30

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO SPRAY PAINTING ON REAR AFFECTED AREA	800.00	8600
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	100.00	50
	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	150.00	120
	TO REMOVE & RE-INSTALL SPARE COMPARTMENT TRIMS	100.00	50
	Sub Total	1985.00	1550
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		SUB TOTAL	4,905.00
		GST 7.0 %	343.35
		TOTAL	5,248.35

Remarks:

Acknowledged by Repairer
Signature:
Date:

Surveyor's name:

Tanjin 97445749

Principal's name:

AHAMADI BIN KAMSIDIN

Survey Date & Time:

16/11/17 @ 1440

Ex 900
Resurvey before paint
Sur @ lkkamp.com
6 days.
Revert

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 20/11/2017
To : AXA INSURANCE PTE LTD

SUPPLEMENTARY

Attn : Motor Claim Department FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD
Certificate No : GA012858/1 Accident Date : 10/11/2017
Vehicle No : SJV-6602-P Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Special Nett Item			
1	REVERSE CAMERA	300.00	dis ✓
	Sub Total	300.00	hmi

Remarks:

SUB TOTAL 300.00
GST 7.0 % 21.00
TOTAL 321.00

Surveyor's name: Tan Jih

Principal's name: AHAMADI BIN KAMSIDIN

Survey Date & Time: 20/11/17

PAGE :

FINALIZATION REPORT
PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lec Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 15/11/2017

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1 Accident Date : 10/11/2017
Vehicle No : SJV-6602-P Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	TAILGATE	450.00	bt
1	TAILGATE EMBLEM CENTRE	28.00	nee
1	REAR WINDSCREEN MOULDING	100.00	nee
1	TAILGATE EMBLEM "VALVE MATIC"	22.00	nee
1	TAILGATE LOCK	125.00	ddl
1	TAILGATE INNER TRIM (LOWER)	120.00	? ante
1	TAILGATE RUBBER	90.00	nee
1	TAILGATE LAMP LH	60.00	coe
1	TAILGATE LAMP RH	60.00	R

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1 Accident Date : 10/11/2017
Vehicle No : SJV-6602-P Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE CHROME GARNISH	70.00	de -
1	REAR LAMP OUTER LH	80.00	ag
1	REAR LAMP OUTER RH	80.00	R
1	REAR BUMPER	190.00	de -
10	REAR BUMPER CLIPS	15.00	ne -
1	REAR BUMPER SIDE RETAINER LH	25.00	ne -
1	REAR BUMPER SIDE RETAINER RH	25.00	ne -
1	REAR BUMPER INNER BRACKET LH	25.00	ne -
1	REAR BUMPER INNER BRACKET RH	25.00	ne -
1	REAR BUMPER REFLECTOR LH	25.00	R

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT.(S)	SURVEYOR APP.
1	REAR BUMPER REFLECTOR RH	25.00	X
1	REAR BUMPER ARM LH	25.00	X
1	REAR BUMPER ARM RH	25.00	X
1	REAR END PANEL	140.00	de
1	REAR END PANEL TOP GARNISH	95.00	de
1	REAR FENDER INNER LOWER TRIM (LH)	420.00	X
1	REAR FENDER INNER LOWER TRIM (RH)	280.00	X
1	SPARE TYRE PANEL		RESTORE
1	REAR FENDER LH		RESTORE
1	REAR FENDER RH		RESTORE

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	2625.00	
	Add 0% On Parts	0.00	
	<u>Special Nett Item</u>		
1	REAR NUMBER PLATE	35.00	ht
1	REVERSE SENSOR	200.00	mm
1	WINDSCREEN SEALANT	60.00	han
	Sub Total	295.00	
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT REAR REPAIR	800.00	700
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	30

Date : 15/11/2017
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT. (\$)	SURVEYOR APP.
	TO SPRAY PAINTING ON REAR AFFECTED AREA	800.00	6600
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	100.00	50
	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	150.00	120
	TO REMOVE & RE-INSTALL SPARE COMPARTMENT TRIMS	100.00	50
	Sub Total	1985.00	1550

S/N - \$ 595.00 ✓

LABOUR - \$ 1550.00

\$ 2145.00 ✗

COR. 15,145.00 (PBP)

6 DAYS REPAIR

EXCESS : \$ 900.00

REMARK : AXA SUPPLY PARTS

Remarks:

SUB TOTAL 4,905.00
GST 7.0 % 343.35
TOTAL 5,248.35

Surveyor's name: Tanjun 97445749

Principal's name: AHAMADI BIN KAMSIDIN

Survey Date & Time: 16/11/17 @ 1440.

Revert

Ex \$900 6 days.
Resony before paint
Sur @ 11kump.com

PLEASE ARRANGE TO SURV
VEHICLE AT 30 BUKIT BATC
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 20/11/2017
To : AXA INSURANCE PTE LTD

SUPPLEMENTARY

Attn : Motor Claim Department

FAX :

Owner : AHAMADI BIN KAMSIDIN
: AXA INSURANCE PTE LTD

Certificate No : GA012858/1

Accident Date : 10/11/2017

Vehicle No : SJV-6602-P

Make & Model : TOYOTA WISH 1.8 X (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AP
<u>Special Net Item</u>			
1	REVERSE CAMERA	300.00	dis ✓
	Sub Total	300.00	pm

Remarks:

SUB TOTAL 300.00
GST 7.0 % 21.00
TOTAL 321.00

Surveyor's name:

Tan Jih

Principal's name: AHAMADI BIN KAMSIDIN

Survey Date & Time:

20/11/17



AXA INSURANCE AUTO PARTS QUOTE/ORDER NO.:

3821

VEHICLE NO.: SJV6802P
MAKE: TOYOTA
MODEL: WISH
YOM:
CHASSIS NO.: ZGE200025625

LOCATION: ETHOZ PROTECT PTE LTD
30 Bukit Batok Crescent
Singapore 658075
TEL NO.: 96248656: Selamat

S/N	Parts Description	Qty	Unit \$	Total \$	Quality		Ex-Stock	Remarks	Order
					Genuine	OEM			
1	TAILGATE	1	\$ 435.00	\$ 435.00	☒	☐	☒		☒
2	TAILGATE EMBLEM CENTRE	1	\$ 25.00	\$ 25.00	☒	☐	☒		☒
3	REAR WINDSCREEN MOULDING	1	\$ 60.00	\$ 60.00	☒	☐	☒	\$16x4	☒
4	TAILGATE EMBLEM "VALVE MATIC"	1	\$ 25.00	\$ 25.00	☒	☐	☒		☒
5	TAILGATE LOCK	1	\$ 115.00	\$ 115.00	☒	☐	☒		☒
6	TAILGATE RUBBER	1	\$ 50.00	\$ 50.00	☒	☐	☒		☒
7	TAILGATE LAMP LH	1	\$ 50.00	\$ 50.00	☒	☐	☒		☒
8	TAILGATE CHROME GARNISH	1	\$ 70.00	\$ 70.00	☒	☐	☒		☒
9	REAR LAMP OUTER LH	1	\$ 85.00	\$ 85.00	☒	☐	☒		☒
10	REAR BUMPER	1	\$ 160.00	\$ 160.00	☒	☐	☒		☒
11	REAR BUMPER CLIPS	10	\$ 1.50	\$ 15.00	☒	☐	☒		☒
12	REAR BUMPER SIDE RETAINER LH	1	\$ 20.00	\$ 20.00	☒	☐	☒		☒
13	REAR BUMPER SIDE RETAINER RH	1	\$ 20.00	\$ 20.00	☒	☐	☒		☒
14	REAR BUMPER INNER BRACKET LH	1	\$ 20.00	\$ 20.00	☒	☐	☒		☒
15	REAR BUMPER INNER BRACKET RH	1	\$ 20.00	\$ 20.00	☒	☐	☒		☒
16	REAR END PANEL	1	\$ 120.00	\$ 120.00	☒	☐	☒		☒
17	REAR END PANEL TOP GARNISH	1	\$ 95.00	\$ 95.00	☒	☐	☒		☒
				TOTAL	\$ 1,385.00	☐	☐		☐



AXA INSURANCE AUTO PARTS QUOTE/ORDER NO.:

3821S1


VEHICLE NO.: SJV6602P
MAKE: TOYOTA
MODEL: WISH
YOM:
CHASSIS NO.: ZGE200025625

LOCATION: ETHIOZ PROTECT PTE LTD
30 Bukit Batok Crescent
Singapore 658075
TEL NO.: 96248656; Selamat

S/N	Parts Description	Qty	Unit \$	Total \$	Quality		Ex-Stock	Remarks	Order
					Genuine	OEM			
1	TAILGATE INNER TRIM (LOWER)	1	\$ 250.00	\$ 250.00	☒	☐	☒		☒
			TOTAL	\$ 250.00	☐	☐	☐		☒



合興汽車零件私人有限公司 8



KING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /

DAIHATSU / KIA / SUZUKI / HONDA

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

STN0045 EMD/GC

3019271941---

TAX INVOICE

M/S: AXA INSURANCE PTE LTD

Image As per Original
--CSU--

NO: DLI9196016
PAGE: 1
DATE: 17/11/2017
A/C CODE: LDAX056
TERMS: CR
P/O NO: 3821 (SJV6602P)



1134478

8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Part No	Description	Location	Qty	Unit Price SIN	Amount SIN
Our D/O No: DDO9020761					
1	T67005-68040	TAILGATE	1	435.00	435.00
2	T90975-02086	LOGO	1	25.00	25.00
3	T75571-68020	W/S MLG RR TOP	1	15.00	15.00
4	T75573-68020	W/S MLG RR RH/LH	2	15.00	30.00
5	T75575-68020	W/S MLG RR LWR	1	15.00	15.00
6	T69350-28150	TAILGATE INNER LOCK	1	115.00	115.00
7	T67881-0M010	TAILGATE W-STRIP	1	50.00	50.00
8	T81591-68010	REFLECTOR LH	1	50.00	50.00
9	T76811-68120	NO. PLATE GARNISH	1	70.00	70.00
10	T81561-68050	TAIL LAMP LH	1	85.00	85.00
11	T52159-68907	BUMPER RR	1	160.00	160.00
12	T52161-0K040	CLIP	10	1.50	15.00
13	T52155-0M020	BUMPER RETAINER RR RH	1	20.00	20.00
14	T52156-0M020	BUMPER RETAINER RR LH	1	20.00	20.00
15	T52575-0M020	BUMPER RETAINER RR RH	1	20.00	20.00
16	T52576-0M020	BUMPER RETAINER RR LH	1	20.00	20.00
17	T58307-68031	TAILLAMP PANEL	1	120.00	120.00
18	T67935-68020-B0	GARNISH	1	95.00	95.00
19	T75444-68010	VALVE MATIC	1	25.00	25.00

Print / MT / 12/12/2017 3:17:25 PM

Cont'd



Volkswagen



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /

DAIHATSU / KIA / SUZUKI / HONDA

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: AXA INSURANCE PTE LTD

NO: DLI9196016


PAGE: 2

TOTAL QUANTITY:	29	TOTAL	SIN 1,385.00
		ADD GST @ 7%	96.95
		GRAND TOTAL	SIN 1,481.95

ETHOZ PROTECT PTE LTD

22 TAMPINES ST 91

(SJV6602P)




Print / MT / 12/12/2017 3:17:25 PM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



E & O E





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE


M/S: AXA INSURANCE PTE LTD

8 SHENTON WAY
#24-01 AXA TOWER,
SINGAPORE 068811
WISH
GARNET

NO: DL19197050
PAGE: 1
DATE: 12/12/2017
A/C CODE: LDAX056
TERMS: CR
P/O NO: 3821S1(SJV6602P)

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
Our D/O No: DDO9020784					
1	T67750-68020-B1	BOARD ASSY BACK DOOR DDS	1	250.00	250.00
TOTAL QUANTITY:			1	TOTAL	SIN 250.00
				ADD GST @ 7%	17.50
				GRAND TOTAL	SIN 267.50

SEND: ETHOZ PROTECT PTE LTD
NO.22 TAMPINES ST 91
JIMMY



Print / MT / 12/12/2017 3:23:10 PM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

