

Surveyor:

REF: CS3/III 1700861/890-2

Special Instruction:

45: \$ 21400.00

ASSIGNMENT (Office)

From (Person): Priya of III Date/Time: 10.11.2017

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: PAL'S Appraiser.

Workshop: Sincere Leed

OD/ (P Re-inspection) / Evaluation

To Inspect Vehicle No: SLE 1092J Insured: SHD 4385Y

at Workshop m/s Sincere Leed Garage Tel: 9815 8358 (Raymond)

of 38 Woodlands Ind Park E1 #05-13

Policy No: Claim No: MCT17050214 / 001 / MP

Sum Insured: Excess:

Make of Veh: D.O.A. 06.05.2017

(Client's Record) 17.11.2017 (Friday) @ 145pm

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 24 days)

Date/Time: 22/1/18 Submit Final Fig \$11,800, 10 days (Red \$ 9600 / 44 %; Original 24 days)

Date/Time	Action/Instruction
	SLE 1092J - CS3/III 1700861/890-2.1
	SHD 4385Y - x
	Katim, Sebastian
	PLS SEE my remarks.
	RECEIVED 24 JAN 2018
	11/1/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 22/1/18 File Pass to Katim

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

Similar

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____


Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____



Remark: The veh had commenced its repair at the time of inspection.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum:	%	3 Val.: Yes or No
100	100	Yes
90	90	Yes
80	80	Yes
70	70	Yes
60	60	Yes
50	50	Yes
40	40	Yes
30	30	Yes
20	20	Yes
10	10	Yes
0	0	Yes

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLE 1072J Yr Regn: 8/7/2016
Type: M Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mitsubishi Attrage C.C. 1193
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 99706 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: mm85TH13444006411 *
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Oil / S/Rim / STD A/Rim or
Tyre Size: F: 185/55 R15 Yoko
R: " Bridgestone
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. $\frac{6}{1}$ mm R/Bal. $\frac{6}{1}$ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 6/5/2017. D.O.I. 12/11/2017.

Survey held at Sincere head

Des. of Damages (Fr) / ~~Rear~~ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

Date/Time, File Pass to?

☐: Prel. Report

1) 73 | 1 | Wisk [] : Final Report

Date/Time. File Return to?

21

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

: Phases

: 2345

55

Report Format :

Lump Sum / I.B.A.: (S)

Add Fee: : Site Insp (\$

☐ Interview (\$

Tech. Invs (\$

Weekend	\$
---------	----




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III17008961/qb-2	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 16-11-2017	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SHD 4385Y	Veh. Inspected	SLE 1092J
Policy No.		Coverage (\$)	0.00
Claim No.	MCT17050214/001/MP	Excess (\$)	0.00
Assign From	PRIYA	Assign Date	10/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/05/2017	Inspection Date	17/11/2017
Survey held at	38 WOODLANDS IND PARK E1 #05-13		
Repairer	SINCERE LEAD AUTOMOTIVE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Manivel Priyadarshini <manivel@iii.com.sg>
Sent: Friday, 10 November, 2017 4:35 PM
To: 'Igene Lim'
Cc: 'Catherine Chong (LKK Auto)'; Admin A
Subject: FW: India ref: MCT17050214/001/MP-Your ref: MN.IG.S4.1711602.st-Accident Involving SHD4385Y & SLE1092J on 06.05.17 Claimant: Choon Hing Minimart

Without Prejudice – Save as to Cost

Dear Igene,

We refer to your below ,

Thank you for the re-inspection confirmation.

Aside to LKK,

Please liaise with Mr. Raymond for the re-inspection.

With Regard's

Priya Manivel

Motor Claims Department

India International Insurance Pte Ltd

Tel : 63476100, Ext-284

Email : manivel@iii.com.sg

From: Igene Lim [mailto:igene.lim@mneduco.com.sg]

Sent: Friday, 10 November, 2017 3:41 PM

To: Manivel Priyadarshini

Subject: RE: India ref: MCT17050214/001/MP-Your ref: MN.IG.S4.1711602.st-Accident Involving SHD4385Y & SLE1092J on 06.05.17 Claimant: Choon Hing Minimart

WITHOUT PREJUDICE

Our Ref : MN.IG.S4.1711602

Hi Priya,

As requested, we have made an arrangement for our client's vehicle **SLE 1092J** to be available for re-inspection on:

Date : 17 November 2017 (Friday)

Time : 1.45 p.m.

Venue : Sincerelead Garage Pte Ltd
38 Woodlands Industrial Park E1, #05-13, Singapore 757700

Contact : Raymond @ 9815-8858

Please let us have your written confirmation on the above arrangement soonest possible.

Kindly also ensure that your appointed surveyor attends to the above without fail.

With thanks & regards,
IGENE LIM (MS)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

From: Manivel Priyadarshini [<mailto:manivel@iii.com.sg>]

Sent: Monday, October 30, 2017 11:04 AM

To: Igene Lim <igene.lim@mneduco.com.sg>

Subject: RE: India ref: MCT17050214/001/MP-Your ref: MN.IG.S4.1711602.st-Accident Involving SHD4385Y & SLE1092J on 06.05.17 Claimant: Choon Hing Minimart

Without Prejudice – Save as to Cost

Dear Igene,

We refer to your email and below email,

We note that the re-appraisal report and your counter proposal had a big difference in COR , So we request to arrange physical re-inspection for your client Veh no: SLE1092J. Please provide the appointment date for the re-inspection to our surveyor (admin-a@lkkauto.com) .

For the earlier settlement Strictly without any admission of liability Can we compromise to settle at @18,000.00 (all in).

Thank You

With Regard's

Priya Manivel

Motor Claims Department

India International Insurance Pte Ltd

Tel : 63476100, Ext-284

Email : manivel@iii.com.sg

From: Igene Lim [<mailto:igene.lim@mneduco.com.sg>]

Sent: Friday, 27 October, 2017 11:34 AM

To: Manivel Priyadarshini

Subject: RE: India ref: MCT17050214/001/MP-Your ref: MN.IG.S4.1711602.st-Accident Involving SHD4385Y & SLE1092J on 06.05.17 Claimant: Choon Hing Minimart

WITHOUT PREJUDICE

Our Ref : MN.IG.S4.1711602

Hi Priya,

We regret to inform that our client is not prepared to accept your offer.

We are instructed to propose a settlement as follows:

(1) Cost of repairs	\$19,260.00
(2) Loss of Use for 24 days	\$ 1,440.00
(3) Pre-Repair Survey Loss of Use for 2 days	\$ 120.00
(4) Survey fees	\$ 1,344.00
(5) GIA report & LTA Search fees	\$ 34.35
(6) Costs and Incidentals	\$ 950.00

	\$23,148.35
	=====

Please revert.

In the event that you are not inclined to go along with our suggestion, please treat this letter as our **10-DAYS' NOTICE** to you of our client's intention to proceed with the issuance of a Writ of Summons against your insured if your said offer is not forthcoming.

With thanks & regards,
IGENE LIM (MS)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

From: Manivel Priyadarshini [<mailto:manivel@jii.com.sg>]

Sent: Friday, October 27, 2017 11:10 AM

To: Igene Lim <igene.lim@mneduco.com.sg>

Subject: India ref: MCT17050214/001/MP-Your ref: MN.IG.S4.1711602.st-Accident Involving SHD4385Y & SLE1092J on 06.05.17 Claimant: Choon Hing Minimart

Without Prejudice Save as to Cost

Dear Igene,

We refer to above matter and LOD,

We had conducted pre-repair inspection and paper survey for your client vehicle SLE1092J. Herewith enclosed re-appraisal report for your perusal, In view of the re-appraisal report Strictly without any admission of liability, we are offering settlement as follows:

Cost of Repair	- \$ 13,400.00
Loss of Use	- \$ 960.00
Survey Fee	- \$ 1,344.00
LTA /GIA fees	- \$ 34.35
<u>Cost Inclusive of Disburs</u>	<u>- \$ 850.00</u>
Total	- \$ 16,588.35

Please confirm acceptance ,we will forward DV asap.

Thank You

With Regard's

Priya Manivel

Motor Claims Department

India International Insurance Pte Ltd

Tel : 63476100, Ext-284

Email : manivel@iili.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached


M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)



Branch Office: 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email: igenc.lim@mneduco.com.sg

Our Ref : MN.IG.S4.1711602.st
Your Ref : SHD 4385Y

24th August 2017

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street,
#04/06-00, IOB Building
Singapore 049711

"WITHOUT PREJUDICE"
BY HAND

MCT/17050214

COMFORT TRANSPORTATION PTE LTD
383 Sin Ming Drive
Gas Building
Singapore 575717

We are in receipt of your letter, which is receiving our attention.
We shall revert shortly, kindly note that we are preserving our
rights to conduct a medical re-examination on your client where
necessary.

Our Ref: MCT/17050214
Name :
Date :
India International Insurance Pte Ltd

CERTIFICATE OF POSTING
(For your information only)

Dear Sir,

CLAIMANT : CHOON HING MINIMART
ACCIDENT ON 06/05/2017 INVOLVING VEHICLES NO. SLE 1092J, SHD 4385Y, SHD 5290E AND SHA 1873R ALONG PIE
(CHANGI AIRPORT) AFTER EUNOS EXIT AT ABOUT 2150 HOURS

We act for CHOON HING MINIMART who were the owners of motor vehicle no. SLE 1092J.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 06/05/2017 ALONG PIE (CHANGI AIRPORT) AFTER EUNOS EXIT involving our client's vehicle registration number SLE 1092J and vehicle registration number SHD 4385Y driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and/or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01. Cost of Repair	S\$21,400.00
02. Loss of Use for 24 days + 4 Sunday & 1 PH x \$80.00 per day	S\$ 2,320.00
03. Loss of Use for 2 days Pre-Repair Survey	S\$ 160.00
04. Survey report fees	S\$ 1,344.00
05. GIA search/report & LTA search fees	S\$ 34.35
06. Costs and Incidentals	S\$ 1,260.00
	S\$26,518.35
	=====

M NEDUMARAN & CO

Advocates & Solicitors

Our Ref : MN.IG.S4.1711602.st

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of SLE 1092J;
- (b) LTA search;
- (c) Certificate of Insurance;
- (d) Vehicle Registration Card;
- (e) Final Repair Bill;
- (f) Surveyor's report & invoice and
- (g) 294 coloured-print photographs depicting the damages to motor vehicle SLE 1092J.
[coloured-print photos will be forwarded to Insurance company only]

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that we have notified your insurer of the accident on 8/5/2017 and a pre-repair inspection of our client's vehicle was carried out by your insurer's appointed surveyor on 8/5/2017, 16/5/2017 & 26/5/2017.

Please also note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

M NEDUMARAN & CO

Nedumaran Muthukrishnan

Encls

Cc: Client (SLE 1092J) (By fax 6287-7949 only)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/05/2017 15:45
Date Of Accident	06/05/2017 21:50
Exact Location Of Accident	PIE (CHANGI AIRPORT) AFTER ENOUS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE1092J
Insured/Policyholder	
Name Of Registered Owner	CHOON HING MINIMART
Co Reg No	02554100E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81270781
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100477941-00000
Cover Note Number	
Driver	
Name of Driver	ANG CHIEW BAK
NRIC No	S20119651
Date Of Birth	24/09/1953
Occupation	OUTDOOR
Date Of Driving Pass	18/10/1972
Driving Experience	44 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81270781
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 15 BEACH ROAD #03-4687
 Postcode 190015
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION- CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name KAMPONG GLAM NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: 17A BEACH ROAD , POSTCODE: 199596 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2989999 - FAX NO: 62936498
 Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

KINDLY REFER TO ATTACH POLICE REPORT NO.T/20170507/2093.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD4385Y

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA1873R

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHD5290E

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name ANG CHIEW BAK

Approximate Age

Injuries Sustain 3 DAYS MC

Injured person in which vehicle? SLE1092J

Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


譽興迷你市場
CHHOON HING MINIMART
Blk 15 Beach Road #01-4581
Singapore 190015 Tel : 62982018

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident

ON THE STATED TIME & DATE, I WAS DRIVING ALONG
 DIE TOWARDS CHANGI AIRPORT ON LANE 1. MY FRONT
 VEHICLE STOPPED HENCE I FOLLOW ALSO. SUDDENLY I
 FELT A GREAT IMPACT COMING FROM MY REAR AND
 PUSH MY VEHICLE. MOVE FORWARD HIT ONTO MY FRONT
 VEHICLE. THEN I REALISED THERE WERE 4 VEHICLES
 INVOLVED IN THIS ACCIDENT. ALL DRIVERS EXCHANGED
 PARTICULARS.

	Reporting Only
	Claim OD
	Claim TP
<input checked="" type="checkbox"/>	Claim OD / TP at other workshop

Declaration

We declare the foregoing particulars are true in every respect.

春興迷你市場
 CHOON HING MINIMART
 Blk 15 Beach Road #01-4551
 Singapore 190015 Tel : 62982619

Policyholder's Signature / Date &
 Time

Driver's Signature (If driver is not the policyholder) / Date
 & Time

Witnessed by Reporting Centre
 Personnel



SINGAPORE POLICE FORCE



T/20170507/2093

1 of 3

Police Station Of Origin:
Kampong Glam NPP
17A Beach Road SINGAPORE 199596
Tel No: 1800-2989999

Report No. T/20170507/2093

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/05/2017 21:25		Vide Report No.:		Station Diary No.: 40	
Informant's Particulars					
Name of Informant: ANG CHIEW BAK			Address: APT BLK 15 BEACH ROAD #03-4687 SINGAPORE 190015		
ID Type / ID No.: NRIC NO / S2011965I			Contact No.: Home/Office: Mobile: 81270781		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63 *	Date of Birth: 24/09/1953	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: UBER DRIVER		Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:			

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/05/2017 21:50	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE (Changi Airport) after Eunos Exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passengers
SHA1873R	Car	HYUNDAI	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO	Blue	Slightly Damaged	0
SHD4385Y	Car	HYUNDAI	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO	Blue	Slightly Damaged	4
SHD5290E	Car	TOYOTA	WISH 2.0 BI- FUEL AUTO	Red	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20170507/2093

Police Station Of Origin:
Kampong Glam NPP
17A Beach Road SINGAPORE 199596
Tel No: 1800-2989999

2 of 3

Report No. T/20170507/2093

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SLE1092J	Car	MITSUBISHI	ATTRAGE 1.2 CVT	Red	Seriously Damaged	3

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ANG CHIEW BAK	ID No.	S2011965I
Related Vehicle	SLE1092J (Car)	Contact No.	81270781
Hospital/Clinic	RAFFLES MEDICAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	07/05/2017	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 06/05/2017, at about 2150hrs, I was driving my car (Registration No: SLE1092J) along Pan Island Expressway (PIE) towards Changi Airport on Lane 1. The vehicle in front of me (Registration No: SHA1873R) made a stop. As such, I braked and stop as well. Out of the sudden, I felt a strong impact coming from my rear and my car moved forward and hit into the rear of the front vehicle.

I immediately alighted from my car and made a check and realized that the car behind me (Registration No: SHD4385Y) collided into the rear of my car. I made further checks and realized there were four vehicles involved in this accident. As such, all the drivers exchanged particulars with each other.

I wish to state that due to the accident, I suffered some pain in my neck area. My teeth also knocked into the steering wheel causing some pain as a result. There is a huge dent at the rear of my car near the rear bumper. Other vehicles had some minor scratch. My other passengers are fine. No one else was injured and no one was conveyed to the hospital. There were no Traffic Police who attended to the case. I am lodging this report to claim third party insurance.



**SINGAPORE
POLICE FORCE**



T/20170507/2093

Police Station Of Origin:
Kampong Glam NPP
17A Beach Road SINGAPORE 199596
Tel No: 1800-2989999

3 of 3





Report No. T/20170507/2093

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: A / LEE ZHAN RUI XAVIER 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 07/05/2017 21:25
Officer In Charge Of Case: TP / AEIT / TAN SIEW GEK Contact No.: 65476230	Classification Of Case:
Authentication Stamp NP168 	

Enquire Vehicle & Owner Information (Vehicle No. SHD4385Y As At 06 May 2017 / 21:50:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: S4.1711602

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHD4385Y

Make Description/Model: HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Insurance Company Name: INDIA INT'L INS PTE LTD

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)



Thank you



Lim Hwee Peng has successfully logged out.

Your last login date and time was 08 May 2017, 14:22:34.

To return to ONE.MOTORING, please click [here](#).

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SHD4385Y -		18.19 Enquire Veh Owner Info (Others) by Law Firm	5.35	08 May 2017 / 14:31:39

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Text size +

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 4100E

Vehicle Details

Vehicle No.: SLE1092J

Vehicle to be Exported: Yes

Intended De-registration
Date: 08 May 2017

Vehicle Make: MITSUBISHI

Vehicle Model: ATTRAGE 1.2 CVT

Primary Colour: Red

Manufacturing Year: 2016

Engine No.: 3A92UDC2163

Chassis No.: MMBSTA13AHH000411

Maximum Power Output: 57.0 kW (76 bhp)

Open Market Value: \$13,744.00

Original Registration
Date: 08 Jul 2016

First Registration Date: 08 Jul 2016

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 07 Jul 2026

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 07 Jul 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$53,694.00

COE Rebate Amount: \$42,955.00

Total Rebate Amount: \$46,705.00

The information contained herein is correct as at 08 May 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)D.O.A. 6/5/2017
Bal: 9yrs 2mtrs.

M.V. \$65K

2500



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.Z.300

MITSUBISHI COMMERCIAL AUTO PROTECTOR
CERTIFICATE NO. 2100477941-00000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$2000.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

1) VEHICLE REGISTRATION NO.

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SLE1092J

2) NAME OF INSURED

Choon Hing Minimart

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

2 Aug 2016

4) DATE OF EXPIRY OF INSURANCE

1 Aug 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person provided he is in the Insured's employ and is driving on their order or with their permission.
A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the
Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said
Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or
has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from
driving the Motor Vehicle.

6) LIMITATION AS TO USE*

- 1) Use in connection with the Insured's business.
 - 2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.
 - 3) Use for social, domestic or pleasure purposes.
- The Policy does not cover : a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing.
b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

APPROVED REPORTING CENTRES / MITSUBISHI AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Gardens Service Centre - 209 Pandan Gdns (Tel: 6568 4555)
- APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)
2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. Ethoz - 30 Bukit Batok Cres (Tel: 66547777)
4. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)
6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)
8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Not Included

* NAMED DRIVER Ang Chiew Bak

HIRE PURCHASE COMPANY MayBank
/EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and
Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-
Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 11 Aug 2016

AIG Asia Pacific Insurance Pte. Ltd.

500722-050
C&C FULCO-CORPORATE
22 UBI ROAD 4
FULCO BUILDING
SINGAPORE 408617
ANSP-MOTOR

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCZSS.

Sincerelead Garage Pte Ltd

38 Woodlands Industrial Park E1 #05-13 Singapore 757700

E-mail : sincerelead@hotmail.com

Fax : 62877949

Name : Choon Hing Minimart

Date : 3-Aug-17

Address : c/o 38 Woodlands Industrial Park E1
#05-13
Singapore 757700

Final repair bill for Mitsubishi Attrage SLE 1092 J

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 21,400.00

Dollars : Twenty One Thousand And Four Hundred Only

PAL'S

APPRAISER PTE LTD
No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 2010002680

Billing Name & Address
Choon Hing Minimart
c/o 38 Woodlands Industrial Park E1
#05-13
Singapore 757700

Invoice No 05-17030/DY

Date 3 Aug 2017

Vehicle No : SLE 1092 J

Model : Mitsubishi Attrage

Item	Descriptions	Amount S\$
1	Date of inspection : <u>11 May 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>294</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1344.00</u>
	SDLS : ONE THOUSAND THREE HUNDRED FORTY-FOUR ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

Report Reference : TP / 05-17030/DY / 2017
Date of Report : 3 Aug 2017

Choon Hing Minimart
c/o 38 Woodlands Industrial Park E1
#05-13
Singapore 757700

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 6 May 2017

As per your instruction dated 11 May 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLE 1092 J. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLE 1092 J
Model : Mitsubishi Attrage
Year / Capacity : 2016/1193
Chassis No : MMBSTA13AHH000411
Engine No : 3A92UDC2163
Mileage : 6900
Colour : Maroon

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	185/55 R15	Yokohama	6.00	mm	Sport
REAR	O/S	:	185/55 R15	Bridgestone	4.00	mm	Sport
FRONT	N/S	:	185/55 R15	Yokohama	6.00	mm	Sport
REAR	N/S	:	185/55 R15	Bridgestone	4.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417583 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Sincerelead Garage Pte Ltd
38 Woodlands Industrial Park E1
#05-13
Singapore 757700

5. Estimated normal period of repair : 24 working days to complete.

6. Enclosed number of photograph : 294 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SLE 1092 J**
 Report No: **TP/ 05-17030/DY / 2017**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Bonnet	Repair	\$ 691.00	\$
2	Front headlamps	Damage	\$ 1088.00	\$ 1088.00
1	Front grille c/w chrome moulding	Damage	\$ 525.00	\$ 525.00
1	Front grille logo	Necessary	\$ 42.00	\$ 42.00
1	Front bumper	Damage	\$ 666.00	\$ 666.00
1	Front bumper clip (1 set)	Necessary	\$ 30.00	\$ 30.00
2	Front bumper fog lamps	Damage	\$ 548.00	\$ 548.00
2	Front bumper fog lamp covers	Damage	\$ 240.00	\$ 240.00
1	Front bumper lower grille	Damage	\$ 156.00	\$ 156.00
2	Front bumper side retainers	Necessary	\$ 24.00	\$ 24.00
2	Front fenders	Repair	\$ 876.00	\$
1	Front support panel	Damage	\$ 1058.00	\$ 1058.00
1	Front drive seat	Damage	\$ 3827.00	\$ Local Repair 3827.00 1977 2
1	Boot lid	Damage	\$ 828.00	\$ 828.00 352
2	Boot lid hinges	Damage	\$ 384.00	\$ 384.00
1	Boot lid lock	Damage	\$ 206.00	\$ 206.00
1	Boot lid logo	Necessary	\$ 41.00	\$ 41.00
1	Boot lid rubber	Necessary	\$ 148.00	\$ 148.00
1	Boot lid 'ATTRAGE' emblem	Necessary	\$ 38.00	\$ 38.00
1	Boot lid 'C & C' emblem	Necessary	\$ 50.00	\$ 50.00
1	Boot lid "AIRTRECK" emblem	Necessary	\$ 48.00	\$ 48.00
2	Rear taillamps	Damage	\$ 552.00	\$ 552.00
2	Rear taillamp panels	Damage	\$ 804.00	\$ 804.00 150
1	Rear end panel inner garnish	Damage	\$ 62.00	\$ 62.00
1	Rear end panel outer garnish	Damage	\$ 56.00	\$ 56.00
1	Rear bumper	Damage	\$ 708.00	\$ 708.00
1	Rear bumper clip (1 set)	Necessary	\$ 30.00	\$ 30.00
1	Rear bumper lower garnish	Damage	\$ 82.00	\$ 82.00
2	Rear bumper reflectors	Damage	\$ 40.00	\$ 40.00
2	Rear bumper side retainers	Necessary	\$ 24.00	\$ 24.00
1	Rear spare tyre board	Damage	\$ 185.00	\$ 185.00
1	Rear spare tyre panel	Damage	\$ 906.00	\$ 906.00
1	Rear chassis member	Repair	\$ 718.00	\$
1	Rear exhaust silencer	Damage	\$ 852.00	\$ 852.00 197
1	Rear exhaust silencer mounting	Necessary	\$ 28.00	\$ 28.00
2	Rear fenders	Damage	\$ 1446.00	\$ 1446.00
2	Rear fender inner trims LHV	Damage	\$ 316.00	\$ 316.00 18

Nett Items Sub Total \$ 18323.00 \$ 16038.00

12 996
 Part Disc - 20%
 1) 10396.80

Vehicle No: SLE 1092 J
Report No: TP/ 05-17030/DY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

Nett Items Total c/f \$ 18323.00 \$ 16038.00

Nett Items

1	Rear seat rear garnish	Damage	\$ 327.00	\$ 327.00 300
			\$ 18650.00	\$ 16365.00

Special Nett Items

1	Front number plate	Damage	\$ 50.00	\$ 50.00 35
1	Rear windscreen seal	Necessary	\$ 90.00	\$ 90.00 60
1	Rear windscreen sealant	Necessary	\$ 100.00	\$ 60.00
1	Rear number plate	Damage	\$ 50.00	\$ 50.00 XNN
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 280.00 200
1	Rear spare tyre insulator	Damage	\$ 120.00	\$ 120.00 80
			\$ 760.00	\$ 650.00

2) 735

Spare Parts Total \$ 19410.00 \$ 17015.00

Vehicle No: **SLE 1092 J**
 Report No: **TP/ 05-17030/DY / 2017**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 19410.00	\$ 17015.00
1	To provide towing service charge.	\$ 80.00	\$ 80.00 70
2	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 55.00	\$ 40.00 30
3	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 55.00	\$ 40.00 30
4	To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	\$ 350.00	\$ 180.00 20
5	To remove and refit fuel tank system.	\$ 150.00	\$ 80.00 70
6	To remove and refit rear bumper sensor.	\$ 130.00	\$ 80.00 30
7	To remove and refit air-con system, refill gas and test for leakages.	\$ 190.00	\$ 120.00 X
8	To remove and refit radiator system.	\$ 120.00	\$ 60.00 X
9	To remove and refit rear windscreen glass.	\$ 170.00	\$ 120.00 100
10	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 110.00	\$ 80.00 50
11	To remove and refit front drive seat.	\$ 180.00	\$ 80.00 50
12	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 3000.00	\$ 2860.00 1400
13	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2800.00	\$ 2640.00 1600
Sub Total		\$ 26800.00	\$ 23475.00

Vehicle No: SLE 1092 J
 Report No: TP/ 05-17030/DY / 2017

LABOUR COST


S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Sub Total c/f	\$ 26800.00	\$ 23475.00
14	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 300.00	\$ 300.00 150
	Total	\$ 27100.00	\$ 23775.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 21400.00

3) 3160

SDLS: TWENTY ONE THOUSAND FOUR HUNDRED ONLY


 Qualified Appraiser

Parts : \$ 10396.80
 S/Nett : \$ 735.00
 Labour : \$ 3660.00

 14791.80
 Lump Sum - 20%

 11853.44

L/S : \$ 11850 @ 10 days.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CS3/III17008961/Sqbe2-2	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 24-01-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SHD 4385Y	Veh. Inspected	SLE 1092J	
Policy No.		Coverage (\$)	0.00	
Claim No.	MCT17050214/001/MP	Excess (\$)	0.00	
Assign From	PRIYA	Assign Date	10/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MMBSTA13AHH000411	Colour	RED	
Odometer	99706	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/55 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/05/2017	Inspection Date	17/11/2017	
Survey held at	38 WOODLANDS IND PARK E1 #05-13			
Repairer	SINCERE LEAD AUTOMOTIVE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1092J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (N)	REPAIRED SEE LABOUR	691.00	-
2	FRONT HEADLAMPS (N)	REPLACED	1,088.00	1,088.00
1	FRONT GRILLE C/W CHROME MOULDING (N)	REPLACED	525.00	525.00
1	FRONT GRILLE LOGO (N)	REPLACED	42.00	42.00
1	FRONT BUMPER (N)	REPLACED	666.00	666.00
1	SET FRONT BUMPER CLIP (N)	REPLACED	30.00	30.00
2	FRONT BUMPER FOG LAMPS (N)	REPLACED	548.00	548.00
2	FRONT BUMPER FOG LAMP COVERS (N)	REPLACED	240.00	240.00
1	FRONT BUMPER LOWER GRILLE (N)	REPLACED	156.00	156.00
2	FRONT BUMPER SIDE RETAINERS (N)	REPLACED	24.00	24.00
2	FRONT FENDERS (N)	REPAIRED SEE LABOUR	876.00	-
1	FRONT SUPPORT PANEL (N)	REPLACED	1,058.00	1,058.00
2	BOOT LID HINGES (N)	REPLACED	384.00	384.00
1	BOOT LID LOCK (N)	REPLACED	206.00	206.00
1	BOOT LID LOGO (N)	REPLACED	41.00	41.00
1	BOOT LID RUBBER (N)	REPLACED	148.00	148.00
1	BOOT LID 'ATTRAGE' EMBLEM (N)	REPLACED	38.00	38.00
1	BOOT LID 'C & C' EMBLEM (N)	REPLACED	50.00	50.00
1	BOOT LID "AIRTRECK" EMBLEM (N)	REPLACED	48.00	48.00
2	REAR TAILLAMPS (N)	REPLACED	552.00	552.00
2	REAR TAILLAMP PANELS (N)	REPLACED	804.00	150.00
1	REAR END PANEL INNER GARNISH (N)	REPLACED	62.00	62.00
1	REAR END PANEL OUTER GARNISH (N)	REPLACED	56.00	56.00
1	REAR BUMPER (N)	REPLACED	708.00	708.00
1	SET REAR BUMPER CLIP (N)	REPLACED	30.00	30.00
1	REAR BUMPER LOWER GARNISH (N)	REPLACED	82.00	82.00
2	REAR BUMPER REFLECTORS (N)	REPLACED	40.00	40.00
2	REAR BUMPER SIDE RETAINERS (N)	REPLACED	24.00	24.00
1	REAR SPARE TYRE BOARD (N)	REPLACED	185.00	185.00
1	REAR SPARE TYRE PANEL (N)	REPLACED	906.00	906.00
1	REAR CHASSIS MEMBER (N)	REPAIRED SEE LABOUR	718.00	-
1	REAR EXHAUST SILENCER (N)	REPLACED	852.00	597.00

Report Ref No. CS3/III17008961/Sqbe2-2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER MOUNTING (N)	REPLACED	28.00	28.00
2	REAR FENDERS (N)	REPLACED	1,446.00	1,446.00
2	REAR FENDER INNER TRIMS (N)	N/S REPLACED	316.00	158.00
1	BOOT LID (N)	REPLACED	828.00	828.00
1	REAR SEAT REAR GARNISH (N)	REPLACED	327.00	300.00
	LESS 10% DISCOUNT		-	-1,144.40
			14,823.00	10,299.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DRIVE SEAT (LOCAL REPAIR) (SN)	REPLACED	3,827.00	350.00
1	FRONT NUMBER PLATE (SN)	REPLACED	50.00	35.00
1	REAR WINDSCREEN SEAL (SN)	REPLACED	90.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	REPLACED	100.00	60.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	REPLACED	350.00	200.00
1	REAR SPARE TYRE INSULATOR (SN)	REPLACED	120.00	80.00
			4,587.00	785.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE CHARGE.		80.00	70.00
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		55.00	30.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		55.00	30.00
	TO REMOVE AND REFIT REAR CUSHION SEATS, RADIO SPEAKER BOARD, INTERIOR UPHOLSTERY TO FACILITATE THE REPAIRS.		350.00	80.00
	TO REMOVE AND REFIT FUEL TANK SYSTEM.		150.00	70.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		130.00	30.00
	TO REMOVE AND REFIT AIR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGES.	NOT NECESSARY	190.00	-
	TO REMOVE AND REFIT RADIATOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		170.00	100.00
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.		110.00	50.00
	TO REMOVE AND REFIT FRONT DRIVE SEATS.		180.00	50.00

Report Ref No. CS3/III17008961/Sqbe2-2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF BONNET, FRONT FENDERS AND REAR CHASSIS MEMBER.		3,000.00	1,400.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		2,800.00	1,600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		300.00	150.00
			7,690.00	3,660.00
GRAND TOTAL			27,100.00	14,744.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,800.00
--	--	--	--	-----------

Report Ref No. CS3/III17008961/Sqbe2-2

YEANG WAI KEEN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.