

range & day

Received

ASS: REQ BY

REF: CS3/EQI17021892/WBSE

Special Instruction:

Surveyor: Wilson

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of EQI

Date/Time: 16/11/17 @ 11:35am

Estimated Cost: Bill to:

OD (H) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFV 5078G

Insured: SJR 1916 M

at Workshop m/s JC Motors

Tel: 6684 6914

of 13 kaki Bukit Rd 4 # 01-15 417807

Policy No: DMCFHQ17-000185

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 11/11/2017

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement

Date/Time: 11:12am @ 16/11/17

Person Contacted: jamie

Vehicle: IN OUT

Date/Time	Action/Instruction (X) Estimate
	SFV 5078G - NA / EQI17021883 / h4-D.O.A : 11/11/2017
	SJR 1916 M - NA / EQI17021883 / h4-D.O.A : 11/11/2017
	Dismantle Part: 20.11.2017



## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

C	Reference No.
C	Customer Code
N	Assign From
C	Assign Date
C	Veh No (Inspected)
C	Veh No (Insured)
C	D.O.A
C	Policy No
C	Claim No
C	Insurance Authorisation (CA /REV/REP)
C	Report Type
C	Weekend Charges
N	Survey held at/Repairer
C	Excess

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

C	Vehicle No
C	Regn Month/Year
N	Vehicle Type
N	Make & Model
C	Engine Capacity. (C.C)
N	Colour
C	Odometer. (Sp.Reading)
C	Chassis No
N	General Condition
N	Steering
N	Brake
N	Modification (Modi)
C	Tyre Size
N	Tyre Make
C	Tyre Balance
C	Date of Inspection
N	Survey held
N	Des.of Damages

**(2) System - (Views/Merimen)**

✓			
---	--	--	--

C	Damaged Vehicle Photographs Uploaded
---	--------------------------------------

**(3) Workshop Estimate/Assignment Form**


N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

**(4) System - (Views/Merimen)**

--	--	--	--

C	Resurvey photo Uploaded
---	-------------------------

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS3/EQ117021892/Wb	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 16-11-2017	
		Code : EQI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SJR 1916M	Veh. Inspected	SFV 5078G
Policy No.	DMCFHQ17-0000185	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	ELAINE CHEONG	Assign Date	16/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	11/11/2017	Inspection Date	16/11/2017
Survey held at	JC MOTORS - 13 KAKI BUKIT RD 4 #01-15		
Repairer	-		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@eqinsurance.com.sg>  
**Sent:** Thursday, 16 November, 2017 11:35 AM  
**To:** 'assignments'  
**Subject:** FW: PRE-INSPECTION OF SFV5078G / EQ REF: SJR1916M (DOA: 11.11.2017)  
**Attachments:** OI - SJR1916M.PDF; PRS - SFV5078G.pdf

Our ref : SJR1916M  
TP ref : SFV5078G  
Policy No. : DMCFHQ17-000185

Dear All,

Please refer to the email below.

Please proceed to survey the third party vehicle, SFV5078G on a without prejudice basis.

We enclosed the following documents for your perusal:

- Insured, SJR1916M – GIA report
- PRS – SFV5078G

Please acknowledge receipt. Thank you.

Regards,

**Elaine Cheong**  
Senior Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of*

---

**From:** Kelley Choong [mailto:kelley@chiaarul.com]  
**Sent:** Wednesday, November 15, 2017 10:09 AM  
**To:** Elaine Cheong  
**Subject:** RE: PRE-INSPECTION OF SFV5078G / EQ REF: SJR1916M (DOA: 11.11.2017)

Dear Elaine,

Our client is agreeable to your proposed surveyor:

6) LKK Auto Consultants Pte Ltd

Tel: 6256-3561

Fax: 6741-4108

Regards,

**Ms Kelley Choong**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Elaine Cheong [<mailto:elaine.cheong@eqinsurance.com.sg>]

**Sent:** Tuesday, November 14, 2017 6:00 PM

**To:** Kelley Choong <[kelly@chiaarul.com](mailto:kelly@chiaarul.com)>

**Subject:** RE: PRE-INSPECTION OF SFV5078G / EQ REF: SJR1916M (DOA: 11.11.2017)

**WITHOUT PREJUDICE**

Dear Kelley,

We refer to your email of 14.11.2017.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

<b>1) AJAX Inspection Services Pte Ltd</b> Tel: 6255 0808 Fax: 6849 9155	<b>2) Automobile Inspection Services Pte Ltd</b> Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
<b>3) LBS Automotive Appraisal Pte Ltd</b> <b>L.B.S. Auto Consultants Pte Ltd</b> Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	<b>4) Priority Services</b> <b>Tel: 62934822</b> <b>Fax: 62963283</b> <b>Contact Person: Hui Lian</b>
<b>5) RT Appraisal Pte Ltd</b> Tel: 67486076 Fax: 67480361	<b>6) LKK Auto Consultants Pte Ltd</b> Tel: 6256-3561 Fax: 6741-4108

Contact Person: Ricky Teng	
<b>7) Kelvin Automotive Appraising Services</b> Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	<b>8) Automotive Appraiser &amp; Surveying Services</b> Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
<b>9) JP Knights Pte Ltd</b> Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

**Elaine Cheong**

Senior Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 62234190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of*

**From:** Kelley Choong [<mailto:kelley@chiaarul.com>]

**Sent:** Tuesday, November 14, 2017 12:15 PM

**To:** Janet Tan; Elaine Cheong

**Subject:** PRE-INSPECTION OF SFV 5078G

Dear Sirs,

Enclosed for your attention.

Regards,

**Ms Kelley Choong**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.



**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

Our Ref : SFV 5078G

Your Ref :

14 November 2017

EQ INSURANCE COMPANY LTD

BY EMAIL

Dear Sir,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : TAY BEE LING PRISCILLA**  
**ACCIDENT INVOLVING SFV 5078G & SJR 1916M ALONG UPPER**  
**SERANGOON ROAD ON 11/11/17**  
**PRE-REPAIR INSPECTION NOTICE**

1. We act for Tay Bee Ling Priscilla, the owner of motor vehicle SFV 5078G, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SJR 1916M damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor cycle at JC Motors (Pte.Ltd.) of 13 Kaki Bukit Road 4 #01-16 Bartley Biz Centre S417807 (T: 6584 6914 / 9743 3222). IS Ivan X
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.

Yours faithfully,

  
**MR ARULCHELVAN S**

cc: Client (Fax: 6584 6912)

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	14/11/2017 10:33
Date Of Accident	11/11/2017 18:50
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFV5078G
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	TAY BEE LING PRISCILLA
NRIC No	S1584419A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82129494
Alternative Phone No	OFFICE-82129494

#### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-2.0 L (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

#### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3018201700
Cover Note Number	

#### Driver

Name of Driver	JOSEPH ONG THIAM SENG
NRIC No	S1707468G
Date Of Birth	25/05/1965
Occupation	INDOOR
Date Of Driving Pass	18/02/1992
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83221731
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name GEYLANG N.P.C  
 Police Station Address ROAD: 132 PAYA LEBAR ROAD , POSTCODE: 409014 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SJR1916M  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number  
 Email Address

## Sketch Plan #2 Pg. 1

### SKETCH PLAN



A, SFY 5072G

B 259. 1914/19

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to TP report T/20171112/2059.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_





**SINGAPORE  
POLICE FORCE**



T/20171112/2059

3 of 3

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

Report No. T/20171112/2059

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 CHAN LIP YANG, DEMIAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt NORASHIKIN BINTE DAUD

Contact No.: 65476439

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

12/11/2017 15:04

Classification Of Case:



# SINGAPORE POLICE FORCE



T/20171112/2059

1 of 3

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

Report No. T/20171112/2059

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 12/11/2017 15:04	Vide Report No.: F/20171111/0230	Station Diary No.: 38
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: JOSEPH ONG THIAM SENG	Address: APT BLK 147 PASIR RIS STREET 13 #09-22 SINGAPORE 510147
ID Type / ID No.: NRIC NO / S1707468G	Contact No.: Home/Office: Mobile: 83221731
Nationality: SINGAPORE CITIZEN	Email:
Sex: Male Age: 52 Date of Birth: 25/05/1965	Type of Informant: Driver
Race: Chinese	Language: Institution / School Name:
Occupation: Operations Manager	Driving Licence Information: Class: 3 Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/11/2017 18:50	Type of Location: Bend
Location: Along Road 1 Traveling Toward Road 2 UPPER SERANGOON ROAD UPPER PAYA LEBAR ROAD				
Weather: Cloudy		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFV5078G	Car		CIVIC 2.0L A		Seriously Damaged	1
SJR1916M	Car		LANCER 1.6 A		Totally Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



**SINGAPORE  
POLICE FORCE**



T/20171112/2059

2 of 3

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

Report No. T/20171112/2059

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	JOSEPH ONG THIAM SENG	ID No.	S1707468G
Related Vehicle	SFV5078G (Car)	Contact No.	83221731
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	11/11/2017	Date Discharge	11/11/2017
No. of Days granted Medical Leave	04	Degree of Injury	Slight
<b>Passenger</b>			
Name	CHAIMAK CHANRAM	ID No.	S7270540H
Related Vehicle	NIL	Contact No.	83736881
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	11/11/2017	Date Discharge	11/11/2017
No. of Days granted Medical Leave	04	Degree of Injury	Slight

**Brief Details.**

On 11 November 2017 at about 6:50pm, I was travelling along Upper Serangoon Road in vehicle bearing license SFV5078G. I am travelling on the right lane, about to make a right turn into Upper Paya Lebar Road. The right green arrow was lit up so I proceeded to make a right turn. Out of a sudden, a car bearing license plate number SJR1916M drove from the on coming lane and collided onto my car. This resulted in my car's front left side to collide into vehicle SFV5078G front bumper. My car suffered damages on the front left side and the headlights were all smashed. The vehicle SJR1916M bonnet was totally smashed after the collision.

After the collision, my passenger and I suffered a minor black out and regained consciousness about 8 minutes after the impact. Both of the front airbags were deployed. While I was being interviewed by the Traffic Police officer, my passenger proceeded to Mount Alvernia Hospital first as she sustained a cut on her left tricep area. I also experienced a pain in my lower back and left knee. As such I went down to Mount Alvernia hospital for a check up and got 4 days of MC from the doctor.

I was instructed by Traffic Police officer to lodge a Road Traffic Accident report.




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
EQ INSURANCE COMPANY LTD		Ref: CS3/EQ117021892/Wbs2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND		Date: 16-04-2018		
COMPLEXSINGAPORE 069110		Code: EQ1		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJR 1916M	Veh. Inspected	SFV 5078G	
Policy No.	DMCFHQ17-000185	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	ELAINE CHEONG	Assign Date	16/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMF26408S202029	Colour	LIGHT GREY	
Odometer	176430 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45R17	GOODYEAR	4 mm	
L/H Front Tyre	225/45R17	GOODYEAR	4 mm	
R/H Rear Tyre	225/45R17	GOODYEAR	4 mm	
L/H Rear Tyre	225/45R17	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S FRONT PORTION.				
5. General Information				
Accident Date	11/11/2017	Inspect Date / Time	16/11/2017 ( 12:40 PM )	
Survey held at	JC MOTORS - 13 KAKI BUKIT RD 4 #01-15			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,900-\$17,900				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			13 Working Days	

Report Ref No. CS3/EQ117021892/Wbs2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, Minst AEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.