

INS. CASE OWNER:

S. Heng
Wong

CC 4/AXA17021896

1 Aug 9

JK
IDAC

Surveyor:

ADRIAN

DOI:

15/11/17

Date / Time:

16/11/17

Registered in Merimen:

15/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

P2 1200G

Name of Insured:

REN QUAN TRANSPORT

Insured Tel No.:

HP:

Excess Sec II :SS

1,500.00

D.O.A.:

14/11/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: LOH LAY CHENG

Driver Tel No.:

92255011

(V/L YES / NO)

Claim No.:

C0459484

Policy No.:

GA164921

Make / Model:

ISRU LT134L-7.80 (M)

Place of Accident:

CHANGI BUSINESS PARK AVE 3

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKN 3334M



INSRS:

WSP: NHT

Tel:

Liability: NON ARC

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SKN 3334M - CE/CTE17007429/S9432 D09 19/01/17

P2 1200G - X

11/12/17 (THU THU)

KAD ESTIMATE & PA

12/1/18

OI collided onto stationary vehicle while
overtake it vehicle.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

27/1/18

Confirm with:

Sukyi

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS

5600.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

420.00

(

560 x 7 days)

Loss of Income (LOI):

SS

(

5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

5.35

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

6025.35

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6025.35

Name 1:

NEW HOCK TECK MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 8241

Fax: 6741 7276

UEN: 201716370K

YEO HAN PING ALVIN

15/11/2017

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AXA

Thin Thin

WVWZZ2A0ZEW 363173

Accident date: 14/11/2017

Estimated repair cost for vehicle no: SKN3334M VOLKSWAGEN A7 1.4 A '14

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Door <i>Dented</i>		1878.25 523.81
2	2	Front R/H Door Hinge <i>But Lower</i>	106.65	213.3 106.65
3	1	Front R/H Door Side Mirror Assy <i>Distorted</i>		1092.45 ✓
4	1	Front R/H Door Inner Lock <i>new</i>		\$357.50 ✓
5	1	Front R/H Door Inner Rubber <i>new</i>		\$133.65 ✓
6	1	Front R/H Door Inner Trim Board <i>3 new</i>		\$888.90 ✓
7	1	Front R/H Door Gear Motor Assy <i>new</i>		\$327.95 ✓
8	1	Front R/H Fender <i>Dented</i>		\$547.75 ✓
9	1	Front R/H Fender Mud Flap <i>new</i>		\$88.60 ✓
10	1	Front R/H Fender Cowling <i>new</i>		\$157.40 ✓
11	1	Front R/H Tyre <i>new</i>		\$450.00 ✓
12	1	Front R/H Rim <i>new</i>		\$1,209.95 ✓
13	1	Front R/H Lower Arm <i>But</i>		\$370.75 ✓
14	1	Front R/H Knuckle Arm <i>But</i>		\$616.45 ✓
15	1	Front R/H Knuckle Arm Bearing <i>new</i>		\$469.25 ✓
16	1	Front R/H Shock Absorber <i>But</i>		\$318.95 ✓
17	1	Front R/H Drive Shaft <i>3 new</i>		\$2,229.95 ✓
18	1	Front Steering Rack <i>new</i>		\$4,921.65 ✓
			Subtotal :-	\$16,272.70

5179.78 SW 700

4920.79

Labour charges

To remove & refit front R/H door, gear motor, trim board,
glass, lock & rubber

~~\$220.00~~ 80

To remove & refit front R/H undercarriage

~~\$380.00~~ 200

To remove & refit front R/H drive shaft & steering rack

~~\$450.00~~ x

To check wheel alignment

~~\$150.00~~ 80

Towing fee

~~\$100.00~~ x

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ x

Panel beating

~~\$1,400.00~~ 500

Spray painting

~~\$1,400.00~~ 500

Subtotal :- \$4,350.00

Total:- \$20,622.70

total: 7010.79

e/c: 5.6K

0.6 Days

5.6K.
0.6 Days

LK2 Ltd Cons: Having signed hereby notify
the Repairer of the following:

- To resurvey & underlined from Lunking
- To disassemble & refit to the Lunking
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	9813F

Vehicle Details

Vehicle No.	SKN3334M
Vehicle to be Exported	Yes
Intended De-registration Date	15 Nov 2017
Vehicle Make	VOLKSWAGEN
Vehicle Model	GOLF A7 1.4 TSI AT 5G13GZ W/O HID
Primary Colour	Grey
Manufacturing Year	2014
Engine No.	CXS095020
Chassis No.	WVWZZZAUZEW363173
Maximum Power Output	90.0 kW (120 bhp)
Open Market Value	\$20,925.00
Original Registration Date	30 May 2014
First Registration Date	30 May 2014
Transfer Count	0
Actual ARF Paid	\$6,295.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	29 May 2024
PARF Rebate Amount	\$4,721.00

Intended COE Rebate Details

COE Expiry Date	29 May 2024
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$60,002.00
COE Rebate Amount	\$39,227.00
Total Rebate Amount	\$43,948.00

The information contained herein is correct as at 15 Nov 2017

Print Received Message

This mail is associated with :

***SKN3334M (C0459484)**
[PZ1200G]

TP
YEO HAN PING ALVIN
Nov 14 2017 5:00PM
[REN QUAN TRANSPORT]
New Hock Teck Motor Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 22/03/2018 11:46 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6025.35) - SKN3334M - Claim Handler: Stacey Ng

Approved:6025.35.

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1712-0058/ SKN3334M
Your Ref : PZ1200G
Date : 19th December 2017

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Dear Sirs,

**RE: ACCIDENT INVOLVING SKN3334M & PZ1200G AT CHANGI BUSINESS PARK AVE 3 ON
14.11.2017, 17:50HR**

We are instructed by **YEO HAN PING ALVIN** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SKN3334M** was damaged by vehicle **PZ1200G** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 5,600.00
2) Loss of Use for 07 days (6 + 1 Weekend)	\$ 420.00
3) LTA Search Fees	\$ 5.35
	<u>\$ 6,025.35</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$6,025.35** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,



NEW HOCK TECK MOTOR PTE LTD



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

12 JANUARY 2018

REN QUAN TRANSPORT
356 YISHUN RING ROAD
#08-1828
SINGAPORE 760356

Dear Sir/Madam,

OUR REF : CC4/AXA17021896/Aua3
YOUR REF : PZ 1200G

**ACCIDENT INVOLVING PZ 1200G AND SKN 3334M ALONG CHANGI BUSINESS
PARK AVE 3 ON 14/11/2017**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s **New Hock Teck Motor Pte Ltd** acting on behalf of the owner of SKN 3334M against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

There is an excess of S\$ 1,500.00 on Third Party claims under your policy. Please make a cheque payment of S\$ 1,500.00 payable to "AXA Insurance Singapore Pte Ltd" with your vehicle registration number and the date of accident indicated on the back of your cheque and mail to AXA Insurance Singapore Pte Ltd.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 07 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to thinthin@lkkauto.com within 07 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at thinthin@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

THIN THIN HLAING
LKK Auto Consultants Pte Ltd
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

Cc AXA Insurance Pte Ltd
(Motor Claims Dept)

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. 9FN 3334M and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 15 day of 11 2017.

Signature :

Name :

ID No. :

Address :

Witness Signature :

Witness Name :

Witness ID :

Witness Address :


Yeo Han Ping Alvin
S85 09813F
Bik 113A #16-283 MUNAIR ROAD S 322113


Chew Yuel Yin
S8826618H
1 Kaki Bukit Avenue 6 #01-43
Singapore 417883



redefining / insurance

WITHOUT PREJUDICE

RECEIVED BY: [Signature]

RECEIVED BY: [Signature]

RECEIVED BY: [Signature]

CLAIM REF : C0459484
INSURED : REN QUAN TRANSPORT

DISCHARGE VOUCHER

We/I [YEO HAN PING ALVIN, S8509813F] hereby agree to accept the sum of dollars Six Thousand Twenty Five and Cents Thirty Five Only (S\$6,025.35) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. PZ 1200G as a result of an accident along CHANGI BUSINESS PARK AVE 3 on 14/11/2017 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SKN 3334M.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. PZ 1200G in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. PZ 1200G.

Dated this 27 day of 03 2018

Claimant's Signature : [Signature]

NRIC no./ Company Stamp : S8509813F

Occupation/ Business : _____

Address : Blk 113A McHuan Rd #16-282 Singapore 372113

Telephone No. : 97512512

Witness's Name : 新 福 德 車 廠 Sukyi Chong

Witness's Signature : [Signature]

Witness's NRIC No. : _____

NEW HOCK TECK MOTOR PTE LTD
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit Singapore 417883
Tel: 6747 9241 Fax: 6741 7276
Email: admin@nhtmotor.com
UEN: 201718370K



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#B1-01,

Singapore 068811

Client: YEO HAN PING ALVIN

Invoice No : NPL1712-0058

Date : 19-Dec-17

Date of Accident : 14-Nov-17

Vehicle No. : SKN3334M

Model Type : VW Golf

Descriptions		Amount
Lump Sum Repair Cost		5,600.00
Total		: 5,600.00

SIN DOLLARS: FIVE THOUSAND AND SIX HUNDRED ONLY





Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 15 Nov 2017 / 13:16:36

Receipt Date/Time : 15 Nov 2017 / 13:16:36

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171115-000955

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - PZ1200G As at 14 Nov 2017/17:50:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - PZ1200G Enquiry Fee 20171115131559064237	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		5.00	0.35	5.35
Rounding Difference				0.00
Total Amount Payable				5.35
Paid By				
	20171115131603507	Direct Debit: eNETS Debit (Internet Banking)		5.35
Total				5.35
Cash Change				0.00
Tendered Amount				5.35
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[Print Receipt](#) [OK](#) [Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2017		15 Nov 2017 16:15 Edit Adj Rpt	\$5,600.00 Edit Estimates	\$5,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	REN QUAN TRANSPORT, Co. Reg. No.: 52896070M, Tel: +6596659336		
Main Claimant:	YEO HAN PING ALVIN, ID: S8509813F		
Vehicle Reg. No.:	SKN3334M	Date of Loss:	14/11/2017 17:00 - :59
Claim Type:	TP / C0459484	Policy/Cover Note No.:	GA164921 (Comprehensive)
Vehicle Reg. No. (Insured):	PZ1200G	Policy No. (Claimant):	5090866199
		Excess:	\$1,500.00
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/11/2017]		
Adj Asg. Remarks:	Marcus Chua of LKK as SJE. NON ARC. Please retrieve TP GIA Report from TP repairer		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)































- AXA_SG (22/03/2018): Alert - Adj Mandate Approved (\$6025.35) - SKN3334M - Claim Handler: Stacey Ng
- AXA_SG (08/12/2017): TP settlement - C0459484/GA164921
- AXA_SG (15/11/2017): WP / New TP Assignment - C0459484/GA164921

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN3334M (C0459484)
[PZ1200G]
TP
YEO HAN PING ALVIN
Nov 14 2017 5:00PM
[REN QUAN TRANSPORT]
New Hock Teck Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>	
Letters/Correspondences			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	15/11/17 15:59	Email from TP - Marcus Chua of LKK	 Load TIF	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 19:11	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/18 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>
2	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/03/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/03/18 09:23	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
19	09/03/18 09:23	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
20	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	09/03/18 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

28	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	09/03/18 09:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	28/03/18 10:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	28/03/18 10:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	28/03/18 10:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	15/11/17 15:20	EMAIL_ABS	1	Load PDF
2	15/11/17 15:20	CO CLAIMAINT_ABS	1	Load PDF
3	15/11/17 16:12	GA164921-Certificate of Insurance.pdf	1	Load PDF
4	15/11/17 16:12	GA164921-Policy Schedule.pdf	1	Load PDF
5	08/12/17 12:07	SKN3334M - TP GIA Report.PDF	1	Load PDF
6	08/12/17 12:07	PZ1200G - INSD GIA Report.PDF	1	Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/17 11:42	TP GIA REPORT	1	Load PDF
2	12/03/18 16:14	LTA SEARCH	1	Load PDF
3	29/03/18 10:58	WORKSHOP INVOICE	1	Load PDF
4	29/03/18 10:58	AUTHORISATION TO ACT FORM	1	Load PDF
5	29/03/18 10:58	DISCHARGE VOUCHER	1	Load PDF
6	29/03/18 10:58	LOD	1	Load PDF
7	29/03/18 10:58	LETTER TO OI	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	PZ1200G (Insd veh)	Model:	VOLKSWAGEN GOLF 1.4 TSI
	SKN3334M (TP veh)		(A7) (5G13GZ) (A)
Date of Accident:	14/11/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		20,622.70
Final Repair Cost	:	\$		5,600.00
Loss of Use	:	\$		420.00
Rental (if any)	:	\$		0.00
LTA / GIA Search Fee	:	\$		5.35
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		6,025.35

7.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability ____ 100 ____ (%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: ____			
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	: \$	6,025.35
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

29 Mar
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17021896/AUA3Q2

Date: 29/03/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA164921

Claimant Vehicle No: SKN3334M

Insured Vehicle No:

PZ1200G

Date of Loss: 14/11/2017

Nature of Claim:

TP

Claim No: C0459484

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN3334M

Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A)

Engine No: CXS095020

Reg. Date: 30/05/2014 (Man. Year: 2014)

Chassis No: VVVZZZAUZEW363173

Colour: Grey

Odometer: 42929 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,272.70	5,620.79	10,651.91	65.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,390.00	2,960.00	68.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,622.70	7,010.79	13,611.91	66.00
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	20,622.70	5,600.00	15,022.70	72.85
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		6,025.35		

INSPECTION

Date of Assignment: 15/11/2017

Date Inspected: 15/11/2017 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2018)
Parts:	144	VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN3334M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT R/H DOOR (CONSISTENT)	Dented	1,878.25 F	*1,523.88 FL
2	1	*FRONT R/H DOOR HINGE (CONSISTENT)	Lower Bent	213.30 F	*106.65 FL
3	1	*FRONT R/H DOOR SIDE MIRROR ASSY (CONSISTENT)	Distorted	1,092.45 F	*1,092.45 FL
4	1	*FRONT R/H DOOR INNER LOCK (CONSISTENT)	Not Necessary	357.50 F	*- FL
5	1	*FRONT R/H DOOR INNER RUBBER (CONSISTENT)	Necessary	133.65 F	*133.65 FL
6	1	*FRONT R/H DOOR INNER TRIM BOARD (CONSISTENT)	Not Necessary	888.90 F	*- FL
7	1	*FRONT R/H DOOR GEAR MOTOR ASSY (CONSISTENT)	Not Necessary	327.95 F	*- FL
8	1	*FRONT R/H FENDER (CONSISTENT)	Dented	547.75 F	*547.75 FL
9	1	*FRONT R/H FENDER MUD FLAP (CONSISTENT)	Not Necessary	88.60 F	*- FL
10	1	*FRONT R/H FENDER COWLING (CONSISTENT)	Not Necessary	157.40 F	*- FL
11	1	*FRONT R/H TYRE (CONSISTENT)	Not Necessary	450.00 F	*- FL
12	1	*FRONT R/H RIM (CONSISTENT)	Cut	1,209.95 FS	*700.00 FS
13	1	*FRONT R/H LOWER ARM (CONSISTENT)	Bent	370.75 F	*370.75 FL
14	1	*FRONT R/H KNUCKLE ARM (CONSISTENT)	Bent	616.45 F	*616.45 FL
15	1	*FRONT R/H KNUCKLE ARM BEARING (CONSISTENT)	Necessary	469.25 F	*469.25 FL
16	1	*FRONT R/H SHOCK ABSORBER (CONSISTENT)	Bent	318.95 F	*318.95 FL
17	1	*FRONT R/H DRIVE SHAFT (CONSISTENT)	Not Necessary	2,229.95 F	*- FL
18	1	*FRONT STEERING RACK (CONSISTENT)	Not Necessary	4,921.65 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,272.70	5,879.78
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	258.99
Total Parts (\$\$)	16,272.70	5,620.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT R/H DOOR ,GEAR MOTOR ,TRIM BOARD ,GLASS ,LOCK & RUBBER	New	220.00	80.00
2	TO REMOVE & REFIT FRONT R/H UNDERCARRIAGE	New	380.00	200.00
3	TO REMOVE & REFIT FRONT R/H DRIVE SHAFT & STEERING RACK	New	450.00	0.00
4	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
5	TOWING FEE	New	100.00	0.00
6	TO CHECK WIRING	New	100.00	30.00
7	TUFF KOTE	New	150.00	0.00
8	PANEL BEATING	New	1,400.00	500.00
9	SPRAY PAINTING	New	1,400.00	500.00
Gross Labour Cost (S\$)			4,350.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >