



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

1 2008 TOYOTA MARK X 2.5 (SJQ5017L)

Date of Loss

14 November 2017

Time of Loss

11.30

Loss Description

SJQ5017L-HIT WALL

Comment

### Workshop Details

Total Rebate Amount

14405

Nett Loss Amount

\$19,595.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion \*

22/07/2018



Days of work completion \*

212



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

SJQ5017L

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

14/05/2009



Mileage

35566

Age of Vehicle

8

### Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2008

ASSESSMENT INFO...

2008

CATEGORY

Driver Name

FNOL INFORMATI...

LIM ENG BENG @ LIM JIA LE

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... MARK X 2.5

ASSESSMENT INFO... MARK X 250G-F A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... GRX1203061863

CATEGORY Date of Birth

FNOL INFORMATI... 20 February 1959

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 59

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... GRX1203061863

CATEGORY Engine No

POLICY INFORMAT... 4GR0472436

ASSESSMENT INFO... 4GR0472436

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2499

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 34000

FNOL INFORMATI... 17

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

|                    |                                     |
|--------------------|-------------------------------------|
| FNOL INFORMATI...  | BLK 290E #07-123, 654290, Singapore |
| POST SURVEY INF... | <input type="text"/>                |

---

|                    |                      |
|--------------------|----------------------|
| CATEGORY           | Address type         |
| FNOL INFORMATI...  | Residential          |
| POST SURVEY INF... | <input type="text"/> |

---

|                    |                      |
|--------------------|----------------------|
| CATEGORY           | Gender               |
| FNOL INFORMATI...  | Male                 |
| POST SURVEY INF... | <input type="text"/> |

---

|                    |                      |
|--------------------|----------------------|
| CATEGORY           | Marital status       |
| FNOL INFORMATI...  | Married              |
| POST SURVEY INF... | <input type="text"/> |

---

|                    |                      |
|--------------------|----------------------|
| CATEGORY           | Identification #     |
| FNOL INFORMATI...  | S1380558Z            |
| POST SURVEY INF... | <input type="text"/> |

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

## Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

## Detailed Assessment

Inspection Date \*

17/11/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/60R16

## Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



## Tyre Condition

Spare wheel

Rear Tyre Size

215/60R16

Front left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear left side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

## Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary   **Parts**

Add

Approve

Deny

|  | EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                     | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR/ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) |
|--|------|-------|-----------|----------|------|-------------------------------|-------------|------------------------|-----------|------------|-------------|------------|-----------|-----------------|----------------|
|  |      | 1     | 1         |          |      | Front bonnet                  |             |                        | Bent      | 0          |             |            |           | 0               | Reviewing      |
|  |      | 2     | 8         |          |      | Front bonnet sponge clips     |             |                        | Necessary | 0          |             |            |           | 0               | Reviewing      |
|  |      | 3     | 8         |          |      | Front bonnet seal clip        |             |                        | Necessary | 0          |             |            |           | 0               | Reviewing      |
|  |      | 4     | 1         |          |      | Front bonnet corner rubber RH |             |                        | Necessary | 0          |             |            |           | 0               | Reviewing      |
|  |      | 5     | 1         |          |      | Front bumper                  |             |                        | Damaged   | 0          |             |            |           | 0               | Reviewing      |
|  |      | 6     | 1         |          |      | Front bumper retainer LH      |             |                        | Necessary | 0          |             |            |           | 0               | Reviewing      |
|  |      | 7     | 1         |          |      | Front bumper retainer RH      |             |                        | Necessary | 0          |             |            |           | 0               | Reviewing      |
|  |      | 8     | 1         |          |      | Front bumper sponge           |             |                        | Cracked   | 0          |             |            |           | 0               | Reviewing      |
|  |      | 9     | 1         |          |      | Front bumper reinforcement    |             |                        | Bent      | 0          |             |            |           | 0               | Reviewing      |
|  |      | 10    | 8         |          |      | Front bumper clips            |             |                        | Necessary | 0          |             |            |           | 0               | Reviewing      |
|  |      | 11    | 1         |          |      | Front fender RH               |             |                        | Buckled   | 0          |             |            |           | 0               | Reviewing      |
|  |      | 12    | 1         |          |      | Front fender inner shield RH  |             |                        | Deformed  | 0          |             |            |           | 0               | Reviewing      |

|  | EDIT | SR NO | QUANTITY | MATERIAL | SIDE | PART NAME                               | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR/ BTTR% | DISCOUNT% | SALVAGE% | PART PRICE(NET) | ACTION (PARTS) |
|--|------|-------|----------|----------|------|-----------------------------------------|-------------|------------------------|-----------|------------|-------------|-----------|----------|-----------------|----------------|
|  |      | 13    | 6        |          |      | Front fender inner shield clips         |             |                        | Necessary | 0          |             |           |          | 0               | Reviewing      |
|  |      | 14    | 1        |          |      | Front headlamp RH                       |             |                        | Broken    | 0          |             |           |          | 0               | Reviewing      |
|  |      | 15    | 1        |          |      | Front headlamp panel RH                 |             |                        | Repair    | 0          | 0           | 0         | 0        | 0               | Deny           |
|  |      | 16    | 1        |          |      | Front bumper foglight cover RH (Grille) |             |                        | Missing   | 0          |             |           |          | 0               | Reviewing      |
|  |      | 17    | 1        |          |      | Front support panel top garnish         |             |                        | Cut       | 0          |             |           |          | 0               | Reviewing      |
|  |      | 18    | 10       |          |      | Front support panel top garnish         |             |                        | Necessary | 0          |             |           |          | 0               | Reviewing      |
|  |      | 19    | 1        |          |      | Air-filter casing                       |             |                        | Cracked   | 0          |             |           |          | 0               | Reviewing      |

## Labour

|  | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                                                                                                                                                                                                     | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE |
|--|------|-------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------|-------|-----------------|---------|--------|
|  |      | 1     |                         | Check wiring function                                                                                                                                                                                                         | 40         | 0             |       | Reviewing       |         |        |
|  |      | 2     |                         | Remove necessary parts; jacking, panel beating, repair and straighten front inner panel, front support panel, front bonnet, front fender RH, front headlamp panel RH, front bumper, front RH wheel housing and affected areas | 700        | 0             | 0     | Reviewing       |         |        |
|  |      | 3     |                         | Putty and respray front inner panel, front headlamp panel RH, front support panel, front fender RH, front bumper, front wheel house RH, front door RH and affected areas                                                      | 800        | 0             | 0     | Reviewing       |         |        |

# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

| EDIT                                                                              | SR NO                                                                             | NAME | ACTION                                              | AMOUNT    | COMMENT | REMOVE                                                                              |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------|-----------------------------------------------------|-----------|---------|-------------------------------------------------------------------------------------|
|  |  | 1    | DAYS OF REPAIR :<br>7 DAYS                          | Reviewing |         |  |
|  |  | 2    | PARTS SUPPLIED<br>BY AXAS<br>SUPPLIER<br>\$1,854.00 | Reviewing |         |  |

# Assessment Details

|                            |            |                          |  |                   |               |                |               |         |
|----------------------------|------------|--------------------------|--|-------------------|---------------|----------------|---------------|---------|
| General & Workshop Details |            | Vehicle & Driver Details |  | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary |
| Claim Amount               | \$1,540.00 |                          |  | Claim Amount      | \$1,540.00    |                |               |         |

| CATEGORY                     | ESTIMATE   | REVISED AMOUNT |
|------------------------------|------------|----------------|
| Labour                       | \$1,540.00 | \$1,540.00     |
| <div>Submit for Review</div> |            |                |