

ASS. PRO. BY: GR REF: CS/FCI17021937 / Gmb n2
ASSIGNMENT (Office)
CWS From (Person): Serene Lee FCI Date/Time: 2.52pm @ 16/11/17
Estimated Cost: _____ Bill to: _____
OD (TP/AWS/TP RES/OD RES/EVA/INV/MV/CS)
To Inspect Vehicle No: SBP303T Insured: SHA 1639B
at Workshop with: Sin Wee Chuan Spray Painting Tel: 67480573
of: Blk 3021A Ubi Rd 1# 01-40
Policy No: _____ Claim No: D17010550MFSH
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A: 10/11/2017
(Client's Record)
CA / REV / REP. / REV 24 HRS 1wp' 17/11/2017 H.O.D. Endorsement: _____
Date/Time: 3.40pm @ 16/11/17 Person Contacted: Mr. Mike Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SBP 303T - X
	SHA1639B - CS/TMI14006404/H1vm3d1-D.O.A: 5/11/2014

Surfacing

REF: FCI

ASSIGNMENT

From: _____ Date: 17/11/17

Estimated Cost: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SBP 303 T

at Workshop m/s Sin Wee Chuan Spray Painting

of Blk 3021 A Ubi Rd 1 # 01-40

Insured: _____

Policy No. 94466300

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBP 303 T Yr Regn: 21 Jan 2013

Type: ☒ M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Jaguar XF C.C. 2179

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 77371 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SAJAC0560DD S69365

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or _____

Brake: ☒ In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 285/30 R20 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ RIR / SUMI /

TOYO / YOKO or _____

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 17-11-17

Survey held at W/S 11AM

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/1/17 email preli to serene.

12/2/18 Part by Part \$ 3204.55 (Red 2475.50, Red 0+3%)

RECEIVED 12 FEB 2018

Date/Time, File Pass to?

12/2/2018



Date/Time, File Return to?

2/

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

Add Fee:



Report Format :

Lump Sum (I.B.): (\$ 3204.55)

TOTAL

140

50

50

82

322



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021937/Ggb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1639B	Veh. Inspected	SBP 303T
Policy No.		Coverage (\$)	0.00
Claim No.	D17010550MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	16/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/11/2017	Inspection Date	
Survey held at	SIN WEE CHUAN SPRAY PAINTING & SERVICE BLK 3021A #01-40 UBI RD 1 SINGAPORE 408715		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / (TP) / TP RES / TL / EVA

Case Handler *Rita*

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

		Y-Date	N-Date	Y-Date	N-Date
(1) Office Assign Form					
C	Reference No.	/			
C	Customer Code	/			
N	Assign From	/			
C	Assign Date	/			
C	Veh No (Inspected)	/			
C	Veh No (Insured)	/			
C	D.O.A	/			
C	Policy No	/			
C	Claim No	/			
C	Insurance Authorisation (CA /REV/REP)	/			
C	Report Type	/			
C	Weekend Charges	/			
N	Survey held at/Repairer	/			
C	Excess	/			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	/			
C	Regn Month/Year	/			
N	Vehicle Type	/			
N	Make & Model	/			
C	Engine Capacity. (C.C)	/			
N	Colour	/			
C	Odometer. (Sp.Reading)	/			
C	Chassis No	/			
N	General Condition	/			
N	Steering	/			
N	Brake	/			
N	Modification (Modi)	/			
C	Tyre Size	/			
N	Tyre Make	/			
C	Tyre Balance	/			
C	Date of Inspection	/			
N	Survey held	/			
N	Des.of Damages	/			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
C Market Value for OD cases
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C Days of repair
C Finalised Amount
C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

Check By:

Rita

12/1/2018

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/201

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	13-11-2017	Our Ref No. D17010550MFSH
Accident Date	10-11-2017	Claim Type. Third Party
Insured Vehicle	SHA1639B	Third Party Vehicle. SBP303T
Survey Location	Blk 3021A Ubi Road 1 #01-40	
Contact Person.	MR MIKE LAW	
Contact No.	67480573/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: NO EST COR * (LIABILITY CLEAR)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN WEE CHUAN SPRAY PAINTING & SERVICE	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230145)



PRI Documents



Close



PRI Header Details

Claim No	D17010550MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CHEONGH
Workshop Name	SIN WEE CHUAN SPRAY PAINTING & SERVICE (Contact Person : MR MIKE LAW)	Survey Location & Contact Details	Blk 3021A Ubi Road 1 #01-40 Mobile: 0 , Phone: 67480573 , Fax: 0 EmailId: MAIL@CHEONGHOH.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST COR * (LIABILITY CLEAR		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1639B	TP Vehicle No	SBP303T
PRI Recieved Date	14-11-2017 10:06:00 PM	Surveyor Appointed Date	16-11-2017 02:51:11 PM	Surveyor Accept Date	16-11-2017 0.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	16-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Monday, 20 November, 2017 12:13 PM
To: 'Claim Workflow System'
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010550MFSH/1
Attachments: SBP 303T.pdf

Dear Serene,

Enclosed herewith preliminary advise of vehicle SBP 303T.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 16 November, 2017 3:56 PM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17010550MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

Sent: Thursday, 16 November, 2017 2:51 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17010550MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010550MFSH

Date: 20-11-2017

Our Ref: CS/FCI17021937/Ggb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SBP 303T.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17-11-2017 at the premises of M/s SIN WEE CHUAN SPRAY PAINTING and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,078.14</u>
Revised Estimate Amount	: S\$ <u>3,449.50</u>
"Check" Items Amount	: S\$ <u>139.45</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Xing Guo Qiang
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7388B
Vehicle Details	
Vehicle No.	SBP303T
Vehicle to be Exported	No
Intended De-registration Date	20 Nov 2017
Vehicle Make	JAGUAR
Vehicle Model	XF 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC
Primary Colour	Grey
Manufacturing Year	2012
Engine No.	4020308224DT
Chassis No.	SAJAC0560DDS69365
Maximum Power Output	147.0 kW (197 bhp)
Open Market Value	\$48,724.00
Original Registration Date	21 Jan 2013
First Registration Date	21 Jan 2013
Transfer Count	0
Actual ARF Paid	\$38,724.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	20 Jan 2023
PARF Rebate Amount	\$29,043.00
Intended COE Rebate Details	
COE Expiry Date	20 Jan 2023
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$96,210.00
COE Rebate Amount	\$49,708.00
Total Rebate Amount	\$78,751.00

The information contained herein is correct as at 20 Nov 2017

OK

SIN WEE CHUAN SPRAY PAINTING & SERVICE

BLK 3021-A, UBI ROAD 1, # 01-40, SINGAPORE 408715

TEL: 67480573 FAX: 67435192

GST M90357486J

Ref: SWC 9128/17

16-11-2017

ESTIMATE REPAIR BILL FOR VEH NO SBP 303 T

Parts Supply

	S\$
1. Rear Bumper / Re	1,450.50
2. Rear Bumper Re-Enforcement / BT	518.05
3. Rear Bumper Lower Diffuser / mis	480.95
4. Rear Boot Lid X repair	1,641.55
5. Rear Bumper Centre Bracket X NN	139.45
Parts Total	4,230.50

2449.5
10%: 2204.55

Labour Charge

	S\$
To Panel-Beating, Renew New Parts,	650.00
To Re-Spray 2K Paint.	800.00
Labour Total	1,450.00

400
600
1000

Parts Total	S\$ 4,230.50
Labour Charge	S\$ 1,450.00
Parts & Labour Total	S\$ 5,680.05
GST 7%	S\$ 397.64
Grand Total	S\$ 6,078.14

Total: 3204.55

**Lost Of Used 6 Days X \$120.00= S\$720.00

4 days
part by part
before paint photos.

22/11/17

SIN WEE CHUAN SPRAY PAINTING & SERVICE

GuoQi Ang - 82880282

17/11/17

MIKE LAW
HP 91074888

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021937/Gnbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1639B	Veh. Inspected	SBP 303T
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010550MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	16/11/2017

2. Vehicle Particulars & Condition

Make & Model	JAGUAR XF	c.c	2179
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	SAJAC0560DDS69365	Colour	GREY
Odometer	77371	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	285/30 ZR20	PIRELLI	6 mm
L/H Front Tyre	285/30 ZR20	PIRELLI	6 mm
R/H Rear Tyre	285/30 ZR20	PIRELLI	6 mm
L/H Rear Tyre	285/30 ZR20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/11/2017	Inspection Date	17/11/2017
Survey held at	SIN WEE CHUAN SPRAY PAINTING & SERVICE BLK 3021A #01-40 UBI RD 1 SINGAPORE 408715		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBP 303T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,450.50	1,450.50
1	REAR BUMPER RE-ENFORCEMENT	BENT	518.05	518.05
1	REAR BUMPER LOWER DIFFUSER	MISSING	480.95	480.95
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,641.55	-
1	REAR BUMPER CENTRE BRACKET	NOT NECESSARY	139.45	-
	LESS 10% DISCOUNT		-	-244.95
			4,230.50	2,204.55
	LABOUR			
	TO PANEL-BEATING,RENEW NEW PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		650.00	400.00
	TO RE-SPRAY 2K PAINT.		800.00	600.00
			1,450.00	1,000.00
	GRAND TOTAL		5,680.50	3,204.55
RECOMMENDED COST OF REPAIRS				3,204.55

Report Ref No. CS/FCI17021937/Gnbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.