

ASS. REC. BY:

REF:

REF: CS3 / ALH17021968 / Gbez

Special Instruction:

DAP 2 days.

Survivor
Mehmet

GQ

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

PLG

Date/Time:

17.11.2017 1:10 PM

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STR 4518

Insured:

SLB 3589X

at Workshop m/s

Twincar Automotive

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 # 01-17

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16.11.2017

CA / REV / REP. / REV 24 HRS WDP

H.O.D. Endorsement:

Date/Time:

17.11.2017 1.18pm

Person Contacted:

Scoring

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (X)	Estimate
1. Review the project scope and objectives.	10
2. Identify the key stakeholders and their roles.	15
3. Develop a detailed project plan and timeline.	25
4. Allocate resources and assign tasks to team members.	20
5. Monitor progress and communicate regularly with stakeholders.	15
6. Address any issues or risks that arise during the project.	10
7. Complete the project and evaluate the results.	10
Total	105

36A 452B - NA / 09117021953 / 13

Dip: 16-11-2017

SLB 3531X - X

Dismantle Part : 20.11.2 017

After repair: 23.11.2017

PKS
XKS

REF:


A16

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Twin car
of _____
insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGR452B Yr Reg: 30 Jan 2007
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Nissan Latio c.c. 1498
Colour: white A/C: _____ Insured / Std / NI / NA
Sp. Reading: 286419 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: IN1BAAC1180001344
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or _____
Brake: ☒ In order / Jammed / Leaked / Burnt or _____
Modi: Nil / ☒ S/Rim / STD A/Rim or _____
Tyre Size: F: 195/60R15
R: 17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / ☒ OKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 17-11-17
Survey held at w/s Twin car. 4:30pm
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated

RECEIVED

Date/Time File Pass to? ☐ : Preli. Report

1: 22.03.2018 ☐ : Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: 180

Transportation

1: S + RS \$

2: Photos

3: Other

20

TOTAL

200

Report Format: PKS

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp. (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile**AIG ASIA PACIFIC INSURANCE PTE LTD**

Ref : CS3/AIG17021968/Gb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 17-11-2017



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLB 3589X	Veh. Inspected	SGR 452B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	17/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/11/2017	Inspection Date	17/11/2017
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Catherine Chong (LKK Auto)

From: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Sent: Friday, 17 November, 2017 1:10 PM
To: 'assignments'; 'Admin A'
Cc: Fong, Andy-SY
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB3589X AND SGR452B ON 16/11/2017
Attachments: Fax408A.TIF; 17112017113756-0001.pdf; 17112017115835.pdf; 17112017123546.pdf

Hi LKK,

Kindly assist to survey. Vehicle is in.

Thanks.

Best Regards
Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2, #01-17
Singapore 417921
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Our Ref: **SGR 452 B**
Your ref: **SLB 3589 X**

17 November 2017

AIG ASIA PACIFIC INSURANCE PTE. LTD. BY EMAIL yokeshi.chan@aig.com ONLY
NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : N HAYATI BINTE AMIR
VEHICLE NUMBER : SGR 452 B
YOUR INSURED VEHICLE NUMBER : SLB 3589 X
ACCIDENT ON 16 Nov 2017 ALONG BKE TWDS WOODLANDS BEFORE MANDAI EXIT
AT ABOUT 18:25 HOURS

We refer to your email dated **17 Nov 2017** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD
Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-17
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....
Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (P)
(4) Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	6	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	2	
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	RA	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	RA	✓	
1159	993327	Rear End Panel	BAC	✓	
1160	993339	Rear End Panel Top Garnish	DIS	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	RA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD	R	
1166	995116	Rear RH Taillamp	RA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	DD	R	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber	BT	R	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: **SGR 452B**

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	BAC	R	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	MT	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	BAC	R	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille	MT	✓	
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 9

Assessor: _____

6 days
22/3/12

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/11/2017 11:55
Date Of Accident	16/11/2017 18:25
Exact Location Of Accident	BKE TWDS WOODLANDS B4 MANDAI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGR452B
Insured/Policyholder	
Name Of Registered Owner	BINTE AMIR,N HAYATI
NRIC No	S0066661J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98755295
Alternative Phone No	OTHERS-62413397

Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00226389/02
Cover Note Number	

Driver

Name of Driver	NOR ASHRAF BIN SAMSUDIN
NRIC No	S8006687B
Date Of Birth	03/03/1980
Occupation	INDOOR
Date Of Driving Pass	14/10/2002
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98755295
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 497H TAMPINES ST 45 #02-100
Postcode	526497
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB3589X
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJP4194U
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name NOR ASHRAF BIN SAMSUDIN

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? SGR452B

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name GEETHA D/O SHANTHA RAM

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? SGR452B

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN

BK1 TWO'S WOODLANDS BY MANOA EXIT

2000-01-01	2000-01-01
2000-01-01	2000-01-01
2000-01-01	2000-01-01

→ 1131122

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. The first part of the document is a header section containing the following information:

a. Title: "The [illegible] of [illegible]"

b. Author: "John [illegible]"

c. Date: "19[illegible]"

2. The second part of the document is a list of [illegible] items, numbered 1 through 10.

3. The third part of the document is a [illegible] section, containing a [illegible] paragraph.

4. The fourth part of the document is a [illegible] section, containing a [illegible] paragraph.

5. The fifth part of the document is a [illegible] section, containing a [illegible] paragraph.

6. The sixth part of the document is a [illegible] section, containing a [illegible] paragraph.

7. The seventh part of the document is a [illegible] section, containing a [illegible] paragraph.

8. The eighth part of the document is a [illegible] section, containing a [illegible] paragraph.

9. The ninth part of the document is a [illegible] section, containing a [illegible] paragraph.

10. The tenth part of the document is a [illegible] section, containing a [illegible] paragraph.

DECLARATION

We declare the foregoing particulars are true to best of our knowledge.

7. Bookkeeper - 1
Date & Time

2000-01-01
 2000-01-01
 2000-01-01

Reporting Center Name
Name
Address

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6661J

Vehicle Details

Vehicle No.	SGR452B
Vehicle to be Exported	No
Intended De-registration Date	20 Nov 2017
Vehicle Make	NISSAN
Vehicle Model	LATIO 1.5L A
Primary Colour	White
Manufacturing Year	2006
Engine No.	HR15388999
Chassis No.	JN1BAAC11Z0001544
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$13,713.00
Original Registration Date	30 Jan 2007
First Registration Date	30 Jan 2007
Transfer Count	0
Actual ARF Paid	\$15,085.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	29 Jan 2022
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$25,323.00
COE Rebate Amount	\$21,225.00
Total Rebate Amount	\$21,225.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Nov 2017

► Nissan Latio Used Vehicle List (7 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Nissan Latio 1.5A Premium (COE\$27,500 till 03/2022)		\$6,300 /yr	05-Apr-2007	1,498 cc	-	Mr Benz Traders	Available

Cheapest In The Market. Excellent Condition, Powerful Engine And Smooth Transmission, Neat Interior And Exterior, Call Now To Make An Appointment To View!

Office No. - 63461282

Bernard Foong - 96609891 | Ansel - 98607949 | Richard - 97711650 | Wee - 92240044

Nissan Latio 1.5A (New 5-yr COE)	\$34,800	\$6,960 /yr	10-Oct-2007	1,498 cc	152,000 km	Carway	Available
---	-----------------	-------------	-------------	----------	------------	--------	------------------

"One Year Warranty!", Purchase With Official Warranty Certificate With A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$599 Low Monthly Instalment, 10% Down P...

Office No. - -

Eugene Ng - 83831777 | Sam Ong - 86660777

Nissan Latio 1.5A (New 5-yr COE)	\$33,388	\$6,670 /yr	26-Nov-2007	1,498 cc	120,123 km	ABS Auto Holding Pte Ltd	Available
---	-----------------	-------------	-------------	----------	------------	--------------------------	------------------

A Deal Not To Be Missed! One Owner And Well Maintained And Low Mileage Car, Trade In Welcomed, Bank And In House Loan Provided, High Loan With \$3000 Down Payment Drive Away! 100% Approval. Call Us For...

Office No. - 64753423

Alex - 82298229 | David - 98806776 | Roy Lee - 83158315 | Kenny - 98259995

Nissan Latio 1.5A (New 5-yr COE)	\$33,888	\$6,770 /yr	28-Nov-2007	1,498 cc	-	ABS Auto Holding Pte Ltd	Available
---	-----------------	-------------	-------------	----------	---	--------------------------	------------------

A Deal Not To Be Missed! One Owner And Well Maintained Car, Trade In Welcomed, Bank And In House Loan Provided, High Loan With \$3000 Downpayment Drive Away! 100% Approval! Call Us For An Appointment At...

Office No. - 64753423

Kenny - 98259995 | Alex - 82298229 | David - 98806776 | Roy Lee - 83158315

Nissan Latio 1.5A (New 5-yr COE)	\$33,800	\$6,760 /yr	06-Dec-2007	1,498 cc	122,000 km	Happy Motoring Pte Ltd	Available
---	-----------------	-------------	-------------	----------	------------	------------------------	------------------

Reliable And Petrol Efficient. Neat And Clean Guarantee Condition! View To Believe! Hurry! Price Negotiable, Trade In Welcome, Car Available In Showroom For Viewing Now, Contact For More Details.

Office No. - 68442228

Sham - 84228768 | Khoo - 96803004

Nissan Latio 1.5A (New 5-yr COE)	\$32,800	\$6,560 /yr	18-Dec-2007	1,498 cc	168,000 km	Carway	Available
---	-----------------	-------------	-------------	----------	------------	--------	------------------

\$585 Low Monthly Instalment / 10% Down Payment, Bank/In House Loan Available, Lowest Down Payment/Flexible Loan Available At Low Interest Rate, Loan Tenure Up To End Of Coe, Free Fully Synthetic Oil S...

Office No. - -

Sam Ong - 86660777 | Eugene Ng - 83831777

Nissan Latio 1.5A (New 5-yr COE)	\$32,500	\$6,500 /yr	31-Dec-2007	1,498 cc	-	Seng Huat Motors Trading Pte Ltd	Available
---	-----------------	-------------	-------------	----------	---	----------------------------------	------------------

Nice Condition, See To Believe. One Of The Lowest Depreciation In Market. We Are COE Cars Specialist Auto Center, Full Range Of COE Cars And Spareparts For Your Choice.

Office No. - 68442050

Ah Hui - 81829553

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, beauty and wellness, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017 Edit Reg		17 Nov 2017 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAN POH CHOO, ID: S1538507C		
Main Claimant:	BINTE AMIR,N HAYATI, ID: S0066661J		
Vehicle Reg. No.:	SGR452B	Date of Loss:	16/11/2017 18:00 - :59
Claim Type:	TP / 5964575914SG	Policy/Cover Note No.:	2100459757 (Comprehensive)
Vehicle Reg. No. (Insured):	SLB3589X	Policy No. (Claimant):	
		Excess:	
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (04/12/2017): NO TP GIA REPORT

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGR452B (5964575914SG)**
[SLB3589X]

TP

BINTE AMIR,N HAYATI

Nov 16 2017 6:00PM

[TAN POH CHOO]

Twincar Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser		v	
Assessment Reports										1 per page		v		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail		Print			
1	04/12/17 10:19	Accident Statement From:SC - Reg. No: SLB3589X, Claimant: TAN POH CHOO								1		Load HTM			
Photos/Images										3 per page		v		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print			
1	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
2	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
3	29/01/18 11:34	Odometer Reading								1		Load JPG		<input checked="" type="checkbox"/>	
4	29/01/18 11:34	Chassis Number								1		Load JPG		<input checked="" type="checkbox"/>	
5	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
6	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
7	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
8	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
9	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
10	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
11	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
12	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
13	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
14	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
15	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
16	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
17	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
18	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
19	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
20	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
21	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
22	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
23	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
24	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
25	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
26	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
27	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
28	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
29	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
30	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	
31	29/01/18 11:34	General View								1		Load JPG		<input checked="" type="checkbox"/>	

32	29/01/18 11:34	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	29/01/18 11:34	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
35	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
36	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
37	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
38	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
39	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
40	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
41	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
42	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
43	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
44	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
45	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
46	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
47	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
48	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
49	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
50	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
51	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
52	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
53	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
54	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
55	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
56	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
57	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
58	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
59	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
60	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
61	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
62	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
63	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
64	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
65	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
66	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
67	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
68	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
69	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
70	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
71	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
72	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
73	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
74	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
75	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
76	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
77	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
78	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
79	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
80	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
81	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>

82	29/01/18 11:35	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
83	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
84	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
85	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
86	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
87	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
88	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
89	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
90	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
91	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
92	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
93	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
94	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
95	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
96	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
97	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
98	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
99	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
100	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
101	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
102	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
103	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
104	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
105	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
106	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
107	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
108	29/01/18 11:35	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17021968/GBE2

Date: 26/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100459757
 Claimant Vehicle No: SGR452B Insured Vehicle No: SLB3589X
 Date of Loss: 16/11/2017 Nature of Claim: TP Claim No: 5964575914SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR452B**
 Make & Model: NISSAN LATIO, 1.5 (A) Engine No: HR15388999
 Reg. Date: 30/01/2007 (Man. Year: 2006) Chassis No: JN1BAAC11Z0001544
 Colour: White Odometer: 286419 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/11/2017
 Date Inspected: 17/11/2017 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)
 2 KAKI BUKIT AVE 2
 #01-17 KAKI BUKIT AUTOHUB
 SINGAPORE 417921

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Cracked	0.00 F	*- F
7	1		*REAR END PANEL	Buckled	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Distorted	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR LH TAILLAMP PANEL	Repair	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR RH TAILLAMP PANEL	Repair	0.00 F	*- F
13	1		*BOOTLID	Dented	0.00 F	*- F
14	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
15	1		*BOOTLID RUBBER	Repair	0.00 F	*- F
16	1		*REAR LH FENDER INNER TRIM	Cut	0.00 F	*- F
17	1		*REAR RH FENDER	Repair	0.00 F	*- F
18	1		*REAR FENDER AIR GRILLE	Cut	0.00 F	*- F
19	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >