

ASS. RES. 50%

FILE CS/MSG17021973 / K9602

Subject

ASSIGNMENT 10/10/00

Minimen

From (Person) Lionel Tan

MSIG

Date/Time 16/11/17 @ 4:50pm

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLK 6372 L

Insured

FBG 3611 G

at Workshop no.

Cheng Hoe Motor

Tel.

6755 6142

of BIK 1019 # 01-374 / 382 - Yishun 7 687 61

Policy No.

MSD / VM7 / 17-979099-WTT

Claim No.

MSC / V / 17-001286

Sum Insured

Excess

Make of Vehi

(Client's Record

D.O.A. 11/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement

Date/Time 9:03am @ 17/11/17

Person Contacted

Sharon

Vehicle IN (OUT)

Date/Time

Action/Instruction () Estimate

SLK 6372 L - X

FBG 3611 G - X

28/11/17 @ 4:27pm revised to Lionel Tan by email.

4/1 @ 2112.87 Confirmed E bidr (Red @ 259.70, 11%)

ASS. REC. BY:

REF:

MS61

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1-B.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLK 63 726 Cr Regn: 03 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Syphy c.c. 1598Colour: M. Red AC: Insured / Std / NI / NASp. Reading: 31983 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MNT BBA B17 F 0023231Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 6 mmL/Bal. P mm L/Bal. 6 mmD.O.A. 11/11/17 D.O.I. 27/11/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear MS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11 File pass to Catherine

RECEIVED 28/11/20

Date/Time, File Pass to?

11/09/11 Final ☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 200

Transportation: _____

S + RS. SI

Photos 10

Others _____

TOTAL

210Report Format: MR-TPLump Sum / I.B.I. (\$) 71287



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17021973/Kqb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 17-11-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBG 3611G	Veh. Inspected	SLK 6372L	
Policy No.	MSD/MT/17-979099-WTT	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (LIONEL TAN)	Assign Date	17/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/11/2017	Inspection Date		
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Cathy): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date

Surveyor (Kenneth): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Ext Submitted	Adj Assigned	Adj Pdt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2017		16 Nov 2017 16:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	STAR FOOD ENTERPRISE, Co. Reg. No.: 53095666K		
Main Claimant:	KOH BI'NA, ID: S8209145I		
Vehicle Reg. No.:	SLK6372L	Date of Loss:	11/11/2017 17:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-979099-WTT (Third Party Only) Coverage: 31/12/2016 - 30/12/2017
Vehicle Reg. No. (Insured):	FBG3611G	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/11/2017]		
Driver/Custodian (Insured):	MOHAMAD HUSSIN BIN SABAKKA MOHAMOOD (/ Male), NRIC: S7028997J		
Adj Asg. Remarks:	Please contact Ms Dorlyn Li @ 6481 2001 to arrange for survey.		

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 28 Nov 2017

Preliminary Advice

Insured Vehicle No	: FBG3611G	Accident Date	: 11/11/2017
TP Vehicle No	: SLK6372L	Assignment Date	: 16/11/2017
Make	: NISSAN SYLPHY	Est. Duration of Repair	: 3.00
Date of Inspection	: 27/11/2017		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,372.57
Revised Amount	:S\$	2,112.87
Check Items (Estimated)	:S\$	69.70
Total	:S\$	2,182.57

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	9145I

Vehicle Details

Vehicle No.	SLK6372L
Vehicle to be Exported	Yes
Intended De-registration Date	13 Nov 2017
Vehicle Make	NISSAN
Vehicle Model	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour	Red
Manufacturing Year	2015
Engine No.	HR16961990B
Chassis No.	MNTBBAB17Z0023231
Maximum Power Output	85.0 kW (113 bhp)
Open Market Value	\$15,545.00
Original Registration Date	27 Mar 2015
First Registration Date	27 Mar 2015
Transfer Count	1
Actual ARF Paid	\$10,545.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	26 Mar 2025
PARF Rebate Amount	\$7,908.00

Intended COE Rebate Details

COE Expiry Date	26 Mar 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$64,700.00
COE Rebate Amount	\$47,672.00
Total Rebate Amount	\$55,580.00

The information contained herein is correct as at 13 Nov 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2017 10:33
Date Of Accident	11/11/2017 17:50
Exact Location Of Accident	AYE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK6372L
Insured/Policyholder	
Name Of Registered Owner	KOH BI'NA
NRIC No	S8209145I
Email Address	BINA.KOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98809449
Alternative Phone No	OTHERS-98809449
Vehicle Particulars	
Manufacturer	NISSAN
Model	SYLPHY-1.6 CVT ABS D/AIRBAG 2WD 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V03366/VPC/R00
Cover Note Number	08/03/2017 - 26/03/2018
Driver	
Name of Driver	XU KAISI KENNY
NRIC No	S8317561C
Date Of Birth	25/05/1983
Occupation	INDOOR
Date Of Driving Pass	29/04/2005
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91559244
Fax Number	
Contact Number	
EMail Address	XUKAISI@HOTMAIL.COM

Email Address

DETAILS OF INJURED PERSON 1

Name	MOHAMAD HUSSIN BIN SABAKKA MOHAMOOD
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBG3611G
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN


VEHICLE NO.: SLK 6372L
INSURER: LIBERTY
DATE & TIME: 11/11/17 @ 1750

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:


13 November 2017



Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Donny (AMIC)

13/11/17



SINGAPORE POLICE FORCE



T/20171111/2179

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

1 of 3

Report No. T/20171111/2179

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/11/2017 22:12		Vide Report No.: D/20171111/0115		Station Diary No.: 126	
Informant's Particulars					
Name of Informant: XU KAISI, KENNY			Address: APT BLK 194B BUKIT BATOK WEST AVENUE 6 #14-239 SINGAPORE 652194		
ID Type / ID No.: NRIC NO / S8317561C			Contact No.: Home/Office: Mobile: 91559244		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 34	Date of Birth: 25/05/1983	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident


Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/11/2017 17:50	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY along AYE (City) 9.9km				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG3611G	Motorcycle			Red	Slightly Damaged	0
FBL3276P	Motorcycle			Orange		0
SGV7989C	Car	HONDA	CIVIC	Silver	No Damage	0
SLK6372L	Car	NISSAN	SYLPHY	Red	Slightly Damaged	3



SINGAPORE POLICE FORCE



T/20171111/2179

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20171111/2179

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMAD HUSSIN BIN SABAKKA MOHAMOOD	ID No.	S7028997J
Related Vehicle	FBG3611G (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	XU KAISI, KENNY	ID No.	S8317561C
Related Vehicle	SLK6372L (Car)	Contact No.	91559244
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/11/2017 at about 1747hrs, I was driving my sister's car, V1) SLK6372L along AYE(City) 9.9km lane 1. Suddenly a car, V2) SGV7989C jam brake, thus I applied my brake too. I then felt something collided onto the rear of V1. I then made a check and discovered that a motorcycle, V3) FBL3276P skidded in the front of V2 and caused V2 to brake. A motorcycle, V4) FBG3611G riding behind me then also skidded and collided onto the left rear side of V1. Police and ambulance then came to scene. Police interviewed us and informed me to lodge a traffic accident report at any police station. Ambulance then conveyed both V3 and V4 riders. I did not know the extend of their injuries. I have In car camera installed in V1.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

Estimate No: ES1791345/AMK
Date: 27 Nov 2017
Policy No: SD17V03366/VPC/R00
Veh Reg No: SLK6372L
Make/Model: NISSAN SYLPHY 1.6 CVT

WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 11/11/2017
TP Veh Reg No: FBG3611G

Chassis No: MNTBBAB17Z0023231
Engine No: HR16961990B
Reg. Date: 27/03/2015

Estimate Repair Cost to Vehicle No :SLK6372L

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER LH SIDE RETAINER (INNER)	52.70	1 PC	52.70	✓
2 REAR BUMPER LH SIDE RETAINER (OUTER)	35.20	1 PC	35.20	✓
			87.90	
		Less 30%	26.37	61.53
Net Price				
3 REAR BUMPER CLIP	4.40	4 PC	17.60	✓
			17.60	
		Less 10%	1.76	15.84
Special Net				
4 REAR BUMPER	321.60	1 PC	321.60	✓
5 REAR BUMPER LH SIDE SPONGE	69.70	1 PC	69.70	✗
6 REAR BUMPER LOWER SKIRT	660.00	1 PC	660.00	✓
7 LH TAILLAMP	193.90	1 PC	193.90	✓
			1,245.20	1,245.20
Labour				
8 REMOVE & REFIX REAR BUMPER,LOWER SKIRT,TAILLAMP;KNOCKING & REPAIR REAR PANEL,REAR LH FENDER & REALIGN THE SAME	450.00	1 LA	450.00	320
9 PUTTY & RESPRAY REAR BUMPER,LOWER SKIRT,REAR LH FENDER,REAR END PANEL & ALL AFFECTED AREAS	600.00	1 LA	600.00	540
			1,050.00	1,050.00
			Total	S\$ 2,372.57
			Add GST @ 7%	166.08
			Total Amount Payable	S\$ 2,538.65

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Dorlyn Li

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2017		16 Nov 2017 16:50 Edit Adj Rpt	S\$2,112.87 Edit Estimates	S\$2,112.87 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by Insurer]
Insured:	STAR FOOD ENTERPRISE, Co. Reg. No.: 53095666K			
Main Claimant:	KOH BI'NA, ID: S8209145I			
Vehicle Reg. No.:	SLK6372L	Date of Loss:	11/11/2017 17:00 - :59	
Claim Type:	TP / MSC/V/17-001786	Policy/Cover Note No.:	MSD/VMT/17-979099-WTT (Third Party Only) Coverage: 31/12/2016 - 30/12/2017	
Vehicle Reg. No. (Insured):	FBG3611G	Policy No. (Claimant):		
		Excess:		
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/12/2017]			
Driver/Custodian (Insured):	MOHAMAD HUSSIN BIN SABAKKA MOHAMOOD (/ Male), NRIC: S7028997J			
Adj Asg. Remarks:	Please contact Ms Doriyn Li @ 6481 2001 to arrange for survey.			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLK6372L (MSC/V/17-001786)
 [FBG3611G]
 TP
 KOH BI'NA
 Nov 11 2017 5:00PM
 [STAR FOOD ENTERPRISE]
 Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser ▼	
Letters/Correspondences				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/11/17 16:09	Non Reporting Letter to OI	1	Load HTM	
Assessment Reports				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/11/17 16:22	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	09/01/18 17:43	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
12	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	09/01/18 17:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	09/01/18 17:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
15	09/01/18 17:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
16	09/01/18 17:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/11/17 16:04	TPD SLK6372L GIA REPORT	1	Load PDF	
2	16/11/17 16:51	TPD SLK6372L - PRI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17021973/KQBE2

Date: 11/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Policy No: MSD/VMT/17-979099-
Ltd. WTT

Claimant Vehicle No: SLK6372L Insured Vehicle No: FBG3611G

Date of Loss: 11/11/2017 Nature of Claim: TP Claim No: MSCN/17-001786

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK6372L**

Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) Engine No: HR16961990B

Reg. Date: 27/03/2015 (Man. Year: 2015) Chassis No: MNTBBAB17Z0023231

Colour: Metallic Red Odometer: 31983 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16

Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,322.57	1,252.87	69.70	5.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	860.00	190.00	18.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,372.57	2,112.87	259.70	10.95
+ GST 7.00/7.00% (\$\$)	166.08	147.90	18.18	10.95
Nett Amount (\$\$)	2,538.65	2,260.77	277.88	10.95

INSPECTION

Date of Assignment: 16/11/2017

Date Inspected: 27/11/2017 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 11 Jan 2018)

Parts: 143 **NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SLK6372L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LH SIDE RETAINER (INNER)	Distorted	52.70 FL	*52.70 FL
2	1		*REAR BUMPER LH SIDE RETAINER (OUTER)	Distorted	35.20 FL	*35.20 FL
3	4		*REAR BUMPER CLIP	Necessary	17.60 FN	*17.60 FN
4	1		*REAR BUMPER	Buckled	321.60 FS	*321.60 FS
5	1		*REAR BUMPER LH SIDE SPONGE	Serviceable	69.70 FS	*- FS
6	1		*REAR BUMPER LOWER SKIRT	Dented / Distorted	660.00 FS	*660.00 FS
7	1		*LH TAILLAMP	Cracked	193.90 FS	*193.90 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	1,350.70	1,281.00
- List Item Discount on L Items 30.00/30.00% (S\$)	26.37	26.37
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1.76	1.76
Total Parts (S\$)	1,322.57	1,252.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER, LOWER SKIRT, TAILLAMP; KNOCKING & REPAIR REAR PANEL, REAR LH FENDER & REALIGN THE SAME	New	450.00	320.00
2	PUTTY & RESPRAY REAR BUMPER, LOWER SKIRT, REAR LH FENDER, REAR END PANEL & ALL AFFECTED AREAS	New	600.00	540.00
Gross Labour Cost (\$\$)			1,050.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >