

musim

Special Instruction:

HS: \$ 4300.00

*Third Parties:*

Claimant:

Surveyor: Constant Appraisers.

Workshop: 6 Speed Autowerks

From (Person): Lionel Tan of MSH Date/Time: 19/02/08  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_


OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: YP 3704U Insured: FBF 3351L  
at Workshop m/s 6 Speed Autoworks Tel: 8533 2934  
of 68 Kaki Bukit Ave 6 #02-05  
Policy No: MSD/VMS/17-359226 -CA Claim No: MSC/V/17-001785  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
Make of Veh: \_\_\_\_\_ D.O.A. 14.11.2017  
(Client's Record)

Do Not Finalize  
H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_  
Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 5 days)  
Date/Time: 27/2/18 Submit Final Fig 2650, 4 days (Red \$ 1650 / 38 %; Original 5 days)

Date/Time	Action/Instruction
	TP 3724U - X
	TBF 3351L - X
-	PRS + Paper survey

  
 27/2/2018

months  
27/2/2018

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

**Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)**

RECEIVED 27 FEB 2018

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value :

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Date: \_\_\_\_\_

Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time 27/2/18 File Pass to typist

2) Date/Time File Return to

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time File Return to

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2017		17 Nov 2017 10:12 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	MD NOOR BIN MAHMUD, ID: S2015554Z, Tel: +6597726214								
Main Claimant:	KHWAN HUP FARMING PTE LTD, Co. Reg. No.: 198401659W								
Vehicle Reg. No.:	YP3724U	Date of Loss:	14/11/2017 00:00 - :59						
Claim Type:	TP / MSC/V/17-001785	Policy/Cover Note No.:	MSD/VMS/17-359226-CA (TP, Fire & Theft) Coverage: 09/02/2017 - 10/05/2018						
Vehicle Reg. No. (Insured):	FBF3351L	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 18/11/2017]								
Driver/Custodian (Insured):	MD NOOR BIN MAHMUD (67), NRIC: S2015554Z, Tel: +6597726214								
Adj Asg. Remarks:	Please contact Ms Sun Sun @ 8533 2934 to arrange for survey .								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Rungs

Survivor  
Merimen

GQ

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSIG

Date/Time

17/11/17 @ 10:12am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 3724U

Insured:

FBF 3351 L

at Workshop m/s

G Speed Autowerkz

Tel:

8533 2934

of 68 kaki Bukit Ave 6 # 02-05, 417896

Policy No: MSD/VMS/17-359226-CA

Claim No:

MSC/V/17-001785

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement:

Date/Time 11:01am @ 17/11/17

Person Contacted

Sun Sun

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

YP3724U-X

FBF3351L-X

After repair: 21.11.2017

02/12/17 11:47am Email to Lionel Tan thru Merimen

MS  
XPL

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD (TP) / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s 6 speed Autowerkz  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 4 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: Y P3724U Yr Regn: 11 Aug 2016  
Type: M.Car / M.Cycle / Bus / Van / Worry / Taxi / Prime Mover /

Truck / Trailer or

Make: Foton BJ1041V9J 06-PP 2775  
Colour: white A/C: Insured / Std / NI / NA  
Sp. Reading: 86967 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: LUBV 3 JBB OFJ 073277

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/75R16 (BS)  
R: 205/70R16 (MAXWAY)

PS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>5/5</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>5/5</u> mm
D.O.A. _____	D.O.I. <u>17-11-17</u>

Survey held at: w/s 6 speed Autowerkz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RG \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17021995/Gb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 17-11-2017



Code : MSG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBF 3351L	Veh. Inspected	YP 3724U
Policy No.	MSD/VMS/17-359226-CA	Coverage (\$)	0.00
Claim No.	MSC/V/17-001785	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	17/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	14/11/2017	Inspection Date	17/11/2017
Survey held at	6 SPEED AUTOWERKZ - 68 KAKI BUKIT AVE 6 #02-05		
Repairer	-		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2017		17 Nov 2017 10:12 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MD NOOR BIN MAHMUD, ID: S2015554Z, Tel: +6597726214		
Main Claimant:	KHWAN HUP FARMING PTE LTD, Co. Reg. No.: 198401659W		
Vehicle Reg. No.:	YP3724U	Date of Loss:	14/11/2017 00:00 - :59
Claim Type:	TP / MSC/V/17-001785	Policy/Cover Note No.:	MSD/VMS/17-359226-CA (TP, Fire & Theft) Coverage: 09/02/2017 - 10/05/2018
Vehicle Reg. No. (Insured):	FBF3351L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/11/2017]		
Driver/Custodian (Insured):	MD NOOR BIN MAHMUD (67), NRIC: S2015554Z, Tel: +6597726214		
Adj Asg. Remarks:	Please contact Ms Sun Sun @ 8533 2934 to arrange for survey .		

[View All](#)[Compose Case Mail](#)

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)  
4 Shenton Way, #21-01 SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6225 7402  
www.msig.com.sg

Your Ref : FBF3351L  
Our Ref : MSC/V/17-001785 (Please quote our reference when replying)

27 Dec 2017

**URGENT 1st REMINDER**  
**By Registered Mail**

MD NOOR BIN MAHMUD  
BLK 368 WOODLANDS AVENUE 1  
#02-801  
SINGAPORE 730368

Dear Sir/Madam

**Accident Reporting**

*(Please ignore this letter if you have already filed an accident report)*

We have not heard from you since we wrote on 16.11.2017, about your non-reporting of this accident.

It is important that you or your authorised driver report any traffic accident involving the insured vehicle to your insurer within 24 hours of the accident or by the next working day.

Please bring your vehicle (even if it was not damaged) to any of our authorised workshops or IDAC centres (list attached) to make a report with these documents:

1. Driving license
2. Identity card
3. Police report (if any)

We look forward to receiving your accident report within 7 days from this letter. Otherwise, we will have to engage the assistance of the Traffic Police.

Please contact us if you need further clarification.

Thank you.

Yours sincerely

Lionel Tan Tian Pei  
Executive  
Claims Services (Motor)  
Tel : 6643 1307  
Fax : +65 6225 7402  
Email : lionel\_tan@sg.msig-asia.com

cc : Commercial Agency Pte Ltd

A Member of MS & AD INSURANCE GROUP



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/11/2017 17:00
Date Of Accident	14/11/2017 17:50
Exact Location Of Accident	ALONG BKE TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP3724U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KHWAN HUP FARMING PTE LTD
Co Reg No	198401659W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93526114
Alternative Phone No	OFFICE-93526114
<b>Vehicle Particulars</b>	
Manufacturer	FOTON
Model	BJ1041V9JD6-FP
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082632643-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	GOPALAKRISHNAN RAJU
Passport No/FIN	G6835386L
Date Of Birth	20/04/1991
Occupation	OUTDOOR
Date Of Driving Pass	15/06/2012
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93526114
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER TO ATTACHED

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBF3351L

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Details of Witness

Name

Phone Number

Email Address



# Sketch Plan #2

## SKETCH PLAN



Vehicle A 7P 3724 U

Vehicle B 7P 3351 L

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling at the fourth lane of BRE on the above mentioned date and time. A motorcycle at the third lane, knocked onto the rear of vehicle (SLP 4819 C), skidded to the fourth lane and hit into the rear right portion of my body.

## DECLARATION

I declare that the above information is true and correct.

Signature of the driver of the vehicle involved in the accident

G. R. S.

Signature of the driver of the vehicle involved in the accident

Signature of the driver of the vehicle involved in the accident

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5082632643-01

Cover : Comprehensive

- |   |                             |
|---|-----------------------------|
| 1. Index mark and Registration Number of Vehicle  | : YP3724U                   |
| Chassis Number  | : LVBV3JBB0FJ073277         |
| 2. Name of Policyholder   | : KHWAN HUP FARMING PTE LTD |
| 3. Effective Date of Insurance  | : 11 Aug 2017               |
| 4. Expiry Date of Insurance   | : 10 Aug 2018               |
| 5. Persons or Classes of Persons entitled to drive#   |                             |
| (a) The Policyholder.   |                             |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.   |                             |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                             |
| 6. Limitations as to Use#   |                             |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.   |                             |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business.   |                             |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: LIAN FONG CREDIT & TRADING PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : LIAN FONG CREDIT & TRADING PTE LTD (00000611198)  
Date of Issue : 24 Jul 2017 14:52 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer




Chief Executive

SENIOR CITIZEN DRIVER LICENSE

License Number: G 6835386L  
Name: GOPALAKRISHNAN RAJU

Birth Date: 20 Apr 1991  
Issue Date: 15 Jun 2012  
Valid Till: 14 Jun 2017

0020778938



YOU ARE LICENSED TO-DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor Cars < 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	15 Jun 2012

IP 428A

Licence No: G6835386L



**DRIVING LICENCE**

Licence Number: **G6835386L**

Name: **GOPALAKRISHNAN RAJU**

Birth Date: **20 Apr 1991**

Issue Date: **16 May 2017**

Valid Till: **14/06/2022**

002683900A



**WORK PERMIT**  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer: **MALAYSIAN FEEDMILLS FARMS P L**

Sector: **AGRI-TECHNOLOGY**

Name: **GOPALAKRISHNAN RAJU**

Occupation: **AGRITECHNOLOGY WORKER**

Work Permit No: **Q 35258817**

Date of Application: **30-12-2015**

Date of Issue: **20-01-2016**

Date of Expiry: **27-12-2017**

16464527



**ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class 3: Motor cars < 3500 kg with or without trailer, vehicles of the class 1 and motor tricycles < 250 kg

EFFECTIVE DATE

28 Jul 2017

S / No. 9000271989

G6835386L



**VISIT PASS**

Immigration Regulations

Name: **GOPALAKRISHNAN RAJU**



Date of Birth: **20-04-1991** Sex: **M** Nationality: **INDIAN**

PRN: **G6835386L** Date of Issue: **20-01-2016** Date of Expiry: **27-12-2017**

**MULTIPLE JOURNEY VISA ISSUED**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	1659W
Vehicle Details	
Vehicle No.	YP3724U
Vehicle to be Exported	No
Intended De-registration Date	20 Nov 2017
Vehicle Make	FOTON
Vehicle Model	BJ1041V9JD6-FP
Primary Colour	White
Manufacturing Year	2015
Engine No.	ISF28S5148T89699069
Chassis No.	LVBV3JBB0FJ073277
Maximum Power Output	-
Open Market Value	\$27,379.00
Original Registration Date	11 Aug 2016
First Registration Date	11 Aug 2016
Transfer Count	0
Actual ARF Paid	\$1,369.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	10 Aug 2026
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$44,082.00
COE Rebate Amount	\$38,453.00
<b>Total Rebate Amount</b>	<b>\$38,453.00</b>

The information contained herein is correct as at 20 Nov 2017

OK

## View Sent Message

This mail is associated with :

\*YP3724U (MSC/V/17-001785)  
[FBF3351L]

TP

KHWAN HUP FARMING PTE LTD

Nov 14 2017 12:00AM

[MD NOOR BIN MAHMUD]

6 Speed Autowerkz Pte Ltd

Resend View Recipients Print Message Delete Message Forward

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 02/12/2017 11:47 AM.  
**To** MSG\_LTTP  
**Subject** Pre-repair Inspection

Dear Lionel,

Refer to your assignment on 17.11.2017 at 10.12AM.

Please be informed that we have inspected the vehicle YP 3724U on 17.11.2017 at 4PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.



# SINGAPORE POLICE FORCE



T/20171121/7013

1 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20171121/7013

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/11/2017 20:22		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: MD NOR BIN MAHMUD			Address: APT BLK 368 WOODLANDS AVENUE 1 #02-801 SINGAPORE 730368		
ID Type / ID No.: NRIC NO / S2015554Z			Contact No.: Home/Office: Mobile: 97726214		
Nationality: SINGAPORE CITIZEN			Email: mdnor@live.com		
Sex: Male	Age: 67	Date of Birth: 19/07/1950	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: Retiree			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/11/2017 17:00	Type of Location: Y-Junction
Location:  BUKIT TIMAH EXPRESSWAY  Going into filter lane exiting BKE, going to SLE				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF3351L	Motorcycle	DAELIM	SV125 CVT	Grey	Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20171121/7013

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20171121/7013

**CONTINUATION OF REPORT**

Rider			
Name	MD NOR BIN MAHMUD	ID No.	S2015554Z
Related Vehicle	FBF3351L (Motorcycle)	Contact No.	97726214
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	14/11/2017	Date Discharge	14/11/2017
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious

Brief Details.

I was riding back home on my scooter. When checking the blind spot to exit BKE to SLE, in split second I only realized that the car in front was braking. To avoid the accident, I swerve to the left and skidded and fell. I could not remember if I hit the car in front as I was badly injured. An ambulance was called and I was taken to KTPH. I was discharged on the day itself after getting stitched up for my wounds.



**SINGAPORE  
POLICE FORCE**



T/20171121/7013

3 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20171121/7013

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
NORHIDAWATI BINTE AHMAD  
Contact No.: 65476310

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
21/11/2017 20:22

Classification Of Case:



**Khoo Teck Puat  
Hospital**  
National Healthcare Group

90 Yishun Central,  
Singapore 768828  
Tel: (65) 6555 8000  
Fax: (65) 6602 3700  
Website: www.ktph.com.sg

**MEDICAL CERTIFICATE**

**ORIGINAL**

**KHANE171232506**

**NAME : MD NOR BIN MAHMUD**  
**NRIC : S2015554Z**

Type of Medical Leave granted : **HOSPITALIZATION LEAVE**

The above named attended Examination/Treatment from **14 Nov 2017 18:40** to **14 Nov 2017 23:30**

The above named is unfit for duty for a period of **14** day(s), from **14 Nov 2017** to **27 Nov 2017** inclusive.

The Certificate is **not valid** for absence from court attendance.

Remarks :

**14 Nov 2017**

**Dr Ramesh Singh, Har-Amree... (63181G)**

**A&E**

Date

Issuing Doctor

Location

Doctor's Signature

Reg No : 20071756-111

..... Tear Along Here .....



**Khoo Teck Puat  
Hospital**  
National Healthcare Group

90 Yishun Central,  
Singapore 768828  
Tel: (65) 6555 8000  
Fax: (65) 6602 3700  
Website: www.ktph.com.sg

**MEDICAL CERTIFICATE**

**DUPLICATE**

**KHANE171232506**

**NAME : MD NOR BIN MAHMUD**  
**NRIC : S2015554Z**

Type of Medical Leave granted : **HOSPITALIZATION LEAVE**

The above named attended Examination/Treatment from **14 Nov 2017 18:40** to **14 Nov 2017 23:30**

The above named is unfit for duty for a period of **14** day(s), from **14 Nov 2017** to **27 Nov 2017** inclusive.

The Certificate is **not valid** for absence from court attendance.

Remarks :

**14 Nov 2017**

**Dr Ramesh Singh, Har-Amree... (63181G)**

**A&E**

Date


Issuing Doctor

Location

Doctor's Signature

Reg No : 20071756-111

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S2015554Z



MD NOR BIN MAHMUD  
محمد نور بن محمود  
Race: MALAY  
Date of Birth: 19-07-1950 Sex: M  
Country of Birth: MALAYSIA

2374834



S2015554Z



Height: 170cm Date of issue: 12-09-1994  
O+

NRIC No: Date: No: 1960514

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S2015554Z  
Name: MD NOR BIN MAHMUD  
Birth Date: 19 Jul 1950  
Issue Date: 28 Aug 2003





000780859K

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	14 Sep 1977
Class 2A	Motorcycles between 201 cc and 400 cc	14 Sep 1977
Class 2	Motorcycles exceeding 400 cc	14 Sep 1977
Class 3	Motor Cars and Motor Tractors the weight of which (laden) does not exceed 2500 kilograms	15 Aug 1985

NP 428A

Licence No: S2015554Z



# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## INVOICE

To: Khwan Hup Farming Pte Ltd  
c/o 68 Kaki Bukit Avenue 6  
#02-05 ARK@Kaki Bukit  
Singapore 417896

Date : 07/12/2017

Invoice No : IV17-12007/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle YP 3724U (Inclusive Of Photographs And Transport Charges)  Our reference : CAS/17-12/007	\$506.00
Total	\$506.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## Automobile Inspection Report

To: Khwan Hup Farming Pte Ltd  
c/o 68 Kaki Bukit Avenue 6  
#02-05 ARK@Kaki Bukit  
Singapore 417896

Date : 07/12/2017

Reference No : CAS/17-12/007

### General Information

Registration No. : YP 3724U  
Accident Date : 14/11/2017

### Particulars of Damaged Vehicle

Colour	: White	Make & Model	: Foton BJ1041V9JD6-FP
Engine Capacity	: 2775 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 56967	Engine No.	: ISF28S5148T89699069
Chassis No.	: LVBV3JBB0FJ073277	Steering	: In Order
Registration Date	: 11/08/2016	Brake	: In Order

### Tyre Condition

	Size	Make	Balance
R/H Front Tyre	205/70R16	BRIDGESTONE	90%
L/H Front Tyre	205/70R16	BRIDGESTONE	90%
R/H Rear Tyre	205/75R15 (D)	MAXWAY	40% / 40%
L/H Rear Tyre	205/75R15 (D)	MAXWAY	40% / 40%

### Inspection

Repairer : 6 Speed Autowerks Pte Ltd  
68 Kaki Bukit Avenue 6, #02-05 ARK@Kaki Bukit, Singapore 417896

### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$6,395.00  
Revised Amount : \$4,300.00  
Less Excess : -  
Nett Total : \$4,300.00

### Remarks

- (A) Survey was done on 16/11/2017
- (B) Re-survey after repair was done on 21/11/2017
- (C) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (D) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>						
1	1pc	Rear box pillar RH	Dented/Warped	1,200.00	1,200.00	500
2	1pc	Rear box door assy RH	Dented/Warped	2,200.00	2,200.00	1800
3	1pc	Rear box door hinge bottom RH	Repair	145.00	-	
4	1pc	Rear side step bracket RH	Dented/Twisted	650.00	650.00	350
Sub total				4,195.00	4,050.00	2650
<u>LABOUR &amp; MISC. CHARGES</u>						
1		To respray painting & etc		700.00	400.00	100
2		Panel beating, cut, weld, remove & replacing above parts		1,500.00	900.00	600
Grand total				6,395.00	5,350.00	
Recommended cost of lump sum repair (To its pre-accident condition)					4,300.00	

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$4,300.00 on a contractual basis. Under normal circumstances, the repair period would be about 5 (Five) working days.

Yours faithfully,

**Constant Appraiser Services**

Lim Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA

3350  
20%: 2650

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2017		17 Nov 2017 10:12 <a href="#">Edit Adj Rpt</a>	<b>S\$2,650.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>			<a href="#">[Created by insurer]</a>						
Insured:	MD NOOR BIN MAHMUD, ID: S2015554Z, Tel: +6597726214								
Main Claimant:	KHWAN HUP FARMING PTE LTD, Co. Reg. No.: 198401659W								
Vehicle Reg. No.:	YP3724U	Date of Loss:	14/11/2017 00:00 - :59						
Claim Type:	TP / MSC/V/17-001785	Policy/Cover Note No.:	MSD/VMS/17-359226-CA (TP, Fire & Theft) Coverage: 09/02/2017 - 10/05/2018						
Vehicle Reg. No. (Insured):	FBF3351L	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 18/11/2017]								
Driver/Custodian (Insured):	MD NOOR BIN MAHMUD (67), NRIC: S2015554Z, Tel: +6597726214								
Adj Asg. Remarks:	Please contact Ms Sun Sun @ 8533 2934 to arrange for survey .								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a> <a href="#">Compose Case Mail</a>						
<ul style="list-style-type: none"> <li>MSIG_LTP (26/02/2018): Paper re-survey report - YP3724U</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*YP3724U (MSC/V/17-001785)**  
**[FBF3351L]**

TP

**KHWAN HUP FARMING PTE LTD**

**Nov 14 2017 12:00AM**

**[MD NOOR BIN MAHMUD]**

**6 Speed Autowerkz Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a> ▼	
<b>Letters/Correspondences</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/11/17 13:31	<b>Non Reporting Letter to OI</b>	1 Load HTM	
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/18 13:21	<b>Accident Statement Addm. #1</b> From: SC - Reg. No: FBF3351L, Claimant: MD NOR BIN MAHMUD	1 Load HTM	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
2	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
3	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
4	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
5	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
6	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
7	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
8	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
9	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
10	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
11	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
12	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
13	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
14	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
15	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
16	27/02/18 14:29	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
17	27/02/18 14:29	<b>Odometer Reading</b>	1 Load JPG	<input checked="" type="checkbox"/>
18	27/02/18 14:29	<b>Chassis Number</b>	1 Load JPG	<input checked="" type="checkbox"/>
19	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
20	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
21	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
22	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
23	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
24	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
25	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
26	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>
27	27/02/18 14:30	<b>Photo After Spray</b>	1 Load JPG	<input checked="" type="checkbox"/>

				<input checked="" type="checkbox"/>
28	27/02/18 14:30	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/11/17 13:30	TPD YP3724U - PRI	Load PDF	
2	27/12/17 14:29	YP3724U E-file, Cert of Ins & LTA Search	Load PDF	
3	27/12/17 14:29	Survey Report & Photo	Load PDF	
4	08/01/18 15:27	Insured Police Report	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021995/GRBS2  
Date: 28/02/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/17-359226-CA  
 Claimant Vehicle No: YP3724U Insured Vehicle No: FBF3351L  
 Date of Loss: 14/11/2017 Nature of Claim: TP Claim No: MSC/V/17-001785

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: YP3724U  
 Make & Model: FOTON BJ1041V9JD6-FP, 2.8 D (M)  
 Reg. Date: 11/08/2016 (Man. Year: 2015)  
 Colour: White  
 Engine Capacity: 2775 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price  
 Engine No: ISF28S5148T89699069  
 Chassis No: LVBV3JBB0FJ073277  
 Odometer: 56967 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/75R16 Rear Tyre Size: 205/70R16 (D)  
 Front Left Side: Bridgestone 6 mm Rear Left Side: MaxWay 5/5 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: MaxWay 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,195.00	2,650.00	1,545.00	36.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	700.00	1,500.00	68.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,395.00	3,350.00	3,045.00	47.62
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	6,395.00	2,650.00	3,745.00	58.56

## INSPECTION

Date of Assignment: 17/11/2017  
 Date Inspected: 17/11/2017 Inspected At: 6 Speed Autowerkz Pte Ltd (HQ)  
 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB  
 Singapore 417896  
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 28 Feb 2018)	
<b>Parts:</b>	N/A	FOTON BJ1041V9JD6-FP 2.8 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP3724U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOX PILLAR RH	Dented / Warped	1,200.00 FS	*500.00 FS
2	1		*REAR BOX DOOR ASSY RH	Dented / Warped	2,200.00 FS	*1,800.00 FS
3	1		*REAR BOX DOOR HINGE BOTTOM RH	Repair	145.00 FS	*- FS
4	1		*REAR SIDE STEP BRACKET RH	Dented / Twisted	650.00 FS	*350.00 FS
<b>Total Parts (S\$)</b>					<b>4,195.00</b>	<b>2,650.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESPRAY PAINTING & ETC.	New	700.00	100.00
2	PANEL BEATING, CUT. WELD, REMOVE & REPLACING ABOVE PARTS.	New	1,500.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,200.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >