

12/03/2017

ASS: REC BY:

REF: CS3/SM017022007/M1be2

range 2 days

Surveyor:

ma

ASSIGNMENT (Office)

From (Person):

Sherry Wong

of

SMO

Date/Time:

17/11/17 @ 2:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 4674 J

Insured:

SKM 5818 B

at Workshop m/s

Nexwave Auto

Tel:

9138 4382

of 160, Sin Ming Drive # 05-15, S75722 Autocity

Policy No:

Claim No:

CMTD1704122/AGC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/11/2017

CA / REV / REP. / REV 24 HRS

lup'

20/11/2017

Date/Time:

4:12pm @ 17/11/17

Person Contacted:

jennie

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

GBD 4674 J - X

SKM 5818 M - X

Dismantle Part: 21.11.2017

After Repair: 30.11.2017


02/12/17 12:45pm Email to Sherry Wong

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBD 4670 Yr Regn: NOV 2014  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HACE C.C. 2982  
Colour: Blue A/C: Insured / Std / NI / NA  
Sp. Reading: 60619 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: 3TFHT02P600152411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/15

R: 195/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front Rear  
R/Bal. 8 mm R/Bal. 8 mm  
L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 16/11/2017 D.O.I. 20/11/2017 @ 10300

Survey held at Nex wave.

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8K-10K 9-10 weeks

Date/Time, File Pass to?

1) 05-12-2017

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report

☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_ S + RS \_\_\_\_\_ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Report Format : PRS

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO17022007/M1b		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 17-11-2017		
		Code : SMO		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SKM 5818B	Veh. Inspected	GBD 4674J	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1704122/AGC	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	17/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	16/11/2017	Inspection Date	20/12/2017	
Survey held at	NEXWAVE AUTO 160 SIN MING DRIVE #05-15 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

**Nivitha (LKK Auto)**

---

**From:** Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>  
**Sent:** Friday, 17 November, 2017 2:52 PM  
**To:** 'Sally Chong'; 'assignments'  
**Cc:** Henry, Irene James; Chan, Shu Hui Agnes; 'nexwaveauto0515'; 'Judy Soh'; 'Nivitha (LKK Auto)'  
**Subject:** RE: OUR REF.: N65-MISC.17 (GBD4674J @ 16.11.2017) SOMPO REF NO : CMTD1704122/AGC

Our Reference: CMTD1704122/AGC  
Your Reference: N65-MISC.17

Date: 17<sup>TH</sup> November 2017

**Without Prejudice**

**BY EMAIL ONLY**

**Attention:**

**M/S VISION LAW LLC**

**Accident involving SKM5818B and GBD4674J on 16/11/2017**

Dear Sirs,

We refer to your email reply dated 17/11/2017.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to **LKK AUTO**,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (GBD4674J).

Thank you.

Best Regards

**Shery Wong**

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Sally Chong [mailto:[sallychong@visionlawllc.com](mailto:sallychong@visionlawllc.com)]

**Sent:** Friday, November 17, 2017 1:57 PM

**To:** Wong, Shi Yi Shery

**Cc:** Henry, Irene James; Chan, Shu Hui Agnes; 'nexwaveauto0515'; 'Judy Soh'

**Subject:** OUR REF.: N65-MISC.17 (GBD4674J @ 16.11.2017) SOMPO REF NO : CMTD1704122/AGC

### **VERY URGENT**

Dear Shery,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

**CLAIMANT: SYSTEM TECHNIC ENGINEERING PTE LTD**

**ACCIDENT INVOLVING GBD 4674J (2<sup>nd</sup>), SKM 5818B (3<sup>rd</sup>) & GBD 7127C (1<sup>st</sup>) ON 16 NOV 2017 ALONG FILTER LANE FROM PUNGOL WAY TO TPE (SLE) AT ABOUT 07:20 HRS**

We refer to your email of 17 Nov 2017 below.

**TAKE NOTICE** that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

<b>Name of Surveyor</b>	<b>Company Name</b>
Nicky Seah	Absolute Appraisal Services

**Please be informed that the said vehicle can be inspected at:-**

Venue : **NEXWAVE AUTO**  
160, Sin Ming Drive, #05-15, Sin Ming Autocity,  
Singapore 575722

Contact : Mr. Douglas Ng (HP: 9398-3688 / TEL: 6454-3616)  
Ms. Jennie Tan (HP: 9138-4382)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

## Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

**From:** Wong, Shi Yi Shery [mailto:Shery.Wong@sompo.com.sg]

**Sent:** Friday, 17 November, 2017 1:53 PM

**To:** 'sallychong@visionlawllc.com'

**Cc:** Henry, Irene James; Chan, Shu Hui Agnes; 'nexwaveauto0515'; 'Judy Soh'

**Subject:** RE: OUR REF.: N65-MISC.17 (GBD4674J @ 16.11.2017) SOMPO REF NO : SKM 5818B

Our Reference: CMTD1704122/AGC

Your Reference: N65-MISC.17

Date: 17<sup>TH</sup> November 2017

**Without Prejudice**

**BY EMAIL ONLY**

**Attention:**

**M/S VISION LAW LLC**

**Accident involving SKM5818B and GBD4674J on 16/11/2017**

Dear Sir

We refer to your Notice of Accident via email dated 17/11/2017.

Please be informed that Agnes is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

### Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	

		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Shery Wong**

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

**From:** Sally Chong [<mailto:sallychong@visionlawllc.com>]

**Sent:** Friday, November 17, 2017 11:59 AM

**To:** Motor Survey; Henry, Irene James

**Cc:** 'nexwaveauto0515'; 'Judy Soh'

**Subject:** OUR REF.: N65-MISC.17 (GBD4674J @ 16.11.2017) SOMPO REF NO : SKM 5818B

**Importance:** High

## **AMENDED COPY** **VERY URGENT**

Dear Sir,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

**CLAIMANT: SYSTEM TECHNIC ENGINEERING PTE LTD**

**ACCIDENT INVOLVING GBD 4674J (2<sup>nd</sup>), SKM 5818B (3<sup>rd</sup>) & GBD 7127C (1<sup>st</sup>) ON 16 NOV 2017 ALONG FILTER LANE FROM PUNGGOL WAY TO TPE (SLE) AT ABOUT 07:20 HRS**

We are instructed by **NEXWAVE AUTO** to notify you of a road traffic accident on **16 NOV 2017** at about **07:20 HRS** **ALONG FILTER LANE FROM PUNGGOL WAY TO TPE (SLE)** involving our client's vehicle registration number **GBD 4674J** and vehicle registration number **SKM 5818B** driven by you/your insured at the material time.



As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

***Sally Chong***

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

C.c.: **VEHICLE OWNER OF SKM 5818B**  
**LUM CHANG BUILDING CONTRACTORS PTE LTD**  
14, Kung Chong Road,  
#08-01, Lum Chang Building,  
Singapore 159150

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---



DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**(2) System - (Views/Merimen)**

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

**(3) Workshop Estimate/Assignment Form**

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


**(4) System - (Views/Merimen)**

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	16/11/2017 15:02
Date Of Accident	16/11/2017 07:20
Exact Location Of Accident	FILTER LANE FROM PUNGGOL WAY TO TPE (SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
------------------------	--

Vehicle Registration Number	GBD4674J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SYSTEM TECHNIC ENGINEERING PTE LTD
Co Reg No	- 3254FM -
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97641685
Alternative Phone No	OFFICE-97641685

### Vehicle Particulars

Manufacturer	TOYOTA
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28625557 MKC
Cover Note Number	

### Driver

Name of Driver	TEO WEE CHONG
NRIC No	S7507422J
Date Of Birth	26/02/1975
Occupation	OUTDOOR
Date Of Driving Pass	09/11/1992
Driving Experience	25 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

refer attached report.

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD7127C

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver KOO HOONG THIAN

NRIC/Passport Number G2488622R

Contact Number 82337812

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Details of Witness

Name

Phone Number

Email Address

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKM5818B

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

CHERN KEY

NRIC/Passport Number

S1682230B

Contact Number

94598148

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1) My van GAP 1578J was carrying the TPE (S) from Selegang Bus Hub toward TPE (S).

2) Suddenly the front of vehicle (GAP 7127C) sudden brake. I was in time to brake my van. But not the car (SKM 5818B) hit the back of my van and pushed my van in front to hit the front van.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/11/12  
13.00PM

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

## Catherine Chong (LKK Auto)

---

**From:** Catherine Chong (LKK Auto) <admin-d@lkkauto.com>  
**Sent:** Saturday, 2 December, 2017 12:45 PM  
**To:** 'Wong, Shi Yi Shery'; 'assignments'  
**Cc:** 'Henry, Irene James'; 'Chan, Shu Hui Agnes'  
**Subject:** RE: OUR REF.: N65-MISC.17 (GBD4674J @ 16.11.2017) SOMPO REF NO : CMTD1704122/AGC

Dear Shery,

Refer to your assignment on 17.11.2017 at 2.52PM.

Please be informed that we have inspected the vehicle GBD 4674J on 20.11.2017 at 10.30AM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, 17 November, 2017 5:11 PM  
**To:** 'Wong, Shi Yi Shery' <Shery.Wong@sompo.com.sg>; 'Sally Chong' <sallychong@visionlawllc.com>; 'assignments' <assignments@lkkauto.com>  
**Cc:** 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'nexwaveauto0515' <nexwaveauto0515@gmail.com>; 'Judy Soh' <judysoh@visionlawllc.com>  
**Subject:** RE: OUR REF.: N65-MISC.17 (GBD4674J @ 16.11.2017) SOMPO REF NO : CMTD1704122/AGC

Dear Shery,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Wong, Shi Yi Shery [mailto:Shery.Wong@sompo.com.sg]  
**Sent:** Friday, 17 November, 2017 2:52 PM  
**To:** 'Sally Chong' <sallychong@visionlawllc.com>; 'assignments' <assignments@lkkauto.com>  
**Cc:** Henry, Irene James <irene.henry@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; 'nexwaveauto0515' <nexwaveauto0515@gmail.com>; 'Judy Soh' <judysoh@visionlawllc.com>; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>  
**Subject:** RE: OUR REF.: N65-MISC.17 (GBD4674J @ 16.11.2017) SOMPO REF NO : CMTD1704122/AGC




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO17022007/M1be2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date:	06-12-2017
		Code:	SMO
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKM 5818B	Veh. Inspected	GBD 4674J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704122/AGC	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	17/11/2017
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTFHT02P600152411	Colour	BLUE
Odometer	60619 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	8 mm
L/H Front Tyre	195 R15	BRIDGESTONE	8 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	8 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information			
Accident Date	16/11/2017	Inspect Date / Time	20/12/2017 ( 10:30 AM )
Survey held at	NEXWAVE AUTO 160 SIN MING DRIVE #05-15 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$10,000.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	

Report Ref No. CS3/SMO17022007/M1be2

Inspected By

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.