

10114

Wilson

### ASSIGNMENT 10 (Feb.)

Männchen

FROM 1750 TO

Joel Goh

C71

16/11/17 @ 4.52pm

## Discussion

Figure 1

OD/TP/WS/TP RES/OD RES/EVA/ENV/MV/CS

To Inspect Vehicle No. \_\_\_\_\_

FBD 2487X

Y

SLA 8185A

at Worcester 12<sup>th</sup>

## Advance Republic

The diagram illustrates a two-dimensional lattice structure. It consists of a grid of points. Arrows indicate interactions between nearest and next-nearest neighbors. The lattice is labeled with 'a' for the nearest neighbor distance and 'b' for the next-nearest neighbor distance.

68-42 5880

of No. 68 Kaki Bukit Ave 6 # 04-06 417896

Policy No.

DMPCS N 3024761701

(C) 1999 by John Wiley & Sons, Inc.

SNM17D06468C02/5

Sun Inside

Exerc.

Make of Veh:

(Client's Record

DCA 7/11/2017

CA / REV / REP. / REV 24 HRS

1 up)

20/11/17 @ Morning

H.O.D. February 2011

Date/Time

1.08pm @ 17/11/17

Person Contacted:

Clement

Vehicle IN 1011

Date: Time:

Action Instruction (✓) Estimate

FBD 2487X - X

SLAS:85A - X

Dismantle Part : 04.12.2017.

PRs  
12.6m

CTI

ADULT INSURANCE

From: Date: 20/11/2017 Vehicle: FBD 2487X Reg: 2008 Dec 27

Estimated Cost: Type: M.Cat: TP Bus/Van/Long Taxi/Prime Mover/ Truck/Trailer/

OD/TP/WS/TP/RES/OD/RES/EVA/INV/MV  
To inspect vehicle No: FBD 2487H  
at Workshop: Advance Republic  
No: 68 kaki Bukit Ave 6 #04-06, 417896  
Insured

Policy No: Gen Cond: Good Yes Poor/Burnt  
Claims No: Steering: In order Jammed/Leaked/Burnt/

Sum Insured: Excess: Brake: In order Jammed/Leaked/Burnt/

Client's Record: Make of Veh: Model: NISSAN STD A/Rim/

Policy Condition: Tyre Size: F: 120/70 2R17  
R: 190/50 2R17  
Remarks: The veh had commenced its repair at the time of inspection.  
BS/DUN/EXNOVA/GY/FS/LIZA/MICHOOTSU/PIR/SUMI-TOYO/YOKO or

Ball or Market Value: Front: Rear:  
D.O.A. Accident Report: Consistent? Yes or No R Bal: 2 P Bal: 3  
GIA/PR/Seen: Consistent? Yes or No L Bal: 2 L Bal: 3

Est. Repairs: 2 days Res: Yes or No D.O.A.: 20/11/2017  
Sum Sum: % S Val: Yes or No Surveyed at: Advance Republic 11-44am

CA / REV / REP. / 24 HRS Des of Damages: Fr: Rear: O/S N/S L/C Rooftop or

Date: Person Contacted: Vehicle IN/OUT: The U/C / Chassis/frame Body Structure affected due to collision

Date/Time Action/Instructions: No Accident Report Given

Range \$550 - \$650

RECEIVED 03 MAR 2018

19/1/2018

Date/Time For Pass 1	<input type="checkbox"/> Prelim. Report	Days Of Repair	<div>Survey Fee</div> <div></div>
03/03/2018	<input type="checkbox"/> Final Report	Resurvey No. of Trip	
Date/Time For Return			
	Add Fee	<input type="checkbox"/> Site Fee \$	
		<input type="checkbox"/> Other Fee \$	
		<input type="checkbox"/> Test Fee \$	
		<input type="checkbox"/> Other Fee \$	
Receipt Format	PRs		
Auto Sign			



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI17022014/Wb

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-11-2017



Code : CTI

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLA 8185A	Veh. Inspected	FBD 2487X
Policy No.	DMPCSN3024761701	Coverage (\$)	0.00
Claim No.	SNM17D06468C02/5	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	17/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	07/11/2017	Inspection Date	17/11/2017
Survey held at	ADVANCE REPUBLIC PTE LTD BLK 68 KAKI BUKIT AVE 6 #04-06 SINGAPORE 417896		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2017		16 Nov 2017 16:52 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

THAM CHEE LEONG, ID: S7507491C

Main Claimant:

LAI WEI YI, LESLIE, ID: S8931457G

Vehicle Reg. No.:

FBD2487X

Date of Loss:

07/11/2017 17:00 - :59

Claim Type:

TP / SNM17D06468C02/5

Policy/Cover Note No.:

DMPCSN3024761701  
(Comprehensive)

Vehicle Reg. No. (Insured):

SLA8185A

Policy No. (Claimant):

DMMPHQ17-000507

Excess:

S\$0.00

Repairer:

Advance Republic Pte Ltd (HQ) 123 KAKI BUKIT AVENUE 1 SHUN LI INDUSTRIAL PARK #01-01, 415996  
Kaki Bukit - Tel: 6842 5880

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]

Claimant's Insurer:

EQ Insurance Company Ltd (HQ) - Tel: 6223 9433

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/11/2017]

Driver/Custodian (Insured):

THAM CHEE LEONG (42 / Male), NRIC: S7507491C

Adj Asg. Remarks:

NO ESTIMATES. ASSIGNED FOR WP PRS

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor** ( ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**(2) System - (Views/Merimen)**

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

**(3) Workshop Estimate/Assignment Form**

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


**(4) System - (Views/Merimen)**

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014

D.O A → 7/11/2017

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	1457G

## Vehicle Details

Vehicle No.	FBD2487X	26	12	2018
Vehicle to be Exported	No	07	11	2017
Intended De-registration Date	02 Dec 2017	19	1	1
Vehicle Make	SUZUKI (Bal: ob			
Vehicle Model	GSR400 M			mark
Primary Colour	Black			
Manufacturing Year	2008	Bal	→	14 1.6 mark
Engine No.	K719103117	→		13.6 mark
Chassis No.	GK7DA103079			
Maximum Power Output	-			
Open Market Value	\$10,295.00			
Original Registration Date	27 Dec 2008			
First Registration Date	27 Dec 2008			
Transfer Count	6			
Actual ARF Paid	\$1,545.00			


## Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

## Intended COE Rebate Details

COE Expiry Date	26 Dec 2018
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$1,059.00
COE Rebate Amount	\$132.00
<b>Total Rebate Amount</b>	<b>\$132.00</b>

The information contained herein is correct as at 02 Dec 2017

 → \$2000  
 OK

MBHH17148630 / AJAX MARS PTE LTD - Bukit Merah  
ENTRY DATE & TIME: 09/11/2017 19:30

**Your NCD will be affected due to late reporting**  
**Actual e-Filing Submission Date & Time: 09/11/2017 20:03**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/11/2017 19:30
Date Of Accident	07/11/2017 17:45
Exact Location Of Accident	SELETAR WEST LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBD2487X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LAI WEI YI, LESLIE
NRIC No	S8931457G
Email Address	LESLIE.LAIWEIYI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97225570
Alternative Phone No	Office-97225570

### Vehicle Particulars

Manufacturer	SUZUKI
Model	GSR400
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMPHQ17-000507
Cover Note Number	

### Driver

Name of Driver	LAI WEI YI, LESLIE
NRIC No	S8931457G
Date Of Birth	04/09/1989
Occupation	INDOOR
Date Of Driving Pass	22/06/2011
Driving Experience	6 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97225570

Fax Number  
 Contact Number OFFICE-97225570  
 EMail Address LESLIE.LAIWEIYI@GMAIL.COM  
 Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

While I FBD2487X was riding along Seletar west link at the first lane, the 3rd party was trailing behind me in close proximity. While riding I wanted to change to the 2nd lane as I was intending to exit at Yishun dam. Suddenly a garbage lorry make an abrupt and sharp Change from lane 3 onto the 2nd lane. As I was still quite a distance away, I decided to shift a little from slightly left of lane 1 as taught in driving centres, to Center line of lane 1 and slow down as I knew I was approaching the exit soon. This was when his vehicle rear ended my bike, as he was attempting to speed past me in the small gap. This cause me to skid. I manage to regain balance and stopped at the side of the road. In which he picked up speed and over take me to lane 3. My 2 friends which were behind his vehicle told me that the driver had been slowing down and picking up speed very close to me in an attempt to force me to give way to him.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA8185A  
 Vehicle Make/Model/Colour HONDA / VEZEL 1.5X CVT  
 Details Of Properties NA  
 Name of Driver ANDY THAM  
 NRIC/Passport Number S7507491C  
 Contact Number 98753130  
 Address  
 Postcode



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


**Details of Witness**

Name

Phone Number

Email Address

## Sketch Plan



## Common Statement

**ACCIDENT STATEMENT (2000 characters)**

While I FBD2487X was riding along Seletar west link at the first lane, the 3rd party was trailing behind me in close proximity. While riding I wanted to change to the 2nd lane as I was intending to exit at Yishun dam. Suddenly a garbage lorry made an abrupt and sharp change from lane 3 onto the 2nd lane. As I was still quite a distance away, I decided to shift a little from slightly left of lane 1 as taught in driving centres, to Center line of lane 1 and slow down as I knew I was approaching the exit soon. This was when his vehicle rear ended my bike, as he was attempting to speed past me in the small gap. This caused me to skid. I managed to regain balance and stopped at the side of the road. In which he picked up speed and overtook me to lane 3. My 2 friends which were behind his vehicle told me that the driver had been slowing down and picking up speed very close to me in an attempt to force me to give way to him.


Taxi Voucher No.:

**DECLARATION**

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 November 2017 6:10 pm

Date/Time

9 November 2017 6:10 pm

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2017 11:44
Date Of Accident	07/11/2017 17:45
Exact Location Of Accident	ALONG SELETAR CLUB ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA8185A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THAM CHEE LEONG
NRIC No	S7507491C
Email Address	RUNTIME88@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98753130
Alternative Phone No	OFFICE-98753130

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3024761701
Cover Note Number	

### Driver

Name of Driver	THAM CHEE LEONG
NRIC No	S7507491C
Date Of Birth	12/02/1975
Occupation	INDOOR
Date Of Driving Pass	29/11/2004
Driving Experience	12 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98753130
Fax Number	
Contact Number	OFFICE-98753130
Email Address	RUNTIME88@HOTMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

### General Information of the Accident

Type Of Accident COLLIDED INTO MOTORCYCLIST

Weather Conditions RAINING

Road Surface WET

### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

AS PER ATTACHED SKETCH PLAN AND ATTACHMENT "A"

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBD2487X

Vehicle Make/Model/Colour BLACK MOTORCYCLE

Details Of Properties

Name of Driver LESLIE LAI

NRIC/Passport Number S8931457G

Contact Number 97225570

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

### Details of Witness

Name

Phone Number

Email Address

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

8/11/17  
(11:30am)

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Handwritten signature and stamp of the Reporting Centre Personnel.

HN T.B.  
0055B.

SKETCH PLAN

See Attachment "A"

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

See Attachment "A"

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 8/11/17 (11:30am)

GIARMC SketchPlanForm V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

HO TB





0055B



Attachment "A"


**中国太平**  
**CHINA TAIPING**
**中国太平保险(新加坡)有限公司**  
**CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**

 3 Anson Road #15-00 Springleaf Tower Singapore 079808  
 Tel: 6389 6111 Fax: 6222 1033  
 Website: www.sg.ctaiping.com  
 Co. Reg. No. 200206384E

DETAIL OF ACCIDENT	
PLEASE EXPLAIN CLEARLY THE CIRCUMSTANCES UNDER WHICH THE ACCIDENT TOOK PLACE. SKETCH: <div style="display: flex; align-items: center; justify-content: center; margin-top: 10px;">  </div>	
<p>Was driving along Seletar Club Road, when the said motorbike signal left and decided to skew to right and cut into my 1st lane. As a result, the bike back storage box hit onto my left bumper.</p>	
<b>NOTE:-</b> Every communication you receive in connection with this matter should be forwarded to the Company without delay.	
<b>DATA PRIVACY STATEMENT</b>	
<p>In accordance with the Personal Data Protection Act 2012, I consent to the collection, use, disclosure of and/or process of my personal data (whether contained in the Claim Form or otherwise obtained) by China Taiping Insurance (Singapore) Pte Ltd, its affiliates and service providers (within or outside Singapore), for the purpose relating to the evaluation of the claim and to provide advice and information relating to the claim to me by Short Message Service (SMS), Multimedia Messaging Service (MMS) and fax messages (notwithstanding the registration of my telephone or mobile number in the Singapore's Do Not Call Registry)</p>	
<p>Yes, I have read and agreed to the above Data Privacy Statement.</p>	
<div style="display: flex; justify-content: space-between;"> <div style="width: 30%;">             Signature of Claimant         </div> <div style="width: 30%;"> <p>Name: <u>Tham Choo Leang (S7507491C)</u></p> <p>NRIC/FIN/Passport No</p> </div> <div style="width: 30%;">             Insured Signature         </div> <div style="width: 30%;">             Driver Signature         </div> </div>	
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>Date <u>8-11-2017.</u></p> </div> <div style="width: 55%;"></div> </div>	
FOR OFFICE USE ONLY	
<b>NAMED DRIVERS:-</b> a. _____ b. _____ c. _____ d. _____ <b>ENDORSEMENTS:-</b> a. _____ b. _____ c. _____	<b>PERIOD OF INSURANCE:-</b> FROM: _____ TO: _____ <b>EXCESS:-</b> a. Section I :- Section II :- b. Unnamed Driver :- TOTAL = NO CLAIM BONUS =

ANNEX E

NOTICE OF REPORTING

This is to confirm that Tham Chee Leong, NRIC: S7507491C, has reported to the Police a non-injury traffic accident which occurred at Seletar Club Road on 07/11/2017 at 5.45pm involving the following vehicles:

SLA8185A (Honda Vezel / Silver)

FBD2487X (Black Motorcycle)

2. If accident was reported to the Police within 24 hrs of its occurrence, then he has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank / Name of Issuing officer: **SGT Muhammad Nabil Amsyar**

Date: 07/11/2017 Time: 8.40PM

S/D Ref: 87

Police Post/ Unit: **BEDOK NORTH NPC**

BEDOK NORTH NPC  
30 BEDOK NORTH ROAD  
SINGAPORE 469676

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2017		16 Nov 2017 16:52 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	THAM CHEE LEONG, ID: S7507491C		
Main Claimant:	LAI WEI YI, LESLIE, ID: S8931457G		
Vehicle Reg. No.:	FBD2487X	Date of Loss:	07/11/2017 17:00 - :59
Claim Type:	TP / SNM17D06468C02/5	Policy/Cover Note No.:	DMPCSN3024761701 (Comprehensive)
Vehicle Reg. No. (Insured):	SLA8185A	Policy No. (Claimant):	DMMPHQ17-000507
		Excess:	S\$0.00
Repairer:	Advance Republic Pte Ltd (HQ) 123 KAKI BUKIT AVENUE 1 SHUN LI INDUSTRIAL PARK #01-01, 415996 Kaki Bukit - Tel: 6842 5880		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Willson] ... [Final Rpt due 27/11/2017]		
Driver/Custodian (Insured):	THAM CHEE LEONG (42 / Male), NRIC: S7507491C		
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED FOR WP PRS		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*FBD2487X (SNM17D06468C02/5)**  
**[SLA8185A]**

**TP**

**LAI WEI YI, LESLIE**

**Nov 7 2017 5:00PM**






**[THAM CHEE LEONG]**

**Advance Republic Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Assessment Reports</b>			1 per page		
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	09/11/17 20:03	<b>Accident Statement</b>		Load HTM	
<b>Photos/Images</b>			3 per page		
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
2	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
3	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
4	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
5	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
6	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
7	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
8	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
9	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
10	09/11/17 19:52	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
<b>Documentation</b>			1 per page		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/11/17 16:58	<b>OI GIA REPORT</b>		Load PDF	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	09/11/17 19:51	<b>Sketch Plan</b> [Linked Accident Report Documents]		Load JPG	
2	09/11/17 19:51	<b>Common Statement</b> [Linked Accident Report Documents]		Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/03/18 12:58	<b>LKKPhotosIn6-1</b>		Load PDF	
2	03/03/18 12:58	<b>LKKPhotosIn6-2</b>		Load PDF	

## Linked Accident Report Documents

			<b>View</b> <a href="#">View in Browser</a>		
<b>Assessment Reports</b>			1 per page		
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	09/11/17 20:03	<b>Accident Statement</b>		Load HTM	

Documentation			1 per page	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	09/11/17 19:51	Sketch Plan	 Load JPG	
2	09/11/17 19:51	Common Statement	 Load JPG	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☒ Handling Insurer

Note: Remarks are private unless you show it to other parties.

//



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CT117022014/WBE2  
**Date:** 09/03/2018

### REFERENCE

**Handling Insurer:** China Taiping Insurance (Singapore) Pte. Ltd. **Policy No:** DMPCSN3024761701  
**Claimant Vehicle No :** FBD2487X **Insured Vehicle No :** SLA8185A  
**Date of Loss:** 07/11/2017 **Nature of Claim:** TP **Claim No:** SNM17D06468C02/5

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** FBD2487X  
**Make & Model:** SUZUKI GSR400M, 398cc **Engine No:** K719103117  
**Reg. Date:** 27/12/2008 (Man. Year: 2008) **Chassis No:** GK7DA103079  
**Colour:** Black **Odometer:** 122630 km  
**Engine Capacity:** 398 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (\$\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

### CONDITION OF TYRES

**Front Tyre Size:** 120/70Z R17 **Rear Tyre Size:** 190/50Z R17  
**Front Left Side:** Michelin 2 mm **Rear Left Side:** Michelin 3 mm  
**Front Right Side:** 0 mm **Rear Right Side:** 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

**Date of Assignment:** 16/11/2017  
**Date Inspected:** 20/11/2017 **Inspected At:** Advance Republic Pte Ltd (HQ)  
 BLK 68 KAKI BUKIT AVE 6 #04-06  
 SINGAPORE 417896  
**Estimated Period of Repair:** 2.0 days

**Adjuster:** Teo Cheng Ming Wilson

**Manager:** CATHERINE CHONG KAI LING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$550.00 -\$650.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Mar 2018)	
Parts:	N/A	SUZUKI GSR400M 398cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD2487X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >