

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/11/2017 18:30
Date Of Accident	16/11/2017 16:00
Exact Location Of Accident	ALONG IRRAWADDY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD245J
Insured/Policyholder	
Name Of Registered Owner	LIM HYOJAE
Passport No/FIN	G3396195U
Email Address	JALIM@WFSCORP.COM
Mobile Phone No	(LOCAL) +65-82239359
Alternative Phone No	OTHERS-82238753

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY
Exact Purpose for which vehicle was being used at time of accident	DRIVING HOME
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095124918
Cover Note Number	

Driver

Name of Driver	KIM JIWON
Passport No/FIN	G3402472W
Date Of Birth	03/03/1983
Occupation	INDOOR
Date Of Driving Pass	22/05/2015
Driving Experience	2 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-82238753
Fax Number	
Contact Number	OTHERS-82239359
Email Address	JALIM@WFSCORP.COM

Address	5 LEEDON HEIGHTS #27-12
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN (TYPE OF COLLISION IS HEAD TO SIDE)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ9122E
Vehicle Make/Model/Colour	HONDA JAZZ
Details Of Properties	
Name of Driver	LIN JINHUA
NRIC/Passport Number	S8974037A
Contact Number	98375581
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Details of Witness

Name	
Phone Number	
Email Address	

Ass. No. 62

N/A

ASSIGNMENT (TOTAL)

By Assessor - 1) Vehicle Information:

- 1) Vehicle hit Vehicle: ☐ 2) Vehicle hit ☐
- a) Motorist ☐ a) Pedestrian ☐
- b) Motorcycle ☐ b) Animal ☐
- c) Bicyclist ☐
- 3) Vehicle hit Road Side Object:
- a) Govt Property ☐ b) Road Work Object ☐
- (E.g. signposts, barrier, etc.) c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God:
- a) Fallen Object ☐ b) Flood ☐
- c) Other ☐
- 6) Parked & Found Damaged:
- a) Vandalism ☐ b) Hit by Moving Object ☐
- 7) Theft Case
- a) Stolen ☐ b) Damage found ☐
- when recovered
- 8) Fire
- a) Whilst driving ☐ b) Parked ☐
- 9) Accident date more than 24hrs ☐

Remarks for internal information

Remarks to appear in Works Order & Assessment report

1) Potential Total Loss ☐2) ABS Light on ☐3) ABS Light on ☐

By Assessor - 1) Vehicle Information:

Veh No: SKD 2457 Yr Reg: OC7 2001Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / M. / Truck / Trailer orMake & Model: Honda COMPASS 2.4 LA7 SRColour: GRAY Transmission Type: Auto / ManualEng/No: R24Z1350660 Reading: 82717O/No: JHMRB3850AC200619Gen. Cond: Good / Fair / Poor / Burnt orSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyro Size F: 215/55 R17R: 215/55 R17BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bul. <u>6</u> mm	R/Bul. <u>6</u> mm
L/Bul. <u>6</u> mm	L/Bul. <u>6</u> mm

Parallel Import: Yes / NoTowed-In: Yes / NoRepair Type: LS / I.B.ITowing Required: Yes / NoNo of Repair Days: 5Vehicle in Idac: Yes / NoD.O.I. 07/11/2017Time: 10: AM

By Assessor - 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto

a. Vehicle ☐ b. Motorcycle ☐ c. Bicyclist ☐ d. Pedestrian ☐e. Animal ☐ f. Govt Object ☐ g. Road Work Object ☐h. Private Property ☐ i. Drain ☐ j. Road Kerb/Grass Verges ☐

3) Vehicle does not seem damaged as a result of:

a. Fallen Object ☐ b. Flood ☐ c. Vandalism ☐ d. Fire ☐e. Moving Object ☐ f. Stolen ☐ g. Stolen & Recovered ☐

Time Stamp

Time Stamp

S. 1234

S. 1234

By Assessor - 2) Comments

MOTOR CAR (Frt)

ACTION/AC

(1) Replace (✓)

(2) Repair (N)

(3) Check (V)

(4) Not Confirmed (NC)

Aug 2008

Front Portion

Vehicle No: SKD 245J

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Spones			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995085	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Ducting			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991923	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Accessories:

Claim Handling

[Task Transfer](#) [Exit](#)
[LOG](#) [GAL](#) [SUB](#)

Accident MT/0970213

Policy No.	5095124918	Vehicle No.	SKD245J	GST Registration No.	
Policyholder Name	LIM HYQJAE			Policyholder NRIC	G3396195U
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	83239359	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KPK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0		

Accident Details

Report Date	17/11/2017 18:37	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Side
Date of Accident	16/11/2017	Time of Accident hh:mm	16:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	ALONG BIRAWADDY ROAD				

Benefits

Excess

Own damage Excess	600.00	Additional Excess	0.00	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	5 LEEDON HEIGHTS	Address 2	#27-12 D'LEEDON	Address 3	SINGAPORE 267952
Address 4		Address Type	Singapore address	Post Code	267952
Unit No.	27-12	Related Policy Number	5095124918		

OI Driver Info

Driver Name	KIM JIWON	Driver Type	Named Driver		
Unnamed driver Name		Driver NRIC	G3402472W	Driver DOB	03/03/1983
Register Date of Driver License	01/01/2005	Driver Age	34	Driving Experience	12
Contact No.(Mobile)		Contact No.(Office)		Contact No.(Home)	
Address 1		Address 2		Address 3	
Address 4		Address Type	Foreign address	Post Code	
Unit No.					
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.	SKD245J	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☒ Yes ☐ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

Claim Type	OD-MD	Insured Name	LIM HYQJAE	Insured NRIC	G3396195U
Contact No.(Mobile)	82239359	Contact No.(Home)	NIL	Contact No.(Office)	
Email Address		OI Vehicle Number	SKD245J	TP Vehicle Number	SK29122E
Claim Description	SKD245J / SK29122E ON 16 Nov 2017			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Date Registered	20/11/2017 10:21	Claim Close Date		Date Received	07/12/2017 13:5
Report Taken By	RDS&J WAHAB	Workshop Repairer		Total Loss but Repaired	

☒ Print AK letter

07/12/2017 13:04 a058324 Modify Claim Type(OD-MX-->OD-MD)

Modification History

Special Claim Creation Approval

Approval		Reason	
----------	--	--------	--

Remarks

[damage assessment](#) [Activity Handling](#) [Attachment](#)

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	ODYSSEY	Engine Capacity	
Date of Registration	24/10/2011	Classis No.	JHMRB3850AC200619	Parallel Import	☐ Yes ☒ No
Towing Required	☐ Yes ☒ No	Vehicle in IDAC	☒ Yes ☐ No	Survey Current Status	
Type of Tender	Own Damage	Assessor Name	ROSLI WAHAB		
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 JBT AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss	☐ Yes ☒ No	Economical Repair Value(\$)	
Market Value (\$)		Scrape Value(\$)			
Remark	VEHICLE IN IDAC BURIT MERAH AND THERE IS CASHCARD \$100 INSIDE THAT ALL.				

Damage Listing

Find a Part	No.	Part No.	Description	Qty	Repair Code
root	1	16000101	BUMPER (FRONT)	1	Replace
Not Applicable	2	16001301	BUMPER BRACKET (FRONT LEFT)	1	Replace
ABS	3	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Replace
ABSORBER	4	16002401	BUMPER CLIPS (FRONT)	1	Replace
ACCELERATOR	5	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm
ACTUATOR	6	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm
ADVERTISEMENT STICKER	7	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace
AIR BAG	8	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace
AIR BLOWER	9	16005501	BUMPER SENSOR (FRONT)	1	Unconfirm
AIR BOX	10	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm
AIR CHAMBER BOX	11	27100301	GRILLE (TOP) (FRONT)	1	Unconfirm
AIR CLEANER	12	27100801	GRILLE EMBLEM (FRONT)	1	Unconfirm
AIR COMPRESSOR	13	27101001	GRILLE MOULDING (FRONT)	1	Unconfirm
AIR CON	14	27700102	HEAD LAMP (RIGHT)	1	Replace
AIR CON (VAN)					
AIR COOLER					
AIR DISTRIBUTOR					
AIR FILTER					
AIR FLOW					
AIR GRILLE					
AIR HORN					

Save Submit

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MA417152649 Vehicle Registration No: SKD 245 J
Name (as shown in NRIC): Lim Hye Jee NRIC/FIN/Passport No: G3396195U
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: 5 leedon heights 29-12 Singapore ()
Contact (Tel): _____ Mobile No.: 8223 9359
Email Address: jalim@wfs corp.com
Date of Accident: 16/Nov/2017 Time of Accident: 1800 hr
Place of Accident: irawady road
Insurance Company: Income

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

to change from reporting to own damage claim

Policyholder / Driver's Signature

Date: 7th dec 2017

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: Roshy YAHYAR

Date: 07/12/2017



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)
51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC

Vehicle Movement Form

Vehicle Check-In

Vehicle No: SKD 245J Date In: 07/11/2017 Time In: 10AM with Keys: Yes

For Office use

Attended by: Rosli

Workshop Collection of Vehicle

Workshop: AMK Autopoint P/L

Collection Date: 08/12/2017 Time: 1435 with Keys: Yes / No

Tow Truck No: SGM 9771S Tow Man: Tan Lee Chin NRIC: S7375936F

Signature: [Signature]

For office use

Attended by: Rosli

Approved by: [Signature]

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Friday, 8 December, 2017 11:19 AM
To: NAC-Bukit Merah; AutoPoint
Subject: SKD245J, OD claim no : MT/0970213

Importance: High

Dear IDAC and AutoPoint,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

Dear AutoPoint,

OD excess of \$600/- is applicable, pls assist to liaise with owner Mr Lim Hyojae at tel : 82239359.

FOR PAYMENT: Please forward the Invoice & Discharge Voucher within 14 days after the repair has been done/ finalized with Surveyor to my email, cc a copy to Yap Chee Ling at cheeling.yap@income.com.sg

Regards.

Without Prejudice

Tan Siew Choo
Senior Claims Executive
Motor Insurance
T +65 6430 7882
www.income.com.sg



Our Ref: MT/CA/OD/051/0970213-001/TSC
08 Dec 2017

AMK AUTOPOINT PTE LTD
BLK 10 ANG MO KIO INDUSTRIAL PARK 2A
#01-22 AMK AUTOPOINT
SINGAPORE 568047

Dear Sir

CLAIM NUMBER: MT/0970213-001

REPAIR OF VEHICLE NUMBER: SKD245J

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 08 Dec 2017

Make: HONDA

Model: ODYSSEY

Estimated Repair Days: 3

Location: NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)

Address: BLK 1007 #01-11 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE INDUSTRIAL ESTATE SINGAPORE 159721

- Benefits Applicable: N/A
 - Excess Applicable: 600
 - Please note that supplementary items will not be allowed.
- If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.
Yours sincerely
Low Choo Mee
Senior Manager
Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.