

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 5	SET RADIATOR GRILLE TOP COVER CLIP	Reviewing	0	NOT NECESSARY	
☐	 6	SET FRONT LICENCE PLATE WITH HOLDER	Reviewing	45	DENTED	
☐	 7	SET RADIATOR GRILLE CLIP	Reviewing	0	NOT NECESSARY	
☐	 8	SET FRONT FENDER LINER CLIP LH	Reviewing	0	NOT NECESSARY	
☐	 9	SET FRONT FENDER LINER CLIP RH	Reviewing	0	NOT NECESSARY	
☐	 10	SET LOUVER COWL TOP CLIP	Reviewing	0	NOT NECESSARY	
☐	 11	BONNET STOPPER	Reviewing	0	SERVICEABLE	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR J BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	40	1			AIRCON CONDENSER			Serviceable	0		10		0
	41	1			AIRCON HOSE - CONDENSER TO COMPRESSOR			Serviceable	0		10		0
	42	1			AIRCON HOSE - COMPRESSOR TO EVAPORATOR			Serviceable	0		10		0
	43	1			AIRCON HOSE - CONDENSER TO EVAPORATOR			Serviceable	0		10		0
	44	1			AIR INTERCOOLER			Serviceable	0		10		0
Labour													
EDIT	SR NO	REPAIR/REPLACE (LABOUR)			PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT		
	1				TO CHECK ELECTRICAL LIGHTING CONCERNED.	20	0	0	Reviewing				
	2				PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	100	0	0	Reviewing				
	3				TO REMOVE AND REFIT FRONT AND REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	0	0	0	Reviewing				
	4				PURTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	200	0	0	Reviewing				
	5				TOWING FEES.	0	0	0	Reviewing				
	6				TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	0	0	0	Reviewing				

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC QUNTY%	SALV AGE%	PART PRICE(NET)
	11	1			BUMPER FOG LAMP COVER LH			Serviceable	0		10		0
	12	1			FRONT WINDSCREEN			Serviceable	0		10		0
	13	1			FRONT WINDSCREEN MOULDING			Serviceable	0		10		0
	14	1			FRONT FENDER LH			Repair	0		10		0
	15	1			FRONT FENDER RH			Repair	0		10		0
	16	1			FRONT FENDER LINER RH			Serviceable	0		10		0
	17	1			FRONT FENDER LINER LH			Serviceable	0		10		0
	18	1			RESONATOR (B/S FENDER LH) AIR BOX			Serviceable	0		10		0
	19	1			RESONATOR HOSE			Serviceable	0		10		0
	20	1			BONNET			Repair	0		10		0
	21	1			BONNET HINGE RH			Repair	0		10		0
	22	1			BONNET HINGE LH			Repair	0		10		0
	23	1			BONNET MOULDING			Serviceable	0		10		0
	24	1			BONNET LOCK			Repair	0		10		0
	25	1			BONNET CABLE			Serviceable	0		10		0

Detailed Assessment

Inspection
Date *

mm/dd/yyyy

Condition of Vehicle at time of survey

General
condition

Excellent

Tyre Condition

Total Loss

Towing Charges

Voluntary
ExcessCompulsory
ExcessYoung/Inexperie
nced/Unnamed
Driver Excess

Other Excess

Steering
(Serviceable)Footbrake
(Serviceable)Handbrake
(Serviceable)Engine
ModificationPre-accident
condition

Excellent

Age of Tyres

Front Tyre Size

Front left side

Front right side

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		mm/dd/yyyy
Address	Singapore	
Address type	Personal Correspondence	Business ▾
Gender	Unknown	Female ▾
Marital status	Unknown	Single ▾
Identification #	S7305711F	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Model	EPICA	
Type		Listed on
Type of Paint		
Chassis No		
Engine No		
Engine Capacity		
Sum Insured		
Market Value		

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
----------	------------------	-------------------------

Direct settlement

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

MessagesInvoicesHistoryDocuments

AssessmentMetricsNotesAdd

Additional Instructions

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	2/27/18 1:11 PM	\$900.00	\$900.00	Open	Share	Clone
TAY Ernest	11/23/17 4:05 PM	\$1,099.40	\$1,099.40	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
EMAIL.pdf	Forms / Claim Documents	Estimate / Quotation	KUMAR Shailendra	November 21, 2017
ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	KUMAR Shailendra	November 21, 2017
SHD9158D TP GIA.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	November 21, 2017
SKM9799X INS GIA.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	November 21, 2017

Direct settlement

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Messages Invoices History Documents

Additional Instructions

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	April 5, 2018
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	April 5, 2018
AUTHORISATION TO ACT.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	April 5, 2018