

Surveyor:

Kenneth

DOI:

ASSIGNMENT

17/11/17

Date / Time:

17/11/17

Registered in Merimen:

20/11/17

Pre-assign / CCU / FTE

GBA 4511 L



Insured Vehicle No.:

Name of Insured:

CHANG KANG ENTERPRISES CO. P/L

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

7. DYNA

Place of Accident:

West Coast Highway

Excess Sec II :S\$

D.O.A.:

Nature of Accident:

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Vao Swee Kiat

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

98621420

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hoe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
17/11/17	YP1100 X;	Non-Reporting ltr (1st):	
17/11/17	GBA 4511 L	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	NA
		Notification ltr (if non-pickup):	
		Call OI:	2017 21-4-18
		After call ltr to OI:	
19-1-18	FILE RECEIVED FROM ZAYER	Documentation Check List:	Handler Typist
21-4-18	@ 440 PM W/ DIC JASON LOW CONFIRMED ACC. AGREED & AWARE NCD ISSUE.	Notification ltr (if non-pickup):	<input checked="" type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input checked="" type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/>
		PIR:	<input checked="" type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input type="checkbox"/>
21-5-18	FOR MANDATE	Payment Breakdown Form:	
13-9-18	RECEIVED 21 MAY 2018	Post-Repair Photos:	<input type="checkbox"/>
11-01-19	Final Liability Ciderwork IMPROVE OFFER	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	S\$	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No. : 27
Repair Cost:	GJ1	S\$	10,486
Loss of Rental (LOR):	S\$	(days)	
Loss of Use (LOU):	S\$	(160 x 14 days)	
Loss of Income (LOI):	S\$	(5 x days)	
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/>
[Tick only one]			
GIA/LTA Search:	S\$	8	
Medical:	S\$	-	
Disbursement:	S\$	-	(e.g. Tow/ Independent)
Legal Cost:	S\$	-	
Total:	S\$	11,894.xx	Global Sum S\$ 11,890
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	S\$	11,890.xx	Name 1: CHENG HOE MOTOR PTE LTD
Payee 2: (Strike if N.A.)	S\$	x	Name 2: X
Payee 3: (Strike if N.A.)	S\$		Name 3: X

ASS. REC. BY:

REF:

A61

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 15 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 7P 1110D Yr Regn: 01.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: JAZZ APR85 c.c. 2999

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 13527 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAA N PR 85141F 710078

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 16/11/17

D.O.A. 17/11/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/11/16 File open to Customer

01 DRIVING L. - CLASS 3; TO CHECK IF 01 ALLOWED ON
HIS VEH. DRIVEN. (LIMIT CAPACITY) ISSUE

11 Sup @ 98000 Confirmed Efrdr (12*2 X 120)

R (\$4,084.97/29%)

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair: _____

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17022081/Kza3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 20-11-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 4511L	Veh. Inspected	YP 1110D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/11/2017	Inspection Date	17/11/2017	
Survey held at	CHENG HOE MOTOR PL 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 SINGAPORE 757700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

YP1110D
TP/AIG

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	1155H

Vehicle Details

Vehicle No.	YP1110D
Vehicle to be Exported	Yes
Intended De-registration Date	17 Nov 2017
Vehicle Make	ISUZU
Vehicle Model	NPR85UH5A
Primary Colour	White
Manufacturing Year	2015
Engine No.	4JJ12E7249
Chassis No.	JAANPR85HF7100785
Maximum Power Output	-
Open Market Value	\$30,570.00
Original Registration Date	25 Jan 2016
First Registration Date	25 Jan 2016
Transfer Count	0
Actual ARF Paid	\$1,529.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	24 Jan 2026
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$46,001.00
COE Rebate Amount	\$36,800.00
Total Rebate Amount	\$36,800.00

The information contained herein is correct as at 17 Nov 2017

OK

YP1110D
TP-AIG

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374-382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/WL

Claim Type: Third Party

Accident Date: 16/11/2017

TP Veh Reg No: GBA4511L

Estimate No: ES1791311/WL

Date: 17 Nov 2017

Policy No: 5076090997-01

Veh Reg No: YP1110D

Make/Model: ISUZU NPR85UH5A

Chassis No: JAANPR85HF7100785

Engine No: 4JJ12E7249

Reg. Date: 25/01/2016

Estimate Repair Cost to Vehicle No :YP1110D

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 TAILGATE LAMPS	134.10	2 PCS	268.20	268.20
		Less 15%	40.23	227.97
Special Net				
2 TAILGATE	1,600.00	1 PC	1,600.00	1,600.00
3 TAILGATE SPEED STICKER	10.00	2 PCS	20.00	20.00
4 REAR NUMBER PLATE	12.00	1 PCS	12.00	12.00
5 REAR SAFETY BAR ASSY WITH BRACKET	750.00	1 PC	750.00	750.00
6 REAR COY PLATE	250.00	1 PCS	250.00	250.00
7 REAR TRUNK END WOODEN CROSS BAR	480.00	1 PCS	480.00	480.00
8 REAR STEP WOODEN MEMBER	180.00	1 PCS	180.00	180.00
9 REAR TRUCK WOODEN FLOOR BOARD	200.00	6 PCS	1,200.00	1,200.00
10 REAR WARNING LIGHT	300.00	1 PCS	300.00	300.00
11 REAR TRUCK RH MARN WOODEN CHASSISS	1,200.00	1 PCS	1,200.00	1,200.00
12 REAR NUMBER PLATE PANEL	120.00	1 PC	120.00	120.00
13 REAR NUMBER PLATE LAMP	45.00	1 PC	45.00	45.00
14 REAR TRUCK CENTRE WOODEN CROSS MEMBER	480.00	1 PCS	480.00	480.00
15 REAR 'U' CRANE WITH NUT	120.00	1 PCS	120.00	120.00
			7,157.00	7,157.00
Labour				
16 TOWING	100.00	1 LA	100.00	100.00
17 REMOVE AND REFIX REAR SAFETY BAR ASSY, TAILGATE, TAIL LAMPS, REAR NUMBER PLATE LAMP PANEL, REAR SPARE TYRE HOLDER, REPAIR RH SIDE GATE, TAILGATE LOCK AND HANDLE, TAIL LAMP PANELS, REAR SPARE TYRE BRACKET, REAR RAILING, REAR RH CHASSISS AND REALIGN THE SAME	1,100.00	1 LA	1,100.00	1,100.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/WL

Claim Type: Third Party

Accident Date: 16/11/2017

TP Veh Reg No: GBA4511L

Estimate No: ES1791311/WL

Date: 17 Nov 2017

Policy No: 5076090997-01

Veh Reg No: **YP1110D**

Make/Model: ISUZU NPR85UH5A

Chassis No: JAANPR85HF7100785

Engine No: 4JJ12E7249

Reg. Date: 25/01/2016

Estimate Repair Cost to Vehicle No :YP1110D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
18 REMOVE AND REFIX REAR EXHAUST, STRAIGHTEN AND CHECK LEAKING	80.00	1 LA	80.00	60
19 REMOVE AND REFIX REAR TRUCK ASSY, CANVAS ASSY, REAR TRUCK FLOOR BOARD PLATE. TO REPLACE REAR TRUCK WOODEN CROSS MEMBER, MAIN CHASSISS, WOODEN FLOOR BOARD AND REALIGN REAR TRUCK POSITION INCLUDING SUPPLY ALL NECESSARY MATERIALS	3,800.00	1 LA	3,800.00	2900
20 TP PUTTY AND RESPRAY ON TAILGATE, RH SIDE GATE, REAR RAILING, TAILGATE LOWER MEMBER, SIDE GATE LOWER MEMBER, STEP MEMBER, MAIN CHASSISS AND ALL AFFECTED AREA	1,300.00	1 LA	1,300.00	1000
21 TO REMOVE AND REFIX REAR WARNING LIGHTS, REPAIR WIRE HANESS AND CHECK WARNING LIGHT SYSTEM	120.00	1 LA	120.00	60
			6,500.00	6,500.00
			Total	SS 13,884.97
			Add GST @ 7%	971.95
			Total Amount Payable	SS 14,856.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

張建福(機件)拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 13892

Date: 16/11/17

寶號

Messrs: 2A 14

車號

Vehicle No: YP 1110 D

車型

Model No: 146ny

由

From: West Coast Way

到

To: Woodland 8200

時間(日/夜)

Time (day/night):

其他

Others:

CASH \$: 100 | 2,

CHEQUE:

經手人

Authorised by:

收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Class	Type	Minimum age	Notes
1	Invalid Carriages.	18	Only issued to those with physical disabilities, in lieu of other classes of licences
2B	Motor cycles with an engine capacity not exceeding 200cc.	18	
2A	Motor cycles with an engine capacity not exceeding 400cc.	19	Possession of Class 2B for at least one year
2	Motor cycles with an engine capacity exceeding 400cc.	20	Possession of Class 2A for at least one year
3	(a) Motor cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and (b) Motor tractors and other motor vehicles of unladen weight not exceeding 2500 kg	18	Manual and Automatic Transmissions. 61 - 2982 cc 1720 kg
3A	(a) Motor Cars without clutch pedals of unladen weight not exceeding 3000 kg with not more than 7 passengers exclusive of the driver; and (b) Motor tractors and other motor vehicles without clutch pedals of unladen weight not exceeding 2500 kg.	18	Automatic Transmission only. (It is an offence for a 3A licensed persons to operate a Class 3 (Manual) Vehicle. Any persons who wish to operate a Manual Vehicle is required to have a full Class 3 Licence.)
3C	(a) Motor cars constructed solely and adapted to carry not more than 7 passengers (exclusive of the driver) and the weight of which unladen does not exceed 3,000 kilograms only. ^[1]	18	Work Permit and S-Pass holders only need to pass the Basic Theory Test to convert their foreign driving licence to be allowed to drive all Class 3 vehicles except for light goods vehicles, mini vans and small buses.
3CA	(a) Motor Cars without clutch pedals of unladen weight not exceeding 3000 kg with not more than 7 passengers exclusive of the driver. ^[1]	18	The Class 3CA licence is introduced to new drivers who only want to drive automated Class 3C vehicles.
4A	Omnibus	21	Persons must be working for a public bus company as a Bus Captain. Licence will be revoked once he/she leaves the company.
4	Heavy motor vehicles of unladen weight exceeding 2500 kg which are constructed to carry load or passengers.	21	Persons must hold a Class 3 Qualified Licence before applying for a Class 4 licence. The minimum age for driving this vehicle is 21.
5	Heavy motor vehicles not constructed to carry any load and the unladen weight exceeds 7250 kg.	21	Persons must hold a Class 4 Qualified Licence before applying for a Class 5 licence. The minimum age for driving this vehicle is 21.

Types of driving licence

- Provisional Driving Licence (PDL)** - possessed by learners in driving schools. A PDL can only be applied after passing the Basic Theory Test(BTT), which can be taken at any of the established driving schools in Singapore. From 1 Dec 2017 onwards, PDL Hardcopy will no longer be issued. The learner can now apply on the Police@SG Website. The PDL is required before any person can start learning to drive on public roads and operating a motorcar. This licence itself carries several restrictions, some of which are listed below:
 - A Certified Driving Instructor (CDI) must be present to guide the learner driver.
 - A learner driver is not allowed to use the expressway and some busy roads such as those in Chinatown and Orchard Road.
 - A "L" plate must be placed at the front and rear of the car.

Status of Driving Licence

Licence No. :	S1727987D
Status of Driving Licence :	Valid
Class of Driving Licence :	3
Expiry Date :	Valid for life unless revoked, suspended or disqualified.

The above information is accurate as at 22/11/2017 12:01 AM.

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	:	GBA4511L
Claimant Vehicle No.	:	YP1110D
Date of Accident	:	16/11/2017
Traffic Accident involving vehicle/s No.	:	WEST COAST HIGHWAY FLYOVER OF JALAN BUROH

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 10,486.00	
2	Loss of Rental	\$ 1,680.00	\$120 X 14 days
3	LTA Search	\$ 8.00	
TOTAL		\$ 12,174.00	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561

Print Received Message

This mail is associated with :

***YP1110D (7807919625SG)**
[GBA4511L]

TP

800 SUPER WASTE MGMT PTE LTD

Nov 16 2017 9:00AM

[CHIANG KANG ENTERPRISES COMPANY PTE LTD]

Cheng Hoe Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 15/03/2019 10:52 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11894.00) - YP1110D - Claim Handler: Chan, Kian-Meng

Approved:11894.00:Kindly settle at best. Cost of Repair: \$ 10,486.00 Loss of Use: \$ 1,600.00 (12+2 days @ S\$ 100.00/day*) Search Fee: \$ 8.00 Total: \$ 11,894.00

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Saturday, 21 April 2018 4:44 PM
To: jasonlow2003@yahoo.com.sg
Subject: ACCIDENT INVOLVING GBA 4511L AND YP 1110D ON 16/11/2017 WEST COAST HIGHWAY

Our ref: CC4/AIG17022081/K1ja3

CHIANG KANG ENTERPRISES COMPANY PTE LTD

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING GBA 4511L AND YP 1110D ON 16/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.


AUTHORISATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, 800 Super Waste Management Pte Ltd (the third party claimant) of 17A Senoko
Way S 758056 (address), owner of YP1110D (vehicle no.) hereby
authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to
my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. YP1110D that
was damaged pursuant to the accident which occurred on 16/11/2017 (date) along West Coast Highway
Flyover of Jalan Buroh (location) involving vehicle no/s GBA4511L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the
workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice
and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is
concerned.

Dated this 17 (day) of Nov (month) 2017 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

This Discharge Voucher applies solely for Claimant's claim for property damages only and does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident. This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, **CHENG HOE MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$11890.00 (Global Sum)**, for vehicle no **YP1110D** that was damaged pursuant to the accident which occurred **16/11/2017** (date) along **West Coast Highway Flyover of Jalan Buroh** (location) involving vehicle no/s **GBA4511L**.

This is pursuant to the inspection conducted on **17/11/2017** (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner **800 Super Waste Management Pte Ltd** ("the third party claimant") of vehicle no. **YP1110D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage **YP1110D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of 04 (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/WL
Claim Type: Third Party
Accident Date: 16/11/2017
TP Veh Reg No: GBA4511L

NO: CL8180977
Date: 07 Sep 2018
Policy No: 5076090997-01
Veh Reg No: YP1110D
Make/Model: ISUZU NPR85UH5A
Job No: JC1598214

Description

To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.
(As recommended by your appointed surveyor)

Quantity	List Price	PAGE:1 Amount
1 PC	SS 9,800.00	SS 9,800.00

Total	SS 9,800.00
Add GST @ 7%	686.00
Total Amount payable	SS 10,486.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 050358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD	BILL NO: B078 / 2017
YOUR REF:	
OUR REF : ACS.CH.LTA.2017 (NOV 2017)	DATE : 11/12/17

TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.

LTANET SEARCHES FOR THE MONTH NOV 2017

S/NO	TP NO.	CHM	DOA	
1	1/11/2017	SCH8223T	SKU695D	1/11/2017
2	1/11/2017	SJR4411H	GBD4847C	19/10/2017
3	4/11/2017	SJQ3278M	SJL6047U	3/11/2017
4	6/11/2017	SKV9346Y	SJC3602	3/11/2017
5	7/11/2017	SLJ3508M	SJV1481D	3/11/2017
6	3/8/2017	GBC2120J	SGE2083M	26/7/2017
7	7/11/2017	FBD8294X	SJJ8958M	5/11/2017
8	8/11/2017	SKS3898B	SJG2379P	8/11/2017
9	8/11/2017	GZ4253R	GBC7507U	8/11/2017
10	9/11/2017	GBE8204B	GBE5271B	8/11/2017
11	11/11/2017	SLM471M	GY4150J	10/11/2017
12	11/11/2017	SLR372P	SKG6455P	10/11/2017
13	14/11/2017	SJU3682H	SJS7344T	13/11/2017
14	15/11/2017	YM6746C	SJM8895U	15/11/2017
15	16/11/2017	FBG3611G	SLK6372L	11/11/2017
16	17/11/2017	SLS1746H	SE2T	5/11/2017
17	17/11/2017	GBA4511L	YP1110D	16/11/2017
18	20/11/2017	SJL9280S	SFY2146Y	19/11/2017
19	20/11/2017	SFH6565J	SGF2728G	20/11/2017
20	21/11/2017	SLG6253T	SDL8138Z	20/11/2017
21	22/11/2017	GR7057M	SLA8214A	21/11/2017
22	24/11/2017	SLF2888T	SGA8885Y	23/11/2017

sub-total c/f

\$ 176.00

M/s. A C SYED & PARTNERS
ADVOCATES & SOLICITORS
SINGAPORE

We reserved the right to forward a subsequent bill for any
disbursements omitted herein.

E. & O.E

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING







































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Nov 2017 Edit Reg		17 Nov 2017 00:00 Edit Adj Rpt	\$59,800.00 Edit Estimates	\$59,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHIANG KANG ENTERPRISES COMPANY PTE LTD , Co. Reg. No.: 198304039K								
Main Claimant:	800 SUPER WASTE MGMT PTE LTD , Co. Reg. No.: 198601155H								
Vehicle Reg. No.:	YP1110D	Date of Loss:	16/11/2017 09:00 - :59 [21 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7807919625SG	Policy/Cover Note No.:	0999995013 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBA4511L	Policy No. (Claimant):	5076090997-01						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Woodlands) 38 Woodlands Industrial Park E1, #05-04/05, 757700 Woodlands - Tel: 6765 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/11/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (15/03/2019): Alert - Adj Mandate Approved (\$\$11894.00) - YP1110D - Claim Handler: Chan, Kian-... AIG_SG_EXPRESS (26/11/2018): Alert - Adj Mandate Approved (\$\$6788.00) - YP1110D - Claim Handler: Mohd-Rasheed... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YP1110D (7807919625SG)
 [GBA4511L]
 TP
 800 SUPER WASTE MGMT PTE LTD
 Nov 16 2017 9:00AM
 [CHIANG KANG ENTERPRISES COMPANY PTE LTD]
 Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1		Edit				
Assessment Reports															1 per page		<input type="checkbox"/>			
No	Finalized On	ATIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	21/11/17 10:40	Accident Statement From:OD – Reg. No: GBA4511L, Claimant: CHIANG KANG ENTERPRISES COMPANY PTE LTD												1		Load HTM				
Photos/Images															3 per page		<input type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
2	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
3	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
4	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
5	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
6	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
7	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
8	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
9	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
10	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
11	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
12	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
13	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
14	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
15	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
16	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
17	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
18	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
19	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
20	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
21	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
22	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
23	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
24	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
25	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
26	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
27	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
28	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
29	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				
30	11/06/18 11:24	General View												1		Load JPG <input checked="" type="checkbox"/>				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/06/18 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/11/17 15:51	ACKNOWLEDGEMENT EMAIL FROM AIG DD 17.11.2017	 Load PDF	
2	20/11/17 15:51	EMAIL FROM AIG DD 17.11.2017	 Load PDF	
3	20/11/17 15:51	TP GIA REPORT	 Load PDF	
4	22/11/17 11:14	TP ESTIMATE + TOWING	 Load PDF	
5	26/10/18 17:08	LTA SEACRH	 Load PDF	
6	20/11/18 11:02	EDDIES	 Load PDF	
7	28/02/19 16:08	LETTER TO OI	 Load PDF	
8	12/04/19 08:51	WORKSHOP INVOICE	 Load PDF	
9	12/04/19 08:51	AUTHORISATION TO ACT FORM	 Load PDF	
10	12/04/19 08:51	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBA4511L (Insd veh)	Model:	ISUZU NPR85UH5A 3.0 D (M)
	YP1110D (TP veh)		
Date of Accident:	16/11/2017		

Global Sum Settlement	: <input checked="" type="checkbox"/> [X] Yes	: <input type="checkbox"/> [] No	
Repair Estimate	: \$		14,856.92
Final Repair Cost	: \$		11,890.00
Loss of Use	: \$		14.00 days at \$100.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$		11,890.00

Is Third Party Workshop GIA Registered? ☒ [X] YES ☐ [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	: \$	11,890.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

12 Apr
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022081/KJA3Q2

Date: 12/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999995013

Claimant Vehicle
No : YP1110D

Insured Vehicle No : GBA4511L

Date of Loss: 16/11/2017

Nature of Claim: TP

Claim No: 7807919625SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP1110D

Make & Model: ISUZU NPR85UH5A, 3.0 D (M)

Engine No: 4JJ12E7249

Reg. Date: 25/01/2016 (Man. Year: 2015)

Chassis No: JAANPR85HF7100785

Colour: White

Odometer: 13527 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8

Rear Tyre Size: 195 R15X8 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,384.97	6,525.98	858.99	11.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	5,020.00	1,480.00	22.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,884.97	11,545.98	2,338.99	16.85
Approved Total (Overridden) (\$\$)		9,800.00		
(\$\$)	13,884.97	9,800.00	4,084.97	29.42
+ GST 7.00/7.00% (\$\$)	971.95	686.00	285.95	29.42
Nett Amount (\$\$)	14,856.92	10,486.00	4,370.92	29.42
+ Loss of Use (14.0 x S\$100.00/day) (\$\$)		1,400.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		11,894.00		
Global Sum Settlement (\$\$)		11,890.00		

INSPECTION

Date of Assignment: 17/11/2017

Date Inspected: 17/11/2017 Inspected At:

Cheng Hoe Motor Pte Ltd (Woodlands)
38 Woodlands Industrial Park E1, #05-
04/05
Singapore 757700

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LAMPS	N/S Serviceable / O/S Cracked	268.20 FL	*134.10 FL
2	1		*TAILGATE	Bent	1,600.00 FS	*1,600.00 FS
3	2		*TAILGATE SPEED STICKER	Necessary	20.00 FS	*20.00 FS
4	1		*REAR NUMBER PLATE	Bent	12.00 FS	*12.00 FS
5	1		*REAR SAFETY BAR ASSY WITH BRACKET	Bent	750.00 FS	*750.00 FS
6	1		*REAR CAY PLATE	Bent	250.00 FS	*250.00 FS
7	1		*REAR TRUNK END WOODEN CROSS BAR	Cracked	480.00 FS	*480.00 FS
8	1		*REAR STEP WOODEN MEMBER	Cracked	180.00 FS	*180.00 FS
9	8		*REAR TRUCK WOODEN FLOOR BOARD	Cracked (6 PCS ONLY)	1,600.00 FS	*1,200.00 FS
10	1		*REAR WARNING LIGHT	Serviceable	300.00 FS	*- FS
11	1		*REAR TRUCK RH MARN WOODEN CHASSIS	Cracked	1,200.00 FS	*1,200.00 FS
12	1		*REAR NUMBER PLATE PANEL	Bent	120.00 FS	*120.00 FS
13	1		*REAR NUMBER PLATE LAMP	Serviceable	45.00 FS	*- FS
14	1		*REAR TRUCK CENTRE WOODEN CROSS MEMBER	Cracked	480.00 FS	*480.00 FS
15	1		*REAR U CRANE WITH NUT	Bent	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,425.20	6,546.10
- List Item Discount on L Items 15.00/15.00% (\$\$)	40.23	20.12
Total Parts (\$\$)	7,384.97	6,525.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	100.00	100.00
2	REMOVE AND REFIX REAR SAFETY BAR ASSY ,TAILGATE,TAIL LAMPS ,REAR NUMBER PLATE LAMP PANEL ,REAR SPARE TYRE HOLDER,REPAIR RH SIDE GATE ,TAILGATE LOCK AND HANDLE ,TAIL LAMP PANELS ,REAR SPARE TYRE BRACKET ,REAR RAILING ,REAR RH CHASSIS AND REALIGN THE SAME	New	1,100.00	900.00
3	REMOVE AND REFIX REAR EXHAUST ,STRAIGHTEN AND CHECK LEAKING	New	80.00	60.00
4	REMOVE AND REFIX REAR TRUCK ASSY ,CANVAS ASSY ,REAR TRUCK FLOOR BOARD PLATE ,TO REPLACE REAR TRCK WOODEN CROSS MEMBER ,MAIN CHASSIS ,WOODEN FLOOR BOARD AND REALIGN REAR TRUCK POSITION INCLUDING SUPPLY ALL NECESSARY MATERIALS	New	3,800.00	2,900.00
5	TO PUTTY AND RESPRAY ON TAILGATE ,RH SIDE GATE,REAR RAILING ,TAILGATE LOWER MEMBER ,SIDE GATE LOWER MEMBER ,STEP MEMBER ,MAIN CHASSIS AND ALL AFFECTED AREA	New	1,300.00	1,000.00
6	TO REMOVE AND REFIX REAR WARNING LIGHTS ,REPAIR WIRE HANESS AND CHECK WARNING LIGHT SYSTEM	New	120.00	60.00
Gross Labour Cost (\$\$)			6,500.00	5,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >