

Signature: *Tan Jhi*

REF: III

2088 / Type 3 - P

COE 2018 used

2008 March

ASSIGNMENT

From: _____ Date: 21-11-2017
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJK91K
at Workshop m/s: Mova
of: Blk 1008 Bukit Merah Lane 3
Insured: #01-04
Policy No.: _____
Claims No.: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

10-30am - 10-45am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: A48K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJK91K Yr Regn: 2008 March
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BMW 730 Li C.C. 2996
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 109419 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WS4HN2206017 E97741
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Mil / S/Rim / STD A/Rim or
Tyre Size: F: 245/50 R18 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental

Front: C mm Rear: C mm
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 21/11/17 @ 1040

Survey held at Mova BM

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time: File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

Add Fee: ☐ Site Insp (\$)

☐ \$ - RS \$

☐ Interview (\$)

☐ Photos

☐ Tech. Insp (\$)

☐ Other

☐ Weekend (\$)

TOTAL

Report Format: _____

Lump Sum / I.B. It (\$)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	2941F
Vehicle Details	
Vehicle No.	SJK91K
Vehicle to be Exported	No
Intended De-registration Date	22 Nov 2017
Vehicle Make	B.M.W.
Vehicle Model	730LI
Primary Colour	Black
Manufacturing Year	2007
Engine No.	07646601N52B30AF
Chassis No.	WBAHN22060DE97741
Maximum Power Output	190.0 kW (254 bhp)
Open Market Value	\$88,298.00
Original Registration Date	28 Mar 2008
First Registration Date	28 Mar 2008
Transfer Count	2
Actual ARF Paid	\$88,298.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Mar 2018
PARF Rebate Amount	\$44,149.00
Intended COE Rebate Details	
COE Expiry Date	27 Mar 2018
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$18,670.00
COE Rebate Amount	\$624.00
Total Rebate Amount	\$44,773.00

The information contained herein is correct as at 22 Nov 2017

OK