

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

20 NOV 2017

Estimate No. : b1 44883
Date Estimated : 18/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Manisha Garg
177 Tanjong Rhu Road
#05-14

Singapore 436607

- ACCOUNT - 121AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN4979X	NS37234	19/06/2014	316iA/4	0

DESCRIPTIONTo replace frt RH fender, frt RH door and attachments
including knock out dent area cause by accident

4250 5,100.00

Painting on frt bumper, frt RH fender, frt RH door, rear
door, rear fender & RH rocker panel cover

3992 4,436.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

451 531.00

To conduct checks on all doors and bootlid central locking
system for proper function.

150 177.00

To check electrical wiring systems for proper function

150 177.00

To remove & install PDC assembly and reconnect to
bumper including conduct check proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).200
1200 236.00

To replace tyre and wheel rim including balancing. (1x).

X 94.00

To check steering geometry and conduct wheel alignment in
accordance with BMW specifications. (1X).

451 531.00

Sundries.

? 150.00

Total Labour 1: 11,609.00

DESCRIPTIONALLOY RIM 7Jx16 V-SPOKE 390
HUB CAP WITH CHROME EDGE (BMW)
FRT RH DOOR
FRT RH SIDE PANEL

QTY	PRIC	VALUE
1	743.60	743.60
1	23.75	23.75
1	1,206.45	1,206.45
1	665.85	665.85

VALUE
743.60
23.75
1,206.45
665.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. NO. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44883
Date Estimated : 18/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN4979X	NS37234	19/06/2014	316iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
FRT RH 2 SIDE PANEL BRACKET	1	31.35	X 31.35
FRT RH 1 SIDE PANEL BRACKET	1	31.35	X 31.35
FRT RH 3 SIDE PANEL BRACKET	1	31.35	? X 31.35
RH UPPER FRONT DOOR HINGE	1	53.30	X 53.30
RH LOWER FRT DOOR HINGE	1	53.30	X 53.30
FRT RH DOOR LOCK	1	240.75	X 240.75
FRT RH DOOR OUTER MOULDING	1	80.25	? X 80.25
FRT RH DOOR INSIDE CHANNEL SEALING	1	68.25	X 68.25
FRT RH DOOR COLUMN B COVER	1	54.25	X 54.25
DOOR WEATHERSTRIP FRONT	1	134.60	new 134.60
FRT RH SEALING WINDOW FRAME INTERIO	1	58.20	X 58.20
FRT RH DOOR WINDOW GUIDE	1	95.95	X 95.95
RH SIDE FRAME FINISHER	1	209.90	X 209.90
FRT RH WHEEL HOUSING COVER	1	112.75	X 112.75

Total Parts : 3,895.20

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 29/11/17 @ 1145 Excess S\$ _____

Surveyor's Name RANU Sign _____

Surveyor's Tel 9000068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 8 days

Resy 64 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	11,609.00
Parts	:	3,895.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,085.29
Grand Total	:	16,589.49

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **