

22/03/2012

REF: CS/MSH17022162/Klgbnz Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

Survivor:

Ma/min

From (Person):

Elaine Ngu

of

MSH

Date/Time:

20.11.2017 5:28pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6915K

Insured:

SGS 13708

at Workshop m/s

Premier

Tel:

6544 6689

of

25 Orangi South Ave 2 # 03-02

Policy No:

A80368650.Qmx

Claim No:

537037

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16.11.2017

CA / REV / REP. / REV 24 HRS

Wp1

H.O.D. Endorsement:

Date/Time:

21.11.2017 9:06am

Person Contacted:

Gony

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6915K - NA / INC14015611/NA
	SGS 13708 - X

DCA: 1110814



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022162/K1gb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 1370S	Veh. Inspected	SHC 6915K
Policy No.	A80368650QMX	Coverage (\$)	0.00
Claim No.	537037	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	20/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/11/2017	Inspection Date	21/11/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Nov 2017		20 Nov 2017 17:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MOK WAI MENG DANIEL, ID: S7043786D, Tel: +6591374484								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHC6915K	Date of Loss: 16/11/2017 19:00 - :59							
Claim Type:	TP / 537037	Policy/Cover Note No.: A80368650QMX(COMP) (Comprehensive) Coverage: 03/03/2017 - 02/03/2018							
Vehicle Reg. No. (Insured):	SGS1370S	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2017]								
Driver/Custodian (Insured):	CHONG HWEI CHI (ZHANG HUICI) (), NRIC: S7232599J, Tel: +6591374494								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Adjuster Immediate Advice

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 22 Nov 2017

Preliminary Advice

Insured Vehicle No	: SGS1370S	Accident Date	: 16/11/2017
TP Vehicle No	: SHC6915K	Assignment Date	: 20/11/2017
Make	: KIA OPTIMA	Est. Duration of Repair	: 3.00
Date of Inspection	: 21/11/2017		
Inspection At	: PREMIER TAXIS PTE LTD - CHANGI (HQ) 23 CHANGI SOUTH AVE 2 #03-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,485.90
Revised Amount	:S\$	1,555.40
Check Items (Estimated)	:S\$	-
Total	:S\$	1,555.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	09 Oct 2015 / 08:42:05	Receipt No.:	AACCK001-AX239-151009-000010
Asset Type:	Vehicle	Transaction Amount:	\$68,559.00
Asset ID:	SHC6915K	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151009084205780548		

Vehicle No.:	SHC6915K
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	09 Oct 2015
Original Registration Date:	09 Oct 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5623411
Engine No.:	D4FDEH313417
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$22,128.00
Minimum PARF Benefit:	\$13,788.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	09 Oct 2015 08:42:05
COE No.:	2015100901003527N
COE Expiry Date:	08 Oct 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$45,439.00
Lifespan Expiry Date:	08 Oct 2023

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/11/2017 09:28
Date Of Accident	16/11/2017 19:15
Exact Location Of Accident	CTE EXITING INTO MOULMEIN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC6915K
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

Driver

Name of Driver	LER BOON SIANG DAVID
NRIC No	S0023381A
Date Of Birth	22/02/1954
Occupation	OUTDOOR
Date Of Driving Pass	28/10/1976
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94357686
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 374 #16-73 HOUGANG ST 31
Postcode	530374
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 1 PAX (FEMALE CHINESE - AS WITNESS) VEH. B - 1 FEMALE PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS1370S
Vehicle Make/Model/Colour	NISSAN SUNNY
Details Of Properties	VEH. B
Name of Driver	MS CHONG HWEI CHI
NRIC/Passport Number	S7232599J
Contact Number	91374494
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT RIGHT PORTION
No. Of Passenger (Including Driver)	2

Details of Witness

Name	MS JOYCE CHUA - PAX IN VEH. A
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



002381-A

17 NOV 2017

Handwritten signature

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3

Describe Circumstance of the Accident.

ON 16/11/2017 @ 1915 HRS, I WAS DRIVING MY TAXI (SHC 6915 K) TRAVELLING FROM CTE INTO MOULMEIN ROAD WITH A PASSENGER ONBOARD (FEMALE CHINESE) IN LANE 3 (ARROW ON ROAD SURFACE SHOWS RIGHT TURN ONLY)

TRAFFIC LIGHT AHEAD SHOWED GREEN ON MY ROUTE FAVOUR & I PROCEED AHEAD - TO TURN RIGHT, BUT SUDDENLY I FELT AN IMPACT FROM MY LEFT.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SGS 1370 S - NISSAN SUNNY) WHICH WAS INITIALLY IN LANE 4 (ARROW ON ROAD SURFACE SHOWS LEFT TURN ONLY) , FAILED TO KEEP FOR PROPER LOOK OUT & FAILED TO OBEY ROAD SIGNAGE - HAD CUTS & ENCROACHED ONTO MY PATH ON MY LEFT ABRUPTLY.


AS SUCH, THE FRONT RIGHT PORTION OF VEHICLE B COLLIDED ON THE LEFT PORTION OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE ENTIRE LEFT PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT RIGHT PORTION.

MY PASSENGER - MS JOYCE CHUA WHO WAS IN THE REAR SEAT, WILLING TO BE MY EYE WITNESS.

NO INJURY INVOLVED.
VEHICLE B HAD A FEMALE PASSENGER ONBOARD.

*VIDEO FOOTAGE CAPTURED.



0023381-A

Driver's Signature & NRIC Number

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC6915K

1 pc	Front n/s fender inner shield <i>x see</i>	\$	120.00
1 pc	Rear n/s wheel cover <i>horizontal</i>	\$	116.00
1 pc	Rear n/s door <i>x repair</i>	\$	791.00
2 pcs	Rear n/s door hinges @\$34.00 <i>x see</i>	\$	68.00
1 pc	Rear n/s door checker <i>x see</i>	\$	32.00
1 pc	Front n/s door <i>x repair</i>	\$	765.00
2 pc	Front n/s door hinges @\$34.00 <i>x see</i>	\$	68.00
1 pc	n/s rocker panel garnish <i>x see</i>	\$	286.00
	<i>Front Fender n/s x repair</i>	\$	2,246.00
		\$	786.10
		\$	1,459.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 35% /o

Acknowledged by Repairer
Signature:
Date:

S/NETT

1 pc	Rear n/s fender sticker <i>new</i>	\$	60.00
1 set	n/s door sticker <i>new</i>	\$	100.00
1 set	n/s rocker panel garnish clips <i>x "</i>	\$	28.00
1 set	Front n/s fender inner shield clips <i>x "</i>	\$	28.00
1 pc	Front n/s fender sticker <i>x "</i>	\$	30.00
	Sundry <i>new</i>	\$	50.00 <i>20</i>
	To check wheel alignment	\$	80.00 <i>x "</i>
	To dismantle and refit the inner component of front o/s door into new shell door	\$	150.00 <i>x "</i>
	To dismantle and refit the inner component of rear o/s door into new shell door	\$	150.00 <i>x "</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender, rear bumper, n/s rocker panel outer, front n/s fender, etc	\$	850.00 <i>400</i>
	To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, front n/s door, n/s rocker panel garnish, front n/s fender	\$	1,300.00 <i>900</i>
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 <i>x "</i>
		\$	<u>4,485.90</u>

Kalok (LKK)
21/11/17 132.hrs.
3 parts
PIP
After Repair photo

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022162/K1GBN2
Date: 08/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80368650QMX (COMP)		
Claimant Vehicle No :	SHC6915K	Insured Vehicle No :	SGS1370S		
Date of Loss:	16/11/2017	Nature of Claim:	TP	Claim No:	537037

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6915K	Engine No:	D4FDEH313417
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5623411
Reg. Date:	09/10/2015 (Man. Year: 2015)	Odometer:	222950 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R16	Rear Tyre Size:	215/65R16
Front Left Side:	Achilles 7 mm	Rear Left Side:	Achilles 7 mm
Front Right Side:	Achilles 7 mm	Rear Right Side:	Achilles 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	1,755.90	255.40	1,500.50	85.45	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,730.00	1,300.00	1,430.00	52.38	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	4,485.90	1,555.40	2,930.50	65.33	
Approved Total (Overridden) (S\$)		1,200.00			
	(S\$)	4,485.90	1,200.00	3,285.90	73.25
+ GST 7.00/7.00% (S\$)		314.01	84.00	230.01	73.25
Nett Amount (S\$)	4,799.91	1,284.00	3,515.91	73.25	

INSPECTION

Date of Assignment:	20/11/2017		
Date Inspected:	21/11/2017	Inspected At:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02 Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 08 Dec 2017)
Parts:	143		KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's		(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6915K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT N/S FENDER INNER SHIELD	Serviceable	120.00 FL	*- FL	
2	1		*REAR N/S WHEEL COVER	Grazed	116.00 FL	*116.00 FL	
3	1		*REAR N/S DOOR	Repair	791.00 FL	*- FL	
4	2		*REAR N/S DOOR HINGES	Serviceable	68.00 FL	*- FL	
5	1		*REAR N/S DOOR CHECKER	Serviceable	32.00 FL	*- FL	
6	1		*FRONT N/S DOOR	Repair	765.00 FL	*- FL	
7	2		*FRONT N/S DOOR HINGES	Serviceable	68.00 FL	*- FL	
8	1		*N/S ROCKER PANEL GARNISH	Serviceable	286.00 FL	*- FL	
9	1		*FRONT FENDER N/S (NPA)	Repair	0.00 FL	*- FL	
10	1		*REAR N/S FENDER STICKER	Necessary	60.00 FS	*60.00 FS	
11	1		*SET N/S DOOR STICKER	Necessary	100.00 FS	*100.00 FS	
12	1		*SET N/S ROCKER PANEL GARNISH CLIPS	Not Necessary	28.00 FS	*- FS	
13	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS	
14	1		*FRONT N/S FENDER STICKER	Not Necessary	30.00 FS	*- FS	
15	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS	
					Sub Total (S\$)	2,542.00	296.00
					- List Item Discount on L Items 35.00/35.00% (S\$)	786.10	40.60
					Total Parts (S\$)	1,755.90	255.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	80.00	-
2	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT O/S DOOR INTO NEW SHEEL DOOR	New	150.00	-
3	TO DISMANTLE AND REFIT THE INNER COMPONENT OF REAR O/S DOOR INTO NEW SHEEL DOOR	New	150.00	-
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE REAR N/S FENDER,REAR BUMPER,N/S ROCKER PANEL OUTER,FRONT N/S FENDER.ETC	New	850.00	400.00
5	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR N/S FENDER,REAR N/S DOOR,FRONT N/S DOOR,N/S ROCKER PANEL GARNISH,FRONT N/S FENDER	New	1,300.00	900.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	-
Gross Labour Cost (S\$)			2,730.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >