

INS. CASE OWNER:

Marsiah

CC 3/AIG1702 2178, Rlybba

LKK:

IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT

Date / Time:

20/11/17

Registered in Merimen:

21/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLJ 71696

Name of Insured:

TAN TEE HOON

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

14/11/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age: TAN YUN RONG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

141451491654

Policy No.:

2100494574-00000

Make / Model:

NISSAN

Place of Accident:

AME AV3

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 41280

INSRS:
WSP:
Tel:
Liability:
RMKS:

SMRT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

23/11/17

SHC 41280 - 15/11/17 (17:00) / KRMH over: 11/11/17

SLJ 71696 - 17

23/11/17 @ 5:30

Called OZ, NO response.

23/11/17 5:35

Called OZ, NO response.

23/11/17

Since liability cleared. Email sent to OZ inform about TP claim. OZ case ended TP vehicle.

RECEIVED 18 DEC 20

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 1350/-

(2 days) Reduction: 34 %

Confirm by:

FINAL SETTLEMENT

Date/Time:

15/12/17 Confirm with me del.

Email

Call

Final Liability:

%

100

Repair Cost:

SS 1,350.00

Loss of Rental (LOR): 112.35

SS 280.88

(2-5 days)

Loss of Use (LOU):

SS 150.00

x2.5 days

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☒LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS 5.00

Medical:

SS

Disbursement:

SS

Legal Cost

SS

(e.g. Tow/ Independent)

Total:

SS 1,785.88

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 1,785.88

Name 1:

SMRT TAXIS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17022178/R1yb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 21-11-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 7169G	Veh. Inspected	SHC 4128D
Policy No.		Coverage (%)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/11/2017	Inspection Date	20/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



21-11-17 16.55

ADV: 22-11-17 / 11:55

22-11-17 / 15:55

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

20-11-17 / 15:55

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4128D
 Ref. No : TAX/11/17/2115
 Reg. Date : 22/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN HOCK KEAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 17/11/2017 09:46:00 PM
 Accident Reported Date / Time : 20/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Rasul
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093164
 Special Instruction to ARC, if any :


SLJ7169G - AIG LKK 45

Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR RASUL

/ HP : 9001 0068, email: rasul@lkkauto.com

lumpsum repair

Prepared Date : 20/11/2017 09:23:02 AM



Recording Camera

Radio Antenna

1st witness

Date

2nd witness

Date

E 12 F
 KM 394071 km

20/11/17
 17:15 Hrs
 13950/11
 Vehicle sent to SMRT Date for: 20-11-17
 Time in: 14:36 Driver:
 Received by (SMRT):


Cc 21/11 17.30 Report

WABA In Site 22/11 11.26 P455

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4128D
 Ref. No : TAX/11/17/2115
 Reg. Date : 22/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN HOCK KEAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 17/11/2017 09:46:00 PM
 Accident Reported Date / Time : 20/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093164
 Special Instruction to ARC, if any :
 SLJ7169G - AIG LKK *(Resy after repair)*
 Prepared Date : 20/11/2017 09:23:02 AM



LKK Auto Consultants hence notify the Reparer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U30-5705707

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	338.00	0.00
Total Spray Painting Charges	378.00	0.00
Total Material Charges	695.82	695.82
Other Charges	656.88	0.00
TOTAL	2,068.70	0.00
Lum Sum Total	2,050.00	0.00
No. of Repair Days	3.00	0.00
Prepared / Adjusted By		0.00 2 days - Luyben
Arc / Surveyor Sign Off Date	20/11/2017 02:48:14 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 20/11/2017 02:48:14 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
159-905		6505548	BUMPER REAR	✓ 1	458.60	25.00	343.95	Replace	Replace	No
			SENSOR REVERSE	✓ 1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	✓ 2	60.00	0.00	120.00	Replace	Replace	No
891-020		6505619	BUMPER LIP REAR	X 1	228.90	25.00	171.68	Replace	Check	No
088-020		6505617	BUMPER LIP COVER RR/LH	X 1	72.20	25.00	54.15	Replace	Check	No
TOTAL MATERIALS								869.78	643.95	
TOTAL MATERIALS(Discounted)								695.82	515.16	
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

643.95
 - 20%

 515.16
 200
 + 616.88

 1332.04

45-81350
 2 days
 ==

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
Total Spray Painting & Panel Beating	378.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET) <i>NEL</i>	296.88	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	656.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photo Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
TOTAL MATERIALS								869.78	869.77	
TOTAL MATERIALS(Discounted)								695.82	695.82	
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Jas Khine (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
<LeeGek@smrt.com.sg>
Sent: Friday, 15 December, 2017 11:01 AM
To: CS A Team; Admin A
Subject: Re: Accident on 17/11/2017 involving SHC 4128D & SLJ 7169G (AIG insured) Our
Ref: TAX/11/17/2115/lg
Attachments: 11 17 2115.pdf

Dear All,

We quantify our claim as follows:-

Cost of repairs	\$1350.00
Loss of rental	\$ 280.88 (\$112.35 x 2.5 days)
Loss of income	\$ 150.00 (\$60.00 x 2.5 days)
LTA search fee	\$ 5.00
	<u>\$1785.88</u>
	=====

We attach the proof of rental, repair bill, laid-up report, GIA report of our taxi and LTA search for your perusal.

Our hirer is using his own lawyer to claim for his injury only.

Please let us hear from you soon.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





Accident Vehicle Laid-Up Report

Registration No. : SHC4128D

Make / Model : TOYOTA PRIUS

Accident Case No. : TAX/11/17/2115

Ref. No. : 24093164

Date and Time Vehicle off-road for Accident Repair : 20.11.2017 09:01:00

Date and Time Repair Completed : 22.11.2017 13:06:24

Remarks :

Generated by : NGSUICHING

Printed on : 22.11.2017

Jas Khine (LKKAuto)

From: Jas Khine (LKKAuto)
Sent: Thursday, 23 November, 2017 5:38 PM
To: 'JAMESTANTC@GMAIL.COM'
Cc: 'HUGOTANYR@GMAIL.COM'
Subject: ACCIDENT INVOLVING SLJ 7169G & SHC 4128D ALONG/AT ANG MO KIO AVE 3 ON 12/11/2017

Our Ref: CC3/AIG17022178/R1yb3

23 NOVEMBER 2017

TAN TEE CHONG
BLK 205 ANG MO KIO AVE 1
#11-1083
SINGAPORE 560205

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 7169G & SHC 4128D ALONG/AT ANG MO KIO AVE 3 ON 17/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter/email.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Thank you.

Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


AUTHORISATION TO ACT

I/We, SMRT TAXIS PTE LTD ("the third party claimant") of 60 WOODLANDS INDUSTRIAL PARK E4, SINGAPORE 757705 (address), owner of SHC 4128D (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SHC 4128D was damaged pursuant to the accident which occurred on 17/11/2017 (date) along AMK AVE 3 (location) involving vehicle no/s SLJ 7169G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 15 (day) of Dec (month) 2017 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **SMRT AUTOMOTIVE SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,350.00** (Repair Cost), **S\$430.88** (Loss of Rental/Use) **S\$5.00** (Disbursement), for vehicle no. **SHC 4128D** that was damaged pursuant to the accident which occurred on **17/11/2017** (date) along **AMK AVE 3** (location) involving vehicle no/s **SLJ 7169G**.

This is pursuant to the inspection conducted on **20/11/2017** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **SMRT TAXIS PTE LTD** ("the third party claimant") of vehicle no. **SHC 4128D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SHC 4128D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of Dec (month) 2017 (year)

Signed by appointed surveyor



Signed by "the workshop" (with chop)





Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV171200019
Date : 01.12.2017
Vehicle No. : SHC4128D
Your Ref No. : TAX/11/17/2115
Our Ref No. : 24093164
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00				\$ 1,350.00

GRAND TOTAL \$ 1,350.00

Remark :

Make/Model : TOYOTA PRIUS
Accident Date : 17.11.2017

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/11/17/2115

From: SMRT Taxis Pte Ltd

Date: 27/11/2017


**ACCIDENT ON 17/11/2017 INVOLVING SHC 4128D & SLJ 7169G
ALONG ANG MO KIO AVENUE 3**

This is to confirm that the daily rental rate for SHC 4128D is \$112.35 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager

Enquire Transaction History**Transaction History Details**

Log Date/Time: 20 Nov 2017 / 09:22:10

Asset Type: Vehicle

Transaction
Amount:

\$5.35

Asset ID: SLJ7169G

Transaction Type: 18.32 Insurance Enquiry
(GIRO Payment)

Channel:

External Agency

User ID: ESASBAHO - BALQISH
BINTE ABDUL HALILBusiness
Transaction
Reference No.:

20171120092210184569

Search Date /
Time: 17 Nov 2017 21:46:00Insurance
Company:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2017 Edit Reg		20 Nov 2017 00:00 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	Tan Tee Chong, ID: S1651633C			[Created by adjuster]	
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K				
Vehicle Reg. No.:	SHC4128D		Date of Loss:	17/11/2017 21:00 - :59	
Claim Type:	TP / 1414514916SG		Policy/Cover Note No.:	2100494534 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLJ7169G		Policy No. (Claimant):	D-17087562MFSH	
			Excess:		
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com				
Claimant's Insurer:	First Capital Insurance Ltd (HQ) - Tel: 62222311				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/11/2017]				

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4128D (1414514916SG)
[SLJ7169G]

TP

SMRT TAXIS PTE LTD

Nov 17 2017 9:00PM

[Tan Tee Chong]

SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer	
Letters/Correspondences											
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						1 per page		☒	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						Thumbnail		Print	
								1		Edit	
Assessment Reports											
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						1 per page		☒	
1	22/11/17 10:37	Accident Statement						Thumbnail		Print	
		From: SC - Reg. No: SLJ7169G, Claimant: TAN TEE CHONG						1		Load HTM	
Photos/Images											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						3 per page		☒	
1	18/12/17 15:51	Odometer Reading						Thumbnail		Print	
2	18/12/17 15:51	Chassis Number						1		Load JPG	
3	18/12/17 15:51	General View						1		Load JPG	
4	18/12/17 15:51	General View						1		Load JPG	
5	18/12/17 15:51	General View						1		Load JPG	
6	18/12/17 15:51	General View						1		Load JPG	
7	18/12/17 15:51	General View						1		Load JPG	
8	18/12/17 15:51	General View						1		Load JPG	
9	18/12/17 15:51	General View						1		Load JPG	
10	18/12/17 15:51	General View						1		Load JPG	
11	18/12/17 15:51	General View						1		Load JPG	
12	18/12/17 15:51	General View						1		Load JPG	
13	18/12/17 15:51	General View						1		Load JPG	
14	18/12/17 15:51	General View						1		Load JPG	
15	18/12/17 15:51	General View						1		Load JPG	
16	18/12/17 15:51	General View						1		Load JPG	
17	18/12/17 15:51	General View						1		Load JPG	
18	18/12/17 15:51	General View						1		Load JPG	
19	18/12/17 15:51	General View						1		Load JPG	
20	18/12/17 15:51	General View						1		Load JPG	
21	18/12/17 15:51	General View						1		Load JPG	
Documentation											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						1 per page		☒	
1	21/11/17 17:42	TP ESTIMATE- MARKED						Thumbnail		Print	
2	21/11/17 17:42	TP GIA REPORT						1		Load PDF	
3	26/12/17 11:11	WORKSHOP INVOICE						1		Load PDF	
4	26/12/17 11:11	AUTHORISATION TO ACT FORM						1		Load PDF	
5	26/12/17 11:11	RELEASE VOUCHER						1		Load PDF	
6	26/12/17 11:11	RENTAL RECEIPT						1		Load PDF	
7	26/12/17 11:11	LTA SEARCH						1		Load PDF	
8	26/12/17 11:11	LETTER TO OI						1		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#) [Save](#) [Print](#)**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLJ7169G (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4128D (TP veh)		
Date of Accident:	17/11/2017		

Global Sum Settlement	: [] Yes	[X] No	
Repair Estimate			\$ 2,432.58
Final Repair Cost			\$ 1,350.00
Loss of Use			\$ 150.00
Rental (if any)			\$ 280.88
LTA / GIA Search Fee			\$ 5.00
Others:			\$ 0.00
Final Settlement Sum			\$ 1,785.88

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks

Payment Instruction: Payee's Breakdown		
1)	SMRT Taxis Pte Ltd	\$ 1,785.88
2)		\$
3)		\$
4)		\$

JOANNE LEE KHANG MIN

26 Dec

LKK Auto Consultants Pte Ltd

2017

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17022178/R1YB3Q2
 Date: 26/12/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100494534
 Claimant Vehicle No: SHC4128D Insured Vehicle No: SLJ7169G
 Date of Loss: 17/11/2017 Nature of Claim: TP Claim No: 1414514916SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4128D
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)
 Reg. Date: 22/11/2013 (Man. Year: 2013)
 Colour: Maroon
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price
 Engine No: 2ZR5906530
 Chassis No: JTDKN36U305705707
 Odometer: 39407 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15
 Front Left Side: Goodyear 5 mm
 Front Right Side: Goodyear 5 mm
 Rear Tyre Size: 195/65 R15
 Rear Left Side: Goodyear 5 mm
 Rear Right Side: Goodyear 5 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,356.58	940.83	415.75	30.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,076.00	520.00	556.00	51.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,432.58	1,460.83	971.75	39.95
Approved Total (Overridden) (S\$)		1,350.00		
Nett Amount (S\$)	2,432.58	1,350.00	1,082.58	44.50
+ Loss of Use (2.5 x S\$60.00/day) (S\$)		150.00		
+ Car Rental (2.5 x S\$112.35/day) (S\$)		280.88		
+ Doc/Search Fee (S\$)		5.00		
Nett Liability (S\$)		1,785.88		

INSPECTION

Date of Assignment: 20/11/2017
 Date Inspected: 20/11/2017 Inspected At:

SMRT Automotive Services Pte Ltd
 (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR C			
2	1		*SENSOR REVERSE (SN)	Deformed	458.60 F	*343.95 F
3	2		*PIXEL STICKE (SN)	Necessary	180.00 F	*180.00 F
4	1		*BUMPER LIP REAR	Necessary	120.00 F	*120.00 F
5	1		*BUMPER LIP COVER RR/LH	Serviceable	228.90 F	*- F
6	1		*ADVERTISEMENT STICKER (SN)	Serviceable	72.20 F	*- F
				Necessary	296.88 F	*296.88 F
Total Parts (S\$)					1,356.58	940.83

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	378.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	60.00
5	TO REPLACE SUNDRY PARTS	New	100.00	20.00
6	TO WASH AND VACUUM	New	60.00	40.00
Gross Labour Cost (S\$)			1,076.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >