

INS. CASE OWNER:

CC 4/III1702

NAME, M. J. [Handwritten]

LKK:

IDAC:

Surveyor:

MJP

DOI:

ASSIGNMENT

27/11/17

Date / Time:

21/11/17

Registered in Merimen:

21/11/17

Pre-assign / CCU / FTE

SHD 66428



Insured Vehicle No. :

Claim No. : MCI17110595

Name of Insured : CTP

Policy No. : MLD0616

Insured Tel No. :

Make / Model : HONDA

Excess Sec II :SS

HP: 15/11/17
D.O.A: 15/11/17

Place of Accident : SEAH INN RD

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : NG BENH GUAN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

YP 42970



INSRS: WSP: Lorraine
Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

| Date/Time | STAGE | DATE / PIC |
|-----------|-----------------------------------|--------------------------|
| 27/11/17 | Non-Reporting ltr (1st): | |
| | Non-Reporting ltr (2nd): | |
| | Non-Reporting ltr (Final): | |
| | Notification ltr (if non-pickup): | |
| | Call OI: | |
| | After call ltr to OI: | |
| 19-1-18 | Documentation Check List: | Handler Typist |
| 22-1-18 | Notification ltr (if non-pickup) | <input type="checkbox"/> |
| | After call ltr to OI: | <input type="checkbox"/> |
| | Authorisation To Act: | <input type="checkbox"/> |
| | Release Voucher: | <input type="checkbox"/> |
| | Final Repair Bill: | <input type="checkbox"/> |
| | Car Rental Invoice: | <input type="checkbox"/> |
| | Towing Invoice: | <input type="checkbox"/> |
| | LTA / GIA : | <input type="checkbox"/> |
| | Medical Bill: | <input type="checkbox"/> |
| | PIR: | <input type="checkbox"/> |
| | Mandate/Reject Instruction: | <input type="checkbox"/> |
| | LOD | <input type="checkbox"/> |
| | Payment Breakdown Form: | <input type="checkbox"/> |
| | Post-Repair Photos: | <input type="checkbox"/> |
| | Others: | <input type="checkbox"/> |

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$\$ (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: Confirm with: Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : If NO or B 28, Ass. Lia :

Repair Cost: \$\$

Loss of Rental (LOR): \$\$ (days)

Loss of Use (LOU): \$\$ (\$ x days)

Loss of Income (LOI): \$\$ (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI (Tick only one)

GIA/LTA Search: \$\$

Medical: \$\$

Disbursement: \$\$ (e.g. Tow/ Independent)

Legal Cost: \$\$

Total: \$\$ Global Sum \$\$:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$\$ Name 1:

Payee 2: (Strike if N.A.) \$\$ Name 2:

Payee 3: (Strike if N.A.) \$\$ Name 3:

COPY SENT

WF

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee: \$250

ASSIGNMENT

Report No: _____ Date: 20/11/2017

Estimated Cost: _____

OD (TP) NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: YP 4297D
at Workshop/ma: Conline Auto
of: 176 Sim ming Drive #04-04

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

10am - 12pm



Remark: The veh. had commenced its repair at the time of inspection.

Bel. or Market Value: _____

ODAC Accident Report: _____ Consistent? : Yes or No

GLA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum. Sur: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YP4297D. Y-Reg: SEP 2016

Type: M/Car - M/Cycle - Bus - Van - Car / Taxi / Prime Mover

Truck / Trailer or: _____

Make: ISUZU. CC: 5193

Colour: Blue

Bo Reading: 55838. * Radio: Insured / Std / NI / NA

Eng No: _____

C No: JHANPR754G7103225

Gen: Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRM / STD A/Rim or

Tyre Size: F: _____ R: 215/75/R17.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R.Bal: 6 mm R.Bal: 6 mm

L.Bal: 7 mm L.Bal: 7 mm

D.O.A: 15/10/07 D.O.I: 22/10/07

Survey held at: _____

Des. of Damages: FR - Rear / Q/S / NS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

L/S \$800

R(\$866.53/527.)

Date Time Pls Pass to: Prel. Report Final Report

Date Time Pls Return to: _____

Days Of Repair: _____ Resurvey No. of Trip: _____

Survey Fee: _____

Transport: _____

Add Fee: 318 1150 \$ 1187 21 \$ 1187 114 \$ 1187 114 \$

Report Format: _____

Lump Sum (if B): _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---------------------------|---|
| INDIA INTERNATIONAL INSURANCE PL | | Ref : CC4/III17022192/zb3 | |
| 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | | Date : 21-11-2017 |  |
| | | Code : III2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHD 6642S | Veh. Inspected | YP 4297D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 21/11/2017 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 15/11/2017 | Inspection Date | |
| Survey held at | CONVINCE AUTO PTE LTD 176 SIN MING DRIVE #04-04 SIN MING AUTOCARE SINGAPORE 575721 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |



Owner : KIM BOCK CONTRACTOR PTE LTD

Attention : Motor Claim Department

Vehicle Make & Model : ISUZU NPR75HG

Vehicle No. YP4297D

ESTIMATE

GST Regn No. : 200516575H

Co. Regn No. : 200516575H

Date : 16-11-17

Accident date : 15-11-17

Claim no : 3 PTY CNTP

Policy No: 1758771700

| No | Description | Qty | Unit | Unit Price | Amount |
|--|---------------------------------|-----|------|------------|-----------------------|
| Parts Replacement -List items | | | | | |
| 1 | FRONT BUMPER | 1 | \$ | 720.00 | \$ 720.00 <i>dat</i> |
| 2 | BUMPER BRACKET | 2 | \$ | 185.00 | \$ 370.00 <i>tz</i> |
| | | | | | \$ 1,090.00 |
| | less 25% | | | | \$ 817.50 |
| | sub total | | | | \$ 817.50 |
| Parts Replacement - special items | | | | | |
| 1 | FRONT NUMBER PLATE | 1 | \$ | 40.00 | \$ 35 40.00 <i>me</i> |
| | sub total | | | | \$ 857.50 |
| Labour & Misc Charge | | | | | |
| 1 | KNOCKING AND REPAIR ABOVE PARTS | 1 | \$ | 400.00 | \$ 200 400.00 |
| 2 | SPRAY PAINTING | 1 | \$ | 300.00 | \$ 200 300.00 |
| | sub total | | | | \$ 700.00 |

Sub Total \$ 1,557.50
 GST \$ 109.03
 Total \$ 1,666.53

No. 22/4/2017
2 wks days
 After repair of the following:
 - spray painting
 - damaged part(s) during resurvey
 - we subject to confirmation
 - survey is on a "Without Prejudice" basis
 - cation(s) is allowed
 - must be reviewed and
 - approval from Insurance Company

4/5 2017
2 wks days

CONVINCE AUTO PTE LTD

176 Sin Ming Drive #04-04 Sin Ming Autocare Singapore 575721
 Tel: +65 6556 1131 Fax: +65 6553 1131 Email: convinceapl@convinceauto.com.sg

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 26 July 2018 3:07 PM
To: 'Sherini Pillai'
Subject: RE: MCT17110595
Attachments: Merimen e-Claims.pdf

Hi Sherini,

As spoken, attached report in Meirmen for your easy reference.

We will submit on wp for your further handling.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Joy Irene (LKKAuto)
Sent: Thursday, 26 July 2018 2:39 PM
To: 'Sherini Pillai' <sherini@iii.com.sg>
Subject: RE: MCT17110595

Hi Sherini,

Done.

Are going to submit on wp?

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Sherini Pillai [<mailto:sherini@iii.com.sg>]
Sent: Thursday, 26 July 2018 9:55 AM

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 20 November, 2017 3:19 PM
To: 'sur@lkkauto.com'
Cc: melvinchua@convinceauto.com.sg; Sherini Pillai; Catherine Chong (LKK Auto)
Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. YP4297D (Accident involving YP4297D and SHD6642S on 15.11.2017)
Attachments: 4_20171120112622.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle YP4297D and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

4.03pm @ 20/11/2017
Vehicle Not In
Melvin

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 227

S&P 'A-' (stable) rated Company

From: melvinchua@convinceauto.com.sg [mailto:melvinchua@convinceauto.com.sg]
Sent: Monday, 20 November, 2017 2:10 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. YP4297D (Accident involving YP4297D and SHD6642S on 15.11.2017)

hi, Adeline Tham , we propose Lkk auto consultants pte ltd for the following survey , kindly let me know when the timing and date that they are coming. please call me before coming I need to arrange the vehicle for this survey. thank you.

----- Original Message -----

From:
"Motor Claim - III" <motorclaim@iii.com.sg>

To:
"melvinchua@convinceauto.com.sg" <melvinchua@convinceauto.com.sg>

Cc:
"Adeline Tham" <adelinetham@iii.com.sg>

Sent:
Mon, 20 Nov 2017 04:11:38 +0000

Subject:
PRE-REPAIR INSPECTION FOR VEHICLE NO. YP4297D (Accident involving YP4297D and SHD6642S on 15.11.2017)

Dear Sir / Mdm

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #04/#05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext-227

S&P 'A-' (stable) rated Company

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 22 Nov 2017 Edit Reg | | 21 Nov 2017 00:00 Edit Adj Rpt | \$800.00 Edit Estimates | \$800.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|--|--|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | [Created by adjuster] | | | | | | | |
| Insured: | COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R | | | | | | | | |
| Main Claimant: | KIM BOCK CONTRACTOR PTE LTD , Co. Reg. No.: 197800646E | | | | | | | | |
| Vehicle Reg. No.: | YP4297D | Date of Loss: | 15/11/2017 15:00 - :59 [13 Months and 26 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / MCT17110595 | Policy/Cover Note No.: | MCOM0015 | | | | | | |
| Vehicle Reg. No. (Insured): | SHD6642S | Policy No. (Claimant): | DMCVSN1758771700 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Convince Auto Pte Ltd (HQ) 176 SIN MING DRIVE #04-04, SIN MING AUTOCARE, 575721 Sin Ming - Tel: | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai] | | | | | | | | |
| Claimant's Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 30/11/2017] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All Compose Case Mail | | | | | | | |
| • III_SG (19/01/2018): Alert - Adj Mandate Maintained - YP4297D - Claim Handler: Sherini Pillai | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*YP4297D (MCT17110595)
[SHD6642S]
TP
KIM BOCK CONTRACTOR PTE LTD
Nov 15 2017 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Convince Auto Pte Ltd

| Upload Documents | | | Upload Photos | | | Compose New Letter | | | View | View in Browser | |
|----------------------|-----------------|--|---------------|-----------|-------------------------------------|--------------------|--|--|------|-----------------|-------------------------------------|
| Video | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | | Thumbnail | Print | | | | | | |
| 1 | 19/01/18 17:15 | Video - IV | | Load MP4 | | | | | | | |
| Photos/Images | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | | |
| 1 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 2 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 3 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 4 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 5 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 6 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 7 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 8 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 9 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 10 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| 11 | 22/11/17 13:10 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | | |
| Documentation | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | | |
| 1 | 21/11/17 15:46 | EMAIL FROM III DD 20112017 | | Load PDF | | | | | | | |
| 2 | 21/11/17 15:46 | NOTICE & GIA REPORT | | Load PDF | | | | | | | |
| 3 | 23/11/17 17:39 | TP ESTIMATE- MARKED | | Load PDF | | | | | | | |
| 4 | 26/07/18 15:11 | EMAIL TO III | | Load PDF | | | | | | | |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | | Thumbnail | Print | | | | | | |
| 1 | 22/11/17 08:55 | Singapore Accident Statement | | Load PDF | | | | | | | |
| 2 | 14/06/18 11:50 | Letter of Demand from Third Party LEE SHERGILL LLP | | Load PDF | | | | | | | |
| 3 | 14/06/18 15:43 | Statutory Declaration from TP witness | | Load PDF | | | | | | | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17022192/M1JB3Q2

Date: 26/07/2018

REFERENCE

| | | |
|---|-----------------------------|---|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant Vehicle No : YP4297D | Insured Vehicle No : | SHD6642S |
| Date of Loss: 15/11/2017 | Nature of Claim: | TP Claim No: MCT17110595 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | |
|--|-------------------------------|
| Reg No: YP4297D | Engine No: 4HK1516061 |
| Make & Model: ISUZU NPR85LU4Y, 3.0 D (M) | Chassis No: JAANPR75HG7103225 |
| Reg. Date: 20/09/2016 (Man. Year: 2016) | Odometer: 55838 km |
| Colour: Blue | |
| Engine Capacity: 5193 cc | |
| Market Value/New Car Price: N/A | |
| Sum Insured (S\$): Market Value/New Car Price | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | |
|------------------------------------|-----------------------------------|
| Front Tyre Size: 215/75 R17.5 | Rear Tyre Size: 215/75 R17.5 |
| Front Left Side: Bridgestone 6 mm | Rear Left Side: Bridgestone 7 mm |
| Front Right Side: Bridgestone 6 mm | Rear Right Side: Bridgestone 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|---------------|---------------|--------------|
| Parts | 857.50 | 575.00 | 282.50 | 32.94 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 700.00 | 400.00 | 300.00 | 42.86 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 1,557.50 | 975.00 | 582.50 | 37.40 |
| Approved Total (Overridden) (S\$) | | 800.00 | | |
| Nett Amount (S\$) | 1,557.50 | 800.00 | 757.50 | 48.64 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 21/11/2017 | |
| Date Inspected: | 22/11/2017 Inspected At: | Convince Auto Pte Ltd (HQ) 176 SIN MING DRIVE #04-04, SIN MING AUTOCARE Singapore 575721 |
| Estimated Period of Repair: | 2.0 days | |

Adjuster: MA CHIN FOOK

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 26 Jul 2018) | |
| Parts: | N/A | ISUZU NPR85LU4Y 3.0 D (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for YP4297D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|--------------------|-----------|--|-----------------|---------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 720.00 FL | *720.00 FL | |
| 2 | 2 | | *BUMPER BRACKET | Repair | 370.00 FL | *- FL | |
| 3 | 1 | | *FRONT NUMBE PLATE | Necessary | 40.00 FS | *35.00 FS | |
| | | | | | Sub Total (\$\$) | 1,130.00 | 755.00 |
| | | | | | - List Item Discount on L Items 25.00/25.00% (\$\$) | 272.50 | 180.00 |
| | | | | | Total Parts (\$\$) | 857.50 | 575.00 |

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---------------------------------|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | KNOCKING AND REPAIR ABOVE PARTS | New | 400.00 | 200.00 |
| 2 | SPRAY PAINTING | New | 300.00 | 200.00 |
| Gross Labour Cost (S\$) | | | 700.00 | 400.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >