

12/20/2017

ASS: REC. BY

REF:

CS/MSG170 22003 / KVBet

Special Instructions

SURJECT

Kunmth

ASSIGNMENT (Office)

Merimen

From (Person): Catherine Thia

of MSG

Date/Time 26/11/17 @ 2:43pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGP 9938T

Insured:

XE2096A

at Workshop m/s

Seng Kin Motor Works

Tel:

64536238

of

Blk 1, 8in Ming Ind. Est #01-131, 575636

Policy No:

78816838mkc.

Claim No:

537213

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/11/2017

CA / REV / REP. / REV 24 HRS

lup?

24/11/2017 @ 11am

H.O.D. Endorsement

Date/Time

20-11-2017

Person Contacted

Ms. Lee

Vehicle

N/A (OLI)

Date/Time

Action/Instruction

(✓)

Estimate

SGP 9938T - NA / TML 13017021 / m2

QAR 150913

XE 2096A - x

27/11/17

Send preli revised by merimen

22/2 @ 7310.00 7310.00 Carbur (Red 6701.95, 48M) (No LS)

MSK

merimen

Date 24.11.2017

SGP 99387

08 10

Estimated Cost

QD / TP / WS / TP RES / OD RES / EVA / INV / MW

To inspect Vehicle No

SGP 99387

at Workshop No

Seng Kim

of

Blk 1 Sin Ming Ind Est #01-131

Insured

Policy No

Claims No

Sum Insured

Excess


Claims Record

Make of Veh

11am.

Policy Condition

Remark: The veh had commenced its
repair at the time of inspection.



Salv or Market Value

IDAO Accident Report

Consistent? : Yes or No

GIA / PP / Seen

Consistent? : Yes or No

Est. Repairs

06 days

Pest: Yes or No

Lim Supp

1B1

3 Valt: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date

Person Contacted

Truck / Trailer

Make

Ford Mondeo

11

2261

Color

M. Grey

H/O Insured: Std / N/A

So Peeling

113093

T-Peak Insured: Std / N/A

Eng No

D-No

WIF-ODXXG BBD-PE-24835

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD S/Rim or

Tyre Size

F:

235/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Continental

Front

Rear

R.Bal

7

mm

R.Bal

7

mm

L.Bal

7

mm

L.Bal

7

mm

D.O.A.

15/11/17

D.O.A.

24/11/17

Survey noted

Des of Damages: Frt / Rear / O/S / N/S / U/O / Rooftop or

O/S R

The U/O / Chassis frame / Body Structure affected due to collision

22/2/2018

Date Time Action Instruction

27/11 13h pas, to Carhome

Date Time For Passout



Prelim Report



Final Report

Date Time For Return

22/2- typist

Days Of Repair

6

Resurvey No. of Trial

1

Survey Fee

300

Transport Fee

10

Report Format

merimen

Number of Pages

7310/2

Add Fee



Pre-Inspection



Inspection



Test



Approval

Survey Department Check List (Case Handler)

Reference No.: **CS MSG HO 2203 Kvb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

| (1) Office Assign Form | | Y-Date | N-Date | Y-Date | N-Date |
|------------------------|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | ✓ | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

| (1) Assignment Form | | Y-Date | N-Date | Y-Date | N-Date |
|---------------------|------------------------|--------|--------|--------|--------|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ | | | |
|---|-------------------------|---|--|--|--|

Check By: **VERON** **22/11/18**
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022203/Kvb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------------------|----------------|------------|
| Insured Veh. | XE 2096A | Veh. Inspected | SGP 9938T |
| Policy No. | 28816838MKC | Coverage (\$) | 0.00 |
| Claim No. | 537213 | Excess (\$) | 0.00 |
| Assign From | MERIMEN (CATHERINE THIA) | Assign Date | 20/11/2017 |

2. Vehicle Particulars & Condition

| | | |
|--------------|--------|--------------|
| Make & Model | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. |
| Chassis No. | | Colour |
| Odometer | - | Steering |
| Brakes | | Modification |
| General | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | |
|----------------|--|-----------------|
| Accident Date | 15/11/2017 | Inspection Date |
| Survey held at | SENG KIN MOTOR WORKS BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636 | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj For | Adj Sec | Adj Final | Status |
|------|-------------|---------------|--|---------|---------|-----------|--|
| Main | 17 Nov 2017 | | 20 Nov 2017 14:43 Assign | | | | New Assignment Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | Highway International Private Limited, Co. Reg. No.: 197501285M | | |
| Main Claimant: | CHIA KAI CHEW, ID: S7819214C | | |
| Vehicle Reg. No.: | SGP9938T | Date of Loss: | 15/11/2017 00:00 - :59 |
| Claim Type: | TP / 537213 | Policy/Cover Note No.: | 28816838MKC Coverage: 26/08/2017 - 25/08/2018 |
| Vehicle Reg. No. (Insured): | XE2096A | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Seng Kin Motor Works (HQ) BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636, 575636 Sin Ming - Tel: | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2017] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 27 Nov 2017

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : XE2096A | Accident Date | : 15/11/2017 |
| TP Vehicle No | : SGP9938T | Assignment Date | : 20/11/2017 |
| Make | : FORD MONDEO | Est. Duration of Repair | : 0.00 |
| Date of Inspection | : 24/11/2017 | | |
| Inspection At | : SENG KIN MOTOR WORKS (HQ) BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636 SINGAPORE 575636 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,279.30 |
| Revised Amount | :S\$ | 6,683.05 |
| Check Items (Estimated) | :S\$ | 4,908.30 |
| Total | :S\$ | 11,591.35 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.


Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

- Cert No./Policy No.** : D17MTPV01002257
- 1. Registration No.** : SGP9938T
- 2. Insured Name** : CHIA KAI CHEW
- 3. Commencement Date** : 17 FEBRUARY 2017 00:00
- 4. Expiry Date** : 16 FEBRUARY 2018 23:59
- 5. Coverage** : Market value at time of loss - Comprehensive - ExcelDrive GOLD
- 6. Excess** : \$800 - Section I
(Waived up to S\$1,000 Standard Excess each claim at ExcelDrive Workshops for first two claims per policy year)
- 7. Voluntary Excess** : Buy Up : \$500 - Section I
- 8. Persons or Classes of Persons entitled to drive***
- a) The Insured.
The Insured may also drive a motor car other than those belonging to or hired (under a hire purchase agreement or otherwise) to him or his employer or his partner.
- b) Any other person who is driving on the Insured's order or with his permission.
- c) In the event of the death of the insured
- i) any member of the insured's family, or a paid driver who has been driving the car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
- ii) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the insured.
- Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.
- 9. Limitations as to use***
Use only for social, domestic and pleasure purposes and for the Insured's business.
The Policy does not cover
Use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.
- 10. ExcelDrive Workshops & Accident Reporting**
It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.
- It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, otherwise claim is not payable.
In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6226 3323
- Visit www.sompo.com.sg for list of ExcelDrive Workshops and Accident Reporting Centers.
- 11. Loss of Use**
As provided in policy wordings.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.26

Sompo Insurance Singapore Pte. Ltd.



Date/Time of Issue : 25 JANUARY 2017 17:15

**Limitation rendered inoperative by section 8 of the Motor Vehicles(Third-Party Risks and Compensation)Act (Chapter 189 and section 95 of the Road Transport Act, 1987(Malaysia), are not to be Included under these headings.*

IMPORTANT NOTICE

- Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicles without a valid policy of insurance under the Act.
- Insureds are further warned that on the sale of a motor vehicle or if for any reason the Insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189)
- The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
- Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.
- Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy

Intermediary Code & Name : 11C14709 & CHIA NGAN BOEY CI Code: 22A FDJDPZT4KD4YMOAA

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|----------------------------|--|
| Date Of Report | 16/11/2017 11:57 |
| Date Of Accident | 15/11/2017 12:45 |
| Exact Location Of Accident | JUNCTION OF TELOK BLANGAH RISE / TELOK BLANGAH WAY |
| Country/State of Loss | SINGAPORE |

| DETAILS OF OWN VEHICLE | |
|--|-------------------------------------|
| Vehicle Registration Number | SGP9938T |
| Insured/Policyholder | |
| Name Of Registered Owner | CHIA KAI CHEW |
| NRIC No | S7819214C |
| Email Address | SYSINVEN@HOTOMAIL.COM |
| Mobile Phone No | (LOCAL) +65-98282889 |
| Alternative Phone No | OFFICE-98282889 |
| Vehicle Particulars | |
| Manufacturer | FORD |
| Model | MONDEO-2.3 TREND (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | REPORTING ONLY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | SOMPO INSURANCE SINGAPORE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | D17MTPV01002257 |
| Cover Note Number | |
| Driver | |
| Name of Driver | CHIA KAI CHEW |
| NRIC No | S7819214C |
| Date Of Birth | 06/06/1978 |
| Occupation | INDOOR |
| Date Of Driving Pass | 12/03/2009 |
| Driving Experience | 8 YEARS AND 8 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98282889 |
| Fax Number | |
| Contact Number | OFFICE-98282889 |
| Email Address | SYSINVEN@HOTOMAIL.COM |

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BUKIT MERAH WEST NPC

Police Station Address ROAD: 500 BUKIT MERAH VIEW #01-01 , POSTCODE: 159682 ,
COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT /STATEMENT & SKETCH

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE2096A

Vehicle Make/Model/Colour ISUZU FORWARD FV

Details Of Properties

Name of Driver LEE KOK LEONG

NRIC/Passport Number S1810551I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature

Date & Time: 16TH Nov 2017
1157 HOURS

Driver's Signature

(If driver is not the policyholder)
Date & Time:


COMFORTDELORO ENGINEERING PTE LTD
203 SIN LING DRIVE
SINGAPORE 572717


Reporting Centre Personnel's Signature

Name: May Lin
NRIC/FIN No.: S13473841F

Sketch Plan Pg. 2

TELOK BLANGAH
CRESCENT

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

TRAFFIC LIGHT IN FAVOUR AND AETOS OFFICERS SIGNALLED SG9938T TO PROCEED WITH WAY. SG9938T MOVED FROM LOCATION ① TO LOCATION ②. SG9938T WAS STATIONARY AT LOCATION ①. SG9938T MOVED OFF SLOWLY TO LOCATION ② DUE TO UNEVEN ROAD SURFACE OF ROAD WORKS. SG9938T WAS FIRST CAR IN LOCATION ①. XE 2096A SPEEDUP FROM ITS LOCATION ①, WHEN SG9938T SAW XE 2096A FROM ITS RIGHT BLINDSPOT, NEARING LOCATION ② SG9938T APPLIED EMERGENCY BRAKES. HOWEVER XE 2096A PERFORMED SHARP LEFT TURN, DESPITE SG9938T HAD STOPPED AND HORNED XE 2096A TO WARN OF DANGER IN COLLISION. XE 2096A SHARP LEFT TURN AND FAST ACCELERATION HAD IMPACT AND KNOCKED INTO SG9938T AT LOCATION ②. XE 2096A HAD ONLY MANAGED TO STOP ONLY AT LOCATION ③ AFTER THE ACCIDENT. SG9938T HAD REMAINED STATIONARY AT LOCATION ③ AFTER THE ACCIDENT.

FURTHER INFORMATION, PLEASE REFER TO POLICE REPORT No. T/2017115/2151 DATED: 15TH Nov 2017 TIMED: 1734 HOURS

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 16TH Nov 2017
1143 HOURS

Driver's Signature
(if driver is not the policyholder)
Date & Time:

COMFORTDELTA ENGINEERING PTE LTD
303 SIN KANG DRIVE
SINGAPORE 702777

Reporting Centre Personnel's Signature
Name: May Lin
NRIC/FIN No.: S137387F



Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

Report No. T/20171115/2151

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|------------------|--------------------------|
| Date/Time Report Made: 15/11/2017 17:34 | Vide Report No.: | Station Diary No.: 33 |
|--|------------------|--------------------------|

Informant's Particulars

| | | | | | |
|--|------------|------------------------------|---|----------------------------|--|
| Name of Informant: CHIA KAI CHEW | | | Address: APT BLK 58 TELOK BLANGAH HEIGHTS #11-39 SINGAPORE 100058 | | |
| ID Type / ID No.: NRIC NO / S7819214C | | | Contact No.: Home/Office: Mobile: 98282889 | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 39 | Date of Birth: 06/07/1978 | Type of Informant: Driver | | |
| Race: Chinese | | | Language: | Institution / School Name: | |
| Occupation: Self Employed | | | Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry: | | |

General Information of the Accident

| | | | | |
|---|------------|---|--|-------------------------------------|
| Type of Accident: | Non-Injury | Drink Drive: No | Date/Time of Accident: 15/11/2017 12:45 | Type of Location: |
| Location: Junction of Road 1 and Road 2 TELOK BLANGAH RISE TELOK BLANGAH WAY Traffic Junction of Telok Blangah Rise towards Telok Blangah Way | | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: |
| Traffic Flow: | | Traffic Control: Controlled by Others e.g. Workmen | | Traffic Volume: |
| Type of Collision: | | | | Anyone conveyed by ambulance: No |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No. of Passenger |
|-------------|--------|-------|--|--------|------------------|------------------|
| SGP9938T | Car | FORD | MONDEO TREND 2.3 4-DOOR AUTOMATIC | Silver | Slightly Damaged | 1 |
| XE2096A | TANKER | ISUZU | | | | 1 |

Details of Vehicle Insurance

| Vehicle No. | Insurance Company | Insurance No. | Effective | Expiry Date |
|-------------|-------------------|---------------|-----------|-------------|
|-------------|-------------------|---------------|-----------|-------------|



Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date and time, I was travelling along Telok Blangah Rise on the left lane on a two way lane in my vehicle registration number SGP9938T. There were road works on going at the said junction and the traffic was controlled by AETOS officer and the contractor workers. As the road towards Telok Blangah Way was in the midst of road works, the left lane was closed thus I have to turn in towards the right lane. The right lane along Telok Blangah Rise was also closed due to the road works. I was the asked to proceed to make my left turn by the AETOS officer and as I was turning in, I was able to see from my right side that an Oil Tanker registration number XE2096A was speeding up towards the same direction.

I then immediately stop my vehicle and horn at the said tanker however he continue driving and subsequently the left rear of the tanker hit the right side of my vehicle causing the bumper and the front right side to be damage. Both me and the tanker driver alighted from our vehicles, made a check and took photos of the accident. Subsequently we move our vehicle to the left lane so as to not block the traffic. Both me and said driver exchange particulars and we both agreed to claim from our insurance company.

The said driver also had right up a statement indicating that he was at fault and acknowledge the accident and claiming from the insurance. I also observed that there was an in car camera in the Tanker. The passenger of the Tanker also provided his particulars: Kenny S1796686C. That's all.



Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 NURUL 'AIN BINTE NOR RIZAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/11/2017 17:34

Officer In Charge Of Case:

TP / GIA /


Staff Sgt TANG SIEW PING

Contact No.: 65476430

Classification Of Case:

Authentication Stamp

NP168




SN 41

SKETCH PLAN

TELOK BLANGAH
CRESCENT

RW ROAD WORKS LANE C/C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

| |
|---|
| TRAFFIC LIGHT IN FAVOUR AND AETOS OFFICERS SIGNALLING SGP9938T TO PROCEED WITH WAY. SGP9938T MOVED FROM LOCATION ① TO LOCATION ②: SGP9938T WAS STATIONARY AT LOCATION ①. SGP9938T MOVED OFF SLOWLY TO LOCATION ② DUE TO UNEVEN ROAD SURFACE OF ROAD WORKS. SGP9938T WAS FIRST CAR IN LOCATION ①. XE 2096A SPEED UP FROM ITS LOCATION ③, WHEN SGP9938T SAW XE 2096A FROM ITS RIGHT BLINDSPOT, NEARING LOCATION ② SGP9938T APPLIED EMERGENCY BRAKES. HOWEVER XE 2096A PERFORMED SHARP LEFT TURN, DESPITE SGP9938T HAD STOPPED AND HORNED XE 2096A TO WARN OF DANGER IN COLLISION. XE 2096A SHARP LEFT TURN AND FAST ACCELERATION HAD IMPACT AND KNOCKED INTO SGP 9938T AT LOCATION ②. XE 2096A HAD ONLY MANAGED TO STOP ONLY AT LOCATION ③ AFTER THE ACCIDENT. SGP9938T HAD REMAINED STATIONARY AT LOCATION ② AFTER THE ACCIDENT. |
| FURTHER INFORMATION, PLEASE REFER TO POLICE REPORT No. T/20171115/2151 DATED: 15TH Nov 2017 TIMED: 1734 HOURS |
| |
| |
| |
| |
| |
| |
| |

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time: 16TH Nov 2017
1143 HOURS

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name: Mary Lim
NRIC/FIN No.: S13473871F

17th November 2017

Mr. Chia Kai Chew
Blk. 58 Telok Blangah Heights #11-39
Singapore 100058

M/S. MSIG Insurance (Singapore) Pte Ltd
Motor Claim Department
16 Raffles quay #24-01
Hong Leong Building
Singapore 048581

Fax: 62257402

Dear Sir/Madam,

Accident on 15/11/2017 junction of Telok Blangah Rise/Telok Blangah way
Involving vehicles no: SGP 9938T & XE 2096A


I the owner of vehicle no: SGP 9938T had involved an accident with your
Insured Vehicle no: XE 2096A.

The accident was caused solely by your Insured's negligence and I am proceeding
A THIRD PARTY claim against you whatever cost incurred by me.

Meanwhile kindly arrange your assessor to pre-survey my damaged vehicle at M/S
Seng Kin Motor Works of Blk. 1 Sin Ming Industrial Estate #01-131 Singapore 575636
Contact no: 64536238 within two days hereof this letter.

Enclose herewith our driver's IDAC accident report for your perusal.

Yours faithfully



Encl:
c.c. seng kin motor works



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGP 9938T

INSPECTION





Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate

#01-131 Singapore 575636.

TEL: 64536238, 64532961 FAX: 64580453

B. Reg. No. 111182/00W

CHIA KAI CHEW

APT. BLK.58 TELOK BLANDAH HEIGHTS #11-39

SINGAPORE 100058

Attention: Motor Claim Department

Contact: 98282889

Estimate: ES000077

Date: 16/11/2017

Vehicle Num.: SGP 9938T

Make/Model: FORD MONDEO-2009

Chassis/Eng#: WFODXXG8BD9E24835

Accident Date: 15/11/2017

Claim No.:

Reference: TP/SKMSIG/2017/024

Policy No.: D17MTPV0100-2257

Amended Estimate

Not Authorized

Revised B4 paint

8 7296.00 7310

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

| LIST ITEMS: | | |
|-------------|--------|---------------------------------------|
| 1. | 2 PCS | FRT. O/S & N/S HEADLAMP ASSY |
| 2. | 2 PCS | FRT. O/S & N/S HEADLAMP LOWER BRACKET |
| 3. | 1 PCE | FRT. SUPPORT PANEL |
| 4. | 1 PCE | FRT. RADIATOR GRILLE |
| 5. | 10 PCS | FRT. GRILLE CLIPS |
| 6. | 1 PCE | FRT. BUMPER |
| 7. | 1 PCE | FRT. O/S BUMPER NOZZLE COVER |
| 8. | 1 PCE | FRT. O/S BUMPER NOZZLE MOTOR |
| 9. | 1 PCE | FRT. O/S BUMPER INNER PART |
| 10. | 1 PCE | FRT. BUMPER REINFORCEMENT |
| 11. | 1 PCE | FRT. BUMPER SPONGE |
| 12. | 1 PCE | FRT. BUMPER CENTRE GRILLE |
| 13. | 1 PCE | RADIATOR ASSY |
| 14. | 1 PCE | AIR-COND CONDENSER |

Air - cond

List Total S\$:

18.00% Discount S\$:

208

NETT ITEMS:

| | | |
|----|-------|-------------------|
| 1. | 1 PCE | FRT. O/S FENDER |
| 2. | 1 PCE | FRT. O/S TYRE RIM |

Nett Total S\$:

| | | |
|----------|-----------|---|
| 1,860.00 | 3,720.00 | ✓ |
| 125.00 | 250.00 | X |
| | 1,160.00 | ✓ |
| | 280.00 | ✓ |
| 3.50 | 35.00 | ✓ |
| | 1,498.00 | ✓ |
| | 81.00 | ✓ |
| | 541.00 | ✓ |
| | 105.00 | ✓ |
| | 1,422.00 | X |
| | 195.00 | X |
| | 220.00 | X |
| | 1,365.00 | X |
| | 2,040.00 | X |
| | 12,912.00 | |
| | 1,936.80 | |
| | 10,975.20 | |

| | | |
|---|----------|---|
| R | 750.00 | ✓ |
| R | 350.00 | X |
| | 1,100.00 | |

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate
#01-131 Singapore 575636.
TEL: 64536238, 64532981 FAX: 64580453
B. Reg. No. 111182/OOW

CHIA KAI CHEW
APT. BLK.68 TELOK BLANDAH HEIGHTS #11-39
SINGAPORE 100058

Attention : Motor Claim Department
Contact : 98282889

Estimate : ES000077

Date : 16/11/2017
Vehicle Num. : SGP 9938T
Make/Model : FORD MONDEO-2009
Chassis/Eng# : WFODXXGBBD9E24835
Accident Date : 15/11/2017
Claim No. :
Reference : TP/SK/MSIG/2017/024
Policy No. : D17MTPV0100-2257

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

LABOUR :
LABOUR CHARGES TO REMOVE AIR-COND, CONDENSER, TO
REPLACE NEW & REFIX SAME & REFILL GAS.

100/ 150.00

LABOUR TO REMOVE & REFIT BODY DAMAGED PARTS, CUT, WELD
PANEL BEAT, STRAIGHTEN & REALIGN FRT. AFFECTED PARTS.

600/ 900.00

TO PUTTY AND SPRAY PAINT

600/ 900.00

TO SPRAY UNDERSEAL.

30/ 40.00

Labour Total S\$:

1,890.00

14,011.95

E. & O.E.

Total S\$: 13,965.20

for Seng Kin Motor Works



成金摩嘜 Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate

#01-131 Singapore 575636.

TEL: 64536238, 64532961 FAX: 64580453

B. Reg. No. 111182/OOW

CHIA KAI CHEW

APT. BLK 58 TELOK BLANDAH HEIGHTS #11-39

SINGAPORE 100058

Attention : Motor Claim Department

Contact : 98282889

Estimate : ES000077

Date : 16/11/2017

Vehicle Num. : SGP 9938T

Make/Model : FORD MONDEO-2009

Chassis/Eng# : WFODXXG8BD9E24835

Accident Date : 15/11/2017

Claim No. :

Reference : TP/SK/MSIG/2017/024

Policy No. : D17MTPV0100-2257

Not Authorized
21 Sep 8?
Resony After Pain

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

- LIST ITEMS :
1. 2 PCS FRT. O/S & N/S HEADLAMP ASSY
 2. 2 PCS FRT. O/S & N/S HEADLAMP LOWER BRACKET
 3. 1 PCE FRT. SUPPORT PANEL
 4. 1 PCE FRT. RADIATOR GRILLE
 5. 10 PCS FRT. GRILLE CLIPS
 6. 1 PCE FRT. BUMPER
 7. 1 PCE FRT. O/S BUMPER FOG LAMP
 8. 1 PCE FRT. O/S BUMPER FOG LAMP COVER
 9. 1 PCE FRT. BUMPER REINFORCEMENT
 10. 1 PCE FRT. BUMPER SPONGE
 11. 1 PCE FRT. BUMPER REINFORCEMENT
 12. 1 PCE FRT. BUMPER SPONGE
 13. 1 PCE FRT. BUMPER CENTRE GRILLE
 14. 1 PCE RADIATOR ASSY
 15. 1 PCE AIR-COND CONDENSER

List Total S\$:

15.00% Discount S\$:

- NETT ITEMS :
1. 1 PCE FRT. O/S FENDER
 2. 1 PCE FRT. O/S TYRE RIM

Nett Total S\$:

| | | | |
|---------------|----------|-----------|----------|
| <i>my car</i> | 1,860.00 | 3,720.00 | <i>L</i> |
| | 125.00 | 250.00 | <i>7</i> |
| | | 1,160.00 | <i>7</i> |
| <i>car</i> | | 280.00 | <i>7</i> |
| <i>3.50</i> | | 35.00 | <i>7</i> |
| <i>R</i> | | 1,498.00 | <i>7</i> |
| | | 551.00 | <i>7</i> |
| <i>NSP</i> | | 125.00 | <i>7</i> |
| | | 1,422.00 | <i>7</i> |
| <i>my car</i> | | 175.00 | <i>7</i> |
| <i>R</i> | | 1,422.00 | <i>X</i> |
| <i>5</i> | | 195.00 | <i>X</i> |
| <i>5</i> | | 220.00 | <i>X</i> |
| <i>5</i> | | 1,365.00 | <i>X</i> |
| | | 2,040.00 | <i>7</i> |
| | | 14,458.00 | |
| | | 2,168.70 | |
| | | 12,289.30 | |
| <i>R</i> | 750.00 | <i>L</i> | |
| <i>R</i> | 350.00 | <i>X</i> | |
| | | 1,100.00 | |

CONTINUE / ...

1. Name of the insured

2. Address of the insured

3. Name of the insured's agent

4. Name of the insured's agent

5. Name of the insured's agent

6. Name of the insured's agent

7. Name of the insured's agent

8. Name of the insured's agent

9. Name of the insured's agent

10. Name of the insured's agent

11. Name of the insured's agent

12. Name of the insured's agent

13. Name of the insured's agent

14. Name of the insured's agent

15. Name of the insured's agent

16. Name of the insured's agent

17. Name of the insured's agent

18. Name of the insured's agent

19. Name of the insured's agent

20. Name of the insured's agent

21. Name of the insured's agent

22. Name of the insured's agent

23. Name of the insured's agent

24. Name of the insured's agent

25. Name of the insured's agent

26. Name of the insured's agent

27. Name of the insured's agent

28. Name of the insured's agent

29. Name of the insured's agent

30. Name of the insured's agent

31. Name of the insured's agent

32. Name of the insured's agent

33. Name of the insured's agent

34. Name of the insured's agent

35. Name of the insured's agent

36. Name of the insured's agent

37. Name of the insured's agent

38. Name of the insured's agent

39. Name of the insured's agent

40. Name of the insured's agent

41. Name of the insured's agent

42. Name of the insured's agent

43. Name of the insured's agent

44. Name of the insured's agent

45. Name of the insured's agent

46. Name of the insured's agent

47. Name of the insured's agent

48. Name of the insured's agent

49. Name of the insured's agent

50. Name of the insured's agent

51. Name of the insured's agent

52. Name of the insured's agent

53. Name of the insured's agent

54. Name of the insured's agent

55. Name of the insured's agent

56. Name of the insured's agent

57. Name of the insured's agent

58. Name of the insured's agent

59. Name of the insured's agent

60. Name of the insured's agent

61. Name of the insured's agent

62. Name of the insured's agent

63. Name of the insured's agent

64. Name of the insured's agent

65. Name of the insured's agent

66. Name of the insured's agent

67. Name of the insured's agent

68. Name of the insured's agent

69. Name of the insured's agent

70. Name of the insured's agent

71. Name of the insured's agent

72. Name of the insured's agent

73. Name of the insured's agent

74. Name of the insured's agent

75. Name of the insured's agent

76. Name of the insured's agent

77. Name of the insured's agent

78. Name of the insured's agent

79. Name of the insured's agent

80. Name of the insured's agent

81. Name of the insured's agent

82. Name of the insured's agent

83. Name of the insured's agent

84. Name of the insured's agent

85. Name of the insured's agent

86. Name of the insured's agent

87. Name of the insured's agent

88. Name of the insured's agent

89. Name of the insured's agent

90. Name of the insured's agent

91. Name of the insured's agent

92. Name of the insured's agent

93. Name of the insured's agent

94. Name of the insured's agent

95. Name of the insured's agent

96. Name of the insured's agent

97. Name of the insured's agent

98. Name of the insured's agent

99. Name of the insured's agent

100. Name of the insured's agent



成金摩嘜 Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate
#01-131 Singapore 575636.
TEL: 64536238, 64532961 FAX: 64580453
B. Reg. No. 111182/OOW

CHIA KAI CHEW
APT. BLK 58 TELOK BLANDAH HEIGHTS #11-39
SINGAPORE 100058

Attention : Motor Claim Department
Contact : 98282889

Estimate : ES000077

Date : 16/11/2017
Vehicle Num. : SGP 9938T
Make/Model : FORD MONDEO-2009
Chassis/Eng# : WFODXXG8BD9E24835
Accident Date : 15/11/2017
Claim No. :
Reference : TP/SK/MSIG/2017/024
Policy No. : D17MTPV0100-2257

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

| | | | | |
|--|--|--|-----|----------|
| LABOUR : | | | | |
| LABOUR CHARGES TO REMOVE AIR-COND, CONDENSER, TO REPLACE NEW & REFIX SAME & REFILL GAS. | | | | 150.00 ? |
| - | | | | |
| LABOUR TO REMOVE & REFIT BODY DAMAGED PARTS, CUT,WELD , PANEL BEAT, STRAIGHTEN & REALIGN FRT. AFFECTED PARTS. | | | 60m | 900.00 |
| - | | | | |
| TO PUTTY AND SPRAY PAINT | | | 60m | 800.00 |
| - | | | | |
| TO SPRAY UNDERSEAL. | | | 30l | 40.00 |
| Labour Total S\$: | | | | 1,890.00 |

E. & O.E.

Total S\$: 15,279.30

=====

for Seng Kin Motor Works

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|------|-------------|---------------|--|---|---|-------------|---|
| Main | 17 Nov 2017 | | 20 Nov 2017 14:43 Edit Adj Rpt | \$7,310.00 Edit Estimates | \$7,310.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | Highway International Private Limited, Co. Reg. No.: 197501285M | | |
| Main Claimant: | CHIA KAI CHEW, ID: S7819214C | | |
| Vehicle Reg. No.: | SGP9938T | Date of Loss: | 15/11/2017 00:00 - :59 |
| Claim Type: | TP / 537213 | Policy/Cover Note No.: | 28816838MKC Coverage: 26/08/2017 - 25/08/2018 |
| Vehicle Reg. No. (Insured): | XE2096A | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Seng Kin Motor Works (HQ) BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636, 575636 Sin Ming - Tel: | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2017] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SGP9938T (537213)**

[XE2096A]

TP

CHIA KAI CHEW






























Nov 15 2017 12:00AM

[Highway International Private Limited]

Seng Kin Motor Works

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ▼

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|-----------------|---|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/11/17 14:52 | Adjuster Immediate Advice |  Load HTM | |
| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 27/11/17 14:41 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 22/02/18 11:41 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |

| | | | | | |
|---|----------------|-----------------------|--|----------|--|
| 1 | 20/11/17 14:46 | PRI and TP GIA Report |  | Load PDF | |
|---|----------------|-----------------------|--|----------|--|

Documents Checklist

| | | | |
|--|--------------|-------------|--------------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022203/KVBE2
Date: 26/02/2018

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|-------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 28816838MKC |
| Claimant Vehicle No : | SGP9938T | Insured Vehicle No : | XE2096A |
| Date of Loss: | 15/11/2017 | Nature of Claim: | TP |
| | | Claim No: | 537213 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|------------------------------------|-----------------------------------|--------------------|-------------------|
| Reg No: | SGP9938T | Engine No: | 9E24835 |
| Make & Model: | FORD MONDEO, 2.0 TREND S/W (A) | Chassis No: | WF0DXXGGBD9E24835 |
| Reg. Date: | 17/08/2010 (Man. Year: 2009) | Odometer: | 113093 km |
| Colour: | Metallic Grey | | |
| Engine Capacity: | 2261 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|---------------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|--------------------------|------------------|-------------------------|------------------|
| Front Tyre Size: | 235/45 R17 | Rear Tyre Size: | 235/45 R17 |
| Front Left Side: | Continental 7 mm | Rear Left Side: | Continental 7 mm |
| Front Right Side: | Continental 7 mm | Rear Right Side: | Continental 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 12,121.95 | 5,980.00 | 6,141.95 | 50.67 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,890.00 | 1,330.00 | 560.00 | 29.63 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (\$\$) | 14,011.95 | 7,310.00 | 6,701.95 | 47.83 |

INSPECTION

| | | |
|------------------------------------|------------|--|
| Date of Assignment: | 20/11/2017 | Seng Kin Motor Works (HQ) |
| Date Inspected: | 24/11/2017 | Inspected At: |
| | | BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131, |
| | | Singapore 575636 |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Feb 2018)

Parts: N/A FORD MONDEO 2.0 TREND S/W (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGP9938T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|-------------|-------------|--------------|
| 1 | 2 | | *FRT O/S & N/S HEADLAMP ASSY | MTG Cracked | 3,720.00 FL | *3,720.00 FL |
| 2 | 2 | | *FRT O/S & N/S HEADLAMP LOWER BRACKET | Serviceable | 250.00 FL | *- FL |
| 3 | 1 | | *FRT SUPPORT PANEL | Cracked | 1,160.00 FL | *1,160.00 FL |
| 4 | 1 | | *FRT RADIATOR GRILLE | Cracked | 280.00 FL | *280.00 FL |
| 5 | 10 | | *FRT GRILLE CLIPS | Necessary | 35.00 FL | *35.00 FL |
| 6 | 1 | | *FRT BUMPER | Bent | 1,498.00 FL | *1,498.00 FL |
| 7 | 1 | | *FRT O/S BUMPER NOZZLE COVER | Cracked | 81.00 FL | *81.00 FL |
| 8 | 1 | | *FRT O/S BUMPER NOZZLE MOTOR | Cracked | 541.00 FL | *541.00 FL |
| 9 | 1 | | *FRT O/S BUMPER INNER PART | Cracked | 105.00 FL | *105.00 FL |
| 10 | 1 | | *FRT BUMPER REINFORCEMENT | Repair | 1,422.00 FL | *- FL |
| 11 | 1 | | *FRT BUMPER SPONGE | Serviceable | 195.00 FL | *- FL |
| 12 | 1 | | *FRT BUMPER CENTRE GRILLE | Serviceable | 220.00 FL | *- FL |
| 13 | 1 | | *RADIATOR ASSY | Serviceable | 1,365.00 FL | *- FL |
| 14 | 1 | | *AIR-COND CONDENSER | Serviceable | 2,040.00 FL | *- FL |
| 15 | 1 | | *AIR-DUST | Missing | 55.00 FL | *55.00 FL |
| 16 | 1 | | *FRT O/S FENDER | Repair | 750.00 FS | *- FS |
| 17 | 1 | | *FRT O/S TYRE RIM | Repair | 350.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (S\$) | 14,067.00 | 7,475.00 |
| - List Item Discount on L Items 15.00/20.00% (S\$) | 1,945.05 | 1,495.00 |
| Total Parts (S\$) | 12,121.95 | 5,980.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO REMOVE AIR-COND, CONDENSER, TO REPLACE NEW & REFIX SAME & REFILL GAS | New | 150.00 | 100.00 |
| 2 | LABOUR TO REMOVE & REFITT BODY DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN FRT AFFECTED PARTS | New | 900.00 | 600.00 |
| 3 | TO PUTTY AND SPRAY PAINT | New | 800.00 | 600.00 |
| 4 | TO SPRAY UNDERSEAL | New | 40.00 | 30.00 |
| Gross Labour Cost (S\$) | | | 1,890.00 | 1,330.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >