

ASSIGNMENT REF: REF CS3/MSG17018815 / W 10-17 ^{range}

WILSON
ASSIGNMENT (Office)
From (Person): Irene Tan @ MSIG Date/Time: 21.11.2017

Estimated Cost: _____
OD / (TP) WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: G22179K Insured: YN1975K

at Workshop of: Michelin Engineering Tel: 90475313
of 56 Loyang Way, #06-07, 508775

Policy No: A28695601MCC Claim No: 531386/II

Sum Insured: _____ Excess: _____
Make of Veh: _____ DOA: 28/9/17
(Client's Record):

CA / REV / REP. / REV 24 HRS 'up'
Date/Time: 21/10/17 10:19am Person Contacted: Malcom

Vehicle IN (OUT) OUT

Date/Time	Action/Instruction (X) Estimate	DO NOT INITIALISE
	G22179K-x	
	YN1975K-x	
	Dismantle Part: 09.10.2017	
	After repair: 17.10.2017	

30.10.17 3:56pm Email to Irene Tan thru merimen.

5/12/17 Submit LS \$2500 (Red 600, 1990), 3 days,

[Signature]
5/12/2017

RECEIVED 05 DEC 2017

PRS

REF: MBH

Refimen

ASSIGNMENT

From: Date: 06102017

Veh No: GZ 2179K Yr Reg: 2006 / Jun 20

Estimated Cost

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: GZ 2179K
at Workshop m/s: Michelin Engineering
of: 56 Loyang Way #06-07

Make: Mitsubishi L300 cc 2477

Colour: white, A/C Insured / Std / NI / NA

Sp. Reading: 616274 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: JMAJNP15VBAD00744

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 195 R14 C

R: 195 R14 LT.

Bal. or Market Value:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

IDAC Accident Report: Consistent? : Yes or No

TOYO / YOKO or CST (K) Bright Way (K)

GIA / PR Seen: Consistent? : Yes or No

Front R/Bal: 4 mm R/Bal: 4 mm

Est. Repairs: days Res: Yes or No

L/Bal: 4 mm L/Bal: 4 mm 11-15mm

Lum Sum: % 3 Val: Yes or No

D.O.A. D.O.I: 6/10/2017

CA / REV / REP. / 24 HRS

Survey held at: 56 Loyang Way

Date: Person Contacted:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Accident Report Not Available
Fit Windscrew spot cracked and LHF Signal lamp
cover cracked (side) found not accident
related.

Range -> \$3300 - \$4500

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

1) 01.11.2017

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: Site Insp (\$)

Transportation:

Report Format: PRS

Interview (\$)

\$ + RS \$

Lump Sum / I.B.I: (\$)

Tech. Insp (\$)

Photos

Weekend (\$)

Others

TOTAL

Signature
11/11/2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17018815/Wvb-1

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1975K	Veh. Inspected	GZ 2179K
Policy No.		Coverage (\$)	0.00
Claim No.	531386/IT	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/09/2017	Inspection Date	21/11/2017
Survey held at	MICHELIN ENGINEERING PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

5a. Remarks

<p>A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.</p>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Auth'd	Status
Main	28 Sep 2017		02 Oct 2017 09:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LION CITY DISTRIBUTION PTE LTD, Co. Reg. No.: 200400525E		
Main Claimant:	ATLANTIS CAR & TRUCK RENTAL PTE LTD, Co. Reg. No.: 201511709R		
Vehicle Reg. No.:	GZ2179K	Date of Loss:	28/09/2017 11:00 - :50
Claim Type:	TP / 531386	Policy/Cover Note No.:	A28695601MKC (Comprehensiv Coverage: 22/03/2017 - 21/03/2018)
Vehicle Reg. No. (Insured):	YN1975K	Policy No. (Claimant):	
Repairer:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way,, #06-07 Loyang Enterprise Building,, 5087751 64404428		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] due 23/11/2017]		
Driver/Custodian (Insured):	ZHANG YUNYU (), NRIC: 0 75297882, Tel: +6581197164		

[View All](#) [Complete](#)

ASSOCIATED MAIL RECEIVED

- MSIG_SG (21/11/2017): Report Send Back Alerts - GZ2179K (TP)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Delete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Created By
No results.									

Catherine Chong (LKK Auto)

From: Irene Tan <irene_tan@sg.msig-asia.com>
Sent: Tuesday, 21 November, 2017 3:55 PM
To: Veron Chen (LKKAuto); Shiau Chan (LKKAuto)
Cc: assignments; Admin-D (LKKAuto)
Subject: Please prepare paper survey report of 3rd party's vehicle no.: GZ21777. Our claim no.: 531386/IT

Dear Veron,

We refer to your PRI report dated 3.11.17.

Please prepare and upload your paper survey report into the Merimen asap.

Best Regards

Irene Tan

Senior Executive, Claims Services (Motor)

Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 0485811 | T: +65 6220


9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



EAST ASIA LAW CORPORATION

Advocates & Solicitors

133 New Bridge Road #10-02
 Chinatown Point Singapore 059413
 Tel: 65 6323 2565 Fax: 65 6323 2373
 E-mail: law@ealc.com.sg
 Website: www.ealc.com.sg

Kasturibai Manickam
 Jocinda Wong Jia Heng

ACRA Reg. No.
 200309625D

(Service of Court documents by way of fax is not accepted)



T

Our Ref: 2017.6208.EA.MK.YA
 Your Ref: YN1975K 531396

13-Nov-2017

WITHOUT PREJUDICE

PDX#6173
 MSIG INSURANCE SINGAPORE PTE LTD
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807
 Attn: Motor Claims Department

CERTIFICATE OF POSTING
 LION CITY DISTRIBUTIONS PTE LTD
 9 Woodlands Link
 Singapore 738723

PDX Intercompany Exchange Ltd

 01 00149803
 FROM EAST ASIA LAW CORP.
 PDX Ref No: 6208

Dear Sir,

CLAIMANT: ATLANTIS CAR & TRUCK RENTAL PTE LTD
ACCIDENT INVOLVING GZ2179K & YN1975K ON 28 SEPTEMBER 2017 ALONG HOUGANG STREET 11 (BESIDE THE PARK RESIDUAL)
LOADING AT ABOUT 1115 HOURS

ATLANTIS CAR & TRUCK RENTAL
 We act for ATLANTIS CAR & TRUCK RENTAL PTE LTD, the owner of vehicle no. GZ2179K, whose vehicle was damaged as a result of the above-mentioned accident by vehicle no. YN1975K and our search reveals that you were the insurers of motor vehicle no. YN1975K.

We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1)	Costs of repair	\$	3,100.00
2)	Loss of Use (PR1 2+7)	\$	1,350.00
3)	Survey report fee	\$	589.00
4)	LTA search fee	\$	8.00
5)	GIA search fee/report fee	\$	29.00
6)	Costs + GST	\$	963.00
7)	Incidentals + GST	\$	53.50
	Total:	\$	6,092.50

We enclose copies of the following documents supporting our client's claim for your attention:-

- 1) GIA accident report of our client's repo GZ2179K
- 2) LTA search for YN1975K
- 3) Final repair bill for GZ2179K
- 4) Original Survey report enclosing original color copies of photographs depicting damages to vehicle no. GZ2179K
Enclosed document may be photocopied on both sides to save paper and be environment friendly.

Please note that if you are insured and you wish to claim your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days from the receipt of this letter failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. The amount claimed herein is quantified based on the supporting documents in our file. Until a settlement is reached, all negotiations are conducted on a without prejudice basis that the damages quantified herein are subject to revision if so instructed.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us the particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

Kasturibai Manickam
 East Asia Law Corporation

Enc.
 cc:

Ref: GZ2179K

Shu Hui
 1. ↑ TOB
 2. Upload
 3. Mkl

10348j
 15

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2017 15:35
Date Of Accident	28/09/2017 11:15
Exact Location Of Accident	HOUANG STREET 11 (BESIDE THE COFFEE SHOP) LOADING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ2179K
Insured/Policyholder	
Name Of Registered Owner	ATLANTIS CAR & TRUCK RENTAL PTE LTD
Co Reg No	201511709R
Email Address	PANPACIFICLEASING22@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64404428

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	L300 HR M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5079651876-01
Cover Note Number	13/01/2017 TO 12/01/2018

Driver

Name of Driver	SARAWANAN ARUMUGAM
NRIC No	S8682177Z
Date Of Birth	11/12/1986
Occupation	OUTDOOR
Date Of Driving Pass	08/04/2013
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87191909
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address APT BLK 627 PASIR RIS DRIVE 3 #04-332 (S) 510627

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE

Weather Conditions DRIZZLING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN1975K

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver ZHANG YUNYU

NRIC/Passport Number G2162381

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

28/9/2017
15:57



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: G22195K

B: YN1975K ←



Accident Sketch Plan Pg. 1

Describe Circumstances of the Accident

I am arrived about 11.00 am to deliver goods to clinic (Daily Clinic) at Hungary st 11. Unfortunately the loading bay occupied and I waited about 10 minutes. While I waited I do stop the engine, and put hazard light, ~~stand~~ go out stand beside the my Van.

About 11:15 am I hear sound that my in front ~~van~~ my hit my van that the van going out never realise behind got van.

Insurance Co. MetLife


Vehicle No. CR2411 Date of Accident 20/7/2012

Reporting Only
 Own Damage Claim
 Third Party Claim
 Other Workshop

Declaration

We declare the foregoing particulars are true in every respect.

POLICYHOLDER'S SIGNATURE / DATE & TIME

DRIVER'S SIGNATURE (if driver is not the policyholder) / DATE & TIME




WITNESSED BY REPORTING CENTRE PERSONNEL

Enquire PARF/COE Rebate for Registered Vehicle

D.O.A → 28/9/2017

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	1709R
Vehicle Details	
Vehicle No.	GZ2179K ^{19 30 01 2021}
Vehicle to be Exported	Yes ^{28 09 2017}
Intended De-registration Date	04 Dec 2017 ^{21 2 3}
Vehicle Make	MITSUBISHI (0.7 March)
Vehicle Model	L300 HR M
Primary Colour	White ^{Bel → 3 yrs 2-7 month}
Manufacturing Year	2005 ^{→ 38-7 month}
Engine No.	4D56LA6130
Chassis No.	JMAJNP15V6A000744
Maximum Power Output	-
Open Market Value	\$12,445.00 ^{Average Depreciation}
Original Registration Date	20 Jan 2006 ^{→ \$7336/yr}
First Registration Date	20 Jan 2006 ^{→ \$611.33/month}
Transfer Count	2
Actual ARF Paid	\$623.00 ^{* M.V}
Intended PARF Rebate Details	^{→ \$611.33/month x 38-7 month}
PARF Eligibility	No
PARF Eligibility Expiry Date	- ^{= \$23658.47}
PARF Rebate Amount	\$0.00 [→]
Intended COE Rebate Details	
COE Expiry Date	19 Jan 2021
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	5
PQP Paid	\$22,583.00
COE Rebate Amount	\$14,108.00
Total Rebate Amount	\$14,108.00
Message	^{Nett Value = \$23658.47}

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 04 Dec 2017

→ \$14,108.
= \$9550.47



MYCARFORUM
MARKETPLACE
Buy / Sell Parts & Accessories
> click here to visit now!

Username / Email Add
password Submit Qu
Connect Sign Up New Account
Forgot Password

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

5/16 Infiniti Q50 2.0A Premium, Wearnes Warranty.



Infiniti Engine Delivers
Impressive Power, R171"
S/Rims, Pirelli Tires, 1 Owner
Shine Connect StarAd

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [View our cars](#)

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 40 results/page

16 vehicles

Mitsubishi L300

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi L300		Any	Any	Any	Any	Any	Any	Available
	Mitsubishi L300 (COE till 06/2021)		\$26,800	\$7,520 /yr	28-Jun-2006	2,477 cc	-	Van	Available
	Fuel Type: Diesel								
	Cheapest In Market, Excellent Condition, Price Negotiable, High Loan Available With Low Interest, Very Reliable Van, Call Fast To View And Check Condition Before Drop By.								PREMIUM AD
	ABWIN Bus Pte Ltd Posted: 04-Dec-2017 Tags: 2006 Mitsubishi L300, 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, L300, Used Mitsubishi								
	Mitsubishi L300 (COE till 04/2022)		\$26,800	\$6,080 /yr	06-May-2002	2,477 cc	-	Van	Available
	Fuel Type: Diesel								
	Original Condition! Reliable Work Horse! Engine And Gearbox In Very Good Condition! Price Negotiable! Up To 100% Loan Available! All Kind Od Trade -In Are Welcome! High Performance L300 To Bring You Ar...								PREMIUM AD
	ABWIN Bus Pte Ltd Posted: 04-Dec-2017 Tags: 2007 Mitsubishi L300, 2002 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, L300, Used Mitsubishi								
	Mitsubishi L300 (COE till 07/2019)		\$11,500	\$6,950 /yr	04-Aug-2004	2,477 cc	-	Van	Available
	Fuel Type: Diesel								
	Owned And Selling First Hand By Owner. COE Is Left With 1 Year 8 Months, Can Be Renewed After That If You Wish. Call/Msg/Email Me For Any Information.								CREDIT OWNER
	Posted: 02-Dec-2017 Tags: 2004 Mitsubishi L300, 2004 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, L300, Used Mitsubishi								
	Mitsubishi L300 (COE till 07/2020)		\$20,777	\$7,910 /yr	21-Jul-2005	2,477 cc	-	Van	Available
	Fuel Type: Diesel								
	One Of The Cheap And Reliable Vans Compared To Other Model, Easy To Maintain, Showroom Condition, New Paint And Leather Seats, High Trade In And High Loan Available, For More Information Please Contact...								PREMIUM AD
	KSL Automotive Pte Ltd Posted: 01-Dec-2017 Tags: 2005 Mitsubishi L300, 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, L300, Used Mitsubishi								
Car Buying	Car Selling	Car Aftermarket							
Car Ownership	On The Move	Lifestyle							
	Mitsubishi L300 (COE till 11/2019)		\$17,800	\$9,040 /yr	24-Nov-2004	2,477 cc	-	Van	Available
	Fuel Type: Diesel								
	Brilliant, 1 Owner, Mileage Low, Condition That You Won't Scrap, Classic And Easy To Maintain, Call Fast, Don't Miss The Best L300 In Town.								PREMIUM AD
	ABWIN Bus Pte Ltd Posted: 01-Dec-2017 Tags: 2004 Mitsubishi L300, 2004 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, L300, Used Mitsubishi								
	Mitsubishi L300 (COE till 07/2020)		\$22,800	\$8,690 /yr	20-Jul-2005	2,477 cc	-	Van	Available
	Fuel Type: Diesel								
	5 Door Unit! New Paint! Engine And Gearbox Condition Tip Top! High Loan High Trade In Available! See To Believe! Call Us Now To Arrange Door Step View!								PREMIUM AD
	Net Link Partners Pte Ltd Posted: 01-Dec-2017 Tags: 2005 Mitsubishi L300, 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, L300, Used Mitsubishi								

Richied Carplates For Sale



Mitsubishi L300 (COE till 09/2020) \$20,800 \$7,360 /yr 04-Oct-2005 2,477 cc - Van Available
Fuel Type: Diesel
 ETS Eligible, Good Condition, Too Good To Scrap, High Paper Value, Come With New Paint, Few Unit To Choose From
 Posted: 01-Dec-2017 Tags: 2005 Mitsubishi L300, 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 09/2021) \$24,800 \$6,500 /yr 27-Sep-2006 2,477 cc - Van Available
Fuel Type: Diesel
 No Repairs Needed, Excellent Mint Condition, New Paint And Leather Seats, Low Mileage, High Trade In And High Loan Available, For More Information Please Contact Our Friendly Staff.
 Posted: 26-Feb-2017 Tags: 2006 Mitsubishi L300, 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 09/2021) \$27,222 \$7,140 /yr 27-Sep-2006 2,477 cc - Van Available
Fuel Type: Diesel
 Come With New Coat Of Paint, Most Wear And Tear Replaced. Please Call For Viewing. Easy High Loan Approval.
 Posted: 25-Nov-2017 Tags: 2006 Mitsubishi L300, 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 08/2020) \$22,800 \$8,380 /yr 24-Aug-2005 2,477 cc - Van Available
Fuel Type: Diesel
 Fast Loan Approval! Low Interest High Loan! Negotiable! Call Fast For An No Obligation Discussion! Door Step Viewing Possible!
 Net Link Partners Pte Ltd
 Posted: 23-Nov-2017 Tags: 2005 Mitsubishi L300, 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 07/2021) \$25,800 \$7,050 /yr 11-Aug-2006 2,477 cc - Van Available
Fuel Type: Diesel
 Price Including A New Paint, And Will Fully Do Up Everything, Engine Tip Top, That's Why We Didn't Scrap. Test It To Believe
 Posted: 11-Nov-2017 Tags: 2006 Mitsubishi L300, 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 10/2020) \$20,800 \$7,340 /yr 05-Oct-2005 2,477 cc - Van Available
Fuel Type: Diesel
 5 Doors, Well Maintained Van. Low Maintenance, Durable Japanese Van Used For Heavy Duty.
 Posted: 24-Oct-2017 Tags: 2005 Mitsubishi L300, 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 10/2020) \$21,800 \$7,530 /yr 27-Oct-2005 2,477 cc - Van Available
Fuel Type: Diesel
 Cheapest In Market! Flexible Loan Available! New Paint And No Repair Needed! Big Space Heavy Duty For Business. Call Us Now For Viewing!
 Posted: 17-Oct-2017 Tags: 2005 Mitsubishi L300, 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 01/2021) \$23,800 \$7,650 /yr 13-Jan-2006 2,477 cc - Van Available
Fuel Type: Diesel
 Well Maintain, High COE Value, New Paintwork, Rear Wooden Floor Board. Engine And Gearbox In Excellent Condition, All Wear And Tear Just Replaced. No Repair Needed.
 Posted: 16-Oct-2017 Tags: 2006 Mitsubishi L300, 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#)



Mitsubishi L300 (COE till 07/2021) \$25,000 \$6,840 /yr 25-Aug-2006 2,477 cc - Van Available
Fuel Type: Diesel
 Reliable And Well Maintained. New COE Until 31st July 2021. All Inquiries.
 Posted: 12-Oct-2017 Tags: 2006 Mitsubishi L300, 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#) **DIRECT OWNER**



Mitsubishi L300 (COE till 07/2021) \$22,750 \$6,220 /yr 16-Oct-2001 2,477 cc - Van Available
Fuel Type: Diesel
 Posted: 05-Oct-2017 Tags: 2001 Mitsubishi L300, 2001 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, L300, Used Mitsubishi [Details](#) **DIRECT OWNER**

Save this search criteria, to get email alerts whenever a match is found.

Make : Model : Price : Depreciation : Reg Date : Eng Cap : Mileage : Veh Type : Status

For old advertisements, view Expired ads

40 results/page

MPPM17128862 / Poon Poong Motors Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 28/09/2017 17:47

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 28/09/2017 17:47
 Date Of Accident 28/09/2017 11:10
 Exact Location Of Accident BLK 159 HOUGANG STREET 11
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YN1975K
Insured/Policyholder
 Name Of Registered Owner LION CITY DISTRIBUTION PTE LTD
 Co Reg No 200400525E
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No Office-68542775
Vehicle Particulars
 Manufacturer MITSUBISHI
 Model FE83BE6SRDEA
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken REPORTING ONLY
 Vehicle Category COMMERCIAL VEHICLE
Insurance Company
 Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy YES
 Policy Number A 28695601 MKC
 Cover Note Number
Driver
 Name of Driver ZHANG YUNYU
 Work Permit No 0 75297882
 Date Of Birth 02/05/1980
 Occupation OUTDOOR
 Date Of Driving Pass 10/10/2013
 Driving Experience 3 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-81197164
 Fax Number

Contact Number
 EMail Address NOEMAIL
 Address BLK 787D WOODLANDS CRESCENT
 #09-42
 Postcode 734787
 Was driver an employee of the Insured's
 Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own
 Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s)
 soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident**Attachment(s)**

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ2179K
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)
Details of Witness
 Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This form must be completed by the policyholder and/or the authorized driver.
3. Information provided must be truthful and accurate, as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind the policy liability.
4. The date and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false information may be referred to the Police for investigation.
6. The report will be forwarded by the Institute of the General Insurance Association of Singapore (GIAS) to the Institute of the General Insurance Association of Singapore (GIAS) for writing and the copies of the report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurer, you hereby consent to the archiving of this report in the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, and I agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIAS") require permitted to collect, use, disclose and/or process my personal data/personal information set out in the form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insured(s) who have insured vehicle(s) involved in the accident (insurers) and the insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers", the Insurers' law firm/ law firm, the Ministry of Justice of Singapore and any relevant government agency/authority (such as the police, for the purposes) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident under my claims;
 - (iii) carrying out further dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of enveloped/signed parcels); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insured(s) who have insured vehicle(s) involved in this accident and the Insurers' law firm/ law firm, may law permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may law be disclosed by any of the Insurers under GI to their third party service providers or agents (including their law firm/ firms), which may be based outside of Singapore, for one or more of the above Purposes.


 Policyholder's Signature / Date & Time
 S24 (b) Plan


 Driver's Signature (if driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel



A = YN 1975K
 B = GZ 2179K

Individual Statement

SINGAPORE ACCIDENT STATEMENT

Accident Date: 28/9/2017	Time: 11:10	(hh:mm) 24 hr format
Location: Woodlands Hill, BIK 159		
Vehicle Number: YN1975K		
Insured Name: Lion City Distribution Pte Ltd		
NRIC/FIN: 200400525E	Contact Number: 65542775	
Make: MITSUBISHI Model: FR-23BE-6SR-DEA		
Are you claiming under your own insurance policy for repair to your vehicle?		
<input type="checkbox"/> Yes If No, Pls select <input type="checkbox"/> Third Party <input checked="" type="checkbox"/> Reporting		
Insurance Company: M S L G		
Type of Policy <input checked="" type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire & Theft <input type="checkbox"/> TP Only		
Policy Number: A 28695601 MKC		
Name of Driver: Zhang YunYu <input type="checkbox"/> Same as Insured		
NRIC/FIN: G 2162381X	Contact Number: 81197114	
Date of Birth: 02-05-1980		
Driving Pass Date: 29/12/2013		
Occupation <input type="checkbox"/> Indoor <input checked="" type="checkbox"/> Outdoor		
Gender <input checked="" type="checkbox"/> Male <input type="checkbox"/> Female		
Email Address: <input checked="" type="checkbox"/> NO EMAIL		
Address of Driver: Woodlands Crescent BIK 484 D		
Hq - 112, S 734787		
Was driver an employee of the Insured's Company? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
If No, Relationship of the Driver with the Insured		
<input type="checkbox"/> Owner <input type="checkbox"/> Spouse <input type="checkbox"/> Friend <input type="checkbox"/> Relative <input type="checkbox"/> Children <input type="checkbox"/> Sibling		
Does the Driver Own Any Other Vehicle? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
If Yes, Vehicle Registration Number of Driver's Own Vehicle		
Insurance Company of Driver's Own Vehicle		
Weather Conditions <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Raining <input type="checkbox"/> Others		
Road Surface <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Wet <input type="checkbox"/> Others		
Was any foreign vehicle involved in this accident? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Was anybody injured in the accident? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
If yes, injured detail		
Was there any video captured by Car Camera? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Was the Accident reported to the Police? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes attach police report		
DETAILS OF 3 rd party Name / Nic Contact		
Veh B: G2 2179K		
Veh C:		
Veh D:		
Veh E:		
Veh F:		

Individual Statement

Michelin Engineering Pte Ltd

52 Joo Chiat Road Singapore 427374

Tel : 64404428 Fax : 83458516

Name : Atlantis Car & Truck Rental Pte Ltd
Address : c/o 52 Joo Chiat Road
Singapore 427374

Date : 26-Oct-17

FINAL REPAIR BILL FOR MITSUBISHI L300 NO. GZ 2179 K

Lump Sum Repair Cost

: \$ 3,100.00

Singapore Dollars : Three Thousand One Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 Autolay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

Invoice No 10-17015/AY

Billing Name & Address
Atlantis Car & Truck Rental Pte Ltd
c/o 52 Joo Chiat Road
Singapore 427374

Date 26 Oct 2017

Vehicle No : GZ 2179 K

Model : Mitsubishi L300

Item	Descriptions	Amount S\$
1	Date of inspection : <u>6 Oct 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>89</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 589.00</u>
	SDLS : FIVE HUNDRED AND EIGHTY-NINE ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

Report Reference : TP / 10-17015/AY / 2017

Date of Report : 26 Oct 2017

Atlantis Car & Truck Rental Pte Ltd
c/o 52 Joo Chiat Road
Singapore 427374

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 28 Sep 2017

As per your instruction dated 6 Oct 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle GZ 2179 K. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : GZ 2179 K
Model : Mitsubishi L300
Year / Capacity : 2006/2477
Chassis No : JMAJNP15V6A000744
Engine No : 4D56LA6130
Mileage : 616274
Colour : White

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 185 R14	CST	7.00	mm	Normal
REAR	O/S	: 185 R14	Brightway	6.00	mm	Normal
FRONT	N/S	: 185 R14	CST	7.00	mm	Normal
REAR	N/S	: 185 R14	Brightway	6.00	mm	Normal

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 2010002681D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Michelin Engineering Pte Ltd
52 Joo Chiat Road
Singapore 427374

5. Estimated normal period of repair : 7 working days to complete.

6. Enclosed number of photograph : 89 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: GZ 2179 K
 Report No: TP/ 10-17015/AY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Front panel ✓ DD	Damage	\$ 715.00	\$ 715.00 ✓
1	Front panel logo ✓	Necessary	\$ 48.00	\$ 48.00 ✓
1	Front panel protector	Damage	\$ 85.00	\$ 85.00 ✓
1	Front headlamp X NN	Intact	\$ 165.00	\$ X ✓
2	Front headlamp rim c/w side lamps ✓ SCR	Damage	\$ 210.00	\$ 210.00 ✓
1	Front bumper DD / SCR	Damage	\$ 641.00	\$ 641.00 ✓
1	Front bumper reinforcement R	Damage	\$ 185.00	\$ 185.00 X ✓
1	Front windscreen rubber ✓ NEC	Necessary	\$ 196.00	\$ 196.00 ✓
			<u>\$ 2245.00</u>	<u>\$ 2080.00</u>
<u>Special Nett Items</u>				
1	Front number plate ✓ DD	Damage	\$ 45.00	\$ 35.00 20 ✓
			<u>\$ 45.00</u>	<u>\$ 35.00</u>

→ \$ 1895

→ \$ 20

Spare Parts Total \$ 2290.00 \$ 2115.00

Vehicle No: GZ 2179 K
 Report No: TP/ 10-17015/AY / 2017

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 2290.00	\$ 2115.00
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 30
2	To remove and refit front windscreen glass.	\$ 150.00	\$ 100.00 60
3	To remove and refit dashboard, meters instrument, disconnect wirings, ductings, connectors to facilitate the repairs.	\$ 400.00	\$ 250.00 200
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 660.00 ✓
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 660.00 400
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 60.00 30 △
Total		\$ 4790.00	\$ 3885.00

→ \$1350

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 3100.00

SDLS: THREE THOUSAND ONE HUNDRED ONLY


 Qualified Appraiser

Parts \$1895.00
 Discount (10%) - \$189.50

 \$1705.50
 Parts (S.N) \$20.00

 \$1725.50
 + Labour \$1350.00 +30

 \$3075.50 +30
 - Discount (20%) - \$615.10

 \$2460.40

 2464.67

*Lump Sum → \$2450 | -2500
 Repair Day → 3 Days

Enquire Vehicle & Owner Information (Vehicle No. YN1975K As At 28 Sep 2017 11:15:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MICHELIN-GZ2179K

Current Owner Details

Owner ID Type: Company

Owner ID: 200400525E

Owner Name: LION CITY DISTRIBUTIONS PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: g

Registered Street Name: WOODLANDS LINK

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 738723

Current Vehicle Details

Vehicle No.: YN1975K

Make Description/Model: MITSUBISHI / FE83BE6SRDEA

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transaction.
Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution.
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)
Last updated on 17 Sep 2017 at 11:15:00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2017		02 Oct 2017 09:34 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	LION CITY DISTRIBUTION PTE LTD, Co. Reg. No.: 200400525E								
Main Claimant:	ATLANTIS CAR & TRUCK RENTAL PTE LTD, Co. Reg. No.: 201511709R								
Vehicle Reg. No.:	GZ2179K	Date of Loss:	28/09/2017 11:00 - :59						
Claim Type:	TP / 531386	Policy/Cover Note No.:	A28695601MKC (Comprehensive) Coverage: 22/03/2017 - 21/03/2018						
Vehicle Reg. No. (Insured):	YN1975K	Policy No. (Claimant):							
		Excess:							
Repairer:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way,, #06-07 Loyang Enterprise Building,, 508775 Loyang - Tel: 64404428								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 23/11/2017]								
Driver/Custodian (Insured):	ZHANG YUNYU (), NRIC: 0 75297882, Tel: +6581197164								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
● MSIG_SG (21/11/2017): Report Send Back Alerts - GZ2179K (TP)									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GZ2179K (531386)
[YN1975K]

TP

ATLANTIS CAR & TRUCK RENTAL PTE LTD

Sep 28 2017 11:00AM

[LION CITY DISTRIBUTION PTE LTD]

Michelin Engineering Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	02/10/17 09:32	Accident Statement <small>From: SC - Reg. No: YN1975K, Claimant: LION CITY DISTRIBUTION PTE LTD</small>		Load HTM			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	30/10/17 15:54	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
2	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
3	30/10/17 15:54	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
4	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
5	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
6	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
7	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
8	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
9	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
10	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
11	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
12	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
13	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
14	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
15	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
16	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
17	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
18	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
19	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
20	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
21	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
22	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
23	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
24	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
25	30/10/17 15:54	General View		Load JPG	<input checked="" type="checkbox"/>		
26	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
27	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
28	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
29	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
30	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
31	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
32	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
33	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
34	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
35	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
36	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
37	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
38	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		

39	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
42	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
43	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
44	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
45	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
46	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
47	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
48	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
49	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
50	30/10/17 15:55	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
51	30/10/17 15:55	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
52	30/10/17 15:55	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
53	30/10/17 15:55	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
54	30/10/17 15:55	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
55	30/10/17 15:55	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
56	30/10/17 15:55	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
57	30/10/17 15:55	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
MSIG Insurance (Singapore) Pte. Ltd. (HQ)				
1	02/10/17 09:32	GZ2179K GIA RPT <small>From: SC - Reg. No: YN1975K, Claimant: LION CITY DISTRIBUTION PTE LTD</small>	Load PDF	
2	02/10/17 09:33	Survey DISAGREE ON SJE, Appoint LKK as Surveyor	Load PDF	
3	02/10/17 09:34	Request Pre-Repair Inspection	Load PDF	
4	21/11/17 14:00	LOD	Load PDF	
5	21/11/17 14:03	Repair Bill, Survey Report & Fees	Load PDF	
6	21/11/17 14:03	PHOTO 1	Load PDF	
7	21/11/17 14:07	PHOTO 2	Load PDF	
8	21/11/17 14:08	PHOTO 3	Load PDF	
9	21/11/17 14:12	PHOTO 4	Load PDF	
10	21/11/17 14:13	PHOTO 5	Load PDF	
11	21/11/17 14:14	Enquiry Vehicle & Owner Info	Load PDF	
12	21/11/17 15:55	Instruction to LKK Auto to prepare paper survey report	Load PDF	
LKK Auto Consultants Pte Ltd (HQ)				
No	Relabel/Reorder		Thumbnail	Print
1	07/12/17 11:33	PRS INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid gray; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17018815/MVBS2-1
Date: 07/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28695601MKC
Claimant Vehicle No :	GZ2179K	Insured Vehicle No :	YN1975K
Date of Loss:	28/09/2017	Nature of Claim:	TP
			Claim No: 531386

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ2179K	Engine No:	4D56LA6130
Make & Model:	MITSUBISHI L300 HR M, 2.5 D (M)	Chassis No:	JMAJNP15V6A000744
Reg. Date:	20/01/2006 (Man. Year: 2005)	Odometer:	616274 km
Colour:	White		
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R14C	Rear Tyre Size:	195 R14LT
Front Left Side:	CST 4 mm	Rear Left Side:	Brightway 4 mm
Front Right Side:	CST 4 mm	Rear Right Side:	Brightway 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,290.00	1,725.50	564.50	24.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,380.00	1,120.00	44.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,790.00	3,105.50	1,684.50	35.17
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	4,790.00	2,500.00	2,290.00	47.81

INSPECTION

Date of Assignment:	02/10/2017	
Date Inspected:	06/10/2017 Inspected At:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way., #06-07 Loyang Enterprise Building, Singapore 508775
Estimated Period of Repair:	3.0 days	

Adjuster: Teo Cheng Ming Wilson

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Dec 2017)	
Parts:	N/A	MITSUBISHI L300 HR M 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ2179K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	715.00 F	*715.00 FN
2	1		*FRONT PANEL LOGO	Necessary	48.00 F	*48.00 FN
3	1		*FRONT PANEL PROTECTOR	Damaged	85.00 F	*85.00 FN
4	1		*FRONT HEADLAMP	Not Necessary	165.00 F	*- FN
5	2		*FRONT HEADLAMP RIM C/W SIDE LAMPS	Scratched	210.00 F	*210.00 FN
6	1		*FRONT BUMPER	Dented / Scratched	641.00 F	*641.00 FN
7	1		*FRONT BUMPER REINFORCEMENT	Repair	185.00 F	*- FN
8	1		*FRONT WINDSCREEN RUBBER	Necessary	196.00 F	*196.00 FN
9	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,290.00	1,915.00
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	189.50
Total Parts (\$\$)	2,290.00	1,725.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS HEADLAMPS.	New	50.00	30.00
2	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.	New	150.00	60.00
3	TO REMOVE AND REFIT DASHBOARD, METERS INSTRUMENT, DISCONNECT WIRINGS, DUCTINGS, CONNECTORS TO FACILITATE THE REPAIRS.	New	400.00	200.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TP THE ORIGINAL POSITION USING POWER TOOLS.	New	900.00	660.00
5	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	900.00	400.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	100.00	30.00
Gross Labour Cost (S\$)			2,500.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >