

REF: AXA

Surveyor: Tan JH

ASSIGNMENT

From: _____ Date: 16/11/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 8602Eat Workshop m/s Sng Ah Teeof Blk 3 Pioneer Rd North # 01-18

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XD8602E Yr Regn: 2014 Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz 3336 c.c. 11946Colour: white A/C: Insured / Std / NI / NASp. Reading: 233555 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB93061622L75+348Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Ni / S/Rim / STD A/Rim orTyre Size: F: 315/80R22.5R: u u (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 9 mm Rear 9/9 mmR/Bal. 9 mm R/Bal. 9h mmL/Bal. 9 mm L/Bal. 9h mmD.O.A. _____ D.O.I. 10/11/17 @ 4pmSurvey held at Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt m/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0681R

Vehicle Details

Vehicle No.: XD8602E

Vehicle to be Exported: No

Intended De-registration
Date: 30 Apr 2017

Vehicle Make: MERCEDES BENZ

Vehicle Model: 3336/6X4

Primary Colour: Orange

Manufacturing Year: 2013

Engine No.: 541972C0898520

Chassis No.: WDB9301622L757348

Maximum Power Output: -

Open Market Value: \$144,654.00

Original Registration Date: 13 Feb 2014

First Registration Date: 13 Feb 2014

Transfer Count: 0

Actual ARF Paid: \$7,233.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Feb 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$55,503.00

COE Rebate Amount: \$37,655.00

Total Rebate Amount: \$37,655.00

The information contained herein is correct as at 29 Apr 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)