

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTI (PA
	8	1			REAR SHOCK ABSORBER DUST COVER LH			Serviceable	0		20		0	Rev
	9	1			REAR SHOCK STOPPER LH			Serviceable	0		20		0	Rev
	10	1			REAR LOWER ARM LH			Serviceable	0		20		0	Rev
	11	1			REAR LOWER ARM BALL JOINT LH			Serviceable	0		20		0	Rev
	12	1			REAR WHEEL COVER LH (HONDA)			Serviceable	0		20		0	Rev
	13	1			REAR BUMPER COVER LH			Cut	210		20		168	Rev
	14	1			REAR BUMPER			Cut	800		20		640	Rev
	15	1			SET REAR BUMPER CLIPS			Necessary	50		20		40	Rev
	16	1			REAR BUMPER RETAINER LH			Necessary	24.8		20		19.84	Rev
	17	1			REAR BUMPER BRACKET LH			Serviceable	0		20		0	Rev
	18	1			REAR BUMPER REFLECTOR LH			Serviceable	0		20		0	Rev

Detailed Assessment

Inspection Date *

11/21/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/60R16

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

215/60R16

FNOL INFORMATION...

POST SURVEY INF...

CATEGORY	Address type
FNOL INFORMATION...	
POST SURVEY INF...	▼

CATEGORY	Gender
FNOL INFORMATION...	Unknown
POST SURVEY INF...	▼

CATEGORY	Marital status
FNOL INFORMATION...	Unknown
POST SURVEY INF...	▼

CATEGORY	Identification #
FNOL INFORMATION...	S7607351A
POST SURVEY INF...	

POLICY INFORMAT... TPVD SLC4445R HONDA

ASSESSMENT INFO...

HONDA

CATEGORY

Model

POLICY INFORMAT... VEZEL

ASSESSMENT INFO...

VEZEL 1.5X CVT

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

RU11106841

POST SURVEY INF...

CATEGORY

Date of Birth

FNOL INFORMATI...

December 31, 1899

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

Age

FNOL INFORMATI...

118

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

Direct settlement

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Add

Additional Instructions

TRANSFER CASE C0460021 Pls follow up frm Smartclaims.

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	7/12/18 4:49 PM	1700	1700	Open	Share	Clone
ANG Flossie	12/5/17 9:33 AM	2171.84	2171.84	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	------------------

Direct settlement

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Documents

History

Invoices

Messages

Notes

Metrics

Assessment

Document Type

TRANSFER CASE C0460021 Pls follow up frm Smartclaims.

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP ESTIMATE MARKED - REVISED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 12, 2018
LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 12, 2018
LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 12, 2018