


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB15C
 Ref. No : TAX/11/17/2129
 Reg. Date : 13/04/2011
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : RAJAMANIKAM S/O
 A.K.VELLOO
 Type of Accident : OTHERS
 Date / Time of Accident : 20/11/2017 02:30:00 PM
 Accident Reported Date / Time : 21/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093215
 Special Instruction to ARC,if any :
 SDU3233S *all/Reson after repair*
 Prepared Date : 21/11/2017 12:14:42 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB021697

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 756.00	0.00
Total Material Charges	: 1,894.54	1,933.20
Other Charges	: 488.44	0.00
TOTAL	: 3,476.98	0.00
Lum Sum Total	: 3,500.00	0.00
No. of Repair Days	: 3.00	0.00 3 day - Long run
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 21/11/2017 04:18:54 PM	01/01/1900 12:00:00 AM

 21/11/17 04:18:54

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/11/2017 04:18:54 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	338.00	0.00 300
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO REPSRAY FRONT BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0.00 148.44
Total Other Costs	488.44	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96636328	RIGHT	6504581	PANEL FRT FENDER RH	1	606.00	10.00	545.40	Replace	Replace <i>Due</i>	No
93744489	FRONT	6504592	BUMPER FRT ASSY	1	1,238.00	10.00	1,114.20	Replace	Replace <i>Due</i>	No
96644858	FRONT	6504614	LAMP HEAD RH	1	841.00	10.00	756.90	Replace	Replace <i>Due</i>	No
TOTAL MATERIALS							2,416.50	2,416.50		
TOTAL MATERIALS(Discounted)							1,894.54	1,933.20		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									