

Surveyor *P. Gnan*

REF: AXA

04657

ASSIGNMENT

From: _____ Date: 30/11/2017

Estimated Cost: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGA 8198M

at Workshop m/s Cycle & Carriage
of 209 Pandan Garden

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Andre

11am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGA 8198M

Yr Regn: 2014 Dec

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: CITROEN GRAND C4 PICASSO 1.6 1560

Colour: BLUE A/C Insured / Std / NI / NA

Sp. Reading: 80810 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF 73A9H C86 J615590

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/11/17 D.O.I. 30/11/17

Survey held at C&C CPN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

☐ S-RS (\$

☐ Photos

☐ Charts

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$